

CITY OF MILWAUKEE

2020 FEB -5 P 3: 06

CITY CLERK'S OFFICE

January 29, 2020

City Clerk
200 E. Wells St, Room 205
Milwaukee, WI 53202-3567

RE: C.I. File No. 1030-2020-58

RECEIVED
OFFICE OF CITY ATTORNEY


FEB 10 2020

3:30 A.M./P.M.

City Attorney:

I received your response to my claim on Wednesday, January 29, 2020. I am appealing your decision and am requesting a hearing. Per your letter I am enclosing a photocopy of the letter's envelope.

Sincerely,



Michael Spence


2689 S. Kinnickinnic Ave, Apt 1
Milwaukee, WI 53207

262-620-5129
mspence8@wi.rr.com

**OFFICE OF
JULIE E. HARRIS**
CITY ATTORNEY
City Hall
111 West Wells Street
Milwaukee, WI 53202-3551

Michael Spence
2689 S. Kinnickinnic Avenue, Apt. 1
Milwaukee, WI 53207

PRESORTED
FIRST CLASS



U.S. POSTAGE PITNEY BOWES
ZIP 53005 \$ 000.38³
02 4W
0000358386 JAN 24 2020

ALL SPS 53207



Michael Spence
2689 S. Kinnickinnic Ave. Apt 1
Milwaukee, WI 53207

CITY OF MILWAUKEE

2020 FEB - 5 P 3:06

CITY CLERK'S OFFICE

City Clerk
200 E. Wells St. Room 205
Milwaukee, WI 53202

CITY CLERK'S OFFICE

2020 JAN 29 PM 1:59

CITY OF MILWAUKEE

January 2, 2020

City Clerk
200 E. Wells St, Room 205
Milwaukee, WI 53202-3567

ATTN: CLAIMS

City Clerk:

RECEIVED
OFFICE OF CITY ATTORNEY

JAN 2 - 2020


3:45 A.M./P.M.

CITY OF MILWAUKEE
2020 JAN -2 P 1:28
CITY CLERK'S OFFICE

On December 30, 2019 at approximately 9:45 P.M. I was involved in an accident with a City of Milwaukee Department of Public Works snow plow (City vehicle Number 25283). It was snowing and the roads were slippery. I was travelling below posted speed northbound on S. Lincoln Memorial Drive. I was turning left toward Carferry Drive there is no stop sign for that movement. A City of Milwaukee snowplow was heading south on S. Lincoln Memorial Drive toward the intersection with Carferry Drive. There is a stop sign for vehicles heading southbound. The snowplow was apparently trying to stop but slid into the intersection where I was turning left. When I saw he was coming into the intersection as I was turning I applied my brakes but ended up sliding into the plow. I sustained heavy damage to the right front end of my vehicle.

I am making a claim for the repair to my vehicle which I think is justified. I have received 2 estimates (attached). I would like to go with Marshall Auto Body. Please review and contact me. I'd like to get the repair done as soon as possible.

Sincerely,



Michael Spence

2689 S. Kinnickinnic Ave, Apt 1
Milwaukee, WI 53207

262-620-5129
mspence8@wi.rr.com



Marshall Service, Inc.

22300 W. Bluemound Rd.
Waukesha, WI 53186
(262) 549-4300 Fax: (262) 549-2080

Est # 79964

Page 1 of 2

Estimate of Repairs

MICHAEL SPENCE
2689 South Kinickinic Ave Apt 1
Milwaukee, WI 53207

(262) 620-5129
(262) 366-7202

Date: 1/2/2020 11:56:28 AM

Make: 2015 Toyota
Model: Prius Two
Style: 4D H/B
License: 113-LDY
Color: Pearl White
VIN No: JTDKN3DU2F0440917
Mileage At Estimate: 132865

Ins. Co:
Adjuster:
Claim #:
Date of Loss:

RECEIVED
OFFICE OF CITY ATTORNEY

JAN 2 - 2020

3:45 A.M./P.M.

Line	Line Items	Parts	Labor	Refinish
C 1	FRONT BUMPER & GRILLE			
C 2	Repl Bumper cover w/o LED h'lamp	266.24 E		
C 3	Repl Bumper cover w/o LED h'lamp			3.3 R
C 4	O/H front bumper		2.5 B	
C 5	Add for Three Stage			2.3 R
C 6	Repl RT Side retainer	48.99 E	0.1 B	
C 7	Repl Spoiler	181.33 E		
C 8	Repl Energy absorber	56.34 E		
C 9	R&I License bracket		0.2 B	
C 10	R&I Lower grille w/o Plug-in w/o fog lamps			
C 11	Repl Emblem w/o precrash	57.29 E		
C 12	Blend RT Tow eye cap			0.1 R
C 13	Blend LT Tow eye cap			0.1 R
C 14	FRONT LAMPS			
C 15	Repl RT Headlamp assy w/o plug-in	305.61 E	0.5 B	
C 16	Aim headlamps		0.5 B	
C 17	Repl RT Turn signal lamp	257.76 E		
C 18	R&I LT Turn signal lamp			
C 19	WINDSHIELD			
C 20	Repl Washer reservoir w/o h'lamp washer	107.92 E	0.7 B	
C 21	FENDER			
C 22	Repl LT Fender	235.53 E	2.3 B	
C 23	Repl LT Fender			2 R
C 24	Deduct for Overlap		-0.3	
C 25	Add for Three Stage			1.4 R
C 26	Repl RT Fender liner w/o Plug-in	92.75 E	0.5 B	
C 27	FRONT DOOR			
C 28	Blend RT Door shell (HSS)			1.4 R
C 29	R&I RT Belt molding		0.3 B	
C 30	R&I RT R&I mirror		0.3 B	
C 31	R&I RT Handle, outside w/"Smart key" white p		0.4 B	
C 32	R&I RT R&I trim panel		0.5 B	
C 33	Flex Paint Additive	7.00 H		
C 34	Haz. Waste Disposal	5.00 W		



Marshall Service, Inc.

Est # 79964

Page 2 of 2

22300 W. Bluemound Rd.
Waukesha, WI 53186
(262) 549-4300 Fax: (262) 549-2080

Estimate of Repairs

MICHAEL SPENCE
2689 South Kinickinic Ave Apt 1
Milwaukee, WI 53207

(262) 620-5129
(262) 366-7202

Date: 1/2/2020 11:56:28 AM

Make: 2015 Toyota
Model: Prius Two
Style: 4D H/B
License: 113-LDY
Color: Pearl White
VIN No: JTDKN3DU2F0440917
Mileage At Estimate: 132865

Ins. Co:
Adjuster:
Claim #:
Date of Loss:

RECEIVED
OFFICE OF CITY ATTORNEY

JAN 2 - 2020

3:45 A.M.P.M.

C	35	Rough Pull		2	F
C	36	Paint Materials	424.00		

		Estimate
OEM Parts (E)	0 @ 0	1,609.76
	Parts	1,609.76
Body Labor (B)	8.5 @ 60	510.00
Refinish Labor (R)	10.6 @ 60	636.00
Structural Labor (F)	2 @ 80	160.00
	Labor	1,306.00
Hardware & Repair Materials (H)	0 @ 0	7.00
Hazardous Waste (W)	0 @ 0	5.00
Paint Materials (P)	0 @ 0	424.00
	Materials	436.00
	SUBTOTAL	3,351.76
	SALE TAX Rate=5.1%	170.94
	TOTAL	3,522.70
	Customer Subtotal	3,522.70
	Deductible	0.00
	Customer Total	3,522.70
	Insurance Total	0.00

THIS IS NOT A FINAL BILL

I hereby authorize the repair work to be done along with necessary parts & materials. You and your employees may operate vehicle for purposes of testing, inspection or delivery. An express mechanics lien is acknowledged on vehicle to secure the amount of repairs thereto. Marshall Services Inc. will not be held responsible for loss or damage to articles left in vehicle in case of fire, theft or accident. I acknowledge that I am responsible for all repair charges incurred. This specifically includes any insurance company deductible payments and Betterments (depreciation). Marshall Services Inc. will work directly with the insurance company (if ins. pay), and any charges not covered by insurance will be my sole responsibility. I acknowledge that I am responsible for all costs associated with the collection of unpaid amounts including but not limited to reasonable attorney fees. I authorize Marshall Services Inc. to act as power of attorney to sign insurance checks to pay for damages to above vehicle. I Authorize you to dispose of old parts unless otherwise instructed in writing on this authorization form. I authorize Marshall Auto Body to obtain sublet services as necessary for the proper repair of said vehicle.

Signed _____ DATE _____

MAACO COLLISION REPAIR & AUTO PAINTING
2775 SOUTH 166TH STREET
NEW BERLIN, WI 53151
PH: (262)784-9540 FAX: (262)784-4195
FEDERAL TAX ID #39-1492087

*** PRELIMINARY ESTIMATE ***

01/02/2020 09:58 AM

Owner

Owner: Michael Spence
Address: 2689 S. Kinnickinnic Ave. Apt. 1
City State Zip: Bay View, WI 53207

Work/Day: (262)620-5129
FAX:

Inspection

Inspection Date: 01/02/2020 09:59 AM

Inspection Type:

Appraiser Name: Myles Beck

Appraiser License # :

Repairer

Repairer: Maaco Collision Repair
Address: 2775 S. 166th Street
City State Zip: New Berlin, WI 53151
Email: maaconewberlin@hotmail.com

Contact:
Work/Day: (262)784-9540
FAX: (262)784-4195

Target Complete Date/Time:

Days To Repair: 8

RECEIVED
OFFICE OF CITY ATTORNEY

Vehicle

JAN 2 - 2020

3:45 A.M./P.M.

2015 Toyota Prius I 4 DR Hatchback
4cyl Hybrid 1.8
Continuously Variable Tr

Lic Expire:
Veh Insp# :
Condition:
Ext. Color: BLIZZARD PRL
Ext. Refinish: Three-Stage User Defined
Ext. Paint Code: 070

VIN: JTDKN3DU2F0440917
Mileage Type: Actual
Code: Y1923A
Int. Color:
Int. Refinish: Two-Stage
Int. Trim Code:

Options

1st Row LCD Monitor(s)
Air Conditioning
Auto Headlamp Control
Carpeting
Color-Keyed Bumper(s)
Digital Clock
Dual Airbags
Illuminated Visor Mirror
Keyless Ignition System
MP3 Decoder
Power Door Locks
Power Windows
Rear Window Defroster

2nd Row Head Airbags
Aluminum/Alloy Wheels
Auxiliary Audio Input
Center Console
Compact Spare Tire
Driver Information Sys
Electric Steering
Intermittent Wipers
LED Brakelights
Overhead Console
Power Mirrors
Projector Beam Headlamps
Rear Window Wiper/Washer

AM/FM CD Player
Anti-Lock Brakes
Bucket Seats
Climate Control For A/C
Daytime Running Lights
Driver Knee Airbag
Head Airbags
Keyless Entry System
Lighted Entry System
Power Brakes
Power Quarter Windows
Pwr Accessory Outlet(s)
Side Airbags

Split Folding Rear Seat	Stability Cntrl Suspensn	Strg Wheel Radio Control
Theft Deterrent System	Tilt Steering Wheel	Tinted Glass
Tire Pressure Monitor	Touch Screen Display	Traction Control System
Trip Computer	USB Audio Input(s)	Velour/Cloth Seats
Wireless Audio Streaming	Wireless Phone Connect	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Front Bumper										
1	EP	6		Cover,Front Bumper	Replace PXN	\$214.00			2.9	SM
2	L	6	14	Cover,Front Bumper	Refinish				5.5	RF
					3.3 Surface					
					1.0 Three-stage setup					
					1.2 Three-stage					
3	EP	12		Supt,Frt Bumper Cover RT	Replace PXN	\$37.00			INC	SM
4	EP	45		Spoiler,Lower Front	Replace PXN	\$151.00			INC	SM
5	E	22		Absorber,Front Bumper	5261147080	\$45.71			0.2	SM
Front End Panel And Lamps										
6	EP	42		Lens,Headlamp RT	Replace PXN	\$259.00			INC	SM
7	EP	1524		Lens,Indicator Lamp RT	Replace PXN	\$197.00			0.1	SM
Radiator Support										
8	EP	64	07	Crsmbr,Rad Panel Upr RT	Replace PXN	\$29.00			1.9	SM
9	L	64		Crsmbr,Rad Panel Upr RT	Refinish				0.6	RF
					0.5 Surface					
					0.1 Two-stage					
Cooling And Air Conditioning										
10	E	159	01	Reservoir,W/S Washer	8531547110	\$62.98			0.5	SM
Front Body And Windshield										
11	I	83		Panel,Hood Aluminum	Repair				1.0*	SM
12	L	83		Panel,Hood	Refinish				3.7	RF
					2.7 Surface					
					1.0 Three-stage					
13	EP	104		Fender,Front RT	Replace PXN	\$200.00			0.4	SM
14	L	104		Fender,Front RT	Refinish				3.2	RF
					1.9 Surface					
					0.5 Edge					
					0.7 Three-stage					
					0.1 Two-stage					
Front Body Interior Sheetmetal										
15	EP	130		Skirt,Inner Fender RT	Replace PXN	\$71.00			INC	SM
Front Doors										
16	BR	208		Door Shell,Front RT High Strength Steel	Blend Refinish				1.4	RF
					0.7 Blend					
					0.7 Three-stage					
17	RI	426		Mldg,Front Door Belt RT	R & I Assembly				1.4	SM
18	RI	230		Mirror,Outer R/C RT	R & I Assembly				0.3	SM
19	RI	228		Handle,Front Door Otr RT	R & I Assembly				0.6	SM

Manual Entries

20 L	Flex Additive	Refinish			
21 SB	Hazardous Waste	Sublet Repair	\$10.00*	0.1*	SM
22 I	Rough Pull Front End	Repair		2.0*	SM*
22 Items					

MC Message

01 CALL DEALER FOR EXACT PART # / PRICE
07 STRUCTURAL PART AS IDENTIFIED BY I-CAR
14 INCLUDES 1.0 HOURS FIRST PANEL THREE-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$108.69	
Other Parts		\$1,158.00	
Paint & Materials	14.4 Hours @ \$40.00	\$576.00	
Parts & Material Total			\$1,842.69
Tax on Parts & Material	@ 5.100%		\$93.98

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs		
Sheet Metal (SM)	\$60.00	8.4	3.0	11.4	\$684.00	
Mech/Elec (ME)	\$95.00					
Frame (FR)	\$68.00					
Refinish (RF)	\$60.00	14.4		14.4	\$864.00	
Labor Total				25.8 Hours		\$1,548.00
Tax on Labor		@ 5.100%			\$78.95	
Sublet Repairs					\$10.00	
Tax on Sublet		@ 5.100%			\$0.51	
Gross Total						\$3,574.13
Net Total						\$3,574.13

Alternate Parts Y/08/08/00/00/00 CUM 08/08/00/00/00 Zip Code: 53151 Audatex Host
Recycled Parts NOT REQUESTED
Rate Name Default

Audatex Estimating 8.0.643 Update 6 ES 01/02/2020 10:03 AM REL 8.0.643 Update 6 DT 12/01/2019
© 2020 Audatex North America, Inc.

0.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
4.6 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S THREE-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned

UC = Replace Reconditioned
N = Additional Labor
IT = Partial Repair
P = Check

TT = Two-Tone
BR = Blend Refinish
CG = Chipguard
AA = Appearance Allowance

SB = Sublet Repair
I = Repair
RI = R & I Assembly
RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

