



ELEVATION NOTES

GENERAL NOTES

- REPAIR AND RE-PAINT EXISTING WOOD TRIM BLACK
- TUCK POINT BRICK IN LIMITED AREAS W/ MORTAR TO MATCH TYPE, COMPOSITION AND COLOR OF EXISTING. PROVIDE SAMPLE AREA OF TUCKPOINTING, WITH BOTH CLEAN JOINTS AND REPOINTED JOINTS FOR REVIEW OF SHPO PRIOR FULL EXECUTION.
- REFURBISH EXISTING WINDOWS AS REQUIRED FOR FULL OPERATION, PAINT BLACK TO MATCH EXISTING

KEY NOTES

- 1** REPLACE EXISTING PIPE RAIL WITH NEW OR RECLAIMED WROUGHT IRON OR BRONZE HANDRAIL
- 2** REMOVE EXISTING CLAY TILES. POUR NEW SLAB PITCHED TO SCUPPERS FOR DRAINAGE. INSTALL NEW CLAY TILES TO MATCH TYPE, COLOR AND PATTERN INCLUDING BORDER
- 3** REPAIR AND REPAINT EXISTING WOOD BOX COLUMNS, CONSIDER FUTURE REPLACEMENT WITH COLUMNS TO MATCH HISTORIC PHOTOGRAPHS
- 4** NEW CANOPY/HOOD SIGN 7" X 120" = 6.75 SF
BRASS OR BRONZE LETTERS W/ GROUND PLACED SPOT UPLIGHTS

PROPOSED NEW WALL SIGN

SIGN MATERIAL
 STAINLESS STEEL BASE PLATE W/
 BLACK PATINA'D STAINLESS LETTERS
 SLIGHTLY RAISED FROM PLANE OF BASE PLATE
MOUNTING
 4 CORNER PIN MOUNT, CONCEALED, AND
 LOCATED IN MORTAR JOINTS OF MASONRY
ILLUMINATION
 CEILING MOUNTED SPOT LIGHT,
 SEE SPI.1 SITE PLAN FOR LOCATION

1 EAST ELEVATION
 A3.1 SCALE: 1/4" = 1' - 0"

DATE	REASON
06.11.19	HPC SUBMITTAL
08.13.19	BOZA SUBMITTAL
11.01.19	HISTORIC
04.28.20	EXTERIOR SIGNAGE