





HANDRAIL



COLUMN CAP



RAILING SPACER
1-1/8 THICK



RAILING
TOE RAIL

EXISTING RAILING DETAILS
920 N. 29TH ST.
10/28/2025