

August 25, 2025

City Clerk

Attn: Claims

200E. Wells Street, Room 205

Milwaukee, WI 53202

Dear Sir or Madam:

A tree hit our car and severely damaged my car and damaged the frame and three windows. The tree must've been neglected to be cut down properly and fell due to being old. I saw debris on top of my car one day from parking under the tree but didn't think anything of it, this was actually the tree getting ready to fall down which it did the next day. The tree stretched all the way across the street and was blocking the road.

We seeking \$13,000 due to the car being not safe and difficult to get it repaired. Our insurance said it's totalled.

Please contact Tyi and Arlene Carter at 414-364-7809, for any questions.

Also we can be reached by email at tyiacarter22@gmail.com

Tyi Carter

My address is 4805 N Sherman Blvd Apt. ⁴~~3~~
Milwaukee WI. 53209

OFFICE OF CITY ATTORNEY
27 AUG '25 PM 01:23

CITY OF M
2025 AUG 2
CITY CLERK



4805 N Shelburne
Blvd





3:54



RepairEstimate-25-7749... Done

TYI CARTER | 2016 Toyota Corolla S

Comment On: 8/15/2025 08:27 AM
Version: Mitchell Estimating 25.2 OEM AUG 25 V
Mitchell Cloud Estimating™
Copyright 1994-2025 Mitchell International, Inc.
All Rights Reserved
Printed On: 8/15/2025 08:27 AM
Profile: MILWAUKEE WI All Part Types
Page 1 of 8

Parts Profile
MILW WI All Part TypesParts Profile Version
4.0

LABOR					PART					
Line #	Description	Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax	
Front Bumper										
1	101089	Frt Bumper Cover	Remove / Install	Body	1.1#	Existing				
Front Lamps										
2	101092	L Front Combination Lamp	Remove / Install	Body	0.3#	Existing				
Front Fender										
3	101102	L Fender Outside	Blend	Refinish	0.8 C	Existing				
Windshield										
4	100689	W/Shield Glass	Remove / Replace	Glass	2.1#	Qual Recycled Part	270-61805- 58939	1	\$243.75	Yes
Rocker / Pillars / Floor										
5	100138	L Cowl/Dash Hinge Pillar -S	Remove / Replace	Body	10.8	New	61132-02340	1	\$350.28	Yes
6	AUTO	L Hinge Pillar	Refinish Only	Refinish	1.5 C					
7	102012	L Cowl/Dash Hinge Pillar Reinf (H55) -S	Remove / Replace	Body	3.0	Qual Recycled Part	N05044.2	1	\$218.75	Yes
8	100142	L Cowl/Dash Inner Hinge Pillar (H55) -S	Remove / Replace	Body	2.0	New	61024-02260	1	\$350.28	Yes
Front Door										
9	100604	L Frt Door Shell (Steel/Hss)	Remove / Replace	Body	5.5#	Qual Recycled Part	120-BB1571- 60478	1	\$600.00	Yes
10	AUTO	L Frt Door Outside	Refinish Only	Refinish	2.2 C					
11	AUTO	L Frt Add For Jamb & Interior	Refinish Only	Refinish	1.0 C					
12	AUTO	L Frt Add To R&L/R&R Side Air Bag Sensor	Remove / Replace	Mechanical	0.3					
13	100013	L Frt Door Rear View Mirror	Remove / Replace	Body	INC#	Qual Recycled Part	N05048.1	1	\$62.50	Yes
14	AUTO	L Frt Door Trim Panel	Remove / Install	Body	INC					
15	102074	L Frt Door Blackout Tape	Remove / Replace	Body	0.3#	Aftermarket New	7592202191- 0331LD	1	\$26.74	Yes
16	900501	Per Toyota Non-Reusable Part								
17	100614	L Frt Otr Door Belt Moulding	Remove / Replace	Body	INC	New	75720-02310	1	\$75.50	Yes
18	100677	L Frt Door Weatherstrip	Remove / Replace	Body	INC	New	67862-02260	1	\$90.80	Yes
19	100884	L Frt Door Moveable Glass	Remove / Replace	Glass	INC	Aftermarket New	FD26047GTY	1	\$223.07	Yes
20	100886	L Frt Door Glass Run	Remove / Replace	Body	INC#	New	68151-02310	1	\$84.15	Yes
Rear Door										
21	101236	L Rear Door Outside	Refinish Only	Refinish	1.8 C	Existing				
22	100194	L Rear Otr Door Belt Moulding	Remove / Install	Body	0.2	Existing				
23	101231	L Rear Otr Door Handle	Remove / Install	Body	1.0#	Existing				

Comment On: 8/15/2025 08:27 AM
Version: Mitchell Estimating 25.2 OEM AUG 25 V
Mitchell Cloud Estimating™
Copyright 1994-2025 Mitchell International, Inc.
All Rights Reserved
Printed On: 8/15/2025 08:27 AM
Profile: MILWAUKEE WI All Part Types
Page 2 of 8

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Roof									
24	100440	Roof Panel	Repair	Body	8.0"	Existing			
25	AUTO	Roof Panel Outside	Refinish Only	Refinish	2.4 C	Existing			



3:54



RepairEstimate-25-7749... Done

Rear Door		Replace				
101324	L Rear Door Outside	Refinish Only	Refinish	1.8 C	Existing	
3 of 8		Remove / Install	Body	0.2	Existing	
		Remove / Install	Body	1.0#	Existing	

Created On: 8/15/2025 08:27 AM
Version: Mitchell Estimating 25.2 OEM AUG 25.V
Printed On: 8/15/2025 08:27 AM
File: MILWAUKEE WIAI Part Types
Page 2 of 8

		LABOR			PART					
Line #	Description		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Roof										
24	100440	Roof Panel	Repair	Body	8.0*	Existing				
25	AUTO	Roof Panel Outside	Refinish Only	Refinish	2.4 C	Existing				
26	101166	L Roof Moulding	Remove / Install	Body	0.3	Existing				
27	100196	Roof Headliner	Remove / Install	Body	5.5#	Existing				
Back Window										
28	100197	Back Window Glass	Remove / Install	Glass	2.4#	Existing				
Quarter Panel										
29	101553	L Quarter Outer Panel Assy	Repair	Body	6.0*#	Existing				
30	AUTO	L Quarter Panel Outside	Refinish Only	Refinish	1.8 C	Existing				
Rear Lamps										
31	100203	L Rear Combination Lamp	Remove / Install	Body	0.8#	Existing				
Rear Bumper										
32	101248	Rear Bumper Cover	Remove / Install	Body	0.8	Existing				
Additional Costs & Materials										
33	AUTO	Paint/Materials	Additional Cost						\$740.00	Yes
34	AUTO	Hazardous Waste Disposal	Additional Cost						\$3.00*	Yes
35	936023	Car Cover	Additional Cost						\$10.00*	Yes
Additional Operations										
36	AUTO	Clear Coat	Additional Operation	Refinish	3.0				\$0.00	
Special / Manual Entry										
37	900500	URETHANE KIT (ADHESIVE BONDED GLASS ONLY) (2 @ \$20.00)	Remove / Replace	Glass*	0.0*	Sublet	Sublet	2	\$40.00*	Yes
38	900500	Post Scan	Additional Labor	Mechanical*	0.5*	Existing		0		
39	900500	Pre Scan	Additional Labor	Mechanical*	0.5*	Existing		0		
40	900500	CORROSION PROTECTION	Additional Labor	Refinish*	0.3*	Existing		0		Yes
41	900500	Glass clean up	Additional Labor	Body*	2.0*	Existing				

* Judgment Item

T Included in Two Tone Calculation

Labor Note Applies

d Discouraged by Manufacturer

C Included in Clear Coat Calculation

A Included in Clear Coat and Two Tone Calculation

r CEG R&R Time Used for this Labor Operation

[] Verify the part number and price before ordering

Parts Vendors

