



GERMANTOWN MUTUAL INSURANCE COMPANY

W209 N11845 Insurance Place P.O. Box 1020

Germantown, Wisconsin 53022-8220

Phone 800-236-4642

gmic@gmic.com

gmic.com

June 20, 2024

City Clerk
Attn: Claims
200 E. Wells St. Room 205
Milwaukee, WI 53202-3567

RE: Our Insured: Bayer & Sons LLC
Our Claim #: 2401372
Recovery Amt: \$7,561.46
Date of Loss: April 14, 2024

To whom it may concern,

We have been informed that you are the liability in regard to this loss. This is to notify you of our subrogation rights under this claim. Our insured has presented a claim that based on our investigation, this incident was caused by your negligence.

We are looking for 100% reimbursement, our recovery total is \$7,561.46. Pertinent documents have been provided for your record.

- Damages: \$ 6,561.46
- Deductible: \$ 500.00
- Recovery: \$ 7,561.46

Please remit this payment to Germantown Mutual Insurance Company immediately.

Thank you.
Sincerely,

Russell Molitor

Russell Molitor

Claims Representative

P 262.509.2217 | F 262.623.3117

E rmolitor@gmic.com




**GERMANTOWN MUTUAL
INSURANCE COMPANY**

Celebrating 170 years!

CITY OF MILWAUKEE
2024 JUN 25 AM 8:18
CITY CLERK'S OFFICE

OFFICE OF CITY ATTORNEY
25 JUN 24 AM 8:18









SOUTHEAST DAMAGE APPRAISAL
S43W25676 Maryanna Drive, WAUKESHA, WI 53189
Office: (414) 588-3466
pat.rohde@sdaservice.net

Estimate ID
18061668
S1
Quote ID
135730481
Claim Number
2401372

SDA File# 240635GM

Owner
Matthew Bayer
W327 S7589 Squire Lane
Mukwonago, WI 53149
(262) 599-3088 (Mobile)
bayermb77@gmail.com

Appraiser
pat.rohde
pat.rohde@sdaservice.net
Classification
Field

Supplemented By
pat.rohde
pat.rohde@sdaservice.net
Classification
Field

Germantown Mutual Insurance

Payer
Insurance

Loss Type
Collision

Claim Number
2401372

Adjuster
Danelle Norberg
(262) 509-2283 (Work)
dnorberg@gmic.com

Deductible
1000.00 - Not Waived

Reported Date
04/15/2024

Loss Date
04/14/2024

Repair Facility
Caliber Collision West Allis
Lincoln
11330 W. Lincoln Ave
West Allis, WI 53227
License Number: 33-07030794
(414) 327-7100 (Work)
kyle.nesbit@calibercollision.com

2020 GMC Terrain Denali 4 Door Utility 2.0L 4 Cyl Gas Injected Turbocharged FWD

Exterior Color
41A (Black)

Interior Color
Black

License
WI-AWX-1082

VIN
3GKALSEXXLL315199

Condition
Very Good

Drivable
No

Odometer
45274

Production Date
07/2020

Mitchell Service Code
912032

Primary Point of Impact
Left Front Side (10)

Options

Air Conditioning

Alum/Alloy Wheels

AM-FM Stereo

Anti-Lock Brake Sys. (ABS)

Auto Air Condition

Options

Automatic Headlights	Auxiliary Input	Bluetooth Wireless Connectivity	Cruise Control	Daytime Running Lights
Driver Seat With Power Lumbar Support	Driver-Front Air Bag	Dual A/C	Electronic Parking Aid	Electronic Stability Control
Exterior Memory Mirrors	First Row Bucket Seat	Fog Lights	Front Heated Seats	Front Seats With Power Lumbar Support
HD Radio	Heated Mirror	Heated Steering Wheel	Interior Automatic Day/Night Or Electrochromatic Mirror	Keyless Entry System
Leather Seats	Leather Steering Wheel	Left-Curtain Air Bag	Luggage Rack	Manual Sunroof
Memory Seats	MP3 Player	Navigation Sys.	Passenger-Front Air Bag	Power Door Locks
Power Driver Seat	Power Passenger Seat	Power Rear Liftgate	Power Remote Mirror	Power Windows
Premium Sound Sys.	Privacy Glass	Rear Bench Seat	Rearview Camera	Remote Decklid Or Tailgate Release
Remote Vehicle Starter System	Satellite Radio	Second Row Side Airbag With Head Protection	Side Airbags	Side Blind Zone Alert
Smart Key System	Steering Wheel Mounted Audio Control	Telematic Systems	Theft Deterrent Sys.	Tire Pressure Monitoring System
Traction Control/Electronic	Trailer Hitch	Trip Computer	Universal Garage Door Opener	

Matthew Bayer | 2020 GMC Terrain Denali

Parts Profile
SDA Profile

Parts Profile Version
2.0

LABOR				PART					
Line #	Description	OperationType	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Front Bumper									
1	202068 Frt Bumper Cover Assy	Overhaul	Body	3.4#	3.4	Existing			
2	202076 Frt Add w/Parking Sensor	Remove / Replace	Body	0.4	0.4				
3	200668 Frt Bumper License Plate Bracket	Remove / Install	Body	INCr	0.2	Existing			
4	200670 Frt Lwr Bumper Cover	Repair	Body	2.0*#	0.7	Existing			
5	AUTO Frt Lwr Cover	Refinish Only	Refinish	1.4 C	1.4	Existing			
Grille									
6	203500 Add W/Surround View Camera	Remove / Replace	Body	0.2	0.2				
7	201072 Grille Assembly	Remove / Install	Body	INCr#	0.3	Existing			
8	AUTO Frt Bumper Cover	Remove / Install	Body	INC#	2.3				
Front Lamps									
9	201176 Headlamps	Check / Adjust	Body	0.4	0.4	Existing			
10	201178 L Front Combination Lamp	Remove / Install	Body	INC#	0.3	Existing			
11	201078 L Frt Combination Lamp Assembly	Repair	Body	1.0*#	0.3	Existing			
12	900501 Repair mounting tabs								
Front Fender									
13	201401 L Fender Panel	Remove / Replace	Body	1.6#	2.2	Aftermarket Certified	GM1240408C 1	\$359.00	Yes

LABOR						PART				
Line #	Description	Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
14	AUTO L Fender Outside	Refinish Only	Refinish	2.1 C	2.1					
15	AUTO L Add To Edge Fender	Refinish Only	Refinish	0.5 C	0.5					
S1 16	200207 L Fender Liner	Remove / Replace	Body	INC	0.3	New	23462425	1	\$123.07	Yes
17	200750 L Fender Liner Retainer	Remove / Replace	Body	0.0	0.0	New	11612035	1	\$6.94	Yes
18	201188 L Fender Wheel Opening Mldg	Refinish Only	Refinish	0.7 C	0.7	Existing				
19	201190 L Upr Fender Moulding	Remove / Install	Body	INC#	0.2	Existing				
20	201191 R Fender Wheel Opening Mldg	Remove / Install	Body	INC	0.3	Existing				
S1 21	200749 L Fender Wheel Opening Mldg	Repair	Body	1.0*	0.3	Existing				
22	900501 Repair Wheel Opening Mldg									
Front Inner Structure										
S1 23	200628 L Lwr Frt Body Side Rail Assy (HSS/UHSS)	Repair	Body	1.0*	10.5	Existing				
S1 24	AUTO L Lwr Side Rail	Refinish Only	Refinish	0.5*	1.0	Existing				
25	900501 Modified Refinish									
ABS / Brakes										
S1 26	200302 L ABS Frt Sensor -M	Remove / Replace	Mechanical	0.5#	0.5	New	84449199	1	\$27.38	Yes
Wheel										
27	201520 Alloy Wheel	Remove / Replace	Body	0.3	0.3	New	22968933	1	\$718.18	Yes
28	900501 Insurance quality LKQ & Remanufactured not Available									
29	202371 Wheel Tire Pressure Sensor	Remove / Replace	Body	0.0	0.0	New	13540604	1	\$84.93	Yes
Front Suspension										
30	201948 L Frt Susp Hub Assy -M	Remove / Replace	Mechanical	INC#	1.0	New	13547478	1	\$141.44	Yes
S1 31	201952 L Frt Susp Caliper -M	Remove / Install	Mechanical	0.5*#	0.5	Existing				
S1 32	202015 L Frt Susp Steering Knuckle -M	Remove / Replace	Mechanical	1.8#	1.8	New	84210076	1	\$103.86	Yes
S1 33	202023 L Frt Susp Strut -M	Remove / Replace	Mechanical	0.7#	1.4	New	[84865811]	1	\$137.78	Yes
34	203329 L Lwr Frt Susp Control Arm Assy -M	Remove / Replace	Mechanical	0.6#	1.6	New	87821885	1	\$204.48	Yes
35	201985 L Frt Susp Rear Bolt -M (2 @ \$7.18)	Remove / Replace	Mechanical	0.0	0.0	New	11611268	2	\$14.36	Yes
S1 36	201987 L Frt Susp Stabilizer Bar Link -M	Remove / Replace	Mechanical	0.4#	0.4	New	84517192	1	\$26.23	Yes
Front Drive Axle										
S1 37	200287 L Frt Drive Axle Shaft -M	Remove / Replace	Mechanical	0.3#	0.3	New	[84615505]	1	\$308.77	Yes
Cowl & Dash										
S1 38	201614 L Cowl/Dash Cowl Top Extension	Remove / Replace	Body	0.0	0.0	New	84416167	1	\$23.23	Yes

LABOR				PART						
Line #	Description	Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Front Door										
S1 39 200494	L Frt Door Outside	Refinish Only	Refinish	1.6 C	2.0	Existing				
S1 40 200500	L Frt Door Assembly	Remove / Install	Body	1.0#	1.0	Existing				
S1 41 202515	L Frt Door Shell	Repair	Body	0.5*#	5.3	Existing				
42 200512	L Frt Rear View Mirror	Remove / Install	Body	INC#	0.7	Existing				
43 200514	L Frt Otr Door Belt Moulding	Remove / Install	Body	0.5#	0.9	Existing				
44 200515	L Frt Lwr Door Moulding	Remove / Install	Body	0.3	0.3	Existing				
S1 45 201771	L Frt Uprr Door Reveal Moulding	Remove / Install	Body	0.2*	0.3	Existing				
S1 46 201777	L Frt Lwr Door Moulding	Repair	Body	0.5*	0.3	Existing				
S1 47 AUTO	L Frt Lwr Door Moulding	Refinish Only	Refinish	0.8 C	0.8	Existing				
48 201787	L Frt Door Moulding Retainer (4 @ \$5.81)	Remove / Replace	Body	0.0	0.0	Aftermarket New	1561439	4	\$23.24	Yes
49 202890	L Frt Door Moulding Retainer (4 @ \$5.68)	Remove / Replace	Body	0.0	0.0	Aftermarket New	1446686	4	\$22.72	Yes
50 203527	L Frt Door Moulding Retainer (2 @ \$3.33)	Remove / Replace	Body	0.0	0.0	Aftermarket New	1457520	2	\$6.66	Yes
S1 51 201785	L Frt Door Moulding Insert	Remove / Install	Body	0.2*	0.0	Existing				
52 200532	L Frt Door Trim Panel	Remove / Install	Body	INC	0.4	Existing				
53 200544	L Frt Otr Door Handle	Remove / Install	Body	0.3#	0.3	Existing				
Side Body										
S1 54 200786	L Hinge Pillar	Refinish Only	Refinish	2.0 C	2.0	Existing				
S1 55 200945	L Side Body Panel Assembly -S	Repair	Body	2.5*#	22.0	Existing				
56 900501	Repair at Lower Hinge Pillar									
S1 57 200951	L Lwr Fender Rear Bracket	Repair	Body	0.5*		Existing				
58 200450	L Rocker Moulding	Remove / Install	Body	INC	0.5	Existing				
Additional Costs & Materials										
59 AUTO	Paint/Materials	Additional Cost							\$654.50*	Yes
60 AUTO	Hazardous Waste Disposal	Additional Cost							\$5.00*	Yes
61 936014	Flex Additive	Additional Cost							\$8.00*	Yes
62 936001	Towing	Additional Cost							\$140.00*	Yes
63 900501	Tow Invoice from N & S Towing									
Additional Operations										
64 AUTO	Clear Coat	Additional Operation	Refinish	2.3	0.0				\$0.00	
65 933018	Mask For Overspray	Additional Operation	Body*	0.3*	0.0				\$10.00*	

LABOR						PART		
Line #	Description	Operation	Type	Total Units	CEG	Type	Number	Qty Total Price Tax
66 933021	De-Nib And Finesse	Additional Refinish Operation		1.1	0.0			\$0.00
67 931127	Pre Repair Scan	Additional Mechanical Operation		0.5*	0.0			\$40.00*
68 931128	Post Repair Scan	Additional Mechanical Operation		0.5*	0.0			\$80.00*
69 933056	Calibrate Surround View System	Additional Mechanical Operation		0.0	0.0			\$450.00*
Special / Manual Entry								
70 900500	Mount & Balance L/F Wheel & Tire	Additional Body* Labor		0.0*	0.0	Sublet		\$35.00*
71 900500	4 Wheel Alignment	Additional Body* Labor		0.0*	0.0	Sublet		\$129.95*
72 900500	L/F Tire Hankook Ventus S1 Noble 2	Remove / Body* Replace		0.0*	0.0	Aftermarket New	1	\$340.00* Yes
73 900506	L/F Tire Hankook Ventus S1 Noble 2 50.00%	Part Betterment						\$170.00
74 900501	Price from Tire Rack							

* Judgment Item

C Included in Clear Coat Calculation

T Included in Two Tone Calculation

A Included in Clear Coat and Two Tone Calculation

Labor Note Applies

r CEG R&R Time Used for this Labor Operation

d Discontinued by Manufacturer

[] Verify the part number and price before ordering

Parts Vendors

KENT AUTOMOTIVE
1666 E. TOUHY AVE.
DES PLAINES IL 60018
(888) 937-5368 (Work)
(888) 937-5368 (Work)

KEYSTONE-INS QUALITY PRT
5050 N. WREN DR.
APPLETON WI 54913
(800) 422-1995 (Work)
(920) 731-3030 (Work)

Line	Part #	Total Price
48	1561439	\$23.24
49	1446686	\$22.72
50	1457520	\$6.66

Line	Part #	Total Price
13	GM1240408C	\$359.00

Disclaimer: This estimate has been prepared based on the use of one or more replacement parts supplied by a source other than the manufacturer of your motor vehicle. Warranties applicable to these replacement parts are provided by the manufacturer or distributor of the replacement parts rather than by the manufacturer of your motor vehicle.

Estimate Totals

Labor	Units	Rate	Sublet Add'l Amount	Totals
Body Labor	18.1	\$70.00	\$164.95 \$10.00	\$1,441.95
Refinish Labor	13.0	\$70.00		\$910.00
Mechanical Labor	5.8	\$155.00	\$570.00	\$1,469.00

Total Labor	36.9	\$164.95		
			Taxable	\$3,820.95
			Tax 5.9000%	\$225.44
			Non-Taxable	\$0.00
			Pre-Tax Discount 0.00%	\$0.00
			Labor Total	\$4,046.39
Parts	Amount			
Taxable Parts	\$2,672.27			\$2,672.27
			Parts Adjustments	\$0.00
			Tax 5.9000%	\$157.66
			Non-Taxable	\$0.00
			Pre-Tax Discount 0.00%	\$0.00
			Parts Total	\$2,829.93
Costs	Amount			
Paint Materials	\$654.50			\$654.50
Shop Materials	\$0.00			\$0.00
Other Additional Costs	\$153.00			\$153.00
			Taxable	\$807.50
			Tax 5.9000%	\$47.64
			Non-Taxable	\$0.00
			Pre-Tax Discount 0.00%	\$0.00
			Costs Total	\$855.14
Paint Materials:				
- Rate: \$55.00				
- Rate Max: 99.9 units				
- Additional Rate: \$0.00				
Gross Totals	Amount			
Gross Total	\$7,731.46			\$7,731.46
			Taxable	\$7,300.72
			Tax	\$430.74
			Non-Taxable	\$0.00
			Pre-Tax Discount 0.00%	\$0.00
			Gross Total	\$7,731.46
Adjustments	Amount			
Betterment	-\$170.00			-\$170.00
Deductible	-\$1,000.00			-\$1,000.00
Total Customer Responsibility				-\$1,170.00
			Net Estimate Total	\$6,561.46
			Less Original Net Total	\$4,337.62
			Net Supplement Amount	\$2,223.84
			S1: pat rohde	\$2,223.84

NO SUPPLEMENTS WITHOUT PRIOR APPROVAL

Disclaimer: Any person who knowingly presents a false or fraudulent claim for payment of a loss or benefit or knowingly presents false information in an application for insurance is guilty of a crime and may be subject to fines and confinement in prison.

Estimate Event Log

Job Created	4/16/2024 01:16 PM
Supplement 1 Started	4/16/2024 01:22 PM
Supplement 1 Printed	5/9/2024 12:26 PM
Supplement 1 Committed	5/9/2024 12:26 PM
Estimate Version	1
Estimate Retrieval ID	1000922592

Supplement Delta Report

Comparison of Estimate 18061668 Original Estimate & Supplement 1

Date & Time	Estimate ID	Supplement No.	Profile ID
5/9/2024	18061668	1	75
12:26:09 PM			

Matthew Bayer | 2020 GMC Terrain Denali

Damage Assessed By	Supplemented By	Date of Loss
pat rohde	pat rohde	04/14/2024

Global Changes

No Deductible, Deductible Reduction Credit, Insurance Pre-Paid Amount, Part Adjustments, or Related Prior Damage changes were made.

Estimate Line Changes - Primary Estimate

Supp/		LABOR				PART		
Line #	Item Description	Operation	Type	Total Units	CEG	Type	Number	Price
Changed Entries								
	14	L Fender Liner	Remove / Install	Body	INC	0.30	Existing	Existing \$0.00
S1	16	L Fender Liner	Remove / Replace	Body	INC	0.30T	New	23462425 \$123.07
	19	L Fender Wheel Opening Mldg	Remove / Replace	Body	INC	0.30T	New	84579541 \$138.87
S1	21	L Fender Wheel Opening Mldg	Repair	Body	1.00*	0.00	Existing	Existing \$0.00
	23	L Frt Susp Hub Assy -M	Remove / Replace	Mechanical	1.00	1.00T	New	13547478 \$141.44
S1	30	L Frt Susp Hub Assy -M	Remove / Replace	Mechanical	INC	1.00T	New	13547478 \$141.44
	24	L Lwr Frt Susp Control Arm Assy -M	Remove / Replace	Mechanical	1.60	1.60T	New	87821885 \$204.48
S1	34	L Lwr Frt Susp Control Arm Assy -M	Remove / Replace	Mechanical	0.60	1.60T	New	87821885 \$204.48
	28	L Frt Otr Door Belt Moulding	Remove / Install	Body	0.90	0.90	Existing	Existing \$0.00

Supp/		LABOR				PART			
Line #		Item Description	Operation	Type	Total Units	CEG	Type	Number	Price
S1	43	L Frt Otr Door Belt Moulding	Remove / Install	Body	0.50	0.90	Existing	Existing	\$0.00
	36	Paint/Materials	936008			T			\$396.00*
S1	59	Paint/Materials	936008			T			\$654.50*
	41	Clear Coat	Add'l Opr	Refinish	1.70	0.00			\$0.00
S1	64	Clear Coat	Add'l Opr	Refinish	2.30	0.00			\$0.00

Deleted Entries

S1 26		L Frt Door Outside	Blend	Refinish	0.80	1.00	Existing	Existing	\$0.00
-------	--	--------------------	-------	----------	------	------	----------	----------	--------

Added Entries

S1 11		L Frt Combination Lamp Assembly	Repair	Body	1.0*	0.00	Existing	Existing	\$0.00
S1 12		Repair mounting tabs	900501						
S1 22		Repair Wheel Opening Mldg	900501						
S1 23		L Lwr Frt Body Side Rail Assy (HSS/UHSS)	Repair	Body	1.0*	0.00	Existing	Existing	\$0.00
S1 24		L Lwr Side Rail	Refinish	Refinish	0.5*	1.00	Existing	Existing	\$0.00
S1 25		Modified Refinish	900501						
S1 26		L ABS Frt Sensor -M	Remove / Replace	Mechanical	0.50	0.50T	New	84449199	\$27.38
S1 31		L Frt Susp Caliper - M	Remove / Install	Mechanical	0.5*	0.50	Existing	Existing	\$0.00
S1 32		L Frt Susp Steering Knuckle -M	Remove / Replace	Mechanical	1.80	1.80T	New	84210076	\$103.86
S1 33		L Frt Susp Strut -M	Remove / Replace	Mechanical	0.70	1.40T	New	84865811	\$137.78
S1 36		L Frt Susp Stabilizer Bar Link -M	Remove / Replace	Mechanical	0.40	0.40T	New	84517192	\$26.23
S1 37		L Frt Drive Axle Shaft -M	Remove / Replace	Mechanical	0.30	0.30T	New	84615505	\$308.77
S1 38		L Cowl/Dash Cowl Top Extension	Remove / Replace	Body	0.00	0.00T	New	84416167	\$23.23
S1 39		L Frt Door Outside	Refinish	Refinish	1.60	2.00	Existing	Existing	\$0.00
S1 40		L Frt Door Assembly	Remove / Install	Body	1.00	1.00	Existing	Existing	\$0.00

Supp/		LABOR				PART			
Line #		Item Description	Operation	Type	Total Units	CEG	Type	Number	Price
S1	41	L Frt Door Shell	Repair	Body	0.5*	0.00	Existing	Existing	\$0.00
S1	45	L Frt Upr Door Reveal Moulding	Remove / Install	Body	0.2*	0.30	Existing	Existing	\$0.00
S1	46	L Frt Lwr Door Moulding	Repair	Body	0.5*	0.00	Existing	Existing	\$0.00
S1	47	L Frt Lwr Door Moulding	Refinish	Refinish	0.80	0.80	Existing	Existing	\$0.00
S1	51	L Frt Door Moulding Insert	Remove / Install	Body	0.2*	0.00	Existing	Existing	\$0.00
S1	54	L Hinge Pillar	Refinish	Refinish	2.00	2.00	Existing	Existing	\$0.00
S1	55	L Side Body Panel Assembly -S	Repair	Body	2.5*	0.00	Existing	Existing	\$0.00
S1	56	Repair at Lower Hinge Pillar	900501						
S1	57	L Lwr Fender Rear Bracket	Repair	Body	0.5*	0.00	Existing	Existing	\$0.00

Estimate Totals Changes

Estimate Type	Total Tax	Gross Total	Customer Responsibility	Net Estimate Total
Original Estimate	\$306.85	\$5,507.62	-\$1,170.00	\$4,337.62
Supplement 1	\$430.74	\$7,731.46	-\$1,170.00	\$6,561.46

Net Estimate Totals

Estimate Type	Net Amount
Supplement 1	\$2,223.84
Net Supplement	\$2,223.84
Original Estimate	\$4,337.62
Net Estimate Total	\$6,561.46

Estimate Type	Program Calc Version	Data Versions
Original Estimate	8	APR_24_V
Supp 1	4	APR_24_V

45274mi



MFD BY GENERAL MOTORS DE MEXICO, S. DE R.L. DE C.V.

07/20

GVWR
2100 KG
4630 LB

GAWR FRT
1175 KG
2590 LB

GAWR RR
1200 KG
2645 LB



384A

THIS VEHICLE CONFORMS TO ALL
APPLICABLE U.S. FEDERAL MOTOR
VEHICLE SAFETY AND THEFT PREVENTION
STANDARDS IN EFFECT ON THE DATE OF
MANUFACTURE SHOWN ABOVE.

3GKALSEXXLL315199


TYPE: M.P.V.


TIRE SIZE
FRT 235/50R19 H
RR 235/50R19 H
SPA T125/70R17 M

RIM
19X7.5J
19X7.5J
17X4BT

MODEL: X9TXN26















PROTECH

AUTOMOTIVE SOLUTIONS

DATE

4/25/2024

1900 Lakeway Dr. #400
Lewisville, TX 75057
Phone: 800-892-6124
ar@protechas.com

INVOICE #

15413997

Tax ID# 75-2598604

BILL TO

Caliber Collision Center #3359
11330 W Lincoln Ave
West Allis, WI 53227

VIN# 3GKALSEXXLL315199

RO# 3359009334

Item	Description	Qty	Rate	Amount
Labor	PERFORMED PRE SCAN DIAGNOSTIC OF VEHICLE	1.0	40.00	40.00

Balance Due

\$40.00

Diagnostic Fault Codes Present

System	Status	System	Status
AMPLIFIER	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
BODY CONTROL MODULE	Fault	BODY CONTROL MODULE	Fault
INSTRUMENT CLUSTER	Fault	HVAC CONTROLS	Fault
LIFEGATE CONTROL MODULE	Fault	INSTRUMENT CLUSTER	Fault
PARKING ASSIST CONTROL MODULE	Fault	PARKING ASSIST CONTROL MODULE	Fault
SERIAL DATA GATEWAY MODULE	Fault	POWER STEERING CONTROL MODULE	Fault
VIDEO PROCESSING CONTROL MODULE	Fault	VIDEO PROCESSING CONTROL MODULE	Fault
VIDEO PROCESSING CONTROL MODULE	Fault	VIDEO PROCESSING CONTROL MODULE	Fault



BUICK GMC / GREENFIELD

Phone: (414) 545-7015 • U.S.A. WATS 1-800-236-7901
Fax: (414) 290-7178 • U.S.A. WATS Fax: (888) 236-7901
3615 S. 108th St. • Greenfield, WI 53228 • www.Kunesgreenfield.com

WE WOULD LIKE TO BECOME YOUR PREMIER GM PARTS SUPPLIER

CUST NO.	TAX EXEMPT NUMBER	CUST. P. O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE NO.
3011	456-1030307475-04 414-327-7100	3359009334 T#3	LOCAL	CHARGE	GERMAN FLORES	04/24/24	170415 BUW

B
I
L
L
T
O

CALIBER WEST ALLIS LINCOLN AVE
11330 W LINCOLN AVE
WEST ALLIS, WI 53227

S
H
I
P
T
O

3GKALSEXXLL315199

SHIP QTY	B. O. QTY	PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT	
0	①	22968933 WHEEL 5.803	SPORD	718.18	445.27	0.00	PARTS DEPT. HOURS MONDAY - FRIDAY 7:00 AM - 6:00 PM SATURDAY 8:00 AM - 3:00 PM
1	0	84579541 MOLDING 8.132	18E	138.87	50.00	0.00	
1	0	87821885 ARM 6.168 *	545	204.48	86.10	86.10	
0	①	84278262 FENDER 8.130	719	432.47	126.78	126.78	
1	0	13547478 HUB 6.307 *	1016	141.44	268.13	0.00	
2	0	11547341 RETAINER 1.269	1031	8.87	87.69	87.69	
1	0	13540604 SENSOR 5.890	1115D	84.93	5.50	11.00	
1	0	11612035 RETAINER 8.950	1167D	6.94	52.66	52.66	
4	0	11547581 CLIP 8.309	1176	10.76	4.30	4.30	
2	0	11611268 BOLT 8.900	1179	7.18	26.68	26.68	
4	0	15864780 RETAINER 12.118	2048D	8.27	4.45	8.90	DELIVERED BY X CW
					5.13	20.52	
						SUBTOTAL	424.63
						TAX	0.00
						FREIGHT	0.00
						PAY THIS AMOUNT	424.63

SUBTOTAL

TAX

FREIGHT

PAY THIS AMOUNT



GENUINE PARTS

Engine and Transmissions

QUALITY IS IN OUR PEOPLE
All claims and returned goods must be accompanied by this invoice. No returns after 30 days. All returned merchandise subject to 20% handling charge. No returns on electrical or special order items. All returned merchandise must be in original returnable container and must meet manufacturer packaging standards.
We are not responsible for damage to parts not installed by our service department. The factory warranty constitutes all of the warranties with respect to the sale of this item(s). The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item(s).

CUSTOMER COPY



0201G170415

STOCKING ALL GM PARTS LINES

PARTS INVOICE



GMC



19:23:07

OF 1
NET507



BUICK GMC / GREENFIELD

Phone: (414) 545-7015 • U.S.A. WATS 1-800-236-7901
Fax: (414) 290-7178 • U.S.A. WATS Fax: (888) 236-7901
3615 S. 108th St. • Greenfield, WI 53228 • www.Kunesgreenfield.com

WE WOULD LIKE TO BECOME YOUR PREMIER GM PARTS SUPPLIER

CUST NO.	TAX EXEMPT NUMBER	CUST. P. O. NO.	SHIP VIA	PAY	SOLD BY	INVOICE DATE	INVOICE NO.
3011	456-1030307475-04	3359009334	LOCAL	CHARGE	GERMAN FLORES	04/25/24	170415-1
	414-327-7100	T#3					BUW

B
I
L
L
T
O

CALIBER WEST ALLIS LINCOLN AVE
11330 W LINCOLN AVE
WEST ALLIS, WI 53227

S
H
I
P
T
O

3GKALSEXXLL315199

SHIP QTY	B. O. QTY	PART NUMBER / DESCRIPTION	BIN	LIST	NET	AMOUNT	
1	0	22968933 WHEEL 5.803 SPORD	SPORD	718.18	445.27	445.27	PARTS DEPT. HOURS MONDAY - FRIDAY 7:00 AM - 6:00 PM SATURDAY 8:00 AM - 3:00 PM
		CORE PRICE			50.00	50.00	
1	0	84278262 FENDER 8.130 SPORD	719	432.47	268.13	268.13	
Handed out James / cart 4							
				SUBTOTAL		763.40	
				TAX		0.00	
				FREIGHT		0.00	
				PAY THIS AMOUNT		763.40	
QUALITY IS IN OUR PEOPLE All claims and returned goods must be accompanied by this invoice. No returns after 30 days. All returned merchandise subject to 20% handling charge. No returns on electrical or special order items. All returned merchandise must be in original returnable container and must meet manufacturer packaging standards. We are not responsible for damage to parts not installed by our service department. The factory warranty constitutes all of the warranties with respect to the sale of this item(s). The seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item(s).							

DELIVERED TIME

DELIVERED BY

X

 GENUINE PARTS

Engine and Transmissions

CUSTOMER COPY



0201G170415-1

STOCKING ALL GM PARTS LINES

PARTS INVOICE



GMC

07:06:11

PAGE 1 OF 1
NUMBER 11111111

Specify Viewing Criteria

Feature: Bayer & Sons, LLC / 2020 GMC TERRAIN DENALI Utility Vehicle - Two-Wheel Drive 4-Door

Go

Coverage: Collision, Ded: \$1,000

View By: All Transactions

From: 4 14 2024 To: 6 20 2024

Go

Transaction Information

** indicates Manual Payment

Coverage:

Collision, Ded: \$1,000

Cause of Loss:

Collision

Transaction	Date	Amount	Check #	User	Correct
Open Loss Reserve	04/15/2024	\$4,500.00		Jessica Noreika	
Change Loss Reserve	04/15/2024	\$10,500.00		Danella Norberg	
+ Final Loss Payment	04/22/2024	\$4,337.62		Danella Norberg	Voided
Open Expense Reserve	04/22/2024	\$150.00		Jessica Modrzyk	
+ Partial Expense Payment	04/22/2024	\$150.00	778181	Jessica Modrzyk	☐
- After Close Loss Payment	04/27/2024	\$4,337.62	778342	Danella Norberg	☐
Pay To: Bayer & Sons, LLC W327S7589 Squire Ln 53149 Mail To: Matthew Bayer W327S7589 Squire Ln					
Reason: Bayer & Sons LLC - 2020 GMC Terrain - Minus \$1000 Deductible					
Print Status: Printed					
Print Date: 04/29/2024					
Posted Date:					
Close Expense Reserve	04/27/2024	\$0.00		Danella Norberg	
- After Close Loss Payment	06/04/2024	\$2,223.84	779563	Danella Norberg	☐
Pay To: Caliber Collision Mail To: Caliber Collision 11330 W Lincoln Avenue West Allis, WI 53227					
Tax ID: *****0794					
Reason: Supplement - Bayer & Sons LLC - 2020 GMC Terrain					
Print Status: Printed					
Print Date: 06/05/2024					
Posted Date:					