11	•
*	
	January 7, 2016
And the first of the second section of the section of the second section of the second section of the second section of the section of the second section of the section	
	Dear Dir.
	1 11 11 + to lite an appeal
	De De De De de Carion made unalung damage to my mehicle.
	regarding the decision made innulling themase
# PROSECULAR TO THE CONTRACT OF THE CONTRACT O	to my wehicle.
	Dimonilla
	Direciely - Sharon Shell
and analysis of the same party of specific speci	1046 E. Potter Que
	A STATE OF THE PARTY OF THE PAR
	milu. WT. 53207
	(414) 238-8894
graphy agricultural () . In orași a registrar a registrar a menteral de la	
	BEACH (ED
and the state of t	RECEIVED
and the state of t	JAN 1.1 2016
	OFFICE OF ————————————————————————————————————
	•
	9 2 3 6 6 7
	6 5 3
	o v o v o v o v o v o v o v o v o v o v
والموافقة والمرافقة والموافقة والموافقة والموافقة والموافقة والموافقة والموافقة والموافقة والموافقة والموافقة	S OFFICE 50

-

Print

-CK/PDC/FILE

Ci JSP, D. Thomas

From: shazadi 7 (shazadi 7@hotmail.com)

Sent: Thu 11/19/15 7:04 AM

To: ghassan.korban@milwaukee.gov (ghassan.korban@milwaukee.gov)

RECEIVED

DEC 15 2015

OFFICE OF CITY ATTORNEY

Dear Mr Ghassan, I am writing to you with the confidence of knowing that you will make sure my request is forwarded to the proper department in the Infrastructure Services Division. Please save this email to add to the packet of photos and the receipt from the VW Dealership that I will be sending to you this morning by USPS Certified Mail that you should receive Friday November 20th or at the latest Monday November 23rd On September 6th, 2015 I was driving my 2011 VW Golf TDI southbound on Logan Ave in Bay View. Since I normally drive another block east and continue southbound on Bay Street, I was not familiar with the condition of the road on South Logan Ave between 2389-2373 S Logan.

To my regret, I was unfamiliar with a 20-25 foot long series of holes in the road at the above addresses. I inadvertently drove over the series of holes which were actually unavoidable. I realized that my car took quite a beating by driving over the series of holes, but it wasn't until the next morning when I was going to run errands that I saw that both tires on the passenger side of my car were nearly flat. I had my son come with an air compressor to fill up my tires and continued with my day. Two days later I realized that both tires on the passenger side no longer were holding the air. Since I had bought new tires in July 2014 and had purchased the extended warranty I made an appointment at the car dealership to have the tires checked.

To my dismay, I was very upset to learn that the series of holes I drove over on Logan Ave did a lot more damage then just ruining two tires. It actually ruined the struts and suspension system in to the front of my car. I had no choice then to have it repaired and the two tires replaced. Luckily the dealership replaced the two tires at no cost because I'd bought the extended warranty, however the repairs to the front end were very expensive. I became a widow March 27th, of 2015 and have an extremely tight budget. I certainly was in no position to pay for these repairs and over the last two months have realized that the city of Milwaukee Infrastructure Services Division need to be held responsible for the neglect and lack of maintenance of South Logan Ave from 2389-2373. It was not winter, or under construction, so there was absolutely no reason for that road to be in such disrepair.

The pictures you will be receiving by certified mail were taken on September 8th where my neighbor held the measuring tape so I could take the photos. I am not a profession photographer so the images are not the best, however they clearly show the neglect and disrepair that I drove over.

I am requesting that the city reimburse me for the amount I spent on the front end damage. After speaking to our family attorney, I'd decided to try and address the situation myself, however I was told by our attorney that if I don't receive satisfaction from the City of Milwaukee for this incident, that he will then step in.

As I have stated before, I have no room in my tight budget for attorney fees, or for that matter, small claims costs. I am hoping to resolve this civilly.

Sincerely, Sharon Shell 1046 E Potter Ave Milwaukee, WI. 53207 414-238-8894

RECEIVED

CUSTOMER #: 25368

JAMES HILL

DEC 15 2015

164013

INVOICE

oucher swagen

Marketplace .

OFFICE OF **CITY ATTORNEY**

2525 S SHORE DR

MILWAUKEE, WI 53207

HOME: 414-238-8894 CONT: 414-238-8894

PAGE 1

6420 S. 108th Street · Franklin, WI 53132 (414) 525-1100 www.boucher.com

HOME: 414-238-8894 CONT: 414-238-8894						
BUS: CELL:	SERVICE ADVISOR:	5158 DUS	TIN J AB	PLANALP	l	
GOLOR YEAR MAKE/MODEL	VIN	LICENSE	MILEAGE	IN/OUT	TAG	
•		•				
BLUE 11 VOLKSWAGEN GOLF TDI	WVWMM7AJ2BW015444	<u></u>	52540/		T707	
DEL DATE IN SERVICE DATE WARR, EXP. PROMIS	ED PO NO.		PAYMENT	INV. DA	ΤĒ	
29NOV10 DD 18:00 10			CASH	11SEP1	5	
R.O. OPENED READY OPTIONS	SOLD-STK:11V010	3)RC=075	9		=	
10SEP15 11SEP15	···					
LINE OPCODE TECH TYPE HOURS		LIST	NET	TOT	AL	
A CUSTOMER STATES BOTH PASSENGER TIP	RES KEEP LOOSING AI	R AND FRO	NT			
PASSENGER TIRE HAS TWO BULGE	ES IN SIDEWALL. INS	PECT AND	ADVISE			
CUSTOMER HAS ROAD HAZARD						
ETPPREP PROTECTION REPAIR						
5078IETPR	,			(N/	C)	
2 42370 KUMHO: 2161793				(N/	C)	
52540 Replaced both passenger side	tires, rotated new	tires up	ı	•	•	
front, took drivers rear tire, dism	nounted it and flip	ped it, r	emounted			
it and balanced and moved it to the	e bassender rear					
***********	********				•	
B CUSTOMER STATES WHEN DRIVING OVER	A BUMP THE REAR EN	D SHAKES	REALLY			
BAD, INSPECT SUSPENSION COME	ONANTS AND ADVISE				,	
FS71 Strut Cartridge/Strut Asse	mbly, Front -					
Replace						
5078 CPV	등 경 경 경		329.00	329.	0.0	
2 42369 F STRUT: 72311		176.26	137.49			
AFTERMARKET		_,,,,	20.,13	2,1.	J 0	
2 1K0-412-331-B MOUNTING		89.10	89.10	178.	20	
2 1K0-412-249-B BEARING		43.75	43.75	87.		
2 1K0-411-315-R CONN LINK		88.88	88.88	177.		
4 N-015-081-6 NUT	* ******	3.74	3.74	14.		
SR42 Alignment, Four Wheel - Ch	ieck and Adiust	13.74 13	J./=	74.	90	
5078 CPV 🔆 🔆 🔆			99.00	99.	00	
52540 Test drove vehicle, duplicate	ed concern but noti	 ced iggue	with	59.	00	
front, not rear of vehicle, inspected and found passenger front strut \$1/61.40						
and sway bar links, performed 4 wheel alignment, test drove and system						
ok	arraiment, cest	arove an	a system)	
***********	*****	*****	**			
C PERFORM ECM UPDATE						
CAUGE. DEDECOMED ECM HDDATE						

PERFORMED ECM UPDATE

23602599 PERFORM VW UPDATE TO Our Primary Concern' BULLETIN 2011082 5078 WPV

CHEVY

HYUNDAI




Jeep

GMC



BUICK*

The only warranties provided on the parts installed are those made by the manufacturer. The seller, Boucher Volkswagen Merketplace, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose.



ENVIRONMENTAL AND SHOP SUPPLY SURCHARGE: A charge is included for the handling and disposal of hazardous waste and similar materials and for supplies consumed in the process of repairing your vehicle. These supplies include solvents, cleaners, rags, towels, nuts, bolts, tape, atc...

LET US SERVE ALL OF YOUR AUTOMOTIVE NEEDS! FOR A COMPLETE LISTING OF BOUCHER DEALERSHIPS, COLLISION REPAIR CENTERS AND HOURS OF OPERATION, PLEASE VISIT OUR WEBSITE AT: www.boucher.com

OR CALL US AT: 1-888-BOUCHER You may also visit us on Facebook or follow our tweets @ BoucherAuto

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
DED/ADJ	
SALES TAX	·
PLEASE PAY THIS AMOUNT	

(N/C)

I acknowledge receipt of a copy of this invoice which contains the revised estimate information, if any, and such revised estimate was previously authorized by me or on my behalf. Customer Signature: _

RECEIVED

CUSTOMER #: 25368

DEC 15 2015

164013

JAMES HILL 2525 S SHORE DR

MILWAUKEE, WI 53207

OFFICE OF CITY ATTÖRNEY *INVOICE*

6420 S. 108th Street · Franklin, WI 53132 (414) 525-1100

www.boucher.com

PAGE 2

HOME: 414-238-8894 CONT: 414-238-8894							111011 2					
BUS: CELL:						5158 DUS						
COLOR	YEAR		MAKE/MODE	;L			VIN		LICENSE	MILEAGE	IN/ OUT	TAG
BLUE	11	VOI	KSWAGEN	GOLF			M7AJ2BW01	5444		52540/	52553	T707
DEL DATE	IN SERVI	E DATE	WARR, EXP.		PROMIS	ED	PO NO.			PAYMENT	INV. D	ATE
29NOV10 DD	1			18	3:00 10		1	.]		CASH	11SEP1	15
READY OPTIONS: SOLD-STK:11V010 3)RC=0759												
10SE	.P15		11SEF	215			•					
LINE OPCOD			YPE HOUR	เร		~			LIST	NET	TOT	ral .
TO 25 75 75		~~~										

FC: PART#: COUNT: CLAIM TYPE: 710

AUTH CODE:

52540 Perf ECM update

D PERFORM LUBE, OIL, AND FILTER CHANGE. TOP. OFF ALL FLUIDS, CHECK AND ADSUST TIRE PRESSURE.

LUB1 PERFORM LUBE OIL AND FILTER CHANGE, CHECK AND TOP OFF ALL FLUIDS, CHECK AND ADJUST

TIRE PRESSURE 5078 CPVM 1 071-115-562-C FILTERELEM 50 G-052-195-1B-DSP_CASTROL LL03

17.95 17.95 11.00 11.00 11.00 0.82 0.82 41.00 1.08 1.00 1.00

1 N-013-849-3 WASHER 52540 PERFORMED LUBE, OIL AND FILTER CHANG, CHECK AND TOP OFF ALL FLUIDS CHECK / ADJUST TIRE PRESSURES AS NEEDED AND VISUALLY INSPECT TIRES FOR WEAR AND DAMAGE.

BB30 BONUS BUCKS 30.00

CPV

-30.00 -30.00

EST: 69.95

DATE:

CASH:

CHECK: PERSONAL II COMPANY II

CHARGE: VISA DXMC.□DIS □ AM □



HYUMBRI





M

BUICK*

The only warrenties provided on the perts Installed are those made by the manufacturar. The seller, Boucher Volkswagen Marketplace, hereby expressly disclaims all warrenties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose

particular purpose.

Motor vehicle repair practices are regulated by Chepter ATCP 132, Wis. Adm. Code, administered by the Bureau of Consumer Protection, Wisconsin Dept. of Agriculture, Trade and Consumer Protection, P.O. Box 8911, Madison. Wisconsin 53708-8911.

ENVIRONMENTAL AND SHOP SUPPLY SURCHARGE: A charge is included for the handling and disposal of hazerdous waste and similar materials and for supplies consumed in the process of repairing your vehicle. These supplies include solvents, cleaners, rags, towels, cuts, bolts, tane, are.


OR CALL US AT: 1-888-BOUCHER You may aiso visit us or Facebook or follow ou

LET US SERVE ALL OF	DESCRIPTION	TOTALS
YOUR AUTOMOTIVE NEEDS! FOR A	LABOR AMOUNT	445.95
COMPLETE LISTING OF BOUCHER	PARTS AMOUNT	786.40
DEALERSHIPS, COLLISION REPAIR	GAS, OIL, LUBE	0.00
CENTERS AND HOURS	SUBLET AMOUNT	0.00
OF OPERATION, PLEASE VISIT OUR	MISC. CHARGES	25.95
WEBSITE AT: www.boucher.com	TOTAL CHARGES	1258.30
OR CALL US AT:	DED/ADJ	30.00
1-888-BOUCHER	SALES TAX	68.79
You may also visit us on Facebook or follow our tweets @ BoucherAuto	PLEASE PAY THIS AMOUNT	1297.09

I acknowledge receipt of a copy of this invoice which contains the revised estimate information, if any, and such revised estimate was previously authorized by me or on my behalf. Customer Signature: ...

Jeep

GMC



Amoln ave

