



MPS - NE Tower Window Condition












MPS - NE Tower Window Condition













MPS - NW Tower Window Condition












MPS - NW Tower Window Condition













MPS - SE Tower Window Condition









This graphic is an artist rendition. While efforts were made to best represent the finished project, variations in display hardware and printing may cause finishes, material patterns, and colors to vary in appearance both electronically and in physical deliverables. This artistic rendering is proposed and conceptual only, and are based upon preliminary development plans, which are subject to withdrawal, revisions and other changes. This rendering should not be relied upon as any warranties or representations express or implied, of the final detail of the proposed improvements. Any features or colors described are representative only, and Christopher Kidd & Associates, LLC reserves the right to make changes or substitutions of equal or better quality.




MPS - SE Tower Window Condition












MPS - SW Tower Window Condition









MPS - SW Tower Window Condition