

July 31, 2023


My name is Jonathan J. Pinales, I'm filling a claim for a incident that happened on July 14, 2023 around 4:20pm, I had my car parked in front of my home, when a huge bark branch broke off and crush my car. It has severe damages and i'm unable to drive it. I'm seeking that the city of Milwaukee pays for my damages. The make and model of my car is a 2004 Toyota Solara. I have attached 2 copies of estimates and the total cost to get it fixed.

Thank you in this matter, if you need further information don't hesitate to contact me at 414-702-3619.

Home Address: 2626 N. Booth St
Milwaukee, WI 53212

Email Address: JonathanJPinales@gmail.com

Sincerely,



7/31/23

CITY CLERK'S OFFICE

2023 JUL 31 PM 2:48

CITY OF MILWAUKEE

**ANDREW AUTOMOTIVE BODY
REPAIR CENTER**

1621 W. LaSalle St., MILWAUKEE, WI 53209
Phone: (414) 540-2559
FAX: (414) 228-7420

Workfile ID: 6b068dc9
PartsShare: 7t59hz
Federal ID: 39-1764755
State EPA: WID988603379

Preliminary Estimate

Customer: PINALES, JONATHAN

Job Number:

Written By: Colleen Jessel

Insured: PINALES, JONATHAN
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

PINALES, JONATHAN

2624 N BOOTH ST
MILWAUKEE, WI 53212
(414) 630-8219 Cell

Inspection Location:

ANDREW AUTOMOTIVE BODY REPAIR
CENTER

1621 W. LaSalle St.
MILWAUKEE, WI 53209
Repair Facility
(414) 540-2559 Business

Insurance Company:

VEHICLE

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

VIN: 4T1CA30P64U001222
License:
State:

Interior Color:
Exterior Color: SILVER
Production Date:

Mileage In:
Mileage Out:
Condition:
Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
Overdrive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Console/Storage
Overhead Console

Wood Interior Trim
Woodgrain

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Home Link

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
Cassette
Premium Radio
CD Changer/Stacker

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags

ROOF

Electric Glass Sunroof

SEATS

Bucket Seats
Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4yRmn7

Preliminary Estimate

Customer: PINALES, JONATHAN

Job Number:

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		FRONT BUMPER					
2		O/H bumper assy				2.2	
3	* <>	Rpr Bumper cover				5.0	2.8
4		Add for Clear Coat					1.1
5		HOOD					
6	Repl	Hood	53301AA081	1	705.71	1.2	3.0
7		Overlap Major Non-Adj. Panel					-0.2
8		Add for Clear Coat					0.6
9		Add for Underside(Complete)					1.5
10		Add for Clear Coat					0.3
11		WINDSHIELD					
12	Repl	Windshield Toyota SLE	56101AA06083	1	947.72	Incl.	
13	**	Repl A/M WINDSHIELD URETHANE KIT		1	30.00 T		
14		ROOF					
15	Repl	Roof panel	63111AA090	1	1,016.69	21.0	3.2
16		Overlap Major Non-Adj. Panel					-0.2
17		Add for Clear Coat					0.6
18	Repl	W'shield header	63102AA904	1	146.65	1.5	
19	Repl	Roof reinf	63144AA070	1	74.19		
20	Repl	Rear header	63133AA050	1	147.97	1.5	
21	Repl	Sunroof reinf	63142AA030	1	238.94		
22	Repl	Headliner w/o head air bags stone	63311AA140B0	1	1,631.79	Incl.	
23		DOOR					
24	R&I	LT R&I door assy				1.1	
25	**	Repl A/M LT Mirror assy w/o heated silver	87940AA906	1	235.00	0.3	0.5
26		Overlap Minor Panel					-0.2
27		Add for Clear Coat					0.1
28		BACK GLASS					
29	Repl	Back glass Toyota w/o diversity ant.	64811AA120	1	807.48	Incl.	
30	**	Repl A/M BACK GLASS URETHANE KIT		1	30.00 T		
31		QUARTER PANEL					
32	*	Rpr RT Quarter panel				12.0	2.7
33		Overlap Major Adj. Panel					-0.4
34	*	Add for Clear Coat					0.5
35	*	Repl LKQ LT quarter panel; coupe - ROOF RAIL +35%	61612AA040	1	418.50	18.0	3.5
		Note: UPPER ROOF RAIL- INCL BACKGLASS LABOR					
36		Overlap Major Adj. Panel					-0.4
37	*	Add for Clear Coat					0.6

Preliminary Estimate

Customer: PINALES, JONATHAN

Job Number:

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

38		Deduct for Overlap					-5.0	
39	#	Rpr CUT AND TRIM					3.0	
40	TRUNK LID							
41		R&I Spoiler					0.4	
42	*	Repl LKQ trunk lid assy +35%	64401AA111	1	297.00		1.0	2.3
43		Overlap Major Adj. Panel						-0.4
44	*	Add for Clear Coat						0.4
45	#	Rpr OVERHAUL LKQ DECKLID					2.5	
46		Repl Nameplate "SOLARA" type 1	75442AA040	1	50.48		0.2	
47		Repl Nameplate "V6"	75444AA020	1	30.17		0.2	
48		Repl Nameplate "SLE"	75443AA150	1	34.77		0.2	
49		Repl Emblem	75441AA060	1	44.79		0.2	
50	REAR LAMPS							
51		R&I RT Combo lamp assy					0.4	
52		R&I LT Combo lamp assy					0.4	
53	REAR BUMPER							
54		R&I R&I bumper cover					1.0	
55	#	Subl HAZARDOUS WASTE		1	5.00 T			
56	**	Repl A/M COVER CAR EXTERIOR		1	10.00 T		0.3	
57	**	Repl A/M FLEX ADDITIVE (PER COVER)		1	10.00 T			
58	**	Repl A/M MASK JAMBS/OPENINGS (PER OPENING)		1	25.00 T		1.2	
59	#	Refn FEATHER EDGE PRIME BLOCK (PER PANEL)						1.5
60	#	Rpr PULL OR CUT FOR ACCESS					1.0	
61	**	Repl A/M WELD THRU PRIMER		1	3.00 T			
62	**	Repl A/M CORROSION PROTECTION		1	10.00 T		0.3	
63	**	Repl A/M SELF LEVELING SEAM SEALER (PER FOOT)		15	41.70 T		0.1	
64	**	Repl A/M 2 PART PRODUCT NOZZLE		4	14.00 T			
65	#	Rpr CLEAN UP BROKEN GLASS					4.0	
66	**	Repl A/M FASTENERS & RIVETS		1	45.00 T			
SUBTOTALS					7,051.55		75.2	23.4

Preliminary Estimate

Customer: **PINALES, JONATHAN**

Job Number:

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					6,827.85
Body Labor	75.2 hrs	@		\$ 70.00 /hr	5,264.00
Paint Labor	23.4 hrs	@		\$ 70.00 /hr	1,638.00
Paint Supplies	23.4 hrs	@		\$ 50.00 /hr	1,170.00
Body Supplies	74.7 hrs	@		\$ 4.00 /hr	298.80
Miscellaneous					223.70
Subtotal					15,422.35
Sales Tax	\$ 15,422.35	@		5.5000 %	848.23
Grand Total					16,270.58

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Preliminary Estimate

Customer: PINALES, JONATHAN

Job Number:

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide AEM8540, CCC Data Date 07/18/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: PINALES, JONATHAN

Job Number:

2004 TOYO Camry Solara SLE Automatic 2D CPE 6-3.3L Gasoline SMPI SILVER

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
25	Keystone, Inc 4410 N. 132ND STREET, SUITE A BUTLER WI 53007 (414) 463-1019	#TO1320240 A/M LT Mirror assy w/o heated silver Quote: 1813441900 Expires: 09/09/23	\$ 235.00
35	LKQ Corp 4410 N 132nd St, Suite A Butler WI 53007 (414) 463-1019	#~326676500 LKQ LT quarter panel; coupe - ROOF RAIL +35% Quarter Panel Assembly SPORT,2DR,W/OSUN L, CPE, L,S#\$TN148 Quote: 1813413329 Expires: 09/09/23	\$ 310.00
42	LKQ Corp 4410 N 132nd St, Suite A Butler WI 53007 (414) 463-1019	#~225404699 LKQ trunk lid assy +35% Decklid / Tailgate SPORT CONV W/SPOILER, SPORT,S#\$NP908 Quote: 1813423543 Expires: 09/09/23	\$ 220.00



East Side Auto Body

3888 N. Fratney St.
Milwaukee, WI 53212
Work Phone: (414) 963-8989
Fax: (414) 963-8852
moesa236@gmail.com

Estimate

Est # 9168
ID # 13473984

Vehicle Info

2004 Toyota -Solara SE Sport
4T1CA30P64U001222
License: AFN1046 WI
Body Type: 2 Door Coupe
Engine: 3.3L 6 Cyl Gas Injected
Transmission: 5 Speed Auto Trans
Drive Type: FWD

Owner

Jonathan Pinales

Insurance Company

Inspection Date: 07/17/2023
Repair Days: 10

	Oper	Description	Part Number	Price	Labor
FRONT BUMPER					
1	Repair	FRT BUMPER COVER			1 hrs. Body 2.4 hrs. Paint panel 1.0 hrs. Refinish
		1 hrs. Clearcoat			
HOOD					
2	Repair	HOOD PANEL			3 hrs. Body 2.8 hrs. Paint panel 1.1 hrs. Refinish
		1.1 hrs. Clearcoat			
WINDSHIELD					
3	Replace	W/SHIELD GLASS	FW02438GBN	\$288.25	3 hrs. Glass
ROOF					
4	Replace	ROOF PANEL	63111-AA090	\$980.61	22.5 hrs. Body 2.6 hrs. Paint panel 1.0 hrs. Refinish
		1 hrs. Clearcoat			
5	Replace	FRT ROOF SUNROOF REINF	0	\$195.00	0.6 hrs. Body
BACK WINDOW					
6	Replace	BACK WINDOW GLASS	0	\$360.23	3 hrs. Glass
LUGGAGE LID					
7	Replace	LUGGAGE LID PANEL	0	\$260.00	1 hrs. Body 2.3 hrs. Paint panel 2.1 hrs. Refinish
		0.9 hrs. Clearcoat, 1.2 hrs. Underside			

Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	28.1	\$70.00	\$1,967.00	✓
Body Supplies	28.1	\$48.00	\$1,348.80	✓
Glass Labor	6.0	\$60.00	\$360.00	✓
Paint Labor	15.3	\$70.00	\$1,071.00	✓
Paint Supplies	15.3	\$48.00	\$734.40	✓
LKQ Parts			\$815.23	✓
OEM Parts			\$1,268.86	✓
Taxable Amount			\$7,565.29	
Tax	5.6%		\$423.66	
Grand Total			\$7,988.95	