



STONE WALL SECTION DETAIL

NOTES:

1. ALL NEW MASONRY REINFORCING & ANCHORS TO BE HOT-DIPPED GALVANIZED, TYP.
2. NEW STONE MORTAR TO BE "S" TYPE WITH AIR-ENTRAINED.
3. EXISTING GRADE REQUIRES REGRADING SUCH THAT IT SLOPES AWAY FROM WALL.
4. EXISTING WALL HAS CEMENT PLASTER. REMOVE PLASTER AND REVIEW CONDITION OF CONCRETE. PERFORM CONCRETE CRACK AND SPALL REPAIR IF REQUIRED.



PIERCE ENGINEERS INC
 CONSULTING STRUCTURAL ENGINEERS
 181 N. Broadway | Milwaukee, WI 53202
 Phone: 414.278.6060 | Fax: 414.278.6061

DRAWN BY: PE
 SCALE: NONE
 BULLETIN NO.:

DATE: 04.14.2025

SHEET NO.: S1.0