I Dawayne Gatzon am Writing this statement regarding damage to my 2021 Chery Suburban by the City of Milwaukee Cottoage truck. This incident accorded March 16th 2022 early Eafter Joon, at 4150 S. Herman 95+ Milw 53207. My Mother who was home at the time witnessed the truck hit our rehicle which was parked right next to the garbage tans. Saw the gentleman 100K and notice and shook his head and got back in the truck We called DPW investigators and had them come out to asess the damage and evidence Still left in the Street. Attached will be two quotes for damages we would

like to be repaired.
Please call if there are
any questions at 262-7575268. 4-10-22

Precision Autobody MKE 2617 S 31st St Rear Milwaukee, WI 53215

Email:fixit@precisionautobodymke.com Phone:(414)252-8952

*** PRELIMINARY ESTIMATE ***

04/15/2022 02:34 PM

Owner

Owner: Dawayne Gatzow

Control Information

Claim #:

Insured Policy #: 262-757-5268

Inspection

Inspection Date: 04/15/2022 02:34 PM

Inspection Type:

Appraiser Name: Sharif 414-552-9400 Address:

Appraiser License #:

Work/Day: (414)252-8952

Repairer

Repairer: Precision Autobody MKE

Address: 3135 W Forest Home ave

City State Zip: Milwaukee, WI 53215

Email: fixit@precisionautobodymke.com

Contact:

Work/Day: (414)252-8952

Work/Day:

Target Complete Date/Time:

Days To Repair: 4

Vehicle

OEM Part Price Quote ID: ****

2021 Chevrolet Suburban Premier 4 DR Wagon 8cyl Gasoline 5.3 10 Speed Automatic

> Lic Expire: Veh Insp#: Condition:

Ext. Refinish: Two-Stage

VIN: 1GNSKFKD2MR155714

Mileage Type: Actual Code: U7446E

Int. Refinish:

Options

2nd Row Head Airbags AM/FM Stereo

Anti-Lock Brakes **Automatic Dimming Mirror**

Blind Spot Sensor

Carpeting

Cross Traffic Alert Driver Seat Memory **Dual Power Seats Electronic Transfer Case**

Floor Mats Garage Door Opener 3rd Row Head Airbags Active Grille Shutter **Auto Dimming Ext Mirrors** Automatic High Beam Bose Sound System

Center Console Cruise Control **Dual Airbags**

Dual Pwr Lumbar Supports Engine Stop/Start Full Size Spare Tire Hands Free Tailgate

4-Wheel Drive

Aluminum/Alloy Wheels Auto Emergency Braking Automatic Power Locks

Bucket Seats

Corrective Lane Assist **Driver Information Sys Dual Exhaust System** Elect. Stability Control Ext Mirror Turn Signals Fwd. Collision Alert Head Airbags

1		

Heated Power Mirrors	Heated Rear Seats	Heated Steering Wheel
Heated/Cooled Frt Seats	High Definition Radio	Illuminated Visor Mirror
In-Vehicle WiFi	Intermittent Wipers	Keyless Entry System
Keyless Ignition System	LED Brakelights	LED Daytime Running Lts
LED Headlamps	Laminated Glass	Lane Departure Alert
Leather Seats	Leather Steering Wheel	Limited Slp Differential
Mirror(s) Memory	Navigation System	OnStar System
Parking Assist System	Pedestrian Detection Sys	Power Liftgate
Power Steering	Power Windows	Privacy Glass
Pwr 2nd Row Bench Seat	Pwr Accessory Outlet(s)	Pwr Fold 3rd Row Seat(s)
Pwr Folding Ext Mirrors	Pwr Tilt/Tele. Str Wheel	Rear View Camera
Rear Window Defroster	Rear Window Wiper/Washer	Remote Starter
Roof Rails	Safety Alert Seat(s)	Side Airbags
Side Steps	SiriusXM Satellite Radio	Strg Wheel Radio Control
Theft Deterrent System	Three Zone Climate Ctrl	Tire Pressure Monitor
Touch Screen Display	Traction Control System	USB Audio Input(s)
Voice Activatd Cellphone	Wireless Charging Pad	Wireless Phone Connect

Dama	ges					·····					
Line	Op	Guide	MC	Description		MFR.Part i	No.	Price	ADJ% B%	Hours	R
Rear Bu	យេវិទ	<u>er</u>									
	Ε	566		Cover,Rear B		84893406	3M Part	\$730.78		3,1	SM
2	L	566	13	Cover,Rear B	umper Upr	Refinish 2.4 Sur 0.6 Two 0.5 Two	-stage setup			3.5	RF
3	Ε	1206		Cover,RR But	mper Lower	84751057	3M Part	\$348.78		INC	SM
4	Ε	1475		Brkt,Rear Bur	nper Mtg	84701985	3M Part	\$26.65		INC	SM
5	RI	1365		Harness,Rear	r Bumper	R & I Asser	nbly	•		1.0*	ME
6	E	1121		Pad,Rear Bur	nper Štep	84286523 (\$73.60		INC	SM
7	Ε	1593		Mldg,Rear Bu	imper	84371054 (3M Part	\$115.82		INC	SM
8	E	1474		Cover, Trailer		84340919		\$55.95		INC	SM
lanual	Entr	<u>ies</u>									
9	SB	M03		Flex Additive		Sublet Rep	air	\$15.00*			RF
10	L	M15		Color Tint		Refinish		•		0.5*	RF
11	SB	M60		Hazardous W	aste Removal	Sublet Rep	air	\$5.00*			SM
12	Ł	M66		Color Sand A	nd Buff	Refinish		*****		0.5*	RF
13	N			Covid 19 Clea	aning	Additional L	abor			0.5*	SM ²
14	N			Pre-post scan		Additional L				1.0*	ME'
1	4	Items								7.0	IVIL
				MC	Message						
				13	INCLUDES 0	.6 HOURS FIF	RST PANEL	TWO-STAGE ALLO	WANCE		
E-43		otal & Er									
ESUM	ie i	otal & Er	itries								
EM Pa								\$1,351.58			
Paint &					4.5 h	dours @ \$40	.00	\$180.00			
		rial Tota							\$1,531.58		
ax on I	arts	& Mater	ial			@ 5.60	00%		\$85.77		
abor				Rate	Replace I Hrs	Repair Hrs	Total Hrs				-
heet M	etal	(SM)		\$60.00	3.1	0.5	3.6	\$216.00			

,			

Mech/Elec (ME) Frame (FR)	\$125.00 \$75.00	1.0	1.0	2.0	\$250.00		
Refinish (RF)	\$60.00	4.5		4.5	\$270.00		
Labor Total		1, 11, 11, 11, 11, 11, 11, 11, 11, 11,	****	10.1 Ho	ours	\$736.00	
Tax on Labor		@ :	5.600%		\$41.22	4.44.44	
Subjet Repairs					\$20.00		
Tax on Sublet		@ :	5.600%		\$1.12		
Gross Total						\$2,415.69	
Net Total						\$2,415.69	

Alternate Parts Y/06/00/00/06/06 Cumulative 06/00/00/06/06 Zip Code: 53215 Default OEM Part Prices DT 04/15/2022 02:34 PM EstimateID 944315996494110720 QuoteID ****

SPPL Yes Zip Code: 53215 Default

Rate Name Default

Audatex Estimating 8.1.425 Update 3 ES 04/15/2022 02:42 PM REL 8.1.425 Update 3 DT 04/01/2022 DB 04/08/2022 State Disclosure: Not Selected

© 2022 Audatex North America, Inc.

1.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Rebit
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage
		· ·



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2022 Audatex North America, Inc. AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

BRILYN AUTOBODY LLC 1201 W LAYTON AV **MILWAUKEE WI 53221**

Estimate #8325

Phone/Fax #: 414-281-7210 Email: brilynauto@outlook.com

Date: 4 1/3/22

Name	DAWAYNE GATZOW	Year-Make-Model	2021 CHEV SUBURBAN
Address	4150 S. HERHAN ST		PREMIER
City-State-Zip	MILWAUKEE, 53207	License #	DWNOUT
Cell-Work Phone	262-757-5268	Color	WHITE PEARL
Insured By	,	VIN#	16NSKFKDZMR155714
Claim #		Mileage	
Adjuster			
Adjuster Phone		Adjuster Fax	

3		3 2	3	78 00 83 97 78	730 10 115 19 348	Parts Necessary and Estimate of Labor Required REAR BYMPER COYER RE A OVERHAUL FLE X ADDITIVE CHROME HOLDING L REFLECTOR LOWER COYER W DVAL ETHAUST	Replace X	Repair
			3	00 BI	115 19	REL A OVERHAUL FLEX ADDITIVE CHROME MOLDING L REFLECTOR		
				82 97	115 19	FLEX ADDITIVE CHRONE MOLDING L REFLECTOR		
		6		82 97	115 19	L REFLECTOR		
		6		97	19	L REFLECTOR		
-	2	6				LOWER COVER WIDNAL EXHAUST	1 X	
							×	
						/		
						2 DAYS to REPAIR)		
			A					
,						THREE STALE PEARL		
				00	5	Hazardous Waste Removal/Car Cover		
				-00	5_	Restore Corrosion Protection		
						Tint and Blend		
						Clear Coat		
				80	212	Paint and Materials (38.00)		
/5	2	* 10	/3			SUBTOTAL OF LABOR AND REFINISH HOURS		
336	0	00	<i>ЭЭ8</i>	15	1443	SUBTOTAL		
1	2	OTAL	TOT					
		00	228	15	1443	SUBTOTAL OF LABOR AND REFINISH HOURS		

The above report is based on our inspection and does not cover additional parts or labor that may be required after the work has been opened up. Occasionally after the work has been started, damage or broken parts are discovered which are not evident on the first inspection. Because of this, above prices cannot be guaranteed. This estimate is for immediate acceptance only.

5.5% SALES TAX

GRAND TOTAL

USED PART PRICES ARE SUBJECT TO CHANGE DUE TO AVAILABILITY.

* '			
		·	