BEVERLY A. TEMPLE

BEVERLY A. TEMPLE
THOMAS O. GARTNER
BRUCE D. SCHRIMPF
ROXANE L. CRAWFORD
SUSAN D. BICKERT
HAZEL MOSLEY
HARRY A. STEIN
CTHAPT C. MILKAMAI

HARHY A. STEIN STUART S. MUKAMAL THOMAS J. BEAMISH MAURITA F. HOUREN

INUMAS J. BEAMISH
MAURITA F. HOUREN
JOHN J. HEINEN
MICHAEL G. TOBIN
DAVID J. STANOSZ
SUSAN E. LAPPEN
JAN A. SMOKOWICZ
PATRICIA A. FRICKER
HEIDI WICK SPOERL
KURT A. BEHLING
GREGG C. HAGOPIAN
ELLEN H. TANGEN
MELANIE R. SWANK
JAY A. UNORA
DONALD L. SCHRIEFER
EDWARD M. EHRLICH
LEONARD A. TOKUS
MIRIAM R. HORWITZ
MARYNELL REGAN
G. O'SULLIVAN-CROWLEY
DAWN M. BOLAND
KATHRYN M. ZALEWSKI

KATHRYN M. ZALEWSKI

Assistant City Attorneys

CITY OF MILWAUKEE

GRANT F. LANGLEY

RUDOLPH M. KONRAD PATRICK B. McDONNELL LINDA ULISS BURKE Deputy City Attorneys



OFFICE OF CITY ATTORNEY

800 CITY HALL 200 EAST WELLS STREET MILWAUKEE, WISCONSIN 53202-3551 TELEPHONE (414) 286-2601 TDD (414) 286-2025 FAX (414) 286-8550

July 13, 2004

Napolean White 5044 North 19th Street Milwaukee, WI 53209

RE:

Napolean White

C.I. File No: 04-S-184

Dear Mr. White:

This office is in receipt of your claim in the amount of \$1,471.32, relating to damage sustained to your property on May 14, 2004 due to backwater in your basement at 5044 North 19th Street.

Our investigation reveals that the Infrastructure Services Division records indicate that they investigated a backwater at 5044 North 19th Street on May 14, 2004 and found the Milwaukee Metropolitan Sewerage District interceptor sewer to be surcharged causing the City main sanitary sewer to back-up into the basement. Saturated ground conditions and severe rain that occurred on this date resulted in flows that exceeded the capacity of the system. As such, the City would not be liable. Accordingly, we are denying

If you wish to appeal this decision, you may do so by sending a letter within 21 days of the receipt of this letter to the Milwaukee City Clerk, 200 East Wells Street, Room 205, Milwaukee, Wisconsin 53202,

Very truly yours,

ethern to come

NGLEY

STEVEN M. CARINI Investigator Adjuster

SMC:beg 1029-2004-1705:82914