



AMERICAN FAMILY MUTUAL INSURANCE COMPANY, S.I.  
 6000 AMERICAN PARKWAY  
 MADISON WI 53783

AmFam.com

1-800-MY AMFAM® (692-6326)

February 3, 2020

CITY OF MILWAUKEE  
 2020 FEB 10 P 3:48  
 CLERK'S OFFICE

CITY CLERK  
 C/O CLAIMS  
 200 E WELLS ST  
 MILWAUKEE WI 53202-3515

RECEIVED  
 OFFICE OF CITY ATTORNEY

FEB 10 2020

REGARDING THE CLAIM FOR RAYMOND C SAVAGE FROM LOSS DATE DECEMBER 24, 2019

11:35 (A.M./P.M.)

**Important information regarding this claim**

Please review the following information and contact me with any questions

Claim number	Date of loss	Policy number	Policyholder
01-002-131892	12/24/2019	48RU302601	RAYMOND C SAVAGE

Re: American Family Claim #: 01-002-131892  
 Insured: Raymond Savage  
 Date of Loss: 12/24/2019  
 Claim Amount: \$28,945.18

Milwaukee City Clerk,

American Family Insurance was notified by our insured, Raymond Savage, that a water main broke on 12/24/2019 resulting in water damage to his basement and personal property.

American Family Insurance has paid \$28,445.18 for mitigation/repairs. The insured incurred a deductible expense of \$500.00 resulting in a total claim amount of \$28,945.18.

Our supporting documentation has been included for your review.

Thank you for your time and consideration.

Dated this 3 day of February, 2020.

AMERICAN FAMILY INSURANCE

By:   
 Darren Loomans  
 Subrogation Adjuster

I am here to answer any questions you may have. Please contact me using the information listed below.  
Thank you.

Darren Loomans  
Subrogation Senior Adjuster  
1-800-MYAMFAM (1-800-692-6326) Ext. 44438  
dloomans@amfam.com



**Financials (Total Incurred: \$28,445.18): Checks**

Check Number	Pay To	Payment Method	Net Amount	Issue Date	Scheduled Send Date	Status	Bulk Invoice	Deductible Applied	Service Period Start	Service Period End	Date of Reconciliation
0002501762	RAYMOND C SAVAGE And JOANN P SAVAGE And SELECT PORTFOLIO SERVICING INC ITS SUCCESSORS AND/OR ASSIGNS INSURANCE SERVICE CENTER	Check	\$21,547.38	01/27/2020	01/27/2020	Issued		\$500.00			
0002501768	RAYMOND C SAVAGE And JOANN P SAVAGE	Check	\$6,897.80	01/27/2020	01/27/2020	Issued		-			



January 27, 2020

Claim Scanning Center
6000 American Parkway
Madison, WI 53783-0001
P: 1-866-881-4318 X21775 C: 262-349-0264
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

RAYMOND C SAVAGE AND JOANN P SAVAGE
6041 W Fond Du Lac Ave
Milwaukee, WI 53218-5629

Claim Number: 01002131892
Date of Loss: 12/24/2019

The attached estimate of damages has been prepared for your property. The estimate has used common prices for labor and material from your area.

Enclosed is our draft for the actual cash value (today's replacement cost less depreciation) of your damaged property. For Dwelling and Structure damages, we may have included your mortgage company, SELECT PORTFOLIO SERVICING INC ITS SUCCESSORS AND/OR ASSIGNS INSURANCE SERVICE C, on the draft as required by your policy.

Summary For Coverage A - Dwelling

Table with 4 columns: Replacement Cost Value, Less Recoverable Depreciation, Less Non Recoverable Depreciation, Actual Cash Value (ACV). Values include \$30,859.87, (\$8,812.49), and Total ACV Settlement of \$21,547.38.

Summary For Mitigation

Table with 4 columns: Replacement Cost Value, Less Recoverable Depreciation, Less Non Recoverable Depreciation, Actual Cash Value (ACV). Values include \$6,897.80 and Total Outstanding ACV Settlement (All Coverages) of \$28,445.18.

See the enclosed estimate for details of your settlement which may include other itemized details not shown above.

If you wish to make a claim for the recoverable depreciation amount, you must do TWO things:

- 1. You must have the item(s) replaced or repaired within one year from your date of loss. \*Exception: Georgia and Washington policies ONLY - Please refer to your policy language as well as the section of this estimate titled Claiming Recoverable Depreciation following the Estimate Recap or Coverage Limit Details sections.
2. You must submit a final repair bill or purchase receipt showing the item(s) has been repaired or replaced.

The attached estimate is what we expect to be the reasonable cost to repair or replace the property. This estimate may not include permit fees. If total charges for repair/replacement plus permits exceed the amount shown here for that repair/replacement, prior to any deductible, then additional amounts may be payable. If the actual cost is more or less, the final payment will be adjusted accordingly. If you wish, you may repair or replace with higher quality items, however, you will be responsible for any increase in cost.



Please refer to your policy under either CONDITIONS - SECTION I or HOW WE SETTLE LOSSES - SECTION I for further details on determining your loss settlement.

Please present this estimate to a contractor or repair facility of your choice BEFORE you authorize the start of repairs. If any additional damage or costs are identified, for which you believe we should be responsible, they must be approved by a representative of American Family Insurance prior to having the additional work done. If you, your contractor, or repair facility have any questions, please contact us at (262) 349-0264.

American Family Insurance appreciates your business.

Thank You,  
Russ Pubanz



American Family Mutual Insurance Company, S.I.

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE
6041 W Fond Du Lac Ave
Milwaukee, WI 53218-5629

Phone: (262) 409-6307

Claim Rep.: Russ Pubanz
Estimator: Russ Pubanz

Claim Number: 01002131892 Policy Number: 48RU302601 Type of Loss: Water/Plumbing

Table with 3 columns: Coverage, Deductible, Policy Limit. Rows include Coverage A - Dwelling, Coverage A - Dwelling Extension, Coverage B - Personal Property, and Mitigation.

Date Contacted: 1/3/2020 3:00 PM
Date of Loss: 12/24/2019 11:00 AM
Date Est. Completed: 1/27/2020 9:42 AM

Price List: WIMW8X\_JAN20\_1
Restoration/Service/Remodel

Sales Taxes: Material Sales Tax @ 5.600%
Services Mat'l Tax @ 5.600%
Service Sales Tax @ 5.600%
Manuf. Home Tax @ 5.600%
Storage Tax @ 5.600%

Overhead: 10.0%
Profit: 10.0%



Estimate Recap For Coverage A - Dwelling

Description	RCV	Recoverable Depreciation	Non-recoverable Depreciation	ACV
Main Level - Water Heater Room	548.13	73.59	0.00	474.54
Main Level - Recreation Room	11,812.77	4,344.97	0.00	7,467.80
Main Level - Furnace Room	549.80	73.59	0.00	476.21
Main Level - Storage Area/Room	541.26	83.06	0.00	458.20
Main Level - Kitchen	4,845.71	826.90	0.00	4,018.81
Main Level - Bedroom	6,186.23	2,226.78	0.00	3,959.45
Main Level - Laundry Room	1,958.83	571.79	0.00	1,387.04
Main Level - Bathroom	3,162.68	219.71	0.00	2,942.97
Main Level - Stairs	667.08	392.10	0.00	274.98
Main Level - Debris Removal	587.38	0.00	0.00	587.38
	<b>30,859.87</b>	<b>8,812.49</b>	<b>0.00</b>	<b>22,047.38</b>

Estimate Recap For Mitigation

Description	RCV	Recoverable Depreciation	Non-recoverable Depreciation	ACV
Main Level - Water Heater Room	103.78	0.00	0.00	103.78
Main Level - Recreation Room	2,859.47	0.00	0.00	2,859.47
Main Level - Furnace Room	107.70	0.00	0.00	107.70
Main Level - Storage Area/Room	139.82	0.00	0.00	139.82
Main Level - Kitchen	529.76	0.00	0.00	529.76
Main Level - Bedroom	1,639.01	0.00	0.00	1,639.01
Main Level - Laundry Room	481.74	0.00	0.00	481.74
Main Level - Bathroom	318.61	0.00	0.00	318.61
Main Level - Miscellaneous	717.91	0.00	0.00	717.91



---

6,897.80                      0.00                      0.00                      6,897.80

**IMPORTANT - Please read the definitions below**

**What is replacement cost (RCV)?**

Replacement cost is the cost to repair the damaged item with an item of like kind and quality, without deduction for depreciation.

**What is depreciation?**

Depreciation is the amount deducted from the replacement cost based upon the age and condition of the item being replaced.

**What is actual cash value (ACV)?**

Actual cash value is based on the cost to repair or replace the damaged item with an item of like kind and quality, **less depreciation.**

*The Actual Cash Value (ACV) is based on an items: Age divided by normal Useful life, unless otherwise noted. Deviation from Age divided by normal Useful life is common due to inspection evaluation, condition of the item, obsolescence, product research, expert opinions, utility/functional value, market value and in some cases all or some of the above. For further information on ACV and the depreciation applied, please contact your claim representative.*

***Physical mail you submit:*** American Family Insurance appreciates your assistance in the handling of your claim. Any documentation you submit will be scanned and electronically retained in your claim file. Please include the claim number on the items submitted. The original documentation will be destroyed after 30 days. If you would like your documents returned, please indicate this on the documents and provide the address to which you would like the documents returned.

***E-mail:*** Our goal is to provide outstanding customer service. If you choose to use e-mail to communicate with us regarding your claim, please be sure to include your name and claim number on the subject line. Please forward any e-mail correspondence regarding your claim to the e-mail address listed below. Thank you for being our customer.

E-mail: [rpubanz@amfam.com](mailto:rpubanz@amfam.com)





RAYMOND\_C\_SAVAGE\_AND

Main Level

Water Heater Room

Height: 8'

Door

176.89 SF Walls  
32.67 SF Floor

2' 8" X 6' 8"

32.67 SF Ceiling  
3.63 SY Flooring

Opens into RECREATION\_R

209.56 SF Walls & Ceiling  
21.67 LF Floor Perimeter  
24.33 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
1. Air mover (per 24 hour period) - No monitoring	3.00 EA	\$25.56	\$0.00	\$4.29	\$80.97	-\$0.00	\$80.97
one unit 3 days							
2. Water extraction from hard surface floor	32.67 SF	\$0.21	\$0.00	\$0.38	\$7.24	-\$0.00	\$7.24
3. Apply anti-microbial agent to more than the floor	76.89 SF	\$0.19	\$0.00	\$0.96	\$15.57	-\$0.00	\$15.57
Rebuild							
4a. Remove Interior door - solid alder - paneled - slab only	1.00 EA	\$8.09	\$1.62	\$0.00	\$9.71	-\$0.59 (6/100yr)	\$9.12
4b. Replace Interior door - solid alder - paneled - slab only	1.00 EA	\$303.45	\$63.50	\$14.03	\$380.98	-\$22.87 (6/100yr)	\$358.11
5. Stain & finish door slab only (per side)	2.00 EA	\$51.77	\$20.88	\$0.88	\$125.30	-\$50.13 (6/15yr)	\$75.17
6. Replace Door knob/lockset - Detach & reset	1.00 EA	\$21.04	\$4.20	\$0.00	\$25.24	-\$0.00	\$25.24
7. Final cleaning - construction - Residential	32.67 SF	\$0.20	\$0.00	\$0.37	\$6.90	-\$0.00	\$6.90
<b>Totals</b>			<b>\$90.20</b>	<b>\$20.91</b>	<b>\$651.91</b>	<b>-\$73.59</b>	<b>\$578.32</b>



Recreation Room

Height: 8'

Door	2' 8" X 6' 8"	Opens into WATER_HEATER
Door	2' 8" X 6' 8"	Opens into FURNACE_ROOM
Door	2' 8" X 6' 8"	Opens into BEDROOM
Missing Wall	3' X 8'	Opens into STAIRS
Missing Wall	8' 10" X 8'	Opens into LAUNDRY_ROOM
Missing Wall	10' 7" X 8'	Opens into KITCHEN
Missing Wall	2' 4" X 8'	Opens into KITCHEN
Door	2' 8" X 6' 8"	Opens into STORAGE_AREA
934.89 SF Walls	668.56 SF Ceiling	1,603.44 SF Walls & Ceiling
668.56 SF Floor	74.28 SY Flooring	115.08 LF Floor Perimeter
		125.75 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
8. Air mover (per 24 hour period) - No monitoring	18.00 EA	\$25.56	\$0.00	\$25.76	\$485.84	-\$0.00	\$485.84
six units 3 days							
9. Dehumidifier (per 24 hour period) - Large - No monitoring	6.00 EA	\$73.13	\$0.00	\$24.57	\$463.35	-\$0.00	\$463.35
two units 3 days							
10. Tear out wet non-salvageable carpet, cut & bag for disp.	310.19 SF	\$0.45	\$0.00	\$1.22	\$140.81	-\$0.00	\$140.81
11. Tear out wet carpet pad and bag for disposal	310.19 SF	\$0.42	\$0.00	\$1.22	\$131.50	-\$0.00	\$131.50
12. Tear out non-salvageable tile floor & bag for disposal	358.37 SF	\$2.67	\$0.00	\$4.82	\$961.67	-\$0.00	\$961.67
13. Tear out baseboard	115.08 LF	\$0.36	\$0.00	\$0.00	\$41.43	-\$0.00	\$41.43
14. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall	115.08 LF	\$2.70	\$0.00	\$2.51	\$313.23	-\$0.00	\$313.23
15. Tear out and bag wet insulation	230.17 SF	\$0.60	\$0.00	\$0.90	\$139.00	-\$0.00	\$139.00
16. Apply anti-microbial agent to more than the floor	902.28 SF	\$0.19	\$0.00	\$11.21	\$182.64	-\$0.00	\$182.64

Rebuild



Recreation Room continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
17. Replace Carpet pad	310.19 SF	\$0.58	\$37.64	\$8.34	\$225.89	-\$135.53 (6/10yr)	\$90.36
18. Replace Carpet - per specs from independent carpet analysis	356.71 SF	\$4.80	\$358.66	\$81.10	\$2,151.97	-\$1,291.19 (6/10yr)	\$860.78
15 % waste added for Carpet - per specs from independent carpet analysis.							
19. Replace Vinyl tile - Standard grade	358.37 SF	\$2.44	\$179.58	\$23.48	\$1,077.48	-\$129.29 (6/50yr)	\$948.19
20. Replace Baseboard - 3 1/4" hardwood	115.08 LF	\$3.98	\$94.60	\$15.02	\$567.64	-\$22.70 (6/150yr)	\$544.94
21. Stain & finish baseboard	115.08 LF	\$1.39	\$32.24	\$1.16	\$193.36	-\$77.34 (6/15yr)	\$116.02
22. Replace 1/2" - drywall per LF - up to 2' tall	115.08 LF	\$9.95	\$230.46	\$7.15	\$1,382.66	-\$0.00	\$1,382.66
23. Tape joint for new to existing drywall - per LF	125.75 LF	\$9.67	\$243.60	\$2.04	\$1,461.64	-\$0.00	\$1,461.64
24. Replace Rigid foam insulation board - 2"	233.72 SF	\$1.60	\$78.10	\$16.49	\$468.54	-\$0.00	\$468.54
25a. Remove Wallpaper	701.17 SF	\$0.70	\$98.16	\$0.00	\$588.98	-\$504.84 (6/7yr)	\$84.14
25b. Replace Wallpaper	701.17 SF	\$2.01	\$289.74	\$39.27	\$1,738.36	-\$1,490.01 (6/7yr)	\$248.35
26. Remove Additional charge to remove non-strippable wallpaper	701.17 SF	\$0.30	\$42.16	\$0.39	\$252.90	-\$216.77 (6/7yr)	\$36.13
27. Replace Prep wall for wallpaper	934.89 SF	\$0.46	\$86.02	\$0.00	\$516.07	-\$0.00 (6/0yr)	\$516.07
28a. Remove Wallpaper border	125.75 LF	\$0.58	\$14.58	\$0.00	\$87.52	-\$75.02 (6/7yr)	\$12.50
28b. Replace Wallpaper border	125.75 LF	\$2.36	\$61.18	\$9.08	\$367.03	-\$314.59 (6/7yr)	\$52.44



Recreation Room continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
29a. Remove Mirror tile	38.50 SF	\$0.33	\$2.54	\$0.00	\$15.25	-\$4.57 (6/20yr)	\$10.68
29b. Replace Mirror tile	38.50 SF	\$4.14	\$32.52	\$3.23	\$195.14	-\$58.55 (6/20yr)	\$136.59
30a. Remove Trim board - 1" x 2" - installed (hardwood - oak or =)	29.00 LF	\$0.36	\$2.08	\$0.00	\$12.52	-\$0.50 (6/150yr)	\$12.02
30b. Replace Trim board - 1" x 2" - installed (hardwood - oak or =)	29.00 LF	\$3.09	\$18.46	\$2.71	\$110.78	-\$4.43 (6/150yr)	\$106.35
31. Stain & finish trim	29.00 LF	\$1.40	\$8.18	\$0.31	\$49.09	-\$19.64 (6/15yr)	\$29.45
32. Contents - move out then reset - Extra large room	1.00 EA	\$173.95	\$34.80	\$0.00	\$208.75	-\$0.00	\$208.75
33. Final cleaning - construction - Residential	668.56 SF	\$0.20	\$0.00	\$7.49	\$141.20	-\$0.00	\$141.20
<b>Totals</b>			<b>\$1,945.30</b>	<b>\$289.47</b>	<b>\$14,672.24</b>	<b>-\$4,344.97</b>	<b>\$10,327.27</b>

Furnace Room

Height: 8'

Door

2' 8" X 6' 8"

Opens into RECREATION\_R

187.56 SF Walls  
40.61 SF Floor

40.61 SF Ceiling  
4.51 SY Flooring

228.17 SF Walls & Ceiling  
23.00 LF Floor Perimeter  
25.67 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
34. Air mover (per 24 hour period) - No monitoring one unit 3 days	3.00 EA	\$25.56	\$0.00	\$4.29	\$80.97	-\$0.00	\$80.97
35. Water extraction from hard surface floor	40.61 SF	\$0.21	\$0.00	\$0.48	\$9.01	-\$0.00	\$9.01
36. Apply anti-microbial agent to more than the floor	87.50 SF	\$0.19	\$0.00	\$1.09	\$17.72	-\$0.00	\$17.72
Rebuild							
37a. Remove Interior door - solid alder - paneled - slab only							



Furnace Room continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
	1.00 EA	\$8.09	\$1.62	\$0.00	\$9.71	-\$0.59 (6/100yr)	\$9.12
37b. Replace Interior door - solid alder - paneled - slab only							
	1.00 EA	\$303.45	\$63.50	\$14.03	\$380.98	-\$22.87 (6/100yr)	\$358.11
38. Stain & finish door slab only (per side)							
	2.00 EA	\$51.77	\$20.88	\$0.88	\$125.30	-\$50.13 (6/15yr)	\$75.17
39. Replace Door knob/lockset - Detach & reset							
	1.00 EA	\$21.04	\$4.20	\$0.00	\$25.24	-\$0.00	\$25.24
40. Final cleaning - construction - Residential							
	40.61 SF	\$0.20	\$0.00	\$0.45	\$8.57	-\$0.00	\$8.57
<b>Totals</b>			<b>\$90.20</b>	<b>\$21.22</b>	<b>\$657.50</b>	<b>-\$73.59</b>	<b>\$583.91</b>

Storage Area/Room

Height: 8'

Door

347.56 SF Walls  
97.28 SF Floor

2' 8" X 6' 8"

97.28 SF Ceiling  
10.81 SY Flooring

Opens into RECREATION\_R

444.83 SF Walls & Ceiling  
43.00 LF Floor Perimeter  
45.67 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
41. Air mover (per 24 hour period) - No monitoring							
	3.00 EA	\$25.56	\$0.00	\$4.29	\$80.97	-\$0.00	\$80.97
one unit 3 days							
42. Water extraction from hard surface floor							
	97.28 SF	\$0.21	\$0.00	\$1.14	\$21.57	-\$0.00	\$21.57
43. Apply anti-microbial agent to more than the floor							
	184.17 SF	\$0.19	\$0.00	\$2.29	\$37.28	-\$0.00	\$37.28
Rebuild							
44a. Remove Interior door unit							
	1.00 EA	\$18.20	\$3.64	\$0.00	\$21.84	-\$1.31 (6/100yr)	\$20.53
44b. Replace Interior door unit							
	1.00 EA	\$187.83	\$39.14	\$7.89	\$234.86	-\$14.08 (6/100yr)	\$220.78
45. Stain & finish door slab only (per side)							
	2.00 EA	\$51.77	\$20.88	\$0.88	\$125.30	-\$50.13 (6/15yr)	\$75.17



Storage Area/Room continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
46. Replace Door knob/lockset - Detach & reset	1.00 EA	\$21.04	\$4.20	\$0.00	\$25.24	-\$0.00	\$25.24
47. Stain & finish door/window trim & jamb (per side)	1.00 EA	\$36.26	\$7.32	\$0.31	\$43.89	-\$17.54 (6/15yr)	\$26.35
48. Contents - move out then reset	1.00 EA	\$57.98	\$11.60	\$0.00	\$69.58	-\$0.00	\$69.58
49. Final cleaning - construction - Residential	97.28 SF	\$0.20	\$0.00	\$1.09	\$20.55	-\$0.00	\$20.55
<b>Totals</b>			<b>\$86.78</b>	<b>\$17.89</b>	<b>\$681.08</b>	<b>-\$83.06</b>	<b>\$598.02</b>

**Kitchen**

**Height: 8'**

**Missing Wall**

**2' 4" X 8'**

**Opens into RECREATION\_R**

**Missing Wall**

**10' 7" X 8'**

**Opens into RECREATION\_R**

198.00 SF Walls

87.19 SF Ceiling

285.19 SF Walls & Ceiling

87.19 SF Floor

9.69 SY Flooring

24.75 LF Floor Perimeter

24.75 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
50. Air mover (per 24 hour period) - No monitoring	6.00 EA	\$25.56	\$0.00	\$8.59	\$161.95	-\$0.00	\$161.95
two units 3 days							
51. Tear out baseboard	24.75 LF	\$0.36	\$0.00	\$0.00	\$8.91	-\$0.00	\$8.91
52. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall	24.75 LF	\$2.70	\$0.00	\$0.54	\$67.37	-\$0.00	\$67.37
53. Tear out and bag wet insulation	49.50 SF	\$0.60	\$0.00	\$0.19	\$29.89	-\$0.00	\$29.89
54. Tear out non-salvageable tile floor & bag for disposal	87.19 SF	\$2.67	\$0.00	\$1.17	\$233.97	-\$0.00	\$233.97
55. Apply anti-microbial agent to more than the floor							



Kitchen continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
	136.69 SF	\$0.19	\$0.00	\$1.70	\$27.67	-\$0.00	\$27.67
Rebuild							
56. Replace Vinyl floor covering (sheet goods) - Standard grade	100.27 SF	\$2.58	\$53.32	\$7.86	\$319.88	-\$38.38 (6/50yr)	\$281.50
15 % waste added for Vinyl floor covering (sheet goods) - Standard grade.							
57. Replace Baseboard - 3 1/4" hardwood	24.75 LF	\$3.98	\$20.34	\$3.23	\$122.08	-\$4.89 (6/150yr)	\$117.19
58. Stain & finish baseboard	24.75 LF	\$1.39	\$6.94	\$0.25	\$41.59	-\$16.64 (6/15yr)	\$24.95
59. Replace 1/2" - drywall per LF - up to 2' tall	24.75 LF	\$9.95	\$49.56	\$1.54	\$297.36	-\$0.00	\$297.36
60. Tape joint for new to existing drywall - per LF	24.75 LF	\$9.67	\$47.94	\$0.40	\$287.67	-\$0.00	\$287.67
61. Replace Rigid foam insulation board - 2"	49.50 SF	\$1.60	\$16.54	\$3.49	\$99.23	-\$0.00	\$99.23
62a. Remove Wallpaper	148.50 SF	\$0.70	\$20.80	\$0.00	\$124.75	-\$106.92 (6/7yr)	\$17.83
62b. Replace Wallpaper	148.50 SF	\$2.01	\$61.36	\$8.32	\$368.17	-\$315.58 (6/7yr)	\$52.59
63. Remove Additional charge to remove non-strippable wallpaper	148.50 SF	\$0.30	\$8.94	\$0.08	\$53.57	-\$45.92 (6/7yr)	\$7.65
64. Replace Prep wall for wallpaper	198.00 SF	\$0.46	\$18.22	\$0.00	\$109.30	-\$0.00 (6/0yr)	\$109.30
65a. Remove Wallpaper border	24.75 LF	\$0.58	\$2.88	\$0.00	\$17.24	-\$14.77 (6/7yr)	\$2.47
65b. Replace Wallpaper border	24.75 LF	\$2.36	\$12.04	\$1.79	\$72.24	-\$61.92 (6/7yr)	\$10.32
66a. Remove Bead board - 3/8" softwood veneer	20.89 SF	\$0.29	\$1.22	\$0.00	\$7.28	-\$0.28 (6/150yr)	\$7.00
66b. Replace Bead board - 3/8" softwood veneer	20.89 SF	\$2.78	\$11.90	\$1.35	\$71.32	-\$2.85 (6/150yr)	\$68.47



Kitchen continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
67. Replace Range - gas - Remove & reset	1.00 EA	\$168.38	\$33.68	\$0.00	\$202.06	-\$0.00	\$202.06
68. Replace Refrigerator - Remove & reset	1.00 EA	\$41.95	\$8.40	\$0.00	\$50.35	-\$0.00	\$50.35
69. Replace Dishwasher - Detach & reset	1.00 EA	\$286.43	\$57.28	\$0.00	\$343.71	-\$0.00	\$343.71
70a. Remove Cabinetry - lower (base) units	8.00 LF	\$7.29	\$11.66	\$0.00	\$69.98	-\$8.40 (6/50yr)	\$61.58
70b. Replace Cabinetry - lower (base) units	8.00 LF	\$174.60	\$292.14	\$63.91	\$1,752.85	-\$210.35 (6/50yr)	\$1,542.50
71. Replace Countertop - flat laid plastic laminate - Detach & reset	8.00 LF	\$15.24	\$24.38	\$0.00	\$146.30	-\$0.00	\$146.30
72. Replace Sink - double - Detach & reset	1.00 EA	\$167.32	\$33.46	\$0.00	\$200.78	-\$0.00	\$200.78
73. Contents - move out then reset	1.00 EA	\$57.98	\$11.60	\$0.00	\$69.58	-\$0.00	\$69.58
74. Final cleaning - construction - Residential	87.19 SF	\$0.20	\$0.00	\$0.98	\$18.42	-\$0.00	\$18.42
<b>Totals</b>			<b>\$804.60</b>	<b>\$105.39</b>	<b>\$5,375.47</b>	<b>-\$826.90</b>	<b>\$4,548.57</b>

Bedroom

Height: 8'

Door

2' 8" X 6' 8"

Opens into RECREATION\_R

Subroom: Bedroom closet (1)

Height: 8'

Door

2' 8" X 6' 8"

Opens into BEDROOM

478.23 SF Walls

171.79 SF Ceiling

650.02 SF Walls & Ceiling

171.79 SF Floor

19.09 SY Flooring

58.45 LF Floor Perimeter

66.45 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
-------------	-----	------------	-------------------	-------	------------------------	-------------------	-------------------

Mitigation

75. Air mover (per 24 hour period) - No monitoring

18.00 EA \$25.56

\$0.00 \$25.76

\$485.84

-\$0.00

\$485.84





Bedroom continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
six units 3 days							
76. Dehumidifier (per 24 hour period) - Large - No monitoring	3.00 EA	\$73.13	\$0.00	\$12.29	\$231.68	-\$0.00	\$231.68
one unit 3 days							
77. Tear out wet carpet pad and bag for disposal	171.79 SF	\$0.42	\$0.00	\$0.67	\$72.82	-\$0.00	\$72.82
78. Tear out wet non-salvageable carpet, cut & bag for disp.	171.79 SF	\$0.45	\$0.00	\$0.67	\$77.98	-\$0.00	\$77.98
79. Tear out non-salvageable tile floor & bag for disposal	171.79 SF	\$2.67	\$0.00	\$2.31	\$460.99	-\$0.00	\$460.99
80. Tear out baseboard	58.45 LF	\$0.36	\$0.00	\$0.00	\$21.04	-\$0.00	\$21.04
81. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall	58.45 LF	\$2.70	\$0.00	\$1.28	\$159.10	-\$0.00	\$159.10
82. Tear out and bag wet insulation	116.89 SF	\$0.60	\$0.00	\$0.46	\$70.59	-\$0.00	\$70.59
83. Apply anti-microbial agent to more than the floor	291.34 SF	\$0.19	\$0.00	\$3.62	\$58.97	-\$0.00	\$58.97
Rebuild							
84. Replace Carpet pad	171.79 SF	\$0.58	\$20.84	\$4.62	\$125.10	-\$75.05 (6/10yr)	\$50.05
85. Replace Carpet - per specs from independent carpet analysis	212.25 SF	\$4.80	\$213.42	\$48.26	\$1,280.48	-\$768.30 (6/10yr)	\$512.18
86. Replace Baseboard - 3 1/4" hardwood	58.45 LF	\$3.98	\$48.04	\$7.63	\$288.30	-\$11.54 (6/150yr)	\$276.76
87. Stain & finish baseboard	58.45 LF	\$1.39	\$16.38	\$0.59	\$98.22	-\$39.30 (6/15yr)	\$58.92
88. Replace 1/2" - drywall per LF - up to 2' tall	58.45 LF	\$9.95	\$117.04	\$3.63	\$702.25	-\$0.00	\$702.25



Bedroom continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
89. Tape joint for new to existing drywall - per LF	66.45 LF	\$9.67	\$128.74	\$1.08	\$772.39	-\$0.00	\$772.39
90. Replace Rigid foam insulation board - 2"	119.56 SF	\$1.60	\$39.94	\$8.44	\$239.68	-\$0.00	\$239.68
91a. Remove Wallpaper	358.67 SF	\$0.70	\$50.22	\$0.00	\$301.29	-\$258.24 (6/7yr)	\$43.05
91b. Replace Wallpaper	358.67 SF	\$2.01	\$148.20	\$20.09	\$889.22	-\$762.18 (6/7yr)	\$127.04
92. Remove Additional charge to remove non-strippable wallpaper	358.67 SF	\$0.30	\$21.56	\$0.20	\$129.36	-\$110.88 (6/7yr)	\$18.48
93. Replace Prep wall for wallpaper	478.23 SF	\$0.46	\$44.00	\$0.00	\$263.99	-\$0.00 (6/0yr)	\$263.99
94a. Remove Interior door unit	2.00 EA	\$18.20	\$7.28	\$0.00	\$43.68	-\$2.62 (6/100yr)	\$41.06
94b. Replace Interior door unit	2.00 EA	\$187.83	\$78.30	\$15.77	\$469.73	-\$28.19 (6/100yr)	\$441.54
95. Stain & finish door slab only (per side)	4.00 EA	\$51.77	\$41.78	\$1.77	\$250.63	-\$100.26 (6/15yr)	\$150.37
96. Replace Door knob/lockset - Detach & reset	2.00 EA	\$21.04	\$8.42	\$0.00	\$50.50	-\$0.00	\$50.50
97. Stain & finish door/window trim & jamb (per side)	4.00 EA	\$36.26	\$29.26	\$1.25	\$175.55	-\$70.22 (6/15yr)	\$105.33
98. Contents - move out then reset	1.00 EA	\$57.98	\$11.60	\$0.00	\$69.58	-\$0.00	\$69.58
99. Final cleaning - construction - Residential	171.79 SF	\$0.20	\$0.00	\$1.92	\$36.28	-\$0.00	\$36.28
<b>Totals</b>			<b>\$1,025.02</b>	<b>\$162.31</b>	<b>\$7,825.24</b>	<b>-\$2,226.78</b>	<b>\$5,598.46</b>



Laundry Room

Height: 8'

Door

2' 8" X 6' 8"

Opens into BATHROOM

Missing Wall

8' 10" X 8'

Opens into RECREATION\_R

186.22 SF Walls

73.61 SF Ceiling

259.83 SF Walls & Ceiling

73.61 SF Floor

8.18 SY Flooring

22.83 LF Floor Perimeter

25.50 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
100. Air mover (per 24 hour period) - No monitoring	6.00 EA	\$25.56	\$0.00	\$8.59	\$161.95	-\$0.00	\$161.95
two units 3 days							
101. Tear out baseboard	22.83 LF	\$0.36	\$0.00	\$0.00	\$8.22	-\$0.00	\$8.22
102. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall	22.83 LF	\$2.70	\$0.00	\$0.50	\$62.14	-\$0.00	\$62.14
103. Tear out and bag wet insulation	45.67 SF	\$0.60	\$0.00	\$0.18	\$27.58	-\$0.00	\$27.58
104. Tear out non-salvageable tile floor & bag for disposal	73.61 SF	\$2.67	\$0.00	\$0.99	\$197.53	-\$0.00	\$197.53
105. Apply anti-microbial agent to more than the floor	120.17 SF	\$0.19	\$0.00	\$1.49	\$24.32	-\$0.00	\$24.32
Rebuild							
106. Replace Vinyl floor covering (sheet goods) - Standard grade	84.65 SF	\$2.58	\$45.00	\$6.64	\$270.04	-\$32.41 (6/50yr)	\$237.63
15 % waste added for Vinyl floor covering (sheet goods) - Standard grade.							
107. Replace Baseboard - 3 1/4" hardwood	22.83 LF	\$3.98	\$18.78	\$2.98	\$112.62	-\$4.51 (6/150yr)	\$108.11
108. Stain & finish baseboard	22.83 LF	\$1.39	\$6.38	\$0.23	\$38.34	-\$15.34 (6/15yr)	\$23.00
109. Replace 1/2" - drywall per LF - up to 2' tall	22.83 LF	\$9.95	\$45.72	\$1.42	\$274.30	-\$0.00	\$274.30
110. Tape joint for new to existing drywall - per LF	25.50 LF	\$9.67	\$49.40	\$0.41	\$296.40	-\$0.00	\$296.40



Laundry Room continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
111. Replace Rigid foam insulation board - 2"	46.56 SF	\$1.60	\$15.56	\$3.29	\$93.35	-\$0.00	\$93.35
112a. Remove Wallpaper	139.67 SF	\$0.70	\$19.56	\$0.00	\$117.33	-\$100.56 (6/7yr)	\$16.77
112b. Replace Wallpaper	139.67 SF	\$2.01	\$57.70	\$7.82	\$346.26	-\$296.79 (6/7yr)	\$49.47
113. Remove Additional charge to remove non-strippable wallpaper	139.67 SF	\$0.30	\$8.40	\$0.08	\$50.38	-\$43.18 (6/7yr)	\$7.20
114. Replace Prep wall for wallpaper	186.22 SF	\$0.46	\$17.14	\$0.00	\$102.80	-\$0.00 (6/0yr)	\$102.80
115a. Remove Wallpaper border	25.50 LF	\$0.58	\$2.96	\$0.00	\$17.75	-\$15.22 (6/7yr)	\$2.53
115b. Replace Wallpaper border	25.50 LF	\$2.36	\$12.40	\$1.84	\$74.42	-\$63.78 (6/7yr)	\$10.64
116. Replace Dryer - Remove & reset	1.00 EA	\$31.47	\$6.30	\$0.00	\$37.77	-\$0.00	\$37.77
117. Replace Washing machine - Remove & reset	1.00 EA	\$34.95	\$7.00	\$0.00	\$41.95	-\$0.00	\$41.95
118. Contents - move out then reset	1.00 EA	\$57.98	\$11.60	\$0.00	\$69.58	-\$0.00	\$69.58
119. Final cleaning - construction - Residential	73.61 SF	\$0.20	\$0.00	\$0.82	\$15.54	-\$0.00	\$15.54
<b>Totals</b>			<b>\$323.90</b>	<b>\$37.28</b>	<b>\$2,440.57</b>	<b>-\$571.79</b>	<b>\$1,868.78</b>

Bathroom

Height: 8'

Door

2' 8" X 6' 8"

Opens into LAUNDRY\_ROOM

174.22 SF Walls  
35.00 SF Floor

35.00 SF Ceiling  
3.89 SY Flooring

209.22 SF Walls & Ceiling  
21.33 LF Floor Perimeter  
24.00 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
-------------	-----	------------	-------------------	-------	------------------------	-------------------	-------------------



Bathroom continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
Mitigation							
120. Air mover (per 24 hour period) - No monitoring	6.00 EA	\$25.56	\$0.00	\$8.59	\$161.95	-\$0.00	\$161.95
two units 3 days							
121. Water extraction from hard surface floor	35.00 SF	\$0.21	\$0.00	\$0.41	\$7.76	-\$0.00	\$7.76
122. Tear out wet drywall, cleanup, bag, per LF - up to 2' tall	21.33 LF	\$2.70	\$0.00	\$0.47	\$58.06	-\$0.00	\$58.06
123. Tear out and bag wet insulation	42.67 SF	\$0.60	\$0.00	\$0.17	\$25.77	-\$0.00	\$25.77
124. Tear out wet paneling, bag for disposal	85.33 SF	\$0.48	\$0.00	\$0.53	\$41.49	-\$0.00	\$41.49
125. Tear out trim	21.33 LF	\$0.36	\$0.00	\$0.00	\$7.68	-\$0.00	\$7.68
126. Apply anti-microbial agent to more than the floor	78.56 SF	\$0.19	\$0.00	\$0.97	\$15.90	-\$0.00	\$15.90
Rebuild							
127. Replace Base shoe	21.33 LF	\$1.14	\$4.96	\$0.53	\$29.81	-\$1.19 (6/150yr)	\$28.62
128. Seal & paint base shoe or quarter round	21.33 LF	\$0.72	\$3.10	\$0.12	\$18.58	-\$7.43 (6/15yr)	\$11.15
129a. Remove Interior door unit	1.00 EA	\$18.20	\$3.64	\$0.00	\$21.84	-\$1.31 (6/100yr)	\$20.53
129b. Replace Interior door unit	1.00 EA	\$187.83	\$39.14	\$7.89	\$234.86	-\$14.08 (6/100yr)	\$220.78
130. Stain & finish door slab only (per side)	2.00 EA	\$51.77	\$20.88	\$0.88	\$125.30	-\$50.13 (6/15yr)	\$75.17
131. Replace Door knob/lockset - Detach & reset	1.00 EA	\$21.04	\$4.20	\$0.00	\$25.24	-\$0.00	\$25.24



Bathroom continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
132. Stain & finish door/window trim & jamb (per side)	1.00 EA	\$36.26	\$7.32	\$0.31	\$43.89	-\$17.54 (6/15yr)	\$26.35
133. Replace 1/2" - drywall per LF - up to 2' tall	21.33 LF	\$9.95	\$42.70	\$1.33	\$256.26	-\$0.00	\$256.26
134. Tape joint for new to existing drywall - per LF	24.00 LF	\$9.67	\$46.50	\$0.39	\$278.97	-\$0.00	\$278.97
135. Replace Rigid foam insulation board - 2"	43.56 SF	\$1.60	\$14.56	\$3.07	\$87.33	-\$0.00	\$87.33
136. Replace Plastic tile	96.00 SF	\$8.20	\$160.08	\$13.22	\$960.50	-\$57.62 (6/100yr)	\$902.88
137a. Remove Vanity	2.50 LF	\$7.29	\$3.64	\$0.00	\$21.87	-\$2.63 (6/50yr)	\$19.24
137b. Replace Vanity	2.50 LF	\$179.95	\$94.12	\$20.72	\$564.72	-\$67.78 (6/50yr)	\$496.94
138. Replace Sink - single - Detach & reset	1.00 EA	\$156.58	\$31.32	\$0.00	\$187.90	-\$0.00	\$187.90
139. Replace Toilet - Detach & reset	1.00 EA	\$254.37	\$50.94	\$0.30	\$305.61	-\$0.00	\$305.61
<b>Totals</b>			<b>\$527.10</b>	<b>\$59.90</b>	<b>\$3,481.29</b>	<b>-\$219.71</b>	<b>\$3,261.58</b>

Stairs

Height: 16' 1"

Missing Wall

3' X 16' 1 7/16"

Opens into RECREATION\_R

283.22 SF Walls  
64.36 SF Floor

35.50 SF Ceiling  
7.15 SY Flooring

318.72 SF Walls & Ceiling  
28.45 LF Floor Perimeter  
23.83 LF Ceil. Perimeter

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
140a. Remove Carpet pad	64.36 SF	\$0.12	\$1.54	\$0.00	\$9.26	-\$5.55 (6/10yr)	\$3.71
140b. Replace Carpet pad	64.36 SF	\$0.58	\$7.80	\$1.73	\$46.86	-\$28.12 (6/10yr)	\$18.74
141. Remove Carpet - per specs from independent carpet analysis							



Stairs continued...

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
	64.36 SF	\$0.27	\$3.48	\$0.00	\$20.86	-\$12.51 (6/10yr)	\$8.35
142. Replace Carpet - per specs from independent carpet analysis							
	74.02 SF	\$4.80	\$74.42	\$16.83	\$446.55	-\$267.94 (6/10yr)	\$178.61
15 % waste added for Carpet - per specs from independent carpet analysis.							
143. Replace Step charge for "waterfall" carpet installation							
	12.00 EA	\$9.00	\$21.66	\$0.30	\$129.96	-\$77.98 (6/10yr)	\$51.98
144. Final cleaning - construction - Residential							
	64.36 SF	\$0.20	\$0.00	\$0.72	\$13.59	-\$0.00	\$13.59
<b>Totals</b>			<b>\$108.90</b>	<b>\$19.58</b>	<b>\$667.08</b>	<b>-\$392.10</b>	<b>\$274.98</b>

Debris Removal

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
145. Dumpster load - Approx. 20 yards, 4 tons of debris							
	1.00 EA	\$489.48	\$97.90		\$587.38	-\$0.00	\$587.38
<b>Totals</b>			<b>\$97.90</b>		<b>\$587.38</b>	<b>-\$0.00</b>	<b>\$587.38</b>

Miscellaneous

Description	Qty	Unit Price	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
146. Equipment setup, take down, and monitoring (hourly charge)						
	16.00 HR	\$42.49	\$38.07	\$717.91	-\$0.00	\$717.91
<b>Totals</b>			<b>\$38.07</b>	<b>\$717.91</b>	<b>-\$0.00</b>	<b>\$717.91</b>

	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
<b>Estimate Totals</b>	<b>\$5,099.90</b>	<b>\$772.02</b>	<b>\$37,757.67</b>	<b>-\$8,812.49</b>	<b>\$28,945.18</b>

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



**1-DSCN3989**

Date Taken:

Risk



**2-DSCN3990**

Date Taken:

right elevation



# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



**3-DSCN3991**

Date Taken:

right elevation water through window wells



**4-DSCN3992**

Date Taken:

rec room

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001

P: 1-866-881-4318 X21775 C: 262-349-0264

Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



**5-DSCN3993**

Date Taken:

rec room



**6-DSCN3994**

Date Taken:

rec room couch

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001

P: 1-866-881-4318 X21775 C: 262-349-0264

Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



7-DSCN3995

Date Taken:

rec room couch



8-DSCN3996

Date Taken:

kitchen

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001

P: 1-866-881-4318 X21775 C: 262-349-0264

Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



9-DSCN3997

Date Taken:

laundry area



10-DSCN3998

Date Taken:

rec room

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892


Policy #: 48RU302601



11-DSCN3999

Date Taken:

bathroom



12-DSCN4000

Date Taken:

rec room

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



13-DSCN4001

Date Taken:

bedroom



14-DSCN4002

Date Taken:

bedroom

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



**15-DSCN4003**

Date Taken:

laundry area



**16-DSCN4004**

Date Taken:

bedroom

# Photo Sheet

American Family Mutual Insurance Company, S.I.

Claim Scanning Center  
6000 American Parkway  
Madison, WI 53783-0001  
P: 1-866-881-4318 X21775 C: 262-349-0264  
Fax: 1-866-774-4561 Email: rpubanz@amfam.com

Insured: RAYMOND C SAVAGE AND JOANN P SAVAGE

Claim #: 01002131892

Policy #: 48RU302601



17-DSCN4005

Date Taken:

rear storage