

June 01, 2007

CITY OF MILWAUKEE

2007 JUN -5 AM 11:40

Re: Angelica Seda  
C.I. File No.: 07-S-143

RONALD E. LEONHARDI  
CITY CLERK


Dear Grant Langley (City Attorney);

I received the letter stating my claim was denied for the damage sustained to my vehicle on March 31, 2007 when the traffic light at the intersection of Lovers Lane Rd and Silver Spring near 45 malfunctioned causing a collision with another vehicle and I.

In the letter I was sent it states that my loss doesn't involve the City of Milwaukee and that it can't be held liable. I would like to know why the City of Milwaukee wouldn't be held liable if the county highway is under the jurisdiction of Milwaukee County since I didn't receive the reason/explanation on why I was denied in the letter I was sent.

It states I may wish to contact the Engineer but it doesn't say why. Are they responsible for the malfunctioning of the lights and will they be able to help me with my claim? I would like to appeal this denial but want to know if I need to contact the Engineer before setting up a hearing. I can be reached at (414)-881-3346, if I do not answer please leave a message or you can write me a letter and I will get back to you as soon as possible. Thank you for your time and response.

Sincerely,



Angelica Seda

OFFICE OF  
CITY ATTORNEY

2007 JUN -5 PM 3:14

CITY OF MILWAUKEE  
RECEIVED

City Clerk  
ATTN: CLAIMS  
200 E. Wells St., Room 205  
Milwaukee, WI 53202

MILWAUKEE  
2007 APR 23 AM 9:38  
RO: [REDACTED]  
CITY CLERK


To whom it may concern to;

This claim I am filing is for my damaged vehicle due to a collision that occurred between another party and I because of the malfunction traffic lights that are by Silverspring & Lovers Lane Rd. by I-45. The collision occurred on the date of March 31, 2007 which was a Saturday around 4:30pm. Supposedly both our lights were green since the other party had told me she had the green left turn arrow light. The other party stated she had the green left arrow and was coming from the East and was trying to make a left turn to get onto I-45 heading southbound. I was coming from the West (Menomonee Falls) heading East and I had the green solid light to keep going straight. We both kept going and that is when the collision occurred.

There have been many accidents in the past due to the malfunctioning of the lights. I don't think that both lights should be green at the same time. A police officer Watts from district #4 had mentioned that she has sat at one end and viewed that cars from both ends would keep going without stopping and that there have been many collisions at these lights.

Under the circumstances of the collision my car has some damage to it and my claim is to get my car fixed. I went to two different places for estimates; AUTOCRAFT, INC. gave me an estimate of \$2,199.69 and CARSTAR gave me an estimate of \$3,228.92 just for the damage on the outside of my vehicle. I have attached the paperwork for the two estimates for the outer damaged area on my vehicle. My mailing address is 5340 N. Lovers Lane Rd. Apt# 166, Milwaukee, WI 53225. My phone number where I can be reached at is (414)-881-3346. Thank you for your time.

Sincerely,



Angelica Seda  
5340 N. Lovers Lane Rd. Apt# 166  
Milwaukee, WI 53225

MILWAUKEE  
CITY ATTORNEY  
2007 APR 23 PM 3:09  
CITY CLERK

N56 W13480 SILVER SPRING RD.  
 MENOMONEE FALLS, WI 53051  
 1-262-783-4730

# AUTOCRAFT, INC.

414-881-3346

OWNER <i>MARILICA SEDA</i>	PHONE (HOME)	PHONE (WORK)	ADDRESS	DATE
MAKE OF CAR <i>FORD</i>	YEAR <i>97</i>	MODEL <i>TRUCK</i>	LICENSE NO.	STOCK NO.
INSURANCE CO.	INS. APPRAISER	PHONE	CLAIM NO.	COLOR <i>Black</i>
				COLOR CODE NO.

Repair	Replace	ESTIMATE SHEET & REPAIR ORDER	LABOR	PAINT	PARTS	SUBLET
/		<i>Front bumper cover</i>	<i>75</i>	<i>35</i>	<i>312.00</i>	
/		<i>Left fender</i>	<i>78</i>	<i>34</i>	<i>144.00</i>	
/		<i>Left mirror</i>	<i>1.00</i>		<i>7.00</i>	
/		<i>Upper control arm</i>	<i>20</i>	<i>10</i>		
/		<i>Left shock absorbers</i>	<i>15</i>		<i>140.00</i>	
		<i>Am. H/R</i>	<i>6</i>			
		<i>Alignment &amp; Check Suspension</i>				<i>99.95</i>
		<i>Tire &amp; Balanc</i>		<i>10</i>		
		<i>0.00</i>		<i>30</i>		
<b>TOTALS</b>			<i>9410</i>	<i>5683</i>	<i>683.00</i>	

*42199.60*

Labor	<i>410.00</i>
Paint	<i>525.00</i>
Parts	<i>683.00</i>
Sublet	<i>99.95</i>
Paint & Body Mtis.	<i>75.00</i>
Towing & Protective Storage	
Advance Charges	
Subtotal	<i>2092.95</i>
Tax	<i>106.74</i>
Total	<i>2199.69</i>

All Parts Prices Subject to Invoice

The manual used to make your Damage Report is to be used as a guide only. Therefore, after work is started additional damage or parts replacement could be evident. Naturally this Damage Report cannot

04/02/2007 at 03:26 PM  
68518

Job Number:

**CARSTAR LOU'S AUTOBODY - GREENFIELD**  
Federal ID #:391519593  
4739 SOUTH 27TH ST  
GREENFIELD, WI 53221  
(414)282-8580 Fax: (414)282-8533

**PRELIMINARY ESTIMATE**

Written By: Mariusz Staniszc  
Adjuster:

**Insured:** ANGELA SEDA  
**Owner:** ANGELA SEDA  
**Address:** 5340 N LOVERS LN. RD.APT 166  
MILWAUKEE, WI 53225  
**Cellular:** (414)881-3346

**Claim #**  
**Policy #**  
**Deductible:**  
**Date of Loss:**  
**Type of Loss:**  
**Point of Impact:** 11. Left Front

**Inspect**  
**Location:**

**Insurance**  
**Company:**

Days to Repair

1997 FORD TAURUS GL 6-3.0L-FI 4D WGN Int:

**VIN:** 1FALP57U1VG291563 **Lic:** WI **Prod Date:** **Odometer:**

Air Conditioning	Rear Defogger	Tilt Wheel
Intermittent Wipers	Tinted Glass	Dual Mirrors
Luggage/Roof Rack	Clear Coat Paint	Power Steering
Power Brakes	Power Windows	Power Antenna
Power Mirrors	AM Radio	FM Radio
Stereo	Search/Seek	Driver Air Bag
Passenger Air Bag	4 Wheel Disc Brakes	Cloth Seats
Bucket Seats	Recline/Lounge Seats	Automatic Transmission
Overdrive		

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
1		FRONT BUMPER				
2		O/H front bumper			3.2	
3	O Repl	Bumper cover	1	342.97	Incl.	3.0
4		Add for Clear Coat				1.2
5	Repl	LT Bumper cover reinforcement outer	1	24.17	Incl.	
6		FRONT LAMPS				
7	Repl	LT Headlamp assy to 6/10/98	1	170.50	Incl.	
8		Aim headlamps			0.5	
9	Repl	LT Side marker lamp	1	10.17	Incl.	
10	R&I	RT Park lamp assy			Incl.	
11	R&I	LT Park lamp assy			Incl.	
12		COOLING				
13	Repl	Radiator support upper support	1	210.53	2.0	1.2
14		HOOD				

**PRELIMINARY ESTIMATE**

1997 FORD TAURUS GL 6-3.0L-FI 4D WGN Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
15*	Rpr	Hood			2.0	2.8
16		Add for Clear Coat				1.1
17		FENDER				
18	Repl	LT Fender	1	192.38	4.0	2.2
19		Overlap Major Adj. Panel				-0.4
20		Add for Clear Coat				0.4
21		Add for Edging				0.5
22		Add for Clear Coat				0.1
23		Deduct for Overlap			-0.7	
24	Repl	LT Fender liner front half 3.0 liter SOHC	1	52.98	Incl.	
25#	Subl	2 WHEEL ALIGNMENT	1	59.99		
26#		HAZARDOUS WASTE DISPOSAL	1	3.00		
27#	Repl	CORROSION PROTECTION	1	18.00	0.3	
28#	Repl	FLEX ADDITIVE	1	10.00		
29#		TRAM MEASUREMENT			0.5	
30#	Rpr	FRAME RACK SET UP			2.0 F	
31	Blnd	RT Fender				1.1
32		FRONT DOOR				
33	Blnd	LT Door shell				1.0
34*	R&I	LT Body side mldg paint to match			0.3	
35	R&I	LT Belt w'strip wagon			0.3	
36	R&I	LT Mirror heated			0.5	
37	R&I	LT Handle, outside w/o keyless entry			0.4	
38		PILLARS, ROCKER & FLOOR				
39	R&I	LT Rocker molding front w/o SHO paint/match			Incl.	
40	R&I	RT Rocker molding front w/o SHO pacific green			0.5	
41	R&I	RT Rocker molding rear, all paint/match			0.5	
42	R&I	LT Rocker molding rear, all paint/match			Incl.	

Subtotals ==> 1094.69 16.3 14.2

Parts		1094.69
Body Labor	14.3 hrs @ \$ 50.00/hr	715.00
Paint Labor	14.2 hrs @ \$ 50.00/hr	710.00
Frame Labor	2.0 hrs @ \$ 56.00/hr	112.00
Paint Supplies	14.2 hrs @ \$ 30.00/hr	426.00

SUBTOTAL \$ 3057.69  
Sales Tax \$ 3057.69 @ 5.6000% 171.23

**PRELIMINARY ESTIMATE**

1997 FORD TAURUS GL 6-3.0L-FI 4D WGN Int:

-----	
GRAND TOTAL	\$ 3228.92
ADJUSTMENTS:	
Deductible	0.00
-----	
CUSTOMER PAY	\$ 0.00
INSURANCE PAY	\$ 3228.92

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DE2JN96 Database Date 03/2007, CCC Data Date 03/2007, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2006 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

CCC Pathways - A product of CCC Information Services Inc.