



East and North Elevations



North Elevation



Northwest Elevation




Southwest Elevation



Southeast Elevation



East Elevation




Roof plan with gutters and downspouts. New copper half-round gutters and corrugated copper downspouts will be installed. They will be similar to existing.



The new slate roof will match the original 1880 roof which is still on the tower. Buckingham Virginia slate will be used.





Here is a sample board for the Buckingham slate roof and copper gutter. Other examples of Milwaukee Buckingham slate roofs are: Immanuel Presbyterian, 1100 N. Astor St. Gesu Church, 1145 W. Wisconsin Ave. St. James Episcopal, 833 W. Wisconsin Ave.



The current slate was installed about 10 years ago and the roof has failed. It is a mix of grey and green slate and not appropriate for this building.



The finial on the tower is rusting away.



The tower finial will be replaced with a custom matching finial made of copper and brass.



Areas to receive masonry repairs are outlined in black and include all three chimneys.

Holton Brothers is the masonry subcontractor.







4

↳ Severely Eroded Mortar