

## Askin, Tim

---

**From:** Marcia Mikich <mamikich@gmail.com>  
**Sent:** Monday, April 10, 2023 3:00 PM  
**To:** Historic Preservation Commission  
**Subject:** slight change in door from submitted plans  
**Attachments:** Re-issued COA 06-29-2022 to extend completion date.docx (3).pdf; SIMPSON 37682 DUTCH DOOR SPECS.pdf

You don't often get email from mamikich@gmail.com. [Learn why this is important](#)

Hello - attached is my COA for the porch addition to my property at 1810 N. Palmer St.

When the plans were submitted and approved - it listed Simpson exterior door 37214 - Bunglalow Door - Dutch 36 x84. On the plans it showed a door with an arched window frame and 6 lites. However Simpson door 37214 - which has the arched frame, does not come in 6 lites - only 9 lites. The 9 lites do not look appropriate for the rest of the house. The windows are 6 lites.

We would like to substitute the attached door - which is the same thing that was drawn on the plans - except there is no arched frame. It is wood and will be stained per the guidelines you gave. All of these doors have a 12-16 week lead time so it will not be installed until later this summer.

My question is - Can we substitute the straight window frame instead of the arch? Please advise. thanks

Marcia Mikich  
1810 N. Palmer St.  
Milwaukee, WI 53212

920-279-0280