CITY OF MILMAUKEE

Care Sie Care

2008 AUG 28 AM 8: 22

RONALD D. LEONHARDT CITY CLERK

City Of Milwaukee 200 East Wells Street Room 205 Milwaukee, WI 53202

Re: Mike Heinen

C.I File No: 08-S-569

Dear Mr. Langley:

We have received your denial letter for the above stated claim. We at this time would like to appeal this decision due to the fact that we feel the city is liable for damages to our vehicle obtained on June 12, 2008 by man hole cover that is owned by the city of Milwaukee on the west bound side between 4<sup>th</sup>-6<sup>th</sup> St and Morgan/Holt Ave.

At this time we will request from the Milwaukee County Sheriffs department the dispatched officer and unit assigned to the incident reported at approximately 10pm on June 12<sup>th</sup>, 2008. We will also ask for any other reported incidents at that time from others that we observed getting damaged at that time.

Until then we ask that this case be left open until we have resolved this matter to our satisfaction.

Very truly yours,

Mike Heinen

Cc: Milwaukee County Sheriff's Department

CITY FICE OF

2008 AUG 29

CITY OF MILWAUKEE RECEIVED

2008 JUL -7 PM 3: 27

OFFICE OF CITY ATTORNEY

July 1, 2008

To Whom It May Concern:

I'm writing to you in regards to an incident that happened on Thursday June 12, 2008. I was driving west bound on Morgan/Holt Ave about 6<sup>th</sup> Street, under the freeway bridge at 10pm when a man hole cover blew up under my car as I drove by. The sheriff's department came and told us to contact the City of Milwaukee and you would take of this. The man hole cover damaged the bottom of my car and my tire. I have enclosed an estimate for the cost of \$2,746.44 for the damages.

I'm hoping to get this fixed in a timely manner – if you can please contact me ASAP at 414-559-1390 or my wife Linda at 414-649-3558 to make arrangements for this.

I appreciate your prompt attention on this.

Sincerely,

Mike Heinen 2827 S 57<sup>th</sup> Street Milwaukee, WI 53219 414-559-1390 RONALD D. LEONHARDT

2008 JUL -7 AM II: 4

## AUTO BODY SPECIALISTS LLC 6024 WEST MITCHELL STREET

WEST ALLIS, WI 53214

PHONE: (414)545-9211 FAX: (414)545-7416

TAX ID: 391922584

CD LOG NO 84-1 DATE 06/26/08

06/26/08

SHOP: AUTO BODY SPECIALISTS LLC INSP DATE: ADDRESS: 6024 W MITCHELL STREET CONTACT: DAVID JAMBREK PHONE 1: CITY STATE: WEST ALLIS, WI (414)545-9211 ZIP: 53214-FAX: (414)545-7416

EMAIL: AUTOBODYSPECIALISTS@HOTMAIL.COM

OWNER: HEINEN, MICHAEL CELL PHONE: (414)559-1390

ADDRESS: 2827 S 57TH ST CITY STATE: MILWAUKEE, WI

ZIP: 53219

POINT OF IMPACT: 0

LIC#: VIN: STATE: 2G1WM15K269243380

BODY COLOR: BLUE MILEAGE:

ACCTNG CTL#: CONDITION:

NG=REPLACE NAGS

\*=USER-ENTERED VALUE E=REPLACE OEM
EC=REPLACE ECONOMY UE=REPLACE OE SURPLUS
UM=REMAN/REBUILT PRT EU=REPLACE SALVAGE UC=RECONDITIONED PRT

EP=REPLACE PXN

OE=REPLACE PXN OE SRPLS PC=PXN RECONDITIONED PM=PXN REMAN/REBUILT ET=PARTL REPL LABOR TE=PARTL REPL PRICE IT=PARTIAL REPAIR

I=REPAIR L=REFINISH BR=BLEND REFINISH TT=TWO-TONE CG=CHIPGUARD SB=SUBLET

RI=R&I ASSEMBLY P=CHECK N=ADDITIONAL LABOR

AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

2006 CHEVROLET MONTE CARLO LT 3.5 2DOOR COUPE 6 CYL 3.5 LITER FLEX

CODE: U2463B/A OPTNS F/24C

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES REMOTE KEYLESS IGNITION

(	ΟP	GDE	MC	DESCRIPTION		MFG.PART NO.	PRICE	AJ% B%	HOURS R
-									
1	N	0000		UNIBODY-FRAME INC SET	ľU	ADDNL LABOR OPERA			1.0*1
•	$^{ m rE}$	0327	07	PANEL ASSY, BODY SID F	3.1	PART/PARTIAL REPL	841.78		1
1	ΒR	0183	13	PANEL, BODYSIDE OTR F	RТ	BLEND REFINISH			1.4 4
	I	0188	07	PANEL, ROCKER R	RΤ	REPAIR			4.0*1
]	L	0188		PANEL, ROCKER R	۲S	REFINISH			1.3 4
Ι	ΞΤ	0628	07	PANEL, ROCKER R	T	LABOR/PARTL REPLA			6.6 1
]	L	0628		PANEL, ROCKER R	۲S	REFINISH			0.2 4
	Ι	0192	07	PANEL, ROCKER INNER R	۲T	REPAIR			3.0*1
]	L	0192		PANEL, ROCKER INNER R	₹T	REFINISH			0.6 4
Ε	$\Xi$	0162		MLDG, ROCKER PANEL R	۲r	15869285 GM PART	115.00		INC 1

2006 CHEVROLET	MONTE	CARLO	LT	3.5	2DOOR	COUPE	
CD LOG NO 84-1							

E	1007	CLIP, ROCKER PANEL M RT	MULTI-PART GM PAR	65.34	1
L	0366	PILLAR, BODY LOCK RT	REFINISH		1.2 4
RΙ	0396	QTR GLASS R & I RT	R&I ASSEMBLY		INC 1
EC	0380	01 SEALANT KIT, QTR GLA RT	ECONOMY PART	25.00*	1.9 1
RΙ	0534	TAILLAMP ASSEMBLY RT	R&I ASSEMBLY		0.3 1
N	0566	REAR BUMPER COVER R&I	ADDNL LABOR OPERA		0.5*1
		LOOSEN FOR REFINISHING			
L	M14	CORROSION PROTECTION	REFINISH		0.3*4
L	M15	COLOR TINT	REFINISH		0.5*4
EC	M17	COVER CAR EXTERIOR	ECONOMY PART	8.00*	1*
N		ROUGH PULLS	ADDNL LABOR OPERA		2.0*1*
EC		LR TIRE	ECONOMY PART	100.68*	0.3*1*
N		MASK JAMBS	ADDNL LABOR OPERA	·	0.5*1*

## 22 ITEMS

MC MESSAGE(S)

- 01 CALL DEALER FOR EXACT PART NUMBER / PRICE
- 07 STRUCTURAL PART AS IDENTIFIED BY I-CAR
- 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS OTHER PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL				5.600%	1,022.12 133.68 165.00 1,320.80 73.96
LABOR 1-SHEET METAL	RATE 50.00	REPLACE H	HRS 9.1	REPAIR HRS	1,005.00
2-MECH/ELEC 3-FRAME	65.00 50.00	٥		11.0	1,000.00
4-REFINISH 5-PAINT MATERIAL	50.00	5	5.5		275.00
LABOR TOTAL	30.00				1,280.00
TAX ON LABOR		@		5.600%	71.68
SUBLET REPAIRS TOWING					
STORAGE					
GROSS TOTAL					2,746.44
NET TOTAL					2,746.44

SHOPLINK U1707 ES CD LOG 84-1 DATE 06/26/08 03:38:52PM R6.37 CD 06/08 PXN: Y/00/00/00/00 CUM 00/00/00/00 GEOCODE 53214 HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.4 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

\_\_\_\_\_\_