

Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

LIVING WITH HISTORY

Property 2933 W. MC KINLEY BL. COLD SPRING PARK

Description of work Repairs per attached scope of work. Carefully read all conditions on these two cover pages.

Date issued 4/21/2021 PTS ID 115120 COA: REPAIRS

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. *The following conditions apply to this certificate of appropriateness:*

MASONRY

New mortar must match the original mortar in terms of color, texture, grain size, joint width, and joint finish/profile. The compressive strength of the repointing mortar shall be equal or less than the compressive strength of the original mortar and surrounding brick or stone. The replacement mortar shall contain approximately the same ingredient proportions of the original mortar. Mortar that is too hard is subject to premature failure and could damage the masonry. See the city's books *As Good As New* or *Good for Business*, Masonry Chapters, for more information. In most cases, this means a lime mortar with natural hydraulic cement rather than Portland cement. No joint of a width less than 3/8" may be cleaned of damaged/decomposed mortar with power disc grinders. No over-cutting of the joints is permitted. Remove decomposed mortar back into the wall 2.5 times the height of the joint before repointing. When installing new flashing at a masonry feature, the flashing must be stepped or cut into the mortar joints. The bricks may not be cut to install flashing at an angle.

New brick must match as closely as possible the color texture, size, and finish of the original brick.

A sample panel of brick and mortar must be reviewed and approved by HPC staff prior to general installation of the material.

UNDER NO CIRCUMSTANCES SHALL UNPAINTED MASONRY BE PAINTED, BE GIVEN A WATERPROOFING TREATMENT, OR CLEANED BY ABRASIVE MEANS; THIS STATEMENT SUPERSEDES ANY OTHER WORDING IN THIS DOCUMENT INDICATING THE CONTRARY.

WOOD

All finish wood must be smooth and free of knots and must be painted or treated with an opaque stain upon completion. Note: when new, bare wood is left exposed to the exterior elements for a period of only a week or two, the life the of the paint job subsequently applied to it

will be decreased. The use of a naturally decay-resistant wood species for exterior finish applications is required for porch areas. Using western white pine or Ponderosa pine is "at your own risk" because this wood has no natural decay resistance and can deteriorate in some exterior settings in just a few years.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Dean Doerrfeld of the Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: Dean.Doerrfeld@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.milwaukee.gov/build, or call (414) 286-8210.

The arms

City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Robert Bauman, Contractor, Inspector Peter Rafalski



Federal Tax ID #39-1415612

Client: SWITZER, CHERYL Cellular: (414) 559-9878

Property: 2933 W McKinley Blvd

Milwaukee, WI 53208

Operator: DDOLDENB

Estimator: Dan Oldenburg Cellular: (414) 430-3024

Position: Estimator E-mail: ddoldenburg@kelmann.com

Company: Kelmann Restoration
Business: 12001 W. Dearbourn Ave.
Wauwatosa, WI 53226

Colllision

Type of Estimate:

Date Entered: 1/25/2021 Date Assigned:

Price List: WIMW8X_JAN21

Labor Efficiency: Restoration/Service/Remodel

Estimate: 21-0067-RCN-ADJ

Following is our summary of restoration services to be rendered at the subject property.

Effective April 22 nd, 2010, the EPA mandates that any child occupied building built before 1978 be tested for lead-based paint prior to the disturbance of building materials. Lead-Safe Certified Restorers must use lead-safe practices until it can be determined that no lead exists in painted/finished surfaces. More information about the new lead rule is available at www.epa.gov/lead < http://www.epa.gov/lead >.

The State of Wisconsin is administering its own lead law with more stringent requirements. Under Wisconsin's lead rule, there is no op- out clause for the homeowner. More information about the new lead rule is available at www.dhs.wi.gov/lead/WIInfo.htm http://www.dhs.wi.gov/lead/WIInfo.htm >.



Federal Tax ID #39-1415612

21-0067-RCN-ADJ

Main Level

Living Room		Height: 9' 3"
13: 7: 14 10 10 10 10 10 10 10 10 10 10 10 10 10	281.74 SF Walls	161.17 SF Ceiling
T = 1	442.91 SF Walls & Ceiling	161.17 SF Floor
ny Window Living Room	17.91 SY Flooring	34.31 LF Floor Perimeter
11 50 10" 50 10" 50 100 100 100 100 100 100 100 100 100	49.22 LF Ceil. Perimeter	
` <u> </u> -		
Missing Wall - Goes to Floor	9' 10" X 6' 8"	Opens into DINING_ROOM
Missing Wall - Goes to Floor	5' 1" X 6' 8"	Opens into FOYER
Window	2' 4" X 5' 5"	Opens into PORCH
Window	4' 3" X 5' 5"	Opens into PORCH
Window	2' 4" X 5' 5"	Opens into PORCH
Missing Wall - Goes to neither Floor/Ceiling	5' 2'' X 5'	Opens into BAY_WINDOW
DESCRIPTION		OTV

DESCRIPTION	QTY
PREP WORK	
1. Contents - move out then reset	1.00 EA
2. Mask and prep for paint - plastic, paper, tape (per LF)	49.22 LF
3. Dust control barrier per square foot	48.00 SF
Opening to foyer	
4. Floor protection - plastic and tape - 10 mil	161.17 SF
FRAMING	
5. R&R Stud wall - 2x4 (per BF)	219.00 BF
Reframe new exterior wall of living room	
CEILING	
6. 5/8" drywall - hung, taped, ready for texture	161.17 SF
7. Texture drywall - light hand texture	161.17 SF
8. Seal/prime then paint the ceiling twice (3 coats) - 2 colors	
WALLS	
9. Batt insulation - 4" - R13 - unfaced batt	138.51 SF
10. Polyethylene vapor barrier, seam taping & joint caulking	138.51 SF
11. 1/2" drywall - hung, taped, ready for texture	281.74 SF
12. Texture drywall - light hand texture	281.74 SF
13. Seal/prime then paint the walls twice (3 coats) - 2 colors	281.74 SF
1-0067-RCN-ADJ	3/18/2021 Pag



Federal Tax ID #39-1415612

CONTINUED - Living Room

DESCRIPTION	QTY
WINDOW	
14. R&R Vinyl window - double hung, 9-12 sf - High grade	1.00 EA
15. Additional charge for a retrofit window, 3-11 sf	1.00 EA
16. Window drapery - hardware - Detach & reset	3.00 EA
17. Window trim set (casing & stop)	39.50 LF
18. R&R Window stool & apron	7.00 LF
19. Seal & paint window stool and apron	7.00 LF
20. Seal & paint window opening - Large (per side)	3.00 EA
21. Urethane foam sealant	15.50 LF
22. Seal & paint window trim & jamb - Large (per side)	3.00 EA
23. Seal & paint wood window (per side) - Large	3.00 EA
RADIATOR	
24. Clean radiator cover	1.00 EA
25. Prime & paint radiator unit	1.00 EA
26. Radiator cover - Large - Detach & reset	4.00 LF
BASE	
27. R&R Baseboard - 3 1/4" stain grade	34.31 LF
28. R&R Base shoe - stain grade	34.31 LF
29. Stain & finish base shoe or quarter round	34.31 LF
30. Stain & finish baseboard	34.31 LF
FLOOR	
31. Floor protection - cardboard and tape	161.17 SF
During demo, protect hardwood flooring	
32. Sand, stain, and finish wood floor	161.17 SF
33. Add for dustless floor sanding	161.17 SF
ELECTRICAL	
34. Rewire - average residence - copper wiring	161.17 SF
35. R&R Switch - 3 way	1.00 EA
36. R&R Ground fault interrupter (GFI) outlet - tamper resistant	1.00 EA
POST-CONSTRUCTION CLEANING	
37. Final cleaning - construction - Residential	161.17 SF



Federal Tax ID #39-1415612

Bay WIndow

CONTINUED - Living Room

DESCRIPTION QTY

Height: 8'

NOTES:

.6	60.21 SF Walls	7.75 SF Ceiling
Bay Window	67.96 SF Walls & Ceiling	7.75 SF Floor
	0.86 SY Flooring	12.96 LF Floor Perimeter
0001	12.96 LF Ceil. Perimeter	
Missing Wall - Goes to neither Floor/Ceiling	5' 2" X 5'	Opens into LIVING_ROOM
Window	1' 1" X 5' 5"	Opens into Exterior
Window	1' 1" X 5' 5"	Opens into Exterior
Window	1' 1" X 5' 5"	Opens into Exterior
DESCRIPTION		QTY
PREP WORK		
38. Mask and prep for paint - plastic, paper, tape (per LF)		
CEILING		
39. 5/8" drywall - hung, taped, ready for texture		
40. Texture drywall - light hand texture		
41. Seal/prime then paint the ceiling twice (3 coats)		
WALLS		
42. Material Only Stud wall - 2" x 4" x 8' load bearing - 16" oc		
Materials to frame out bay window		
43. Carpenter - General Framer - per hour		
Labor to frame out bay window and retro fit ne	w framing into existing framing	
44. 1/2" drywall - hung, taped, floated, ready for paint		



Federal Tax ID #39-1415612

CONTINUED - Bay WIndow

DESCRIPTION	QTY
45. Texture drywall - light hand texture	30.10 SF
46. Seal/prime then paint part of the walls (2 coats)	30.10 SF
WINDOW	
47. Additional charge for bay and bow windows	10.83 LF
48. Add on for leaded stained glass in windows	17.61 SF
49. Install Wood window - picture (fixed), 3-11 sf	3.00 EA
See quote/budget for material price	
50. Storm window - wood, 12 - 24 sf	3.00 EA
51. Window trim set (casing & stop)	13.00 LF
52. Seal & paint wood window (per side)	3.00 EA
53. Paint window trim & jamb - 2 coats (per side)	3.00 EA
54. Window seat - paint grade	5.42 LF
55. Seal & paint window stool and apron	5.42 LF
POST-CONSTRUCTION CLEANING	
56. Final cleaning - construction - Residential	7.75 SF

NOTES:



Federal Tax ID #39-1415612

50of1 9'10" 10	Dining Room	Height: 9' 3"
	333.64 SF Walls	166.57 SF Ceiling
E Of Signal of the control of the c	500.22 SF Walls & Ceiling	166.57 SF Floor
	18.51 SY Flooring	37.70 LF Floor Perimeter
6, 11" — 6' 11" — 2' - 10 10 10 10 10 10 10 10 10 10 10 10 10	50.37 LF Ceil. Perimeter	
2'6" 6'7" 10		
Missing Wall - Goes to Floor	9' 10" X 6' 8"	Opens into LIVING_ROOM
Missing Wall - Goes to Floor	2' 10" X 6' 8"	Opens into ROOM4
Window	2' 4" X 5' 5"	Opens into Exterior
Window	4' 2" X 5' 5"	Opens into Exterior
Window	2' 4" X 5' 5"	Opens into Exterior

DESCRIPTION	QTY
PREP WORK	
57. Contents - move out then reset	1.00 EA
58. Mask and prep for paint - plastic, paper, tape (per LF)	50.37 LF
59. Mask and cover light fixture	1.00 EA
60. Dust control barrier per square foot	32.00 SF
61. Peel & seal zipper	1.00 EA
CEILING	
62. 5/8" drywall - hung, taped, ready for texture	166.57 SF
63. Texture drywall - light hand texture	166.57 SF
64. Seal/prime then paint the ceiling twice (3 coats)	166.57 SF
WALLS	
65. Batt insulation - 4" - R13 - unfaced batt	84.07 SF
66. Polyethylene vapor barrier, seam taping & joint caulking	84.07 SF
67. 1/2" drywall - hung, taped, ready for texture	333.64 SF
68. Texture drywall - light hand texture	333.64 SF
69. Seal/prime then paint the walls twice (3 coats)	333.64 SF
WINDOWS	
70. Window drapery - hardware - Detach & reset	3.00 EA
71. R&R Casing - 2 1/4"	39.50 LF
72. R&R Window stool & apron	7.00 LF
73. Seal & paint window stool and apron	7.00 LF
74. Seal & paint window trim & jamb - Large (per side)	3.00 EA
75. Seal & paint wood window (per side) - Large	3.00 EA



Federal Tax ID #39-1415612

CONTINUED - Dining Room

DESCRIPTION	QTY
RADIATOR	
76. Clean radiator cover	1.00 EA
77. Prime & paint radiator unit	1.00 EA
78. Radiator cover - Large - Detach & reset	4.00 LF
BASE	
79. R&R Baseboard - 3 1/4" stain grade	37.70 LF
80. R&R Base shoe - stain grade	37.70 LF
81. Stain & finish base shoe or quarter round	37.70 LF
82. Stain & finish baseboard	37.70 LF
FLOOR	
83. Floor protection - cardboard and tape	166.57 SF
During demo, protect hardwood flooring	
84. Sand, stain, and finish wood floor	166.57 SF
85. Add for dustless floor sanding	166.57 SF
ELECTRICAL	
86. Detach & Reset Chandelier	1.00 EA
87. Clean chandelier - above average detail	1.00 EA
88. Rewire - average residence - copper wiring	166.57 SF
89. R&R Dimmer switch	1.00 EA
90. R&R Switch - 3 way	1.00 EA
91. R&R Ground fault interrupter (GFI) outlet - tamper resistant	1.00 EA
POST-CONSTRUCTION CLEANING	
92. Final cleaning - construction - Residential	166.57 SF



Missing Wall - Goes to Floor

12001 West Dearbourn Ave. Wauwatosa, WI 53226 (P) 414-774-3799 www.kelmann.com

Federal Tax ID #39-1415612

Entry 4' 2"	Foyer	Height: 9' 3"
[2] [3] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	292.78 SF Walls	96.28 SF Ceiling
Foyer 2' 9" + 3' 21-	389.06 SF Walls & Ceiling	96.28 SF Floor
	10.70 SY Flooring	29.61 LF Floor Perimeter
	47.44 LF Ceil. Perimeter	
Missing Wall - Goes to Floor	5' 1" X 6' 8"	Opens into LIVING_ROOM
Door	3' X 6' 8"	Opens into ENTRY
Missing Wall	2' 9" X 9' 3"	Opens into STAIRS
Missing Wall	3' 4" X 9' 3"	Opens into STAIRS
Missing Wall	2' 7" X 9' 3"	Opens into STAIRS

Opens into HALLWAY

3' 10" X 6' 8"

DESCRIPTION	QTY
PREP WORK	
93. Contents - move out then reset - Small room	1.00 EA
94. Mask and prep for paint - plastic, paper, tape (per LF)	47.44 LF
95. Floor protection - plastic and tape - 10 mil	96.28 SF
CEILING	
96. Plaster patch / small repair - ready for paint	1.00 EA
97. Thin coat plaster (no lath)	96.28 SF
98. Texture drywall - light hand texture	96.28 SF
99. Seal/prime then paint the ceiling twice (3 coats)	96.28 SF
WALLS	
100. Plaster patch / small repair - ready for paint	1.00 EA
101. Thin coat plaster (no lath)	71.50 SF
Affected shared wall with living room only	
102. Texture drywall - light hand texture	71.50 SF
103. Seal/prime then paint the walls twice (3 coats)	292.78 SF
POST-CONSTRUCTION CLEANING	
104. Final cleaning - construction - Residential	96.28 SF

NOTES:



Federal Tax ID #39-1415612

1'1→3' 10" → ' 1"	Hallway	Height: 9' 3"
in Hallway 1 4 5 5 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	147.67 SF Walls	37.06 SF Ceiling
	184.73 SF Walls & Ceiling	37.06 SF Floor
	4.12 SY Flooring	13.36 LF Floor Perimeter
	22.69 LF Ceil. Perimeter	
Missing Wall - Goes to Floor	2' 10" X 6' 8"	Opens into ROOM4
Missing Wall	3' X 9' 3"	Opens into STAIRS4
Door	2' 8" X 6' 8"	Opens into Exterior
Missing Wall - Goes to Floor	3' 10" X 6' 8"	Opens into FOYER

DESCRIPTION	QTY
PREP WORK	
105. Contents - move out then reset - Small room	1.00 EA
106. Mask and prep for paint - plastic, paper, tape (per LF)	22.69 LF
107. Floor protection - plastic and tape - 10 mil	37.06 SF
CEILING	
108. Plaster patch / small repair - ready for paint	1.00 EA
109. Thin coat plaster (no lath)	37.06 SF
110. Texture drywall - light hand texture	37.06 SF
111. Seal/prime then paint the ceiling twice (3 coats) - 2 colors	37.06 SF
WALLS	
112. Plaster patch / small repair - ready for paint	1.00 EA
113. Thin coat plaster (no lath)	147.67 SF
114. Texture drywall - light hand texture	147.67 SF
115. Seal/prime then paint the walls twice (3 coats) - 2 colors	147.67 SF
POST-CONSTRUCTION CLEANING	
116. Final cleaning - construction - Residential	37.06 SF

NOTES:



Federal Tax ID #39-1415612

Shower Room 2" -5' 10" -
1 3 6 4 × 1 3 × 6 × 7 × 7 × 7 × 7 × 7 × 7 × 7 × 7 × 7
Kitchen 5
m 1'7" ↓
2'8" 3'10" •

Kitchen Height: 9' 3"

 412.86 SF Walls
 168.87 SF Ceiling

 581.73 SF Walls & Ceiling
 168.87 SF Floor

18.76 SY Flooring 45.60 LF Floor Perimeter 55.52 LF Ceil. Perimeter

Missing Wall - Goes to Floor

3' X 6' 8"


Opens into REAR_ENTRY

Missing Wall - Goes to neither Floor/Ceiling
6' 11" X 5'

Opens into FAMILY_ROOM

Missing Wall - Goes to Floor
2' 10" X 6' 8"

Opens into FAMILY_ROOM



Subroom: Room4 (1) Height: 9' 3"

70.12 SF Walls
16.09 SF Ceiling
86.21 SF Walls & Ceiling
1.79 SY Flooring
4.30 LF Floor Perimeter

16.05 LF Ceil. Perimeter

Missing Wall - Goes to Floor

4' 1" X 6' 8"

Opens into KITCHEN

Opens into SHOWER_ROOM

Missing Wall - Goes to Floor

2' 10" X 6' 8"

Opens into HALLWAY

Missing Wall - Goes to Floor

2' 10" X 6' 8"

Opens into DINING_ROOM

DESCRIPTION OTY

DESCRIPTION	VII
PREP WORK	
117. Contents - move out then reset	1.00 EA
118. Mask and prep for paint - plastic, paper, tape (per LF)	71.57 LF
119. Recessed light fixture - Detach & reset trim only	3.00 EA
120. Floor protection - plastic and tape - 10 mil	184.96 SF
CEILING	
121. Seal/prime then paint the ceiling (2 coats)	184.96 SF
WALLS	
122. Drywall patch / small repair, ready for paint	1.00 EA
@ Soffit	
123. Texture drywall - light hand texture	95.63 SF
124. Seal/prime then paint the walls (2 coats)	482.99 SF
POST-CONSTRUCTION CLEANING	
125. Final cleaning - construction - Residential	184.96 SF



Federal Tax ID #39-1415612

CONTINUED - Kitchen

DESCRIPTION QTY

NOTES:



Family Room


Height: 9' 3"

356.51 SF Walls
160.57 SF Ceiling
517.08 SF Walls & Ceiling
17.84 SY Flooring
160.57 SF Floor
39.02 LF Floor Perimeter

50.69 LF Ceil. Perimeter

Missing Wall - Goes to neither Floor/Ceiling 6' 11" X 5' Opens into KITCHEN

Missing Wall - Goes to Floor 2' 10" X 6' 8" Opens into KITCHEN



Subroom: Room9 (2)

121.65 SF Walls
135.83 SF Walls & Ceiling
14.18 SF Ceiling
14.18 SF Floor

1.58 SY Flooring17.48 LF Ceil. Perimeter

11.48 LF Floor Perimeter

Height: 9' 3"


Missing Wall - Goes to Floor

6' X 6' 8"

Opens into FAMILY_ROOM



Federal Tax ID #39-1415612



Subroom: Room13 (1)

17.79 SF Ceiling

146.30 SF Walls164.08 SF Walls & Ceiling

17.79 SF Floor

1.98 SY Flooring17.86 LF Ceil. Perimeter

15.02 LF Floor Perimeter

Height: 9' 3"


Missing Wall - Goes to Floor

2' 10" X 6' 8"

Opens into FAMILY_ROOM

DESCRIPTION	QTY
PREP WORK	
126. Contents - move out then reset	1.00 EA
127. Mask and prep for paint - plastic, paper, tape (per LF)	86.02 LF
128. Floor protection - plastic and tape - 10 mil	192.54 SF
CEILING	
129. Seal/prime then paint the ceiling (2 coats)	192.54 SF
WALLS	
130. Seal/prime then paint the walls (2 coats)	624.46 SF
POST-CONSTRUCTION CLEANING	
131. Final cleaning - construction - Residential	192.54 SF

NOTES:



Bay Roof1

10.85 Surface Area14.86 Total Perimeter Length4.96 Total Hip Length

0.11 Number of Squares

DESCRIPTION QTY

ROOFING




Federal Tax ID #39-1415612

CONTINUED - Bay Roof1

DESCRIPTION	QTY
122 Companion Conoral Framer, per hour	2.00 HR
132. Carpenter - General Framer - per hour Labor to repair damage to roof framing above bay window	2.00 ftK
133. Material Only Sheathing - plywood - 1/2" CDX	10.85 SF
134. Material Only Laminated - comp. shingle rfg w/ felt	1.00 SQ
Materials to replace shingles	
135. Material Only Step flashing	6.17 LF
136. Roofer - per hour	4.00 HR
Labor to perform roofing	
137. R&R Corbel - wood - over 4" wide w/ intricate detail	3.00 EA

NOTES:

2nd Level





Federal Tax ID #39-1415612

CONTINUED - Office

DESCRIPTION	QTY
138. Contents - move out then reset - Large room	1.00 EA
139. Mask and prep for paint - plastic, paper, tape (per LF)	47.67 LF
140. Dust control barrier per square foot	48.00 SF
141. Peel & seal zipper	1.00 EA
142. Floor protection - plastic and tape - 10 mil	141.83 SF
CEILING	
143. Plaster patch / small repair - ready for paint	1.00 EA
144. Thin coat plaster (no lath)	141.83 SF
145. Texture drywall - light hand texture	141.83 SF
146. Seal/prime then paint the ceiling twice (3 coats)	141.83 SF
WALLS	
147. Plaster patch / small repair - ready for paint	1.00 EA
148. Thin coat plaster (no lath)	12.33 SF
149. Texture drywall - light hand texture	12.33 SF
150. Seal/prime then paint the walls twice (3 coats)	328.56 SF
151. Seal & paint trim - two coats	38.83 LF
Plate rail	
WINDOWS	
152. Seal & paint window trim & jamb - Large (per side)	2.00 EA
153. Seal & paint wood window (per side) - Large	2.00 EA
DOOR	
154. Seal & paint door opening - Large (per side)	2.00 EA
155. Seal & paint door opening (per side)	2.00 EA
156. Seal & paint door slab only (per side)	2.00 EA
POST-CONSTRUCTION CLEANING	
157. Final cleaning - construction - Residential	141.83 SF

NOTES:



Federal Tax ID #39-1415612

-4' 4" -2' 10' -4' 4" -
Daughter's Bedroom
S S S S S S S S S S S S S S S S S S S
5'4" - 3'3"

171. Window drapery - hardware - Detach & reset

Daughter's Bedroom

Height: 9' 2"

3.00 EA

189.48 SF Ceiling

49.35 LF Floor Perimeter

189.48 SF Floor

	55.02 LF Ceil. Perimeter		55.02 LF Ceil. Perimeter		
Window	2' 4" X 5' 5"	Opens into Exterior			
Window	4' 2" X 5' 5"	Opens into Exterior			
Window	2' 4" X 5' 5"	Opens into Exterior			
Window	2' X 5' 6''	Opens into Exterior			
Door	2' 10" X 6' 8"	Opens into HALLWAY			
Door	2' 10" X 6' 8"	Opens into OFFICE			
DESCRIPTION			0		

407.69 SF Walls

21.05 SY Flooring

597.18 SF Walls & Ceiling

DESCRIPTION	QTY

PREP WORK	
158. Contents - move out then reset - Large room	1.00 EA
159. Mask and prep for paint - plastic, paper, tape (per LF)	55.02 LF
160. Mask and cover large light fixture	1.00 EA
161. Floor protection - plastic and tape - 10 mil	189.48 SF
CEILING	
162. Plaster patch / small repair - ready for paint	1.00 EA
163. Thin coat plaster (no lath)	189.48 SF
164. Texture drywall - light hand texture	189.48 SF
165. Seal/prime then paint the ceiling twice (3 coats)	189.48 SF
WALLS	
166. Plaster patch / small repair - ready for paint	1.00 EA
Wall area to the right of the windows	
167. Thin coat plaster (no lath)	40.85 SF
Wall area to the right of the windows	
168. Texture drywall - light hand texture	40.85 SF
Wall area to the right of the windows	
169. Seal/prime then paint the walls twice (3 coats)	407.69 SF
170. Seal & paint trim - two coats	49.35 LF
Plate rail	
WINDOWS	



Federal Tax ID #39-1415612

CONTINUED - Daughter's Bedroom

DESCRIPTION	QTY
172. Seal & paint window trim & jamb - Large (per side)	3.00 EA
173. Seal & paint wood window (per side) - Large	3.00 EA
DOOR	
174. Seal & paint door opening (per side)	4.00 EA
175. Seal & paint door slab only (per side)	4.00 EA
POST-CONSTRUCTION CLEANING	
176. Final cleaning - construction - Residential	189.48 SF

NOTES:

Exterior

DESCRIPTION	QTY
EXTERIOR/SIDING	_
177. R&R Siding - plywood - fir face	128.00 SF
Exterior sheathing	
178. R&R House wrap (air/moisture barrier)	128.00 SF
179. Seal & paint wood siding	48.69 SF
180. Finish Carpenter - per hour	6.00 HR
Labor to carefully detach historical wood trim and crown from bay window and return at a later date to reset	
181. Timber frame knee brace - Decorative	2.00 EA
182. Corbel - wood - over 4" wide w/ intricate detail	2.00 EA
183. Painter - per hour	2.00 HR
Labor and materials to paint wood trim and knee braces	
GUTTER/DOWNSPOUT	
184. R&R Gutter / downspout - aluminum - up to 5"	12.00 LF



Federal Tax ID #39-1415612

CONTINUED - Exterior

DESCRIPTION

185. Prime & paint gutter / downspout

NOTES:

General Conditions

DESCRIPTION QTY

INDOOR ENVIRONMENTAL QUALITY CONTROLS

186. Neg. air fan/Air scrub.-Large (per 24 hr period)-No monit.

3.00 DA

1 Unit, rental capped at 3 days.

Reference: National Institute for Occupational Safety and Health (NIOSH). Maintaining indoor environmental quality (IEQ) during construction and renovation projects. By Burton N, Afanuh S. Cincinnati, OH: U.S. Department of Health and Human Services, Centers for Disease Control and Prevention, National Institute for Occupational Safety and Health, DHHS (NIOSH) Publication No. 2020110.

https://www.cdc.gov/niosh/docs/wp-solutions/2020-110/pdfs/2020-110.pdf?id=10.26616/NIOSHPUB2020110

187. Equipment setup, take down, and monitoring (hourly charge)

2.00 HR

HAZARDOUS MATERIALS TESTING

188. Lead swab test - self test (per sample)

2.00 EA

Note - property constructed pre-1978, impacted surfaces will be tested for lead prior to any activities on the impacted surfaces that would generate dust. In the event that test(s) are positive, supplement to this scope and estimate would be presented for additional containment, cleaning and PPE in compliance with EPA-mandated RRP rules.

189. Asbestos test fee - self test (per sample)

2.00 EA

Testing for possible ACBM. In the event that test(s) are positive, supplement to this scope and estimate would be presented for additional containment, cleaning, disposal, and PPE in compliance with EPA and OSHA mandated rules.

CLEANUP AND DEBRIS REMOVAL

190. Add for personal protective equipment (hazardous cleanup)

12.00 EA

As required to ensure worker's safety while performing operations in a restoration environment.

191. Dumpster load - Approx. 20 yards, 4 tons of debris

1.00 EA



Federal Tax ID #39-1415612

CONTINUED - General Conditions

DESCRIPTION QTY

192. Material Only Underlayment - 1/2" OSB

128.00 SF

Tracking pad for dumpster placement.

SUPERVISION / PROJECT MANAGEMENT

193. Residential Supervision / Project Management - per hour

40.00 HR

Note: This is for a Superintendent/Project Manager used to manage residential jobs where Supervision/Project Management is needed to coordinate the work of subcontractors, or perform other project management duties. This item is not intended to be used for a working crew leader. Full time Supervision/Project Management may be typical on larger residential projects where the number of subcontractors and trades justifies full time. A Superintendent/Project Manager may complete tasks such as, but not limited to, create/maintain project schedules, coordinate/meet trades, order materials, inspect job sites, obtain permits, meet with inspectors, etc.

Additional Project manager time to work with the City of Milwaukee Historical Preservation department.

PERMITS & FEES

194. Taxes, insurance, permits & fees (Bid Item)

1.00 EA

Supplement to be presented based on incurred costs.

TEMP WALL / INSULATION

195. R&R Stud wall - 2x4 (per BF)	122.00 BF
196. R&R Batt insulation - 4" - R11- unfaced batt	111.00 SF
197. R&R Rigid foam insulation board - 1"	111.00 SF
221. Install Final adjustment	1.00 EA

NOTES:

Sub Contractors

DESCRIPTION QTY

INITIAL DEBRIS REMOVAL/CLEANUP

198. Hazardous Material Remediation (Bid Item)

1.00 EA



Federal Tax ID #39-1415612

CONTINUED - Sub Contractors


DESCRIPTION	QTY
Bid from Asbestos Abatement LLC	
DEMO OF REMAINING WALLS/CEILING in LR/DR	
199. Hazardous Material Remediation (Bid Item)	1.00 EA
Bid from Asbestos Abatement LLC	
MASONRY	
200. Masonry (Bid Item)	1.00 EA
Bid from Holton Brothers	
STAINED GLASS/LEAD WINDOWS	
201. Windows - Wood (Bid Item)	1.00 EA
Budget from Tosa Glass for (3) lead lined/stained glass windows	
Labor Minimums Applied	
DESCRIPTION DESCRIPTION	QTY
202. Siding labor minimum	1.00 EA
203. Gutter labor minimum	1.00 EA
NOTES:	



Federal Tax ID #39-1415612

Grand Total Areas:


5,391.49	SF Walls	1,704.29	SF Ceiling	7,095.77	SF Walls and Ceiling
1,736.88	SF Floor	192.99	SY Flooring	597.73	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	757.00	LF Ceil. Perimeter
1,736.88	Floor Area	1,881.10	Total Area	4,872.56	Interior Wall Area
2,300.00	Exterior Wall Area	261.22	Exterior Perimeter of		
			Walls		
10.05		0.11	N. 1 60	0.00	m . 15 ' . T . d
10.85	Surface Area	0.11	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	4.96	Total Hip Length		





Main Level

21-0067-RCN-ADJ Page: 21





2nd Level

21-0067-RCN-ADJ Page: 22