CITY OF MILWAUKEE RECEIVED

2010 NOV 16 PM 12: 30

November 10, 2010

CITY ATTORNEY

Tyrone D Diggs 3935 N. 10<sup>th</sup> Street Milwaukee, WI 53206 (414)736-0962

Office of the City Clerk 200 E. Wells St., Room 205 Milwaukee, WI 53202-3567 Attn: Claims

To Whom It May Concern:

As you are aware, the city of Milwaukee experienced harsh weather during the winter seasons for 2008 and 2009. As a result, major streets throughout the city were in poor, unsafe condition. The poor, unsafe street condition caused major damage to the suspension and transmission systems of my vehicle.

I hereby request reimbursement totaling \$7,373.73 for personal funds and/or credit card charges spent on major vehicle repairs. I have enclosed repair receipts and estimates for your review. A complete breakdown of the above of the above request is as follows:

Amount paid for suspension conversion kit
Amount paid for power steering pump
\$1,544.67
\$186.23
Estimated amount for transmission/transaxle
\$5,645.83

Your prompt attention to this matter is greatly appreciated. Should you have any further questions, please contact me at the telephone number listed above.

Tyrone D. Diggs

Enclosure

Sincerely.

## WORK CRDER #

086267 11/03/10 01:23PM

## **TIRES PLUS** 9101 N DEERBROOK TRL BROWN DEER, WI. 53223-2476

SERVICE ADVISOR

19 WESTLEY 414.355.0500

DIGGS, TYRONE 3935 N 10TH ST

414.736.0962

MILWAUKEE, WI 53206-3320

2002 CADILLAC DEVILLE DTS [WHITE] V8-279 4.6L DOHC

LIC # 324-HFU WI 11/03/10 12:17PM IN

VIN# 1G6KF57942U295594 EST. MILEAGE 81,000

Store # 244251 Recommended Services not Authorized by Customer

Status	Description	Qty		Init Price Labor	Extended Pric Job Total Cat. Tota	_
Recmd	BEARING & SEALS (Front-Right) 513179 FRONT HUB ASSEMBLY REMOVE & REPLACE WHEEL BEARING- FRONT, ONE SIDE	1	229.46 0.00	0.00 99.00	328.46	
Recmd	AUTO TRANSMISSION/TRANSAXLE LEFT AXLE BEARING INSIDE TRANSMISSION IS VERY BAD. TRANS IS LEAKING FLUID ALL OVER UNDERSIDE OF VEHICLE. REPLACEMENT OF TRANS RECOMMENDED. CUSTOMER HAS BEEN SHOWN AND ADVISED.	. 0	0.00	0.00	4,796.38	
	3341352 USED WITH 81,000 MILES REMOVE & INSPECT TRANSAXLE ASSEMBLY * REMOVE & REPLACE TORQUE CONVERTER * REPLACE TRANSAXLE ASSEMBLY 7030260 REMAN TRANS WITH 3 YEAR WARRANTY	1 1 1 1	1,089.19 0.00 0.00 0.00 2,798.19	0.00 810.00 9.00 90.00 0.00		
Recmd	AUTO TRANSMISSION/TRANSAXLE 66-1327 R NEW CV COMPL ASSY REMOVE & INSPECT F AXLE SHAFT ASSEMBLY- ONE SIDE LBR-DISC IF DONE WITH WHEEL BEARING System Failure - Required	1 1 -1	144.58 0.00 0.00	0.00 117.00 65.00	196.58	
	-y-tom randro - required				> 5,321.42	<b>5</b> ,3 <b>21</b> .4 <b>2</b>

Recommended Parts: 4,261.42 Labor: 1,060.00 Subtotal: 5,321.42

Shop Supplies: 25.00

Tax (5.60%): 299.41 Total: 5,645.83

HESE PRICES ARE VALID FOR 30 DAYS

abor charges are based on 'Menu Items' of a predetermined amount or the flat rate

harged per the Mitchell Labor Manual @ \$90.00/hr.

LL PARTS ARE NEW UNLESS NOTED OTHERWISE

"MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P. O. BOX 8911, MADISON, WISCONSIN 53708-8911"

Brown Deer Sales Service Center

7440 W. Brown Deer Road

Milwaukee, WI 53223

phone: 414-357-6590 / fax: 414-357-6595

WORK ORDER #6991 07/13/10 ·

TYRONE DIGGS 3935 N 10TH STREET Milwaukee, WI 53223

2002 CADILLAC eng: V8 4.6L 281ci G

vin# 1G6KF57942U295594

**DEVILLE DTS** 

C# 414-736-0962

plate# DI(

BROWN DEER SALE SERU 7440 WEST BROWN DEER MILWAUKEE WI 53223

BATCH: 766 S-A-L-E-S D-R-A-F-T 72758357 295292408863

REF: CD TYPE: VISA TR TYPE: PURCHASE

JUL 16, 10 16:38:34

TOTAL

\$1544.67

ACCT: ÀF: 863634

EXP: \$\$/\$\$

HAME: WE DIEGS LLC TAX

\$13.00

CARDMEMBER ACKNOWLEDGES RECEIPT OF GOUDS AND/OR SERVICES IN THE ARDUMI OF THE TOTAL SHOWN HEREON AND AGREES TO PERFORM THE OBLIGATIONS SET FORTH BY THE CARDMEMBER'S AGREEMENT WITH THE ISSUER

THANKS FOR USING VISA

RUMBING NOISE RI CHECK AIR RIDE SI WANTING TO SWITCH AIR RIDE SYSTEM

CUSTOMER COPY

1449.75 Group Total

SUSPENSION

DIAGNOSTICS

1@ 1000.00 1000.00 FULL CONVERSION KIT

**10YR WARRANTY** 

444

5.00hrs@ 89.95/hr

449.75

Parts Sub-Total

1000.00

**SURCHARGES** 

Hazard Waste

13.00 Group Total

13.00

I, the Registered Owner, authorize you to perform the above repairs, furni any necessary sublet work. Your employees may operate vehicle for insp delivery at my risk. You will not be responsible for loss or damage to vehil in it. I agree to pay reasonable storage on vehicle left more than 48 hrs. a that repairs are completed. An express mechanic's lien is acknowledged secure that amount of repairs thereto.

SIGNED:

1000.00 PARTS LABOR 449.75 Surcharge (s) 13.00 81.92 TAX TOTAL WORK ORDER 1544.67

New

Brown Deer Sales Service Center

7440 W. Brown Deer Road

Milwaukee, WI 53223

phone: 414-357-6590 / fax: 414-357-6595

WORK ORDER #7048 07/17/10

TYRONE DIGGS 3935 N 10TH STREET Milwaukee, WI 53223

**CHASSIS & STEERING** 

SP164402

2002 eng: V8 4.6L 281ci G CADILLAC

vin# 1G6KF57942U295594

|111

**DEVILLE DTS** 

89.74 POWER STEERING PUMP

LIFETIME WARRANTY

plate# DIGG

1.20hrs@ 7

| INSTALL POWER STEE!

C# 414-736-0962

\$186.23

\$2.80

TOTAL EXP: \*\*/\*\* 2537

JUL 19, 10 16:37:43

BROWN DEER SR<u>IF SE</u>RU 7440 WEST BROWN DEER MILWAUKEE WI 53223

BATCH: 767 S-A-L-E-S D-R-A-F-T 7275B357 29529240B883

ACCT: 2 AP: 063743 HANE: WE DIGGS LLC TAX

REF: 0003 CD TYPE: VISA TR TYPE: PURCHASE DATE: JUL 19,

CARDMEMBER ACKNOWLEDGES RECEIPT OF GOODS AND/OR SERVICES IN THE ANOUNT OF THE IDIAL SHOWN HEREON AND AGREES TO PERFORM THE OBLIGATIONS SET FORTH BY THE CARDMEMBER'S AGREEMENT WITH THE ISSUER

THARKS FOR USING VISA

CUSTOMER COPY

Parts Sub-Total

89.74

**SURCHARGES** 

Hazard Waste

89.74

2.61

New

I, the Registered Owner, authorize you to perform the above repairs, furni any necessary sublet work. Your employees may operate vehicle for insp delivery at my risk. You will not be responsible for loss or damage to vehil in it. I agree to pay reasonable storage on vehicle left more than 48 hrs. a that repairs are completed. An express mechanic's lien is acknowledged secure that amount of repairs thereto.

SIGNED:

TOTAL WORK ORDER	186.23
TAX	9.88
Surcharge(s)	2.61
LABOR	84.00
PARTS	89.74