

Historic Preservation Commission Meeting

April 10, 2012



- Good Afternoon!
Please sign in at the door
- If you wish to speak on an issue or have your opinion noted by the commission, please fill out a form at the door and hand it to us

3136 W. Kilbourn

Albrecht and Rincker Hall
exterior rehab

Concordia Historic District



Albrecht Hall (Recitation Hall) undated image pre 1940.



Rincker Library, 1942





Rincker Library front entrance







FIGURE 25: View looking southeast. Connection to Rincker Library appears at right. Discoloration at the building base due to rising damp from excess water infiltration.



FIGURE 26: Severe deterioration of brick and mortar at northeast corner from rising damp caused by the moisture saturated and flooded basement/foundation conditions. Algae growth is also typical in this area.

