

Date: 8-2-08

From: Wallace Owens

To: Milwaukee City Clerk

200 East Wells Street

Room 205

Milwaukee, WI. (53202)

Attention: Grant F. Langley city Attorney

Regarding: C.I. File No. 08-V-151

I am requesting a hearing regarding my
claim relating to damaged sustained to my
1989 Mercedes-Benz on Feb. 7, 2008.

Please notify me by phone:

cell - 414-333-2463 or Work

The Water Department 3850 N. 35th St.

Sincerely,

Wallace Owens

CITY OF MILWAUKEE

2008 MAY -7 PM 1:29

RONALD D. LEONHARD
CITY CLERK

On 2-7-08 Around 7⁴⁵ AM I parked
my car IN the NORTH EAST parking

lot at the city of Milwaukee Towne
Yard, at around 11³⁰ AM when I re-
turned to my car, I Notice that some
damage had occurred to the front end,
This damage was not there when I
parked my car at 7⁴⁵ AM.

The damage was to the drivers side on
the left front upper hood, and light Area
of my car.

On that particular day there were City of
Milwaukee salter, plow trucks and back-
hoes Removing and Clearing snow from

Tower parking lot areas.

AT about 11⁴⁸ AM I informed the Water Control Center of the Accident in the parking lot. Between 12⁰⁰ PM - 1⁴⁵ PM a City Accident investigator arrived and took pictures of the damage to my car and informed my on how to file a claim with The City of Milwaukee.

I also WAS informed that there are cameras located around the building at tower yard for the purpose of taking pictures for security reason.

5148 W. ROSENTHAL DR #3
MILW, WI
53216

WALLACE OWENS
CITY OF MILWAUKEE CONTROL
Department Tapper Specialist
414-333-2403

ME: INVESTIGATOR - PETEL, WHO TOOK
PICTURES OF THE SAMARIT TO MY CAR.

I HAVE ALSO PLACED COPY'S OF MY
AUTO REPAIR ESTIMATES IN THIS
ENVELOPE.

LEONARD AUTO BODY
756 NORTH 109TH STREET
WAUWATOSA, WI 53226
PHONE: (414) 771-3898 FAX: (414) 771-5677

CD LOG NO 7134-1 DATE 02/08/08

SHOP: INSP DATE: 02/08/08
CONTACT: BOB
OWNER: OWENS, WALLACE HOME PHONE: (414) 333-2463
ADDRESS: 5148 W ROSEVELT DR WORK PHONE: (414) 286-3710
CITY STATE: MIL, WI
ZIP: 53216

POINT OF IMPACT: 4

LIC#: STATE: VIN: WBCA39EXKA443388
BODY COLOR: MILEAGE:
CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN 8CYL GASOLINE 5.6
CODE: 30822C/D OPTNS J/24B

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
PASSENGER SIDE AIRBAG

TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
E	0041		HEADLAMP ASSY, HALOG LT	1268201959	615.00			0.6	1
N	0973		HEADLAMPS AIM	ADDNL LABOR OPERA				0.5	1
I	0083		PANEL, HOOD	REPAIR				5.0*	1
L	0083	13	PANEL, HOOD	REFINISH				4.7	4
E	0087		LATCH, HOOD PANEL RT	1268801260	85.00			0.3	1
L	M17		COVER CAR EXTERIOR	REFINISH				0.3*	4*
SB	M60		HAZARD. WSTE. REM.	SUBLET REPAIR	5.00*				1

7 ITEMS

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN
CD LOG NO 7134-1

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				700.00
PAINT MATERIAL				150.00
PARTS & MATERIAL TOTAL				850.00
TAX ON PARTS & MATERIAL @			5.600%	47.60
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	0.9	5.5	320.00
2-MECH/ELEC	65.00			
3-FRAME	50.00			
4-REFINISH	50.00	5.0		250.00
5-PAINT MATERIAL	30.00			
LABOR TOTAL				570.00
TAX ON LABOR		@	5.600%	31.92
SUBLET REPAIRS				5.00
TAX ON SUBLET		@	5.600%	0.28
TOWING				
STORAGE				
GROSS TOTAL				1,504.80
NET TOTAL				1,504.80

SHOPLINK U1529 ES CD LOG 7134-1 DATE 02/08/08 10:18:41AM R6.37 CD 01/08
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53226

HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM.
CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT.
OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON,
WISCONSIN 53708-8911.

SCHOK'S AUTO BODY
5701 WEST BURLEIGH STREET
MILWAUKEE, WI 53210
PHONE: 414-873-9944 FAX: 414-873-5040
FED TAX ID# 39-1330692

CD LOG NO 10454-1 DATE 03/06/08

SHOP: SCHOKS AUTO BODY INSP DATE: 03/06/08
ADDRESS: 5701 W BURLEIGH PHONE 1: (414)873-9944
CITY STATE: MILWAUKEE, WI PHONE 2: (414)873-9951
ZIP: 53210- FAX: (414)873-5040

OWNER: OWENS, WALLACE HOME PHONE: (414)333-2463

POINT OF IMPACT: 4

LIC#: STATE: VIN: WDBCA39EXKA443388
BODY COLOR: MILEAGE:
CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN 8CYL GASOLINE 5.6
CODE: 30822C/D OPTNS J/24B

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
PASSENGER SIDE AIRBAG

TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
---	---	---	-----	-----	-----	---	---	---	---
RI	0029		GRILLE ASSEMBLY	R&I ASSEMBLY				0.6	1
RI	0048		ORNAMENT, GRILLE	R&I ASSEMBLY				0.3	1
E	0041		HEADLAMP ASSY, HALOG LT	1268201959	615.00			0.6	1
N	0973		HEADLAMPS AIM	ADDNL LABOR OPERA				0.5	1
I	0083		PANEL, HOOD	REPAIR				6.0*	1
L	0083	13	PANEL, HOOD	REFINISH				4.7	4

6 ITEMS

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN
CD LOG NO 10454-1

GROSS PARTS				615.00
PAINT MATERIAL				141.00
PARTS & MATERIAL TOTAL				756.00
TAX ON PARTS & MATERIAL @			5.600%	42.34
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	1.5	6.5	400.00
2-MECH/ELEC	75.00			
3-FRAME	55.00			
4-REFINISH	50.00	4.7		235.00
5-PAINT MATERIAL	30.00			
LABOR TOTAL				635.00
TAX ON LABOR		@	5.600%	35.56
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 1,468.90

NET TOTAL 1,468.90

SHOPLINK U2352 ES CD LOG 10454-1 DATE 03/06/08 04:41:20PM R6.37 CD 12/07
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53210
HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. THE ABOVE IS AN ESIMATE BASED ON OUR INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. BECAUSE OF THIS, THE ABOVE PRICES ARE NOT GUARANTEED. EMPLOYEES OF SCHOKS MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING OR DELIVERY AT MY RISK. AN EXPRESS MECHANICS LEIN IS ACKNOWLEDGED ON THE ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS ALSO UNDERSTOOD THAT SCHOKS WILL NOT BE RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND OUR CONTROL.
AUTHORIZED FOR :
REPAIR BY :

MERCEDES-BENZ OF ELMBROOK
2230 E. MORELAND BLVD
WAUKESHA, WI 53186
262-821-5000 FAX: 262-786-7954
FED TAX# 30-0237984

CD LOG NO 3975-1 DATE 02/08/08

SHOP: MERCEDES-BENZ OF ELMBROOK INSP DATE: 02/08/08
ADDRESS: 2230 E. MORELAND BLVD-HW18 CONTACT: RAY MITCHELL
P.O. BOX 439 PHONE 1: (262)821-5000 EXT 357
CITY STATE: WAUKESHA, WI PHONE 2: (262)821-5000 EXT 360
ZIP: 53186- FAX: (262)786-7954
EMAIL: TMANSELL@MBOFELMBROOK.COM

OWNER: WALLACE, OWENS CELL PHONE: (414)333-2463
ADDRESS: 5148 W ROSEVELT DRIVE
CITY STATE: MILWAUKEE, WI
ZIP: 53216
EMAIL: RMITCHELL@MBOFELMBROOK.COM

POINT OF IMPACT: 0

LIC#: RDK-419 STATE: WI VIN: WDBCA39EXKA443388
BODY COLOR: BLACK MILEAGE: 277,997
CONDITION: ACCTNG CTL#:

DRIVEABLE: YES VEH. INSP#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN 8CYL GASOLINE 5.6
CODE: 30822C/D OPTNS J/24B

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
PASSENGER SIDE AIRBAG

TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
RI	0029		GRILLE ASSEMBLY	R&I ASSEMBLY				0.6	1
E	0041		HEADLAMP ASSY, HALOG LT	1268201959	615.00			0.6	1
E	0042		HEADLAMP ASSY, HALOG RT	1268202059	615.00			0.6	1
N	0973		HEADLAMPS AIM	ADDNL LABOR OPERA				0.5	1
I	0083		PANEL, HOOD	REPAIR				5.0	*1

1989 MERCEDES-BENZ 560SEL STD 4DOOR SEDAN
CD LOG NO 3975-1

L	0083	13	PANEL, HOOD	REFINISH		4.7	4
E	M17		COVER CAR EXTERIOR	NEW PART	6.00*		4
E	M60		HAZARD. WSTE. REM.	NEW PART	3.00*		1
E	M66		COLOR, SAND & BUFF	R&I ASSEMBLY		0.5*	4

9 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS	1,239.00
PAINT MATERIAL	166.40
PARTS & MATERIAL TOTAL	1,405.40
TAX ON PARTS & MATERIAL @	5.100% 71.68

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	54.00	1.8	5.5	394.20
2-MECH/ELEC	107.00			
3-FRAME	70.00			
4-REFINISH	54.00	5.2		280.80
5-PAINT MATERIAL	32.00			
LABOR TOTAL				675.00
TAX ON LABOR		@	5.100%	34.43
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 2,186.51

NET TOTAL 2,186.51

UNRELATED PRIOR DAMAGE

GDE	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
---	-----	-----	-----	----	---	-----	-
	HD LMP WIPERS INOP	UNRELATED PRIOR DAMAG					1*
	VEHICLE NOTORIOUS FOR FAILURE						

1 ITEMS

TOTAL UNRELATED PRIOR DAMAGE 0.00

SHOPLINK U4459 ES CD LOG 3975-1 DATE 02/08/08 10:51:01AM R6.37 CD 12/07
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53187
HOST LOG
(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.