

Before and Future Photo Album

AN AMERICAN HOME CAMPAIGN



Model B1 Before Restoration (circa 2007)



Model B1 Restored



Model B1 Living Room Before Restoration



Model B Living Room



Two Family, "Flat C" Before Restoration (circa 2013)



Two Family, "Flat C" Before Restoration



Model C3 "Before" Photo Album



Model C3 Before Restoration (circa 2022)



Model C3 Crumbling flower box (circa 2022)



Model C3 Deteriorated roof overhang, gutters, and trim (circa 2022)



Model C3 Leaking roof - 5 layers, including the original layer of wood shingles (circa 2022)



Model C3 (circa 2022)

- Left: Deteriorating stucco soffit
- Middle: Mechanical systems past useful life
- Above: Deteriorating and lost wood sashes and trim