

**1** EXISTING FIRST FLOOR PLAN  
SCALE: N.T.S.






Photo 1 - West Elevation of the House Facing N. 29th Street





Photo 2 - Front Steps and Porch of the Lower Unit Showing a Sinking Foundation and Deterioration



Photo 3 - Front Porch and Handrails of the Lower Unit Showing a Sinking Foundation and Deterioration



Photo 4 - Front Porch of the Lower Unit Showing a Sinking Foundation and Deterioration



Photo 5 - Front Steps and Porch of the Upper Unit Showing a Sinking Foundation and Deterioration



Photo 6 - Front Porch and Handrails of the Upper Unit Showing a Sinking Foundation and Deterioration





Photo 7 - East Elevation of the House Facing the Backyard



Photo 8 - Back Exterior Stairs Showing Deterioration



Photo 9 - The Two Windows on the East Elevation that will be Replaced with New All-Wood Windows



Photo 10 - View of the South Elevation Showing the First Floor Windows