



CCF 101302

2301 North Holton Street

12/2/2011

Looking west at ramp structure in north sidewalk area of East North Avenue. There is more than 5 feet of clearance between the ramp and the light pole box out.



CCF 101302

2301 North Holton Street

12/2/2011

Looking east at ramp structure in north sidewalk area of East North Avenue. There is more than 5 feet of clearance between the ramp and the back of curb.



CCF 101302

2301 North Holton Street

12/2/2011

Looking northwest at ramp structure in north sidewalk area of East North Avenue.