

Charles J. Walker
4557 N 68th St.
Milwaukee, WI 53218

To Whom It May Concern,

Would you please accept this as
a letter to ask for an appeal on
the decision made on my claim
dated on 2-2-10

Sincerely
Charles J. Walker

CITY OF MILWAUKEE
2010 JUN 25 AM 11:43
RONALD D. LEONHARDT
CITY CLERK

CITY OF MILWAUKEE
RECEIVED
2010 JUN 28 PM 3:10
OFFICE OF
CITY ATTORNEY

Charles J. Watkins
4557 N 68th St.
Milwaukee, WI 53218

City Clerk
Claims

On Feb. 2, 2010 at approximately 3:45 p my
Automobile was Parked at 3717 W. Judd Ave.
and was struck by MPW snow plow,
causing damage to the drivers side.
The front driver door and the side loading
door ~~is~~ am seeking \$1,500.00 for repairs
to the automobile. I call you, My cell
number by phone at 414-461-9671 or 414-954-578

Sincerely
Charles J. Watkins

Enclosed are 2 estimates.

117 OF MILWAUKEE
2010 MAY 18 PM 2:33
RONALD D. CLAY
CITY CLERK

CITY OF MILWAUKEE
RECEIVED
2010 MAY 19 PM 2:51
OFFICE OF
CITY ATTORNEY

JOHN'S A-1 AUTO BODY MILWAUKEE INC.

9209 W FOND DU LAC AVE.
 Milwaukee, WI 53225
 Phone #: (414) 358-1967
 Fax #: (414) 358-1973

Customer No: 2024
 Report No: 2010
 Claim #:
 Assign No:

Estimate

5/17/2010

Vehicle Information

2000 Pontiac Montana
 Style: 4D WGN
 Color:
 Color Code:
 Production Date: / 0
 License: State: WI
 VIN: 1GMDU23EXYD164395
 Miles In: 0
 Miles Out: 0
 Condition:
 Estimator: JAMES MATTHEWS
 Date Assigned: 5/17/2010

Owner - Charles Watkins

4557 N 68th St
 Milwaukee, WI 53218
 Home Phone: (414) 915-4578
 Work Phone: (414) -
 Fax #: (414) -

Accident Location

Phone #1: -
 Phone #2: -

Insured -

Claimant -

Home Phone: (414) -
 Work Phone: (414) -
 Fax #: (414) -
 Date of Loss: 5/17/2010

Home Phone: (414) -
 Work Phone: (414) -
 Fax #: (414) -
 Date of Inspection: 5/17/2010

Description of Work	Part Number	Price	Labor	Paint	Other
FRONT DOOR - DOOR & COMPONENTS					
Repair Left Front Door shell			3.0* body	2.3	
+Clearcoat (0.9)				0.9	
SIDE LOADING DOOR - DOOR & COMPONENTS					
Repair Left Door shell, std WB			3.0* body	2.2	
-Adjacent (0.4) +Clearcoat (0.4)					
Other operations					
* Refinish tint and blend				2.0*	
Sub Totals			6.0	7.4	

**IN BUSINESS SINCE 1990

THANK YOU FOR LETTING US SERVE YOU

	Hours	Rate	Total
Body Labor	6.0hrs	\$52.00/hr	\$312.00 T
Paint Labor	6.1hrs	\$52.00/hr	\$317.20 T
Clearcoat Labor	1.3hrs	\$52.00/hr	\$67.60 T
Paint Supplies	6.1hrs	\$32.00/hr	\$195.20 T
Clearcoat	1.3hrs	\$32.00/hr	\$41.60 T
Tax		\$933.60 @ 5.6000%	\$52.28
Grand Total			\$985.88

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Guide used is (DR1FN97). 12/09

* Indicates Estimator's Judgment
 T Indicates Taxed Item

METICULOUS AUTO / TRUCK BODY INC
 8800 W FOND DU LAC AVE
 MILWAUKEE, WI 53225
 PHONE 414 464 9000 FAX 414 464 5950
 FEDERAL TAX ID 39-1960215

*** PRELIMINARY ESTIMATE ***

05/10/2010 10:17 AM

Owner

Owner: CHARLES WATKINS
 Address: 4557 N 68TH STREET
 City State Zip: Milwaukee, WI 53218

Cell: (414)915-4578
 FAX:

Inspection

Inspection Date: 05/10/2010 10:18 AM

Inspection Type:

Appraiser Name: MICHAEL CAMPANELLI

Appraiser License # :

Repairer

Repairer: Meticulous Auto/Truck Body
 Address: 8800 W Fond du lac Ave.
 City State Zip: Milwaukee, WI 53225
 Email: meticulousinc@sbcglobal.net

Contact:
 Work/Day: (414)464-9000
 FAX: (414)464-5950

Vehicle

2000 Pontiac Montana STD 4 DR Passenger Van
 6cyl Gasoline 3.4
 4 Speed Automatic

Lic.Plate:
 Lic Expire:
 Prod Date:
 Veh Insp# :
 Condition:
 Ext. Refinish: Two-Stage

Lic State: WI
 VIN: 1GMDU23EXYD164395
 Mileage: 150,000
 Mileage Type: Actual
 Code: W6522A
 Int. Refinish: Two-Stage

Options

7 Passenger Seating	AM/FM Stereo Tape	Air Conditioning
Anti-lock Brakes	Bodyside Cladding	Center Console
Cruise Control	Dual Airbags	Fog Lights
Heated Power Mirrors	Intermittent Wipers	Power Brakes
Power Door Locks	Power Steering	Rear Window Defroster
Rear Window Wiper/Washer	Side Airbags	Sliding Driver Side Door
Tachometer	Tilt Steering Wheel	Tinted Glass
Velour/Cloth Seats		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
1	BR	103	13	Fender,Front LT	Blend Refinish				2.0	RF
2	RI	105		Mldg,Wheel Opening LT	R & I Assembly				0.3	SM
3	I	207		Door Shell,Front LT	Repair				3.0*	SM
4	L	207		Door Shell,Front LT	Refinish				2.6	RF
5	RI	261		Mldg,Front Door Lower LT	R & I Assembly				0.4	SM
6	RI	233		N/Plate,Front Door LT	R & I Assembly				0.2	SM
7	RI	229		Mirror,Outer R/C LT	R & I Assembly				0.3	SM
8	RI	227		Handle,Front Door Otr LT	R & I Assembly				0.6	SM
9	I	287		Door Shell,Rear LT	Repair				7.0*	SM

10	L	287	Door Shell, Rear LT	Refinish		2.4	RF
11	RI	270	Mldg, Rear Door Lower LT	R & I Assembly		0.4	SM
12	RI	402	Handle, RR Door Outer LT	R & I Assembly		0.7	SM
13	SB		HAZARD. WSTE. REM.	Sublet Repair	\$6.00*		SM
14	N		COVER CAR EXTERIOR	Additional Labor	\$10.00*		RF
15	N		RE-TAPE NAME PLATE	Additional Labor	\$5.00*	0.3*	SM*
16	N		RE-TAPE CLADDING	Additional Labor	\$10.00*	0.5*	SM*
17	N		RETAPE CLADDING DOOR	Additional Labor	\$10.00*	0.5*	SM*
18	N		RE-TAPE CLADDING FRT FENDE	Additional Labor	\$5.00*	0.3*	SM*

18 Items

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts		\$40.00	
Paint Materials		\$238.00	
Parts & Material Total			\$278.00
Tax on Parts & Material	@ 5.600%		\$15.57

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$54.00	2.9	11.6	14.5	\$783.00
Mech/Elec (ME)	\$80.00				
Frame (FR)	\$65.00				
Refinish (RF)	\$54.00	7.0		7.0	\$378.00
Paint Materials	\$34.00				

Labor Total		21.5 Hours	\$1,161.00
Tax on Labor	@ 5.600%		\$65.02
Sublet Repairs			\$6.00
Tax on Sublet	@ 5.600%		\$0.34
Gross Total			\$1,525.93
Net Total			\$1,525.93

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53225 Audatex Host
 SPPL Yes Zip Code: 53225 Default

Audatex Estimating 6.0.353 ES 05/10/2010 10:22 AM REL 6.0.353 DT 04/01/2010
 Copyright (C) 2009 Audatex North America, Inc.

1.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Reblt	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	