



CITY OF MILWAUKEE
2004 AUG -2 PM 12:07
RONALD W. EDWARDS
CITY CLERK

July 29th, 2004

City of Milwaukee
Milwaukee City Clerk
200 East Wells Street, Room 205
Milwaukee, Wi 53202

Our Claim #: AFV253118
Our Insured: MBW Plumbing Co Inc
Your Client: City of Milwaukee truck
Date of Loss: 05/18/04

To Whom It May Concern::

This letter is in reference to your letter dated 06/25/04, denying your liability for the above referenced claim. We received this letter in our office via fax on July 13th, 2004.

In response to the letter, we would like to appeal this decision and request a hearing for this matter.

Thank you,

Bree Sweetack
Collections/ Subrogation
Integrity Mutual Ins.
1-800-348-1741 ext 291
bsweetack@imico.com

Enc

CITY ATTORNEY
2004 AUG -2 PM 4:48
CITY OF MILWAUKEE

Integrity Mutual Insurance Company
A Member of the Grange Mutual Casualty Group

Michael Wilber
President



M • B • W PLUMBING COMPANY, INC.

OR#225149

2090 SOUTH 55TH STREET • WEST ALLIS, WISCONSIN 53219

(414)671-5255 FAX: (414)671-5257

FAX TRANSMITTAL

DATE 9-13-04 PAGES SENT INCLUDING THIS TRANSMITTAL 2

TO THE ATTENTION OF: Tim Gahagan

COMPANY First Associated Insurance

FROM Mary Jo


REMARKS This is the letter we received from the
city. We appreciate your prompt
action!

Thanks, Mary Jo

Integrat Claims

C# 04-03160

For Your Info.



M • B • W PLUMBING COMPANY, INC.

MP 5037
2090 SOUTH 55TH STREET • WEST ALLIS, WISCONSIN 53219
(414) 671-5255

May 28, 2004

City of Milwaukee
City Clerk
ATTN: CLAIMS
200 E. Wells Street Room 205
Milwaukee, WI 53202-3567

RE: City vehicle #31148 damaging a van owned by MBW Plumbing Co., Inc.

To Whom It May Concern:

On the morning of May 18, 2004, our company van, driven by our plumber, Michael Wilber, was hit by a city of Milwaukee dumpster truck at the self-help lot on Industrial Road. We were called to the property on a service call.

Enclosed please find the information you require for filing a claim:

1. Statement on circumstances of accident
2. Two (2) estimates on repairs to our vehicle
3. Estimate from Ryder truck rental for renting a van while ours is being repaired.

If you need any further information, please give me a call.

Sincerely,


Mary Jo Werner

Mary Jo Werner
Office Manager

encs.

RECEIVED
MAY 28 2004
CITY OF MILWAUKEE

01 JUN -2 PM 4:18
CITY OF MILWAUKEE



M • B • W PLUMBING COMPANY, INC.

MP 5037

2090 SOUTH 55TH STREET • WEST ALLIS, WISCONSIN 53219

(414) 671-5255

STATEMENT OF CIRCUMSTANCES

REGARDING ACCIDENT WITH CITY VEHICLE #31148

MAY 18, 2004

MBW Plumbing Co. was called to the self-help lot on Industrial Road to clean the drain on the oil drop off tank. Upon arriving, I saw the dumpster truck sitting still in front of the tank. I motioned to the driver that I needed to get in front of his truck to get to tank. He looked at me like he did not understand and pulled forward. So I thought he wanted me to go behind him to get to tank. I started behind him and as soon as the front 1/3 of my truck was behind him, I heard the backup alarm of his truck go on. I stopped and beeped my horn. He never looked in his mirrors, and backed into my truck.

HOLZ MOTORS, INC. BODY SHOP

5961 S.108TH PLACE

HALES CORNERS, WI 53130

DIRECT LINE: (414) 529-7848 & (414) 425-2400 FAX: (414) 529-7533

FEDERAL I.D. #39-0792093

CD LOG NO 3636-1 DATE 05/18/04

SHOP: INSP DATE: 05/18/04
CONTACT: BOB GRIESE
OWNER: MBW PLUNBING HOME PHONE: (414)671-5255

POINT OF IMPACT: 12

DAYS TO REPAIR: 1

LIC#: 28520 STATE: WI VIN: 1GCHG35R5Y1183117
BODY COLOR: WHITE MILEAGE: 64,441
CONDITION: GOOD ACCTNG CTL#:

DRIVEABLE: YES VEH. INSP#:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS
EC=REPLACE ECONOMY UC=RECONDITIONED PRT UM=REMAN/REBUILT PRT
EU=REPLACE SALVAGE EP=REPLACE PXN PC=PXN RECONDITIONED
PM=PXN REMAN/REBUILT TE=PARTL REPL PRICE ET=PARTL REPL LABOR
IT=PARTIAL REPAIR I=REPAIR L=REFINISH
BR=BLEND REFINISH TT=TWO-TONE CG=CHIPGUARD
SB=SUBLET N=ADDITIONAL LABOR RI=R&I ASSEMBLY
P=CHECK AA=APPEAR ALLOWANCE RP=RELATED PRIOR
UP=UNRELATED PRIOR

2000 CHEVROLET G35 EXPRESS STD 2DOOR CARGO VAN 8CYL GASOLINE 5.7
CODE: U6167A/E OPTNS R/24GE

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES
HINGED SIDE CARGO DOORS DUAL AIRBAGS

Table with columns: OP, GDE, MC, DESCRIPTION, MFG. PART NO., PRICE, AJ%, B%, HOURS, R. Contains 9 rows of repair items.

9 ITEMS

MC MESSAGE(S)

2000 CHEVROLET G35 EXPRESS STD 2DOOR CARGO VAN
CD LOG NO 3636-1

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				538.50
OTHER PARTS				15.00
PAINT MATERIAL				187.20
PARTS & MATERIAL TOTAL				740.70
TAX ON PARTS & MATERIAL @			5.600%	41.48

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	46.00	5.4		248.40
2-MECH/ELEC	72.00			
3-FRAME	46.00			
4-REFINISH	46.00	7.2		331.20
5-PAINT MATERIAL	26.00			
LABOR TOTAL				579.60
TAX ON LABOR		@	5.600%	32.46
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL	1,394.24
NET TOTAL	1,394.24

ADP SHOPLINK U3508 ES CD LOG 3636-1 DATE 05/18/04 03:12:31PM R6.35 CD 04/04
PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53130

HOST LOG

(C) 1998 - 2004 ADP CLAIMS SOLUTIONS GROUP, INC.

1.6 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

"AFTERMARKET OR REPLACEMENT" PARTS ARE IDENTIFIED ON THE ESTIMATE BY THE WORDS "QUALITY REPLACEMENT PART" "PXN" "OR "ECONOMY PART".YOUR CLAIM REPRESENTATIVE CAN EXPLAIN FURTHER.

"NOTICE: WHEN SELECTING A REPAIR FACILITY, THE VEHICLE OWNER SHOULD CONSIDER THAT THE REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AND THE RESTORATION OF CORRISION RESISTANT COATINGS AS RECOMMENDED BY THE MANUFACTURER. FAILURE TO HAVE THE VEHICLE PROPERLY REPAIRED COULD RESULT IN A SAFETY HAZARD.

B R A E G E R
 4100 S. 27TH STREET
 MILWAUKEE, WI 53221
 PHONE: (414) 281-5000 FAX: (414) 281-8363
 TIN 39-0394520

CD LOG NO 10844-1 DATE 05/18/04

SHOP: 27TH STREET AUTO BODY	INSP DATE: 05/18/04
ADDRESS: 4100 S. 27TH STREET	CONTACT: JIM MCCANN
CITY STATE: MILWAUKEE, WI	PHONE 1: (414)281-0454
ZIP: 53221-	PHONE 2: (414)281-5000 EXT 265
	FAX: (414)281-8363

OWNER: MBW	WORK PHONE: (414)671-5255
ADDRESS: 2090 S 55TH ST	
CITY STATE: WEST ALLIS, WI	
ZIP: 53219-	

POINT OF IMPACT: 12

LIC#: 28570	STATE: WI	VIN: 1GCHG35R5Y1183117	
BODY COLOR: WHITE		MILEAGE:	
CONDITION:		ACCTNG CTL#:	

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UC=RECONDITIONED PRT	UM=REMAN/REBUILT PRT
EU=REPLACE SALVAGE	EP=REPLACE PXN	PC=PXN RECONDITIONED
PM=PXN REMAN/REBUILT	TE=PARTL REPL PRICE	ET=PARTL REPL LABOR
IT=PARTIAL REPAIR	I=REPAIR	L=REFINISH
BR=BLEND REFINISH	TT=TWO-TONE	CG=CHIPGUARD
SB=SUBLET	N=ADDITIONAL LABOR	RI=R&I ASSEMBLY
P=CHECK	AA=APPEAR ALLOWANCE	RP=RELATED PRIOR
UP=UNRELATED PRIOR		

ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY-ADDITIONAL DAMAGE MAY BE PRESENT
 PARTS PRICES ARE SUBJECT TO INVOICE

2000 CHEVROLET G35 EXPRESS STD 2DOOR CARGO VAN 8CYL GASOLINE 5.7
 CODE: U6167A/E OPTNS R/24GE

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
HINGED SIDE CARGO DOORS	DUAL AIRBAGS

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS	R	
EU	0448		DOOR ASSY,HNGD FRT RT	SALVAGE PART	500.00*			2.0	1	
			SMART PARTS QUOTE# 105209							
L	0448	13	DOOR SHELL,HNGD FRT RT	REFINISH				6.5	4	
				3.4 SURFACE						
				1.5 EDGE						
				0.6 TWO STAGE SETUP						
				1.0 TWO STAGE						
RI	0454		HANDLE,SIDE DOOR OT RT	R&I ASSEMBLY					INC 1	

2000 CHEVROLET G35 EXPRESS STD 2DOOR CARGO VAN
 CD LOG NO 10844-1

RI 0444	CYL, SIDE DOOR LOCK	RT R&I ASSEMBLY		0.2	1
L 0318	HINGE, FRT SD DOOR	U RT REFINISH		0.2	4
			0.2 SURFACE		
L 0319	HINGE, FRT SD DOOR	L RT REFINISH		0.2	4
			0.2 SURFACE		
EC M14	CORROSION PROTECTION	ECONOMY PART		0.3	4*
L M15	COLOR TINT	REFINISH		0.5	4*
SB M60	HAZARD. WSTE. REM.	SUBLET REPAIR	5.00*		*1*
E	PINS AND BUSHINGS	NEW PART	25.00*		0.6
					1

10 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				25.00
OTHER PARTS				500.00
PAINT MATERIAL				200.20
PARTS & MATERIAL TOTAL				725.20
TAX ON PARTS & MATERIAL @			5.600%	40.61
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	46.00	2.8		128.80
2-MECH/ELEC	80.00			
3-FRAME	46.00			
4-REFINISH	46.00	7.7		354.20
5-PAINT MATERIAL	26.00			
LABOR TOTAL				483.00
TAX ON LABOR		@	5.600%	27.05
SUBLET REPAIRS				5.00
TAX ON SUBLET		@	5.600%	0.28
TOWING				
STORAGE				

GROSS TOTAL 1,281.14

NET TOTAL 1,281.14

ADP SHOPLINK U3708 ES CD LOG 10844-1 DATE 05/18/04 10:27:53AM R6.35 CD 05/04
 HOST LOG

(C) 1998 - 2004 ADP CLAIMS SOLUTIONS GROUP, INC.

1.6 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

 THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.



FAX COVER PAGE

TO: MB.W. Plumbing

FROM: Tammy

DATE: 5/28/04

FAX #: 671-5257

ATTN: _____

RE: Carco Van Rental Rates are
as follows:

- \$50 per day
- \$250 per week (Keep 7 - pay 5)
- .24¢ per mile
- if you take our insurance,
it's \$22 per day.

THANK YOU



530 South 108 Street
 Milwaukee, WI 53214
 Tel 414.771.6644 Ext 405
 Fax 414.771.5208
 www.ryder.com