



1 of 19: East (primary) elevation, looking northwest; fellowship hall at left.



2 of 19: East (primary) elevation, looking west.



3 of 19: East (primary) elevation, looking south; sanctuary at right.



4 of 19: East elevation, detail of exterior stairs, looking northwest.



5 of 19: East elevation, detail of ramp and sanctuary windows, looking west.



6 of 19: North elevation, looking south.

7 of 19: West (parking lot) elevation, looking southeast - WILL BE PHOTOGRAPHED WEEK OF 7/28

8 of 19: West (parking lot) elevation, looking east - WILL BE PHOTOGRAPHED WEEK OF 7/28



9 of 19: Sanctuary interior, looking northwest towards chancel.



10 of 19: Sanctuary interior, looking southeast.



11 of 19: Sanctuary interior, detail of baptismal pool and lectern, looking west.




12 of 19: Fellowship hall interior, looking southeast.



13 of 19: Narthex interior, looking west.




14 of 19: Narthex interior, looking northwest.



15 of 19: Narthex interior, detail of east vestibule, looking north.



16 of 19: Narthex interior, detail of reception area, looking southwest.



17 of 19: Narthex interior, detail of stairs, looking southwest.



18 of 19: Classroom interior, looking northwest.



19 of 19: Chapel interior, looking southeast.