

Inspection Type	Number	Result	Inspection Date
Periodic Inspection	ELEV-PER-81-17507-H	Pass	2/9/2023
Periodic Inspection	ELEV-PER-81-17506-H	Partial	2/9/2023
Initial Investigation	ENF-2022-32140	No Violation Found	1/30/2023
Initial Investigation	ENF-2022-32140	No Violation Found	1/30/2023
Feeder Inspection	ELEC-22-07398	Pass	1/4/2023
Final Inspection	ELEC-22-07398	Completed	1/4/2023
Progress Inspection	COM-ALT-22-00053	Approved	1/4/2023
Rough-In Inspection	ELEC-22-07398	Pass	12/7/2022
Life Safety Inspection	LSI-14-4693282000-1-H	Passed	11/3/2022
Life Safety Inspection	LSI-14-4693282000-1-H	No Entry	9/21/2022
Electrical Final Inspection	ELEC-FA-21-00165	Completed	12/29/2021
Reinspection	ELEC-FA-21-00165	Completed	12/29/2021

Reinspection	ELEC-FA-21-00165	Completed	12/29/2021
Electrical Final Inspection	ELEC-FA-21-00165	Failed - No Fee	12/28/2021
Electrical Final Inspection	ELEC-FA-20-00344	Information	12/28/2021
Final Inspection	ELEC_LV-21-00030	Completed	12/28/2021
Final Inspection	PLB-20-01002	Pass	12/28/2021
Fire Alarm Witnessing	ELEC-FA-21-00165	Failed - No Fee	12/28/2021
Fire Alarm Witnessing	ELEC-FA-21-00165	Failed - No Fee	12/28/2021
Fire Alarm Witnessing	ELEC-FA-20-00344	Information	12/28/2021
Field Meeting	ELEC-FA-21-00165	Information	11/19/2021
Periodic Inspection	ELEV-PER-81-17506-H	Partial	10/4/2021
Periodic Inspection	ELEV-PER-81-17507-H	Pass	10/4/2021

Life Safety Inspection	LSI-14-4693282000-1-H	Passed	8/31/2021
Life Safety Inspection	LSI-14-4693282000-1-H	Passed	8/31/2021
Facade Inspection	FAC-14-4693282000-1-H	Advisory Issued	8/24/2021
Final Inspection	PLB-20-01002	Partial Approved	7/23/2021
Final Inspection	PLB-20-01002	Partial Approved	7/12/2021
Final Inspection	PLB-20-01002	Partial Approved	6/21/2021
Final Inspection	PLB-20-01002	Partial Approved	5/26/2021
Final Inspection	PLB-20-01002	Partial Approved	5/14/2021
Final Inspection	PLB-20-01002	Partial Approved	4/15/2021
Rough-In Inspection	PLB-20-01002	Pass	3/26/2021
Building Drain Sanitary Inspection	PLB-20-01002	Pass	3/9/2021
Rough-In Inspection	PLB-20-01002	Pass	1/21/2021
Rough-In Inspection	PLB-20-01002	Pass	12/30/2020
Initial Inspection	PLB-CROSSCON-20-02675	Pass	12/16/2020
Order Inspection	ORD-20-13983	Pass	12/16/2020
Rough-In Inspection	PLB-20-01002	Pass	12/16/2020
Admin Ord Inspection	ORD-20-13983	Order Issued	11/20/2020
Admin Ord Inspection	PLB-CROSSCON-20-02675	Order Issued	11/20/2020
Periodic Inspection	ELEV-PER-81-17507-H	Pass	9/21/2020
Periodic Inspection	ELEV-PER-81-17506-H	Pass	9/21/2020
Life Safety Inspection	LSI-14-4693282000-1-H	Passed	8/4/2020
Life Safety Inspection	LSI-14-4693282000-1-H	Passed	11/12/2019
Periodic Inspection	ELEV-PER-81-17506-H	Pass	6/28/2019
Periodic Inspection	ELEV-PER-81-17507-H	Pass	6/28/2019
Periodic Inspection	ELEV-PER-81-17506-H	Pass	3/13/2018
Periodic Inspection	ELEV-PER-81-17507-H	Pass	3/13/2018
Life Safety Inspection	LSI-14-4693282000-1-H	Passed	1/9/2018

Result Comment

Ok. Contact leasing office Oliva/ Mr. Green Inspector Phone: 414-286-2588

Ok. Contact leasing office Oliva. / Mr. green. Elevator is out of service , waiting on parts. Inspected Machine room ,controllor,Pumping unit.Check the hoistway. In the pit. Test and verify in - car emergency telephone, alarm bell , emergency car lighting. Maintenance log, Cat 1 /PRT testing. Inspector Phone: 414-286-2588

No return contact from complainant. Verbal advisory to manager. Exterior ok. B. Kelley 286-2130
Inspector Phone: 414-286-2130

No return contact from complainant. Verbal advisory to property manager. Exterior ok. B. Kelley 286-2130
Inspector Phone: 414-286-2130

200amp feeder, verified #3/0 conductors at 120/240 volt 3 wire. WE Energies OLL letter viewed and verified AIC rating at 13,700A. Breaker verified new and rated at 100,000. Approved Inspector Phone: 414-286-2530

Inspector Phone: 414-286-2530

Inspection date: 1/4/23

Site contact: Andy 847-366-666

Inspection location: cell site

Comments: Progress inspection, approved. Photos provided of prep work for new rooftop antenna platform, call for final inspection once installation is completed.

Inspector Andrea Solomon 414-286-2538 Inspector Phone: 414-286-2538

Viewed PVC raceway in trench, okay to cover from service equipment to where the rigid 90's emerge to go up the side of the building.

Reminders of future information that will need to to provided:

WE Energies service outlet location letter is needed to verify proper main breaker rating.

Used electrical equipment is prohibited.

Need to verify conductor size for 200 amp feeder once installed.

Properly label service equipment to code. Provide labeling.

My jurisdiction ends at the point of the service equipment. All equipment on the load side of the feeder is considered utility owned.

Inspector Phone: 414-286-2530

Inspector Phone: 414-286-5489

Repeated attempts at contacting on phone and in person have been futile so far.

Reviewed paperwork submitted by the building construction inspector and signed off my portion of the permit Inspector Phone: 414-286-2530

Reviewed paperwork submitted by the building construction inspector and signed off my portion of the permit Inspector Phone: 414-286-2530

Date of Inspection: 12/29/21
Site contact: Eric and electrician
Area inspected: re inspection of failed items.
Comments: Approved with NFPA 72 report received.

Inspector Lorie Gallup
Inspector Phone: 414-286-2520

Fire alarm witness test identified issues with first and second floor fire doors between Becher Court and Becher Terrace. Building construction inspector advised contractor on solution and will return tomorrow for reinspection. Today's inspection was successful for laundry room heat detector and ADA rooms. Necessary smokes tested and approved. Future permit to be taken for 2 additional panel changes to the existing Becher Court FA system. New permit will be taken for this phase of work, estimated finish date to be April 2022. Photos of repairs will be uploaded into this permit and construction permit to be reviewed for final sign off. Inspector Phone: 414-286-2530
Possible duplicate permit. Email sent to the contractor to see if permit can be canceled. Inspector Phone: 414-286-2530
Project complete. Final approved. Inspector Phone: 414-286-2530
262-424-1092. First floor unit. 131 room. Was laundry room made into apartment, tub lav we kitchen sink Inspector Phone: 414-286-3311

Inspector Phone: 414-286-2520
Date of Inspection: 12/28/21
Site contact: Electrical and Eric
Area inspected: Fire alarm witnessing.
Comments: Failed. Floor one and two double doors will need to stay closed and all hold open devices deactivated. Two different systems operate separately and doors not tied into both systems. Rework exit signage to separate path of egress with doors remaining closed. Provide signage for doors and proper exit for stairway on 2nd floor door. Will complete and send photos to inspectors. Re-inspection scheduled for 12/29/21 at inspection provide NFPA 72 to be signed. Note: this permit does not have any duct smoke detection and no roof top units. Buildings are separate with different fire alarm systems, connected with double doors on first and second floors only. Strobes will not sync without different panels and rework of system.

Inspector Lorie Gallup
Inspector Phone: 414-286-2520
See previous permit notes. Dated 12-28-2021
Inspector Phone: 414-286-2530
Discussed with contractor on site scope of Fire Alarm work. Reviewed cabinets and discussed internal parts getting replaced and upgraded. Inspector Phone: 414-286-2530
ok. elevator is not in use. partial inspection. mod job project on hold . contractor has not shown up yet (Johnson controls) Inspector Phone: 414-286-2588
ok. Inspector Phone: 414-286-2588

Inspector Phone: 414-286-3199

Last ADA apartment completed on first floor. Still need to finish sealing washers in old laundry room.

Inspector Phone: 414-286-8218

All fixtures set on first floor, except one unit. Inspector Phone: 414-286-8218

All fixtures set for second floor ADA units and first floor laundry room. Inspector Phone: 414-286-8218

All fixtures set for ADA units on third floor. Inspector Phone: 414-286-8218

All fixtures set for ADA units on fourth floor. Inspector Phone: 414-286-8218

Date: 4/14/2021

ADA units in west wing on floors 5 and 6 completed. Inspector Phone: 414-286-8218

Date: 3/26/2021

DWV and copper waterlines in wall rough with Moen posi temp tub and shower mixers. Hand held discussion with Krowski and Kosmatka stating as of now ASME A112.18.3 is approved. Inspector Phone: 414-286-8218

Date: 3/9/2021

Sanitary building drain -100 feet. Air tested. Rooms #126 - #129 - #130 - #132 and #127 (New laundry room). Inspector Phone: 414-286-8218

Date: 1/21/2021

DWV and copper waterlines in wall rough with Moen posi temp mixers in rooms #329 - #330 - #331 - #332 - #429 - #430 - #431 & #432 Inspector Phone: 414-286-8218

Date: 12/30/2020

DWV and copper waterlines in wall rough with Moen posi temp mixers in rooms 529, 530, 531 and 532. Inspector Phone: 414-286-8218

NO VIOLATION OBSERVED. CROSS-CONNECTION SURVEY" PASSED". Inspector Phone: 414-286-8257

ALL VIOLATIONS CORRECTED. ABATE ORDER. Inspector Phone: 414-286-8257

Date: 12/16/2020

4 ADA apartment renovations. DWV and copper waterlines in wall rough with Moen tub and shower mixers. Units #629 - #630 - #631 & #632 Inspector Phone: 414-286-8218

Resulted by batch script.

Resulted by batch script.

ok. Contact Dave Anderson 414-335-1256 or James Wellman 414-335-1276 Inspector Phone: 414-286-2588

ok. Contact Dave Anderson 414-335-1256 or James Wellman 414-335-1276 Inspector Phone: 414-286-2588

Special Enforcement Inspector Yang conducted a fire inspection of this location on 08/04/20, no violations observed--passed. Inspector Phone: 414-286-5496

No violations observed at time of inspection. Inspector Phone: 414-286-3199

Ok. Checked in at front desk

Checked in at front desk

Housing auth. contact Dave Anderson 414-335-1256 Inspector Phone: (414)286-2588 Inspector Phone: (414)286-2588 Inspector Phone: (414)286-2588

Housing Auth. contact Dave Anderson 414-335-1256 Inspector Phone: (414)286-2588 Inspector Phone: (414)286-2588 Inspector Phone: (414)286-2588

No violations observed at time of inspection Inspector Phone: 414-286-3199

	Becher
Periodic	14
Life Safety	7
Façade	1
Complaint	2
Permit	25
Reinspection	1

Inspection Type	Number	Result
Periodic Inspection	ELEV-PER-70-14200-H	Pass
Periodic Inspection	ELEV-PER-70-14199-H	Pass
Life Safety Inspection	LSI-02-4990036110-1-H	Partial Access
Initial Inspection	PLB-CROSSCON-20-11278	Pass
Automatic Sprinkler Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Order Re-Inspection	ORD-22-04694	Meeting to Clarify
Order Re-Inspection	ORD-22-04694	Meeting to Clarify
Order Inspection	ORD-22-04694	Meeting to Clarify
Initial Investigation	ENF-2022-11049	Order Issued
Initial Investigation	ORD-22-04694	Order Issued
Final Inspection	COM-ALT-19-00777	Approved
Final Inspection	ELEC-21-05991	Completed
Final Inspection	COM-ALT-21-00503	Approved
Final Inspection	COM-ALT-21-00450	Approved

Progress Inspection	COM-ALT-18-00865	Fail
Drywall Inspection	COM-ALT-21-00450	Approved
Drywall Inspection	COM-ALT-21-00450	Approved
Framing Inspection	COM-ALT-21-00450	Approved
Framing Inspection	COM-ALT-21-00450	Fail, Not Ready
Life Safety Inspection	LSI-02-4990036110-1-H	Passed

Framing Inspection	COM-ALT-21-00450	Fail
Progress Inspection	COM-ALT-21-00503	Fail
Periodic Inspection	ELEV-PER-70-14199-H	Pass
Periodic Inspection	ELEV-PER-70-14200-H	Pass
Routine Inspection	PWEU-20-04287	Complete - Final
Automatic Sprinkler Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Routine Inspection	PWEU-21-01045	Complete - Final
Final Inspection	COM-ALT-20-00702	Approved
Life Safety Inspection	LSI-02-4990036110-1-H	Passed
Automatic Sprinkler Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4990036110-18-H	Completed
Periodic Inspection	ELEV-PER-70-14199-H	Pass
Periodic Inspection	ELEV-PER-70-14200-H	Pass

Facade Inspection	FAC-14-4990036110-1-H	Advisory Issued
Automatic Sprinkler Periodic Inspection	PBFS-PER-4990036110-18-H	Approved
Water Branch Line Periodic Inspection	PBFS-PER-4990036110-18-H	Approved
Periodic Inspection	ELEV-PER-70-14200-H	Pass
Periodic Inspection	ELEV-PER-70-14199-H	Pass
Life Safety Inspection	LSI-02-4990036110-1-H	Partial Access
Admin Review	PLB-CROSS-15-4990036110-H	FutureInsp
Routine Inspection	PWEU-17-02662	Complete - Final
Life Safety Inspection	LSI-02-4990036110-1-H	Passed
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Pass
Order Re-Inspection	ORD-18-06083	Pass
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Fail
Order Re-Inspection	ORD-18-06083	Fail
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Fail
Order Re-Inspection	ORD-18-06083	Fail
Routine Inspection	PWEU-17-02696	Complete - Final
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Fail
Order Re-Inspection	ORD-18-06083	Fail
Automatic Sprinkler Periodic Inspection	PBFS-PER-4990036110-18-H	Pass
Water Branch Line Periodic Inspection	PBFS-PER-4990036110-18-H	Pass
Cross Connection Survey Periodic Inspection	ORD-18-06083	Order Written
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Order Written
Initial Investigation	ORD-18-06083	Order Issued
Initial Investigation	PLB-CROSS-15-4990036110-H	Order Issued
Order Re-Inspection	ORD-18-05443	Pass
Cross Connection Survey Periodic Inspection	PLB-CROSS-15-4990036110-H	Order Written
Cross Connection Survey Periodic Inspection	ORD-18-06083	Order Written
Initial Investigation	PLB-CROSS-15-4990036110-H	Order Issued
Initial Investigation	ORD-18-05443	Order Issued
Initial Investigation	ORD-18-06083	Order Issued

Inspection Date
11/11/2022
11/11/2022
11/9/2022
10/27/2022
7/18/2022
7/18/2022
5/19/2022
5/18/2022
5/4/2022
4/25/2022
4/25/2022
3/14/2022
2/1/2022
1/28/2022
1/28/2022

1/28/2022

12/1/2021

11/11/2021

11/2/2021

10/27/2021

10/26/2021

10/15/2021

10/15/2021

9/22/2021

9/22/2021

7/6/2021

6/21/2021

6/21/2021

6/9/2021

12/15/2020

10/6/2020

9/24/2020

9/24/2020

9/21/2020

9/21/2020

3/2/2020
12/3/2019
12/3/2019
11/22/2019
11/22/2019
11/12/2019
7/8/2019
7/8/2019
10/11/2018
8/14/2018
8/14/2018
8/9/2018
8/9/2018
7/10/2018
7/10/2018
6/25/2018
6/11/2018
6/11/2018
5/22/2018
5/22/2018
5/10/2018
5/10/2018
5/10/2018
5/10/2018
5/10/2018
4/26/2018
4/26/2018
4/26/2018
4/26/2018
4/26/2018

Result Comment
Ok. Inspector Phone: 414-286-2588
ok Inspector Phone: 414-286-2588
Need access to boiler rm and alarm report. Inspector Phone: 414-286-2130
NO VIOLATIONS OBSERVED, CROSS CONNECTION SURVEY" PASSED". Inspector Phone: 414-286-8257
Inspector Phone: 414-286-3376
Inspector Phone: 414-286-3376
Ok. Contact property manager asst. Ms.Rios. Check and verify the operation of repaired elevator. Re-inspection. Check repair log for work completed. Inspector Phone: 414-286-2588
Ok. Contact maintenance Red. Otis elevator on site replacing the drive. Will call when completed. Inspector Phone: 414-286-2588
Ok. Contact leasing office manager Ms Rios. Contractor Otis elevator has a new drive unit on order. 3-5 day for deliverly. Will advise. Inspector Phone: 414-286-2588
Ok. Contact leasing office Krystal Rios. Check & Verify the operation of elevator. Not working. Otis has part on order. Will advise. Called Otis supervisor Phil Land, check on status. Still on back order.
Ok. Contact leasing office Krystal Rios. Check & Verify the operation of elevator. Not working. Otis has part on order. Will advise. Called Otis supervisor Phil Land, check on status. Still on back order.
Certificate of compliance uploaded and permit is now closed. Inspector Phone: 414-286-2520
Inspector Phone: 414-286-2526
Date: 01/28/2022 All work completed. OK to close permit.
Field contact at time of inspection: John Wilhelmina Inspector Phone: 414-286-5817
Date: 01/28/2022 All work completed. OK to close permit.
Field contact at time of inspection: John Wilhelmina Inspector Phone: 414-286-5817

Date: 01/28/2022

Permit canceled.

No inspections performed under permit.

New work under new permits supersedes the scope of this permit. Inspector Phone: 414-286-5817

Date: 12/01/2021

Drywall inspection of rooftop penthouse.

-Inspection of 2nd layer of drywall at outer side of new space.

OK to proceed.

Field contact at time of inspection: Scott Rybacki

Date: 11/11/2021

Drywall inspection of rooftop penthouse.

-Inspection of 2nd layer of drywall installed on inner side of new space. And 1st layer of outer side of new space.

OK to proceed.

Field contact at time of inspection: Scott Rybacki

Date: 11/02/2021

Framing reinspection of rooftop penthouse.

-Contractor has stamped copy of approved plans onsite.

-Installation of inner 1st layer completed. OK to proceed to 2nd layer.

-Remove wood from stud cavity.

-OK to install 1st outer layer.

Field contact at time of inspection: Scott Rybacki

Date: 10/27/2021

Framing reinspection of rooftop penthouse.

-Contractor to keep stamped copy of approved plans onsite for all future inspections. Plans still not onsite.

-Unable to properly inspect rated wall.

Verification of prescriptive method to be followed, to be determined based on UL assembly used per plan set.

-Remove all drywall on outer side of new space.

-Remove 2nd layer of drywall on inner side of new space.

-Proper fire caulking of all through penetrations will be necessary.

Make all repairs and call for reinspection.

Field contact at time of inspection: Scott Rybacki

Inspector Phone: 414-286-2130

Date: 10/15/2021

Framing inspection of rooftop penthouse.

-Contractor to keep stamped copy of approved plans onsite for all future inspections.

-Unable to properly inspect rated wal framing. 2 sided drywall installed on inner side of new space. With majority of 1 sided drywall installed on outer side of new space. Gaps seen at 1st layer of inner side of new space.

-Properly offset drywall butt joints.

Verification of prescriptive method to be followed, to be determined based on UL assembly used per plan set.

-Remove all drywall on outer side of new space.

-Remove 2nd layer of drywall on inner side of new space.

-Proper fire caulking of all through penetrations will be necessary.

Make all repairs and call for reinspection.

Field contact at time of inspection: Scott Rybacki

Inspector Phone: 414-286-5817

Date: 10/15/2021

Framing inspection of rooftop penthouse.

-Contractor to keep stamped copy of approved plans onsite for all future inspections.

-Unable to properly inspect rated wal framing. 2 sided drywall installed on inner side of new space. With majority of 1 sided drywall installed on outer side of new space. Gaps seen at 1st layer of inner side of new space.

-Properly offset drywall butt joints.

Verification of prescriptive method to be followed, to be determined based on UL assembly used per plan set.

-Remove all drywall on outer side of new space.

-Remove 2nd layer of drywall on inner side of new space.

-Proper fire caulking of all through penetrations will be necessary.

Make all repairs and call for reinspection.

Field contact at time of inspection: Scott Rybacki

Inspector Phone: 414-286-5817

ok Inspector Phone: 414-286-2588

ok Inspector Phone: 414-286-2588

Inspector Phone: null

Inspector Phone: null

Work completed Permit Closed. Completion letter has been submitted and saved in the record.

Inspector Phone: 414-286-2535

Inspector Phone: 414-286-2130

Inspector Phone: null

Inspector Phone: null

ok. Contact Dave Anderson 414-335-1256 or James Wellman 414-335-1276 Inspector Phone: 414-286-2588

ok. Contact Dave Anderson 414-335-1256 or James Wellman 414-286-2931 office. Cell:335-1276

Inspector Phone: 414-286-2588

Inspector Phone: 414-286-3154
Ok. Checked in at office Cat 1 done by Otis 2/7/19
Ok. Checked in at front office Cat 1 was done 2/7/19 by Otis
appointment 11/12/19 at 1:00 with Benny Inspector Phone: 414-286-2130 Benny to call with pull station info
Survey ID: 3020628
5/14 - No work started.
5/31 - Conduit installed. Need sidewalk and grass restoration.
Inspector Phone: 414-286-2130
ALL VIOLATIONS CORRECTED.
ABATE ORDER.
VIOLATIONS STILL REMAIN. Inspector Phone: 414-286-8257 Inspector Phone: 414-286-8257
VIOLATIONS STILL REMAIN, PARTIAL INSPECTION. Inspector Phone: 414-286-8257 Inspector Phone: 414-286-8257
VIOLATIONS STILL REMAIN. Inspector Phone: 414-286-8257
VIOLATIONS STILL REMAIN, EXTEND ORDER 30 DAYS. Inspector Phone: 414-286-8257
VIOLATIONS STILL REMAIN. Inspector Phone: 414-286-8257
VIOLATIONS STILL REMAIN, EXTEND 30 DAYS. Inspector Phone: 414-286-8257
Inspector Phone: null Inspector Phone: null
Inspector Phone: null Inspector Phone: null
ORDER ISSUED 60 DAY.
ORDER ISSUED 60 DAY.
Inspector Phone: 414-286-8257
DISMISS ORDER. Inspector Phone: 414-286-8257
ORDER ISSUED 30 DAY. Inspector Phone: 414-286-8257 Inspector Phone: 414-286-8257
ORDER ISSUED 30 DAY. Inspector Phone: 414-286-8257 Inspector Phone: 414-286-8257
Inspector Phone: 414-286-8257
Inspector Phone: 414-286-8257

Inspection Type	Number	Result
Automatic Sprinkler Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Hose Cab Rack Wet SP Periodic	PBFS-PER-4341716100-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Periodic Inspection	ELEV-PER-70-14188-H	Pass
Periodic Inspection	ELEV-PER-70-14187-H	Pass
Life Safety Inspection	LSI-02-4341716100-1-H	Passed
Life Safety Inspection	LSI-02-4341716100-1-H	Passed
Automatic Sprinkler Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Hose Cab Rack Wet SP Periodic	PBFS-PER-4341716100-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Periodic Inspection	ELEV-PER-70-14187-H	Pass
Periodic Inspection	ELEV-PER-70-14188-H	Pass
Life Safety Inspection	LSI-02-4341716100-1-H	Passed
Automatic Sprinkler Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Hose Cab Rack Wet SP Periodic	PBFS-PER-4341716100-18-H	Completed
Water Branch Line Periodic Inspection	PBFS-PER-4341716100-18-H	Completed
Periodic Inspection	ELEV-PER-70-14188-H	Pass
Periodic Inspection	ELEV-PER-70-14187-H	Pass
Facade Inspection	FAC-14-4341716100-1-H	Advisory Issued
Automatic Sprinkler Periodic Inspection	PBFS-PER-4341716100-18-H	Approved
Hose Cab Rack Wet SP Periodic	PBFS-PER-4341716100-18-H	Approved
Water Branch Line Periodic Inspection	PBFS-PER-4341716100-18-H	Approved
Periodic Inspection	ELEV-PER-70-14187-H	Advisory Issued
Periodic Inspection	ELEV-PER-70-14188-H	Advisory Issued
Life Safety Inspection	LSI-02-4341716100-1-H	Passed
Initial Investigation	ENF-2019-05963	Clean Up Order Issued
Life Safety Inspection	LSI-02-4341716100-1-H	Passed
Automatic Sprinkler Periodic Inspection	PBFS-PER-4341716100-18-H	Pass
Standpipe System Flow Test	PBFS-PER-4341716100-18-H	Pass
Water Branch Line Periodic Inspection	PBFS-PER-4341716100-18-H	Pass
Periodic Inspection	ELEV-PER-70-14187-H	Pass
Periodic Inspection	ELEV-PER-70-14188-H	Pass

Inspection Date

8/29/2022

8/29/2022

8/29/2022

8/19/2022

8/19/2022

6/24/2022

9/17/2021

7/15/2021

7/15/2021

7/15/2021

7/14/2021

7/14/2021

12/7/2020

10/23/2020

10/23/2020

10/23/2020

7/30/2020

7/30/2020

3/2/2020

6/3/2019

6/3/2019

6/3/2019

5/29/2019

5/29/2019

3/25/2019

3/15/2019

12/7/2018

5/24/2018

5/24/2018

5/24/2018

4/4/2018

4/4/2018

Result Comment

Inspector Phone: 414-286-3376

Inspector Phone: 414-286-3376

Inspector Phone: 414-286-3376

Cold call resident let me in got keys from fire box. Inspector Phone: 414-286-8216

Cold call resident let me in got keys from fire box. Inspector Phone: 414-286-8216

2022 Fire inspection conducted. Inspector Phone: 414-286-5150

Inspector Phone: (414) 286-3565

Inspector Phone: 414-286-3376

Inspector Phone: 414-286-3376

Inspector Phone: 414-286-3376

Checked in at front office. Inspector Phone: 414-286-8216

Inspector Phone: 414-286-8216

Inspector Phone: 414-286-8816

Inspector Phone: null

Inspector Phone: null

Inspector Phone: null

Inspector Phone: 414-286-8216

Resident let me in got keys from fire box. Inspector Phone: 414-286-8216

Inspector Phone: 414-286-3154

Inspector Phone: null

Ok. Contact off site Dave (414) 335-1256

Pit needs to be cleaned

Inspector Dale Ostrowski (414)286-8216

ok. contact Dave off site (414) 335-1256

Pit needs to be cleaned

Inspector Dale Ostrowski (414) 286-8216

3/25/2019--Mitchell Court Housing--City owned--verbal advisory for trash chute closer on the 8th floor.

Contacts: Benni @ 286-5824 & Brad (all mechanicals and alarm system @ 331-4861.

Inspector Phone: 414-286-5434

Inspector Phone: 414-286-2130 Inspector Phone: 414-286-2130

Inspector Phone: null Inspector Phone: null

Inspector Phone: null

Inspector Phone: null Inspector Phone: null

contact Dave Anderson Housing auth. 414-335-1256 Inspector Phone: (414)286-2588 Inspector Phone:

(414)286-2588 Inspector Phone: (414)286-2588

Contact Dave Anderson Housing Auth. 414-335-1256 Inspector Phone: (414)286-2588 Inspector Phone:

(414)286-2588 Inspector Phone: (414)286-2588

	Mitchell
Periodic	25
Life Safety	5
Façade	1
Complaint	1
Permit	0
Reinspection	0