

September 17, 2006

CITY OF MILWAUKEE

2006 SEP 19 PM 1:40

City of Milwaukee
200 East Wells Street, Room 205
Milwaukee, Wisconsin 53202

RONALD D. LEONHARDT
CITY CLERK


RE: Grant F. Langley / Steven M. Carini
C.I. File No: 06-S-162

Regarding the letter you sent to me on August 27, 2006, denying my claim for file F.I. File No: 06-S-162. I understand your investigation to say the damage to the front bumper of my vehicle was done after the fact and you are implying that your towing the vehicle did not in any way damage it. However, I know that my vehicle was in excellent condition and was not damaged in any way before the City of Milwaukee towed the vehicle.

When I picked the vehicle up on Saturday May 6th is when I noticed the damage to the front bumper. On Monday May 8th my daughter called the City of Milwaukee to notify the proper authorities of the damage. At this time the City of Milwaukee took pictures of the damage and so did my daughter and they unmistakably stated that they were responsible for the damages. It is evident that the damage to the bumper happened when the vehicle was towed, this was clear on the morning of May 8th. So at this time I am unclear of your new findings and have notified my attorney James J. Hughes of this incident. I will be expecting to hear from you.

Thank you,

Mr. Craig Forstner
Box 165
St. Cloud, WI 53079




CITY OF MILWAUKEE
RECEIVED
2006 SEP 19 PM 3:34
OFFICE OF
CITY ATTORNEY

5/31/06

On the first Friday of May my truck had been towed due to street clearing, on Newhall Street. It was towed early Friday morning and Saturday my daughter and I picked up the Ford Explorer. At this time we did not noticed the damages to the truck. However, later that day while parking in diagonal parking my daughter noticed a tear in the front right bumper. The truck was taken back to the tow lot Monday morning were they had taken a photo of the damages. I am seeking \$750.00 for the damages of my truck

Craig Forstner



Box 165
St. Cloud, WI 53079
(920) 999-4896

CITY OF MILWAUKEE
RECEIVED

2006 MAY 31 PM 3:25

OFFICE OF
CITY ATTORNEY

RONALD S. LEONHARDT
CITY CLERK

2006 MAY 31 PM 1:23

CITY OF MILWAUKEE

City of Milwaukee Tow Lot

COMPLAINT AND INVESTIGATION FORM

-CITY USE ONLY-	-CUSTOMER INFORMATION-
TOW #: <u>1255032</u>	NAME: <u>Jennifer Forstner</u>
DATE: <u>5/8/06</u>	ADDRESS: <u>1711 E. Locust Apts Milwaukee WI</u>
CLERK ID: <u>72</u>	PHONE #: <u>920-948-2154</u>

COMPLAINT:

CITIZEN'S STATEMENT

Tear in front bumper





CITY OF MILWAUKEE
2006 MAY 30 AM 11:56
RONALD G. EDWARDS
CITY CLERK

Jennifer Forstner
SIGNATURE

5/8/06
DATE

-CONT-

CIRCLE AREAS OF DAMAGES USING THE DIAGRAMS BELOW



To file a claim for ***DAMAGE TO** or **THEFT FROM*** your vehicle, Write a detailed letter and send to:

**CITY CLERK'S OFFICE,
200 EAST WELLS STREET
CITY HALL, ROOM 205
MILWAUKEE, WI 53202
414-286-2221**

-CITY USE ONLY-

INVESTIGATION RESULTS

SIGNATURE:

DATE:

School District of Kewaskum


Farmington Elementary School

8736 Boltonville Road

Kewaskum, WI 53040

Phone: 262-692-9032

Fax: 262-692-6863



Number Pages (including cover sheet) 2

Date: 5/21/06

To: Char Rodriguez From: Mary Forstner (Jennifer)

Fax: 414 286 3456 Phone:

Urgent For Review Please Comment Please Reply

Notes: Attention Char Rodriguez

Mission: The Kewaskum School District strives to create and enhance an educational environment that is consistent with community expectations, and challenges students to be their best.

STENZ AUTO BODY INC.
W. 2217 CTH WH
MT. CALVARY, WI 53057
PHONE: (920) 753-5811 FAX: (920) 753-2911
TAX ID# 39-1744914

CD LOG NO 1117-1 DATE 05/15/06

SHOP: STENZ AUTOBODY INC. INSP DATE: 05/15/06
ADDRESS: W 2217 HWY 149 CONTACT: BERNIE
CITY STATE: MT. CALVARY, WI PHONE 1: (920)753-5811
ZIP: 53057- FAX: (920)753-2911

OWNER: FORSTNER, CRAIG HOME PHONE: (920)999-4896
ADDRESS: 101 SOUTH STREET
CITY STATE: ST. CLOUD, WI
ZIP: 53079

POINT OF IMPACT: 3

LIC#: 864-JLV STATE: VIN: 1FMZU83POYZB72440
BODY COLOR: BLUE MILEAGE: 68,959
CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

*** WE APPRECIATE YOUR BUSINESS ***
*** THIS IS A VISUAL INSPECTION AND HIDDEN DAMAGE MAY BE FOUND ***
*** WHEN FRONT BUMPER IS REMOVED, HIDDEN DAMAGE MAY BE FOUND ***

2000 FORD EXPLORER XLT 4DOOR WAGON 8CYL GASOLINE 5.0
CODE: P8433B/F OPTNS B/24SVPUFBCXOILT

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
4-WHEEL DRIVE	BUMPER COVER MOUNTED FOG LAMPS
ELEC REMOTE CONTROL MIRRORS	KEYLESS ENTRY SYSTEM
POWER DOOR LOCKS	POWER WINDOWS
PRIVACY GLASS	LUGGAGE RACK
HEATED TAILGATE GLASS	REAR WIPER
TILT STEERING WHEEL	AUTOMATIC TRANS
CRUISE CONTROL	

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS	R
E	0023		COVER,FRONT BUMPER	YL2Z17757BAA	264.14			2.8	1
L	0023	13	COVER,FRONT BUMPER	REFINISH				3.7	4

2000 FORD EXPLORER XLT 4DOOR WAGON
CD LOG NO 1117-1

RI 0049	DEFL, FRONT BUMPER	R&I ASSEMBLY		INC 1
N M60	HAZARD. WSTE. REM.	ADDNL LABOR OPERA	3.50*	1

4 ITEMS

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				264.14
OTHER PARTS				3.50
PAINT MATERIAL				111.00
PARTS & MATERIAL TOTAL				378.64
TAX ON PARTS & MATERIAL @			5.000%	18.93

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	2.8		140.00
2-MECH/ELEC	65.00			
3-FRAME	50.00			
4-REFINISH	50.00	3.7		185.00
5-PAINT MATERIAL	30.00			
LABOR TOTAL				325.00
TAX ON LABOR @			5.000%	16.25
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 738.82

NET TOTAL 738.82

ADP SHOPLINK U0040 ES CD LOG 1117-1 DATE 05/15/06 03:52:02PM R6.37 CD 04/06
HOST LOG
(C) 1998 - 2006 ADP CLAIMS SOLUTIONS GROUP, INC.

1.1 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

76TH STREET BODY SHOP
 7800 NORTH 76TH STREET
 MILWAUKEE, WI 53223
 PHONE: (414) 357-2121 FAX: (414) 357-2133

CD LOG NO 14226-1 DATE 05/10/06

SHOP: 76TH ST BODY SHOP
 ADDRESS: 7800 N. 76TH ST
 CITY STATE: MILWAUKEE, WI
 ZIP: 53223-

INSP DATE: 05/10/06
 CONTACT: SHANNON LEPINE
 PHONE 1: (414) 357-2121
 PHONE 2: (414) 586-7137
 FAX: (414) 357-2133

OWNER: FORSTNER, CRAIG
 ADDRESS: 101 S SOUTH ST
 CITY STATE: ST CLOUD, WI
 ZIP: 53079

HOME PHONE: (920) 948-2154

LIC#: STATE: WI
 BODY COLOR: BLUE-SILVER
 CONDITION: GOOD

VIN: 1FMZU83P0YZB72440
 MILEAGE:
 ACCTNG CTL#:

PROD. DATE: 03/00

PAINT CODE: LL

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

INITIAL ESTIMATE
 POSSIBLE HIDDEN DAMAGE

2000 FORD EXPLORER XLT 4DOOR WAGON 8CYL GASOLINE 5.0
 CODE: P8433B/F OPTNS B/24SVPUFEBXCXOILT

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
4-WHEEL DRIVE	BUMPER COVER MOUNTED FOG LAMPS
ELEC REMOTE CONTROL MIRRORS	KEYLESS ENTRY SYSTEM
POWER DOOR LOCKS	POWER WINDOWS
PRIVACY GLASS	LUGGAGE RACK
HEATED TAILGATE GLASS	REAR WIPER
TILT STEERING WHEEL	AUTOMATIC TRANS
CRUISE CONTROL	

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
---	---	---	-----	-----	-----	---	---	-----	---
E	0023		COVER, FRONT BUMPER	YL2Z17757BAA	264.14			2.8	1

2000 FORD EXPLORER XLT 4DOOR WAGON
CD LOG NO 14226-1

L 0023 13 COVER, FRONT BUMPER	REFINISH		3.7	4
L M03 FLEX ADDITIVE	REFINISH	12.00*		4*
EC M60 HAZARD. WSTE. REM.	ECONOMY PART	5.00*		1*

4 ITEMS

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS		264.14
OTHER PARTS		17.00
PAINT MATERIAL		103.60
PARTS & MATERIAL TOTAL		384.74
TAX ON PARTS & MATERIAL @	5.600%	21.55

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	2.8		140.00
2-MECH/ELEC	90.00			
3-FRAME	50.00			
4-REFINISH	50.00	3.7		185.00
5-PAINT MATERIAL	28.00			
LABOR TOTAL				325.00
TAX ON LABOR @			5.600%	18.20
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 749.49

NET TOTAL 749.49

ADP SHOPLINK U1836 ES CD LOG 14226-1 DATE 05/10/06 03:52:22PM R6.37 CD 04/06
PXN: NO GEOCODE

HOST LOG

(C) 1998 - 2006 ADP CLAIMS SOLUTIONS GROUP, INC.

1.1 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.