



①



④

↑
These stone
elements will
need to be
replaced. ⑤

The original of hand railing
on intact it will be
preserved in the reconstructed
porch

② Front wall
Bowling forward
causing
of railing to
break

③

This shows the "shear"
effect when railing //
stationary of front wall
pushing out ⑥

