

August 7, 2007

Office of the City Clerk
City Hall, Room 205
200 East Wells Street
Milwaukee, WI 53202-3567

Tammy Harris
4633 North 75th Street
Milwaukee, WI 53218
Claim number 07-S-207

To Whom It May Concern:

I am requesting a fair hearing in response to my claim not being approved. The incident took place on May 24, 2007; a limb of the tree adjacent to 4623 North 75th fell on my parked car resulting in several damages. The total amount of damages to be repaired is 1417.20.

Sincerely,



Tammy Harris

CITY OF MILWAUKEE
RECEIVED

2007 AUG 13 PM 3:38

OFFICE OF
CITY ATTORNEY

CITY OF MILWAUKEE
07 AUG 10 PM 3:21
RONALD B. BOHANNON
CITY CLERK

June 7, 2007

Tammy Harris
4633 North 75th Street
Milwaukee, WI 53218

Office of the City Clerk
City Hall, Room 205
200 East Wells Street
Milwaukee, WI 53202-3570

07 JUN -6 PM 4:35
CITY CLERK

To Whom It May Concern:

On May 24, 2007 at approximately 3:00 P.M. a tree limb fell off the tree residing at 4623 North 75th on to my parked car. I am the owner of a 2007 Kia Rio purchased on April 23, 2007. The tree limb left several damages to my car; there are dents on the hood, roof, mirror, and broken front passenger window. I reported this incident the day of May 24th to the city, was told that I must submit a claim and to get written estimates of the damages. I have required two written estimates from Maaco Auto Shop, and Don's Auto Shop. My contact number is (414) 841-7087. Don's Auto Service estimate \$14,170.00

Sincerely,



Tammy Harris

07 JUN -7 PM 3:35
OFFICE OF
CITY ATTORNEY

Estimate Report

119662

NAME Tommy Harris DATE 6/5/07 WORK PHONE _____ HOME PHONE (414) 841-2087
 ADDRESS 4633 W. 75th St. CITY Milwaukee STATE WI ZIP 53218
 YEAR 07 MAKE KIA MODEL RIO 4DR I.D. NO. _____
 PAINT CODE _____ PRCD. DATE _____ TRIM _____ MILEAGE _____ LICENSE NO. _____ DATE OF LOSS _____
 WRITTEN BY _____ INS. CO. _____ FILE NO. _____ CLAIM NO. _____ PO NO. _____
 ADJUSTER _____ LIC. NO. _____ PHONE _____ Deductible/Betterment _____

LINE NO.	RE-PAIR	RE-PLACE	DETAILS OF REPAIR R=Repair S=Straighten R/C=Recycle/Rechrome/Recore	PARTS INDEX A=Aftermarket N=New U=Used R=Rebuilt	PI	PARTS	LABOR	Deductible/Betterment	
								PAINT	SUBLET/ MISC.
1	X		HOOD			377.55	1.2		
2	X		WINDSHIELD MOLDING			26.90	2.5		
3	X		ROOF				2.0		
4	X		RIGHT MIRROR			149.80	.4		
5	X		11" FRONT DOOR GLASS			110.80	1.0		
6			REFINISH AS NEEDED					4.0	
7			CLEARCOAT					1.0	
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									

I hereby authorize the above work and acknowledge receipt of copy.

TOTALS → 612.05 7.1 5.0

Signed X _____


Date _____

PARTS Prices subject to invoice	\$	612.05
LABOR <u>7.1</u> hrs. @ <u>50.00</u>	\$	355.00
Shop Supplies	\$	
PAINT <u>5.0</u> hrs. @ <u>50.00</u>	\$	250.00
Paint Supplies	\$	125.00
Towing / Storage	\$	
Sublet / Miscellaneous	\$	
SUBTOTAL	\$	1342.05
TAX	\$	75.15
EPA: Waste Disposal Charge	\$	
TOTAL	\$	1417.20

DON'S AUTO SERVICE

Complete Auto Body
& Painting Service

5504 W. Hampton Ave.
Milwaukee, WI 53218
Phone (414) 464-4980
FAX # (414) 464-5304



MAACO COLLISION REPAIR & AUTO PAINTING
 4128 SOUTH 13TH STREET
 MILWAUKEE, WI 53221
 PHONE: 414-282-4567 FAX: 414-282-7177

CD LOG NO 1271-1 DATE 06/05/07

SHOP:

INSP DATE: 06/05/07
 CONTACT: BUDDY

OWNER: HARRIS, TAMMY
 ADDRESS: 463 N. 75TH STREET3
 CITY STATE: MILWAUKEE, WI
 ZIP: 53218

HOME PHONE: (414)841-7087

POINT OF IMPACT: 3

DAYS TO REPAIR: 4

LIC#: STATE:
 BODY COLOR:
 CONDITION: EXCELLENT

VIN: KNADE123276210894
 MILEAGE:
 ACCTNG CTL#:

DRIVEABLE: YES

VEH. INSP#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

2007 KIA RIO LX 4DOOR SEDAN 4CYL GASOLINE 1.6
 CODE: KA214B/B OPTNS B/24HIJ

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
 POWER STEERING
 AIR CONDITIONING

TWO-STAGE - INTERIOR SURFACES
 TILT STEERING WHEEL

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
E	0083		PANEL, HOOD	664001G010	324.55			1.0	1
L	0083	13	PANEL, HOOD	REFINISH				5.2	4
BR	0103		FENDER, FRONT	LT BLEND REFINISH				1.1	4
BR	0104		FENDER, FRONT	RT BLEND REFINISH				1.1	4
SB	0143		WINDSHIELD, SHADED	SUBLET REPAIR	*150.00*				1
E	0246		MIRROR, OUTER R/C	RT 876201G600	128.65			0.3	1
L	0246		MIRROR, OUTER R/C	RT REFINISH				0.6	4

2007 KIA RIO LX 4DOOR SEDAN
CD LOG NO 1271-1

E	0216	GLASS,FRONT DOOR T	RT	824211G010	110.80	1.0	1
I	0341	PANEL,ROOF		REPAIR		1.5*	1
L	0341	PANEL,ROOF		REFINISH		3.1	4
E	M17	COVER CAR EXTERIOR		NEW PART	10.00*		4
E	M60	HAZARD. WSTE. REM.		NEW PART	10.00*		1

12 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS							584.00
PAINT MATERIAL							288.60
PARTS & MATERIAL TOTAL							872.60
TAX ON PARTS & MATERIAL @					5.600%		48.87
LABOR		RATE		REPLACE HRS		REPAIR HRS	
1-SHEET METAL		50.00		2.3		1.5	190.00
2-MECH/ELEC		96.00					
3-FRAME		65.00					
4-REFINISH		50.00		11.1			555.00
5-PAINT MATERIAL		26.00					
LABOR TOTAL							745.00
TAX ON LABOR				@		5.600%	41.72
SUBLET REPAIRS							150.00
TAX ON SUBLET				@		5.600%	8.40
TOWING							
STORAGE							

GROSS TOTAL 1,866.59

NET TOTAL 1,866.59

SHOPLINK UU171 ES CD LOG 1271-1 DATE 06/05/07 04:39:29PM R6.37 CD 05/07

PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53221

HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

2.7 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.
AUDATEX TWO-STAGE EXTERIOR THRESHOLD OF 2.5 HOURS WAS CALCULATED IN THIS ESTIMATE.

THIS IS AN AUDATEX "FAST START" ESTIMATE. PLEASE CALL YOUR LOCAL DEALER TO CONFIRM PART NUMBERS AND PRICES.