

09-5-573-2?

September 21, 2009

CITY OF MILWAUKEE
RECEIVED

2009 SEP 23 PM 2:37

OFFICE OF
CITY ATTORNEY

CITY OF MILWAUKEE
09 SEP 22 PM 3:14
RONALD D. LEONHARDT
CITY CLERK

City of Milwaukee
City Clerk
ATTN: Claims Dept.
200 E. Wells Street
Milwaukee, WI 53202

RE: Personal property loss and damage claim for sewer backup 07/09/2009

At approximately 1:15 am on July 9, 2009, a water main break occurred in the 3400 block of S 86th ST in Milwaukee, roughly along the property line of our residence at 3428 S 86th St. The water released from the water main break traveled underground to an adjacent sanitary sewer manhole riser located approximately 6 to 10 feet from the break in the water main. The high volume of water released into the sewer could not exit properly at the end of our block and as a result a combination of sewage, silt and dirt surrounding the water main break back flowed into the basement of our residence causing considerable damage to property and structure.

At the time of this incident, this combination of sewage and silty water flowed in to our basement from both the floor drain, up through the toilet and even out of our vanity sink, to a depth of approximately 5 inches. Although the city water department was promptly notified of the main break, and crews arrived shortly thereafter, this sewage and main break water mixture continued to flow into our basement for approximately 2-3 hours.

There was a considerable loss of personal property as a result of this sewer back up, and a detailed itemized list is attached. In addition, considerable structural damage to our finished basement in our residence occurred as well. Two itemized estimates are attached for your reference.

It is documented that there have been a number of water main breaks in our neighborhood over the past several months and this information was supplied to residents at a neighborhood meeting hosted by Alderman Joe Dudzik on August 25, 2009. It is our belief that the City of Milwaukee knew there was history of water main breaks in the area. In addition, the sewer inspection report also supplied to residents at that same 8-25-09 meeting showed that the sewer pipe (only) in the 3400 block of S 86th was last inspected and cleaned in April of 2008.

It has come to our attention that the City of Milwaukee on December 15, 2005, signed a stipulation and order in the Milwaukee County Circuit Court, Branch 16 requiring the City of Milwaukee to 'internally inspect each of its sanitary sewer manholes at least once every five years to identify defects which may contribute to leakage.'

According to the 2008 Compliance Maintenance Annual Report (CMAR) filed by Dept of Public Works on behalf of the City of Milwaukee, only 15% of Manhole Inspections and 14% of Manhole Rehabilitations were completed that year, resulting in a Failing or "F" grade for sewerage collection systems as reported to the WI-DNR. Clearly the mandatory and required sanitary sewer manhole inspections and repairs every five years are not being met.

At the August 25, 2009 meeting, DPW Sewers Division Manager, Robert Brooks, stated that the sanitary sewer jetting procedure uses a water spray at approximately 1200 psi. The water main pressure in our neighborhood is typically 50-60 psi. The suggestion by the city officials at this meeting that the force of the water main break somehow crumbled or caused the sanitary sewer manhole riser to develop an opening seems highly unlikely given that the sewer Department themselves routinely use a water jet procedure that uses 1200 psi.

It seems very reasonable to assume that a gradual buildup of sand, silt and gravel at the ends of sanitary sewer pipe in the 3400 block of S 86th ST which impeded and prevented the proper flow of sewage water led directly to the sewer backup into our basement on July 9, 2009.

We believe the City had reasonable opportunity over a period of time to be aware of and correct the existing problems with the sanitary sewer line and water main on our block, and that this incident was not the result of a single causation on July 9th. Furthermore, the City of Milwaukee failed to complete the required sewer manhole inspections according to the Circuit Court Order Stipulation, effective as of June 2006.

Therefore, we feel the City of Milwaukee is clearly liable for damages resulting from the sanitary sewer back up into our basement on July 9, 2009 and we seek compensation for the resulting damages. Our claim for reimbursement is as follows \$15,878.25 for structural loss, plus personal property loss of \$6,678.54 minus our homeowner's insurance settlement of \$5,000.00 for a total of \$17,556.79.

We seek a claim for compensation for the \$17,556.79.

Lon A. Couillard *Peggy L Couillard*
Lon A Couillard Peggy L Couillard

3428 S 86th ST
Milwaukee 53227
1-414-329-7812
peigcouillard@aol.com



CARL KRUEGER CONSTRUCTION, INC.

6060 North 77th Street Milwaukee, WI 53218
PH: 414.536.5225
Fax: 414.536.4039
Fed ID#: 39-1724892

Client: Peggy Couillard
Property: 3428 S. 86th Street
Milwaukee, WI 53227

Home: (414) 329-7812

Operator Info:

Operator: ANGELA

Estimator: Angela Cameron

Type of Estimate: Sewage

Date Entered: 7/21/2009

Date Assigned: 7/15/2009

Date Est. Completed: 7/21/2009

Date Job Completed:

Price List: WIMW5B_JUN09

Restoration/Service/Remodel

Estimate: COUILLARD_PEGGY


File Number: 09-6587.STR

**CARL KRUEGER CONSTRUCTION, INC.**

6060 North 77th Street Milwaukee, WI 53218
 PH: 414.536.5225
 Fax: 414.536.4039
 Fed ID#: 39-1724892

COUILLARD_PEGGY**Main Level****Main Level**

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
1. Dumpster load - Approx. 20 yards, 4 tons of debris	2.00 EA	418.65	0.00	837.30
2. General clean - up final and on-going	16.00 HR	0.00	26.54	424.64
Total: Main Level				1,261.94

**finished****Ceiling Height: 8'**

949.89 SF Walls
 1,584.97 SF Walls & Ceiling
 70.56 SY Flooring
 121.17 LF Ceil. Perimeter

635.08 SF Ceiling
 635.08 SF Floor
 118.25 LF Floor Perimeter

Missing Wall: 1 - 2'11" X 6'8"
 Missing Wall: 1 - 3'0" X 8'0"

Opens into alcove
 Opens into Stair1

Goes to Floor
 Goes to Floor/Ceiling


DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
67. R&R Acoustic ceiling tile -	635.08 SF	0.41	2.84	2,064.01
56. R&R Interior door unit	1.00 EA	12.56	138.14	150.70
57. Stain & finish door/window trim & jamb (per side)	2.00 EA	0.00	28.80	57.60
58. Stain & finish door slab only (per side)	2.00 EA	0.00	32.95	65.90
59. R&R Door knob - interior	1.00 EA	8.37	37.53	45.90
60. R&R Paneling	977.89 SF	0.20	1.76	1,916.67
70. R&R Corner trim - plastic	56.00 LF	0.12	1.24	76.16
68. R&R Outlet	8.00 EA	3.37	11.03	115.20
69. R&R Switch	3.00 EA	3.37	10.63	42.00
71. Light fixture - Detach & reset - Large	1.00 EA	0.00	59.93	59.93
72. Detach & Reset Smoke detector	1.00 EA	0.00	0.00	31.57
76. Apply anti-microbial agent	1,905.25 SF	0.00	0.18	342.95
77. R&R Countertop - Flat laid plastic laminate	6.00 LF	2.89	37.53	242.52

**CARL KRUEGER CONSTRUCTION, INC.**

6060 North 77th Street Milwaukee, WI 53218
 PH: 414.536.5225
 Fax: 414.536.4039
 Fed ID#: 39-1724892

CONTINUED - finished

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
78. R&R Custom cabinets - base units	6.00 LF	5.03	199.13	1,224.96
79. R&R Sink - single - High grade	1.00 EA	12.56	274.21	286.77
80. R&R Sink faucet - Kitchen	1.00 EA	12.56	152.31	164.87
Totals: finished				6,887.71

**Stair1****Ceiling Height: 17'**

227.00 SF Walls
 251.00 SF Walls & Ceiling
 5.91 SY Flooring
 19.00 LF Ceil. Perimeter


24.00 SF Ceiling
 53.23 SF Floor
 24.33 LF Floor Perimeter

Missing Wall: 1 - 3'0" X 17'0" Opens into finished Goes to Floor/Ceiling

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
64. R&R Paneling	48.00 SF	0.20	1.76	94.08
65. R&R Acoustic ceiling tile -	12.00 SF	0.41	2.84	39.00
81. Remove Carpet	53.23 SF	0.18	0.00	9.58
66. Carpet	61.22 SF	0.00	2.89	176.93
15 % waste added for Carpet.				
Totals: Stair1				319.59



6060 North 77th Street Milwaukee, WI 53218
 PH: 414.536.5225
 Fax: 414.536.4039
 Fed ID#: 39-1724892




laundry room

Ceiling Height: 8'

454.00 SF Walls	161.83 SF Ceiling
615.83 SF Walls & Ceiling	161.83 SF Floor
17.98 SY Flooring	56.33 LF Floor Perimeter
56.33 LF Ceil. Perimeter	

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Under steps				
47. R&R Drywall replacement per LF - up to 2' tall	34.00 LF	1.50	6.93	286.62
48. Texture drywall - light hand texture	34.00 SF	0.00	0.40	13.60
49. Seal/prime the walls - one coat	454.00 SF	0.00	0.31	140.74
Main room				
62. Seal then paint the walls (2 coats)	454.00 SF	0.00	0.55	249.70
63. R&R Cabinetry - lower (base) units	3.00 LF	5.03	144.80	449.49
75. Apply anti-microbial agent	485.50 SF	0.00	0.18	87.39
Totals: laundry room				1,227.54



alcove

Ceiling Height: 8'

159.22 SF Walls	30.33 SF Ceiling
189.56 SF Walls & Ceiling	30.33 SF Floor
3.37 SY Flooring	19.42 LF Floor Perimeter
22.33 LF Ceil. Perimeter	


Missing Wall:	1 - 2'11" X 6'8"	Opens into finished	Goes to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
36. R&R Acoustic ceiling tile	30.33 SF	0.41	2.84	98.58
37. R&R Paneling	159.22 SF	0.20	1.76	312.07
42. Content Manipulation charge - per hour	2.00 HR	0.00	32.54	65.08
44. R&R Door opening (jamb & casing) - 32" to 36" wide - hardwood	1.00 EA	4.21	188.87	193.08



6060 North 77th Street Milwaukee, WI 53218
PH: 414.536.5225
Fax: 414.536.4039
Fed ID#: 39-1724892

CONTINUED - alcove

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
45. Stain & finish door/window trim & jamb (per side)	1.00 EA	0.00	28.80	28.80
46. Clean floor - Heavy	91.00 SF	0.00	0.37	33.67
74. Apply anti-microbial agent	91.00 SF	0.00	0.18	16.38
Totals: alcove				747.66



bathroom

Ceiling Height: 8'

229.33 SF Walls	48.00 SF Ceiling
277.33 SF Walls & Ceiling	48.00 SF Floor
5.33 SY Flooring	28.67 LF Floor Perimeter
28.67 LF Ceil. Perimeter	


DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
21. Clean the walls - Heavy	229.33 SF	0.00	0.25	57.33
22. Clean shower door - Heavy	1.00 EA	0.00	16.41	16.41
23. Clean bath accessory - Heavy	3.00 EA	0.00	5.31	15.93
24. Clean bathroom fixtures - Heavy	2.00 EA	0.00	64.12	128.24
26. Clean mirror - Heavy	10.00 SF	0.00	0.55	5.50
27. Clean sink - Heavy	2.00 EA	0.00	9.91	19.82
28. Clean shower - Heavy	2.00 EA	0.00	31.91	63.82
29. Clean towel bar	1.00 EA	0.00	3.88	3.88
30. Clean toilet - Heavy	2.00 EA	0.00	16.51	33.02
31. R&R Toilet seat	1.00 EA	4.56	41.26	45.82
25. Clean floor - tile - Heavy clean	96.00 SF	0.00	0.51	48.96
32. R&R Interior door - oak veneer - pre-hung unit	1.00 EA	12.56	173.95	186.51
33. R&R Door knob - interior	1.00 EA	8.37	37.53	45.90
34. Stain & finish door slab only (per side)	2.00 EA	0.00	32.95	65.90

**CARL KRUEGER CONSTRUCTION, INC.**

6060 North 77th Street Milwaukee, WI 53218
 PH: 414.536.5225
 Fax: 414.536.4039
 Fed ID#: 39-1724892

CONTINUED - bathroom

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
35. Stain & finish door/window trim & jamb (per side)	2.00 EA	0.00	28.80	57.60
38. R&R Drywall replacement per LF - up to 2' tall	28.67 LF	1.50	6.93	241.69
39. Texture drywall - light hand texture	28.67 SF	0.00	0.40	11.47
40. Seal/prime the surface area - one coat	30.00 SF	0.00	0.31	9.30
41. Paint the walls - one coat	229.33 SF	0.00	0.33	75.68
73. Apply anti-microbial agent	144.00 SF	0.00	0.18	25.92
Totals: bathroom				1,158.70

**storage****Ceiling Height: 8'**

688.00 SF Walls	247.47 SF Ceiling
935.47 SF Walls & Ceiling	247.47 SF Floor
27.50 SY Flooring	86.00 LF Floor Perimeter
86.00 LF Ceil. Perimeter	


DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
10. Content Manipulation charge - per hour	12.00 HR	0.00	32.54	390.48
16. Seal then paint the walls (2 coats)	688.00 SF	0.00	0.55	378.40
19. R&R Interior door unit	1.00 EA	12.56	138.14	150.70
20. Stain & finish door/window trim & jamb (per side)	2.00 EA	0.00	28.80	57.60
17. Stain & finish door slab only (per side)	2.00 EA	0.00	32.95	65.90
18. R&R Door knob - interior	1.00 EA	8.37	37.53	45.90
14. Apply anti-microbial agent	742.42 SF	0.00	0.18	133.64
15. Clean floor - Heavy	494.94 SF	0.00	0.37	183.13

Totals: storage

1,405.75

**CARL KRUEGER CONSTRUCTION, INC.**

6060 North 77th Street Milwaukee, WI 53218
 PH: 414.536.5225
 Fax: 414.536.4039
 Fed ID#: 39-1724892

**canning room****Ceiling Height: 8'**

176.00 SF Walls	30.22 SF Ceiling
206.22 SF Walls & Ceiling	30.22 SF Floor
3.36 SY Flooring	22.00 LF Floor Perimeter
22.00 LF Ceil. Perimeter	

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
3. Content Manipulation charge - per hour	3.00 HR	0.00	32.54	97.62
4. Detach & Reset Shelving - 12" - in place	48.00 LF	0.00	0.00	245.28
5. R&R Sheathing - 1" x 6" - tongue and groove	96.00 SF	0.45	2.38	271.68
11. R&R Interior door - oak veneer - slab only	1.00 EA	5.58	95.29	100.87
12. R&R Door knob - interior	1.00 EA	8.37	37.53	45.90
13. Stain & finish door slab only (per side)	2.00 EA	0.00	32.95	65.90
6. Seal then paint the walls (2 coats)	176.00 SF	0.00	0.55	96.80
7. Clean floor - Heavy	60.44 SF	0.00	0.37	22.36
9. Apply anti-microbial agent	90.67 SF	0.00	0.18	16.32
Totals: canning room				962.73
Total: Main Level				13,971.62
Line Item Subtotals: COUILLARD_PEGGY				13,971.62

Adjustments for Base Service Charges**Adjustment**

Carpenter - Finish, Trim/Cabinet	113.82
Carpenter - General Framing	101.90
Cleaning Technician	53.06
Floor Cleaning Technician	62.76
Cleaning Remediation Technician	74.04
Drywall Installer/Finisher	232.64
Electrician	144.78
Flooring Installer	126.58
Hardware Installer	107.02
Plumber	194.04
Painter	87.00



CARL KRUEGER CONSTRUCTION, INC.

6060 North 77th Street Milwaukee, WI 53218
PH: 414.536.5225
Fax: 414.536.4039
Fed ID#: 39-1724892

Adjustments for Base Service Charges	Adjustment
Total Adjustments for Base Service Charges:	1,297.64
Line Item Totals: COUILLARD_PEGGY	15,269.26

Grand Total Areas:

2,883.44 SF Walls	1,176.94 SF Ceiling	4,060.39 SF Walls and Ceiling
1,206.18 SF Floor	134.02 SY Flooring	355.00 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	355.50 LF Ceil. Perimeter
1,206.18 Floor Area	1,261.11 Total Area	2,495.78 Interior Wall Area
1,165.33 Exterior Wall Area	145.67 Exterior Perimeter of Walls	
0.00 Surface Area	0.00 Number of Squares	0.00 Total Perimeter Length
0.00 Total Ridge Length	0.00 Total Hip Length	




CARL KRUEGER CONSTRUCTION, INC.

6060 North 77th Street Milwaukee, WI 53218
PH: 414.536.5225
Fax: 414.536.4039
Fed ID#: 39-1724892

Summary

Line Item Total				13,971.62
Total Adjustments for Base Service Charges				1,297.64
<hr/>				
Subtotal				15,269.26
Overhead	@	10.0% x	15,269.26	1,526.93
Profit	@	10.0% x	15,269.26	1,526.93
Material Sales Tax	@	5.600% x	6,194.86	346.91
<hr/>				
Replacement Cost Value				\$18,670.03
Net Claim				\$18,670.03
<hr/> <hr/>				

Angela Cameron



R-E CONSTRUCTION CO. INC.

P.O. Box 510435
 New Berlin, WI 53151-0435
 (414)-771-3366 (414)-771-2002
 fax

ESTIMATE

DATE
7/22/2009

NAME / ADDRESS		CUSTOMER PHONE		CUSTOMER ALT CONTACT	
Couillard, Lon & Peggy 3428 So. 86th St. Milwaukee, Wis 53227 Wife cell 507-9361 Disk 552 49 - end 553 0 - 9					
INSURANCE COMPANY	DEDUCTIBLE	REP	CLAIM #	ADJUSTER	
Acuity Ins. Co.		PE	LZ 6458	Joe R.	
DESCRIPTION	QTY	COST		TOTAL	
Appraisal of damage to lower level (finish basement) from water, mud, sewage. Any content manipulation and/or storage are not included in this estimate. Floor tile has been tested and does contain asbestos. There was no base of shoe. All measurements are approximate. This appraisal is based on a visual inspection on 7/14/09 any damage to sub wall , insulation, of rough framing could not be viewed.					
Stairway and landing 3'x 11' + 5'6"x 3'					
Repair walls were railing was pulled out	1	85.00		85.00	
Reset hand rail	0.75	45.00		33.75	
Prime as needed	1	35.00		35.00	
Paint	288	0.44		126.72	
Clean steps	12	3.00		36.00	
Bar area 10'6"x 15'x 7'					
Remove wall paneling	252	0.65		163.80	
Remove wall insulation	252	0.35		88.20	
Check rough framing, clean and treat if needed (OPEN)					
Replace wall insulation	252	1.35		340.20	
Wall paneling material	9	28.95		260.55	
Misc. molding	12	4.50		54.00	
Labor to install	9	45.00		405.00	
Disconnect bar if possible (so as to remove floor)	1.25	45.00		56.25	
Move bar twice 3 men .333	2	45.00		90.00	

Please review and give me a call to discuss. Thanks Pat Elliott (414)-771-3366	TOTAL
---	--------------

R-E CONSTRUCTION CO. INC.
P.O. Box 510435
New Berlin, WI 53151-0435
(414)-771-3366 (414)-771-2002
fax

ESTIMATE

DATE
7/22/2009

NAME / ADDRESS					
Couillard, Lon & Peggy 3428 So. 86th St. Milwaukee, Wis 53227 Wife cell 507-9361 Disk 552 49 - end 553 0 - 9		CUSTOMER PHONE		CUSTOMER ALT CONTACT	
INSURANCE COMPANY	DEDUCTIBLE	REP	CLAIM #	ADJUSTER	
Acuity Ins. Co.		PE	LZ 6458	Joe R.	
DESCRIPTION	QTY	COST		TOTAL	
Clean bar	1	65.00		65.00	
Clean back bar	1	65.00		65.00	
Remove floor tile	158	2.15		339.70	
Remove adhesive	158	1.05		165.90	
Floor material mid grade	158	1.40		221.20	
Labor to install	158	1.15		181.70	
Entertainment room 14'6"x 30'x 7'					
Remove wall paneling	518	0.65		336.70	
Remove wall insulation	311	0.35		108.85	
Replace wall insulation	311	1.35		419.85	
Wall paneling material	19	28.95		550.05	
Misc molding	20	4.50		90.00	
Labor to install	19	45.00		855.00	
Remove door unit to laundry	1	29.70		29.70	
Replace door unit to laundry	1	385.00		385.00	
Stain or prime door	1	28.50		28.50	
Varnish or paint door	1	35.00		35.00	
Remove floor tile	435	2.15		935.25	
Remove adhesive	435	1.05		456.75	
Floor material	435	1.40		609.00	
Labor to install	435	1.15		500.25	
Laundry / below steps 13'x 15'					
Clean walls below steps and block work	189	0.35		66.15	
Prime	189	0.34		64.26	
Paint	189	0.44		83.16	
Clean open stud walls x2	724	0.25		181.00	
Clean cabinet	1	35.00		35.00	

Please review and give me a call to discuss. Thanks Pat Elliott (414)-771-3366	TOTAL
---	--------------

R-E CONSTRUCTION CO.-INC.

P.O. Box 510435

New Berlin, WI 53151-0435

(414)-771-3366 (414)-771-2002

fax

ESTIMATE

DATE
7/22/2009

NAME / ADDRESS		CUSTOMER PHONE		CUSTOMER ALT CONTACT	
Couillard, Lon & Peggy 3428 So. 86th St. Milwaukee, Wis 53227 Wife cell 507-9361 Disk 552 49 - end 553 0 - 9					
INSURANCE COMPANY	DEDUCTIBLE	REP	CLAIM #	ADJUSTER	
Acuity Ins. Co.		PE	LZ 6458	Joe R.	
DESCRIPTION	QTY	COST		TOTAL	
Remove tile floor	195	2.15		419.25	
Remove adhesive	195	1.05		204.75	
Flooring material	195	1.40		273.00	
Labor to install	195	1.15		224.25	
Hallway to storage area / bath 6'6"x 7'					
Remote 2 door units	2	29.70		59.40	
Remove wall paneling	189	0.65		122.85	
Check rough framing, clean and treat if needed (OPEN)					
Wall paneling material	7	28.95		202.65	
Labor to install	7	45.00		315.00	
Misc molding	7	4.50		31.50	
Replace 2 door units	2	385.00		770.00	
Stain or prime doors	2	28.50		57.00	
Varnish or paint doors	2	35.00		70.00	
Remove tile floor	46	2.15		98.90	
Remove adhesive	46	1.05		48.30	
Floor tile material	46	1.40		64.40	
Labor to install	46	1.15		52.90	
Bath 5'x 7'					
Clean vanity	1	25.00		25.00	
Clean sink	1	8.50		8.50	
Clean stool	1	8.50		8.50	
Clean wall	192	0.25		48.00	
Prime walls	192	0.34		65.28	
Paint walls	192	0.44		84.48	
Remove floor tile (peel and stick style)	35	1.75		61.25	

Please review and give me a call to discuss. Thanks Pat Elliott (414)-771-3366	TOTAL
---	--------------

R-E CONSTRUCTION CO. INC.
P.O. Box 510435
New Berlin, WI 53151-0435
(414)-771-3366 (414)-771-2002
fax

ESTIMATE

DATE
7/22/2009

NAME / ADDRESS		CUSTOMER PHONE		CUSTOMER ALT CONTACT	
Couillard, Lon & Peggy 3428 So. 86th St. Milwaukee, Wis 53227 Wife cell 507-9361 Disk 552 49 - end 553 0 - 9					
INSURANCE COMPANY	DEDUCTIBLE	REP	CLAIM #	ADJUSTER	
Acuity Ins. Co.		PE	LZ 6458	Joe R.	
DESCRIPTION	QTY	COST		TOTAL	
Replace floor tile	35	2.65		92.75	
Shower Clean complete	1	45.00		45.00	
Work shop/ storage area 11'x 14', + 16'x 19'					
Clean block walls	480	0.35		168.00	
Prime	480	0.34		163.20	
Paint	480	0.44		211.20	
Clean open stud walls 464 x 2	928	0.25		232.00	
Remove floor tile	458	2.15		984.70	
Remove adhesive	458	1.05		480.90	
Floor tile material	458	1.40		641.20	
Labor to install	458	1.15		526.70	
Any concrete prep work (OPEN) Check rough framing, clean and treat if needed (OPEN)					
Clean up rubbish removal of construction material	1	435.00		435.00	
Temp and emergency service (invoiced)					

Please review and give me a call to discuss. Thanks Pat Elliott (414)-771-3366	TOTAL	\$15,878.25
---	--------------	-------------

MICRO ANALYTICAL, INC.
11521 W. NORTH AVE.
MILWAUKEE, WI 53226
(414) 771-0855
FAX (414) 771-6570

-Fax Transmittal

Date: 7/15/09 Pages: 3

To: _____

Company: RE Construction

From: Jon

Subject: _____


FAX #: _____

Comments: _____

If you have any questions regarding this fax transaction, please call (414) 771-0855.

Thank-you.

Confidentiality Notice: Unless otherwise indicated, the information contained in this facsimile communication is confidential information intended for use of the individual named above. If the recipient of this facsimile has received it in error, you are hereby notified that any dissemination or copying of this communication is prohibited. If you have received this facsimile in error, please destroy it immediately and notify the sender at the phone number above.




HERITAGE INSURANCE
Heritage Mutual Insurance Company • Sheboygan, Wisconsin 53081

STATEMENT OF LOSS

Insured Low & Peggy Cuillard Claim Number LZ 6458 Policy Number R 48599
 Representative The Robages Date 7.9.09 loss date

Item Description	Quantity	Where Purchased and Date	Replacement Cost	Depreciation		ACV	Comments
				%	Amount		
Blue fabric rocker	1	Des Moines 1985	249-				
Wooling board cover		?	22.95				
Wooling board cover		Ban Claine	21.83				
cat house		Big lots	40.00				
Albums	149	see attached list	573-				
Antique picture frames	1	wedding gift	150-				
Picture frames	2	M. duval 16x20	15.00				
lg wood BIK frames	4	Regis Parents	100-				
lg Antique frames	2	Regis Parents	100-				
Build a bear	1		26-				
Dave's shoes	7 or	2 Biny 1 running water	225-				
Decorative chips	2 bags	1 Dress 2 work 1 water					
Cake decor		Cook's Specialty	26-				
Sprinkle 5 upstems		" "	15-				
Small gift bags	8	target	16-				
Small tent	1	Iowa	150-				
Small tent	1	Iowa	150-				
Socks		knownt	8-				
lg carpe towels	1	(dunham's)	84.46				
botanical prof. plant press	1	1982 ?	150-			herbarium quality	
16x20 frame	2	Michale	20-				



HERITAGE INSURANCE

Heritage Mutual Insurance Company • Sheboygan, Wisconsin 53081

STATEMENT OF LOSS

Insured Lon & Peggy Ceallard Claim Number LZ 6458 Date 7.9.09 loss date
 Representative Joe Robarge Policy Number R 485 99

Item Description	Quantity	Where Purchased and Date	Replacement Cost	Depreciation		ACV	Comments
				%	Amount		
Sleeper sofa	1	(Blumen) 1999	700 ⁰⁰				
twin bed box	1	Verlo ?	187-				
large Blue chair	1	Milwaukee 1999	350-4				
luggage	2ly	JC Penney's 25"	300 ⁰⁰				
luggage	1md	JC Penney's 25"	130-				
duffle bag	1	Iowa 21" x 2	30-				
dining table	1	Iowa / spoon w/ speed	400-2				
drum case	1	Casico	140 ⁰⁰				used in Sept
drum bag	1	guitar center	89 ⁹⁹				
Hand Drum	1		35 ⁰⁰				
Drum w/ sticks			28-				
wicker waste Basket		mom	15-				
wicker mirror		Broken	29-				
Small bathroom cupboard			40-				
Scale		mom	30-				
Toilet paper	1 pkg + loose		9-				
Chest of drawers	1		349-				6 drawers
Books / China / misc	many		200-4 ⁷⁴				
Drum books	5+		20 ⁰⁰				
futon, mattress	1	1983	100 ⁰⁰				

State law, in some states, requires that we advise you of the following: A person commits insurance fraud which is a crime if he or she knowingly and with intent to defraud any insurance company or person files a statement of claim or makes application for insurance containing any false or deceptive information.

Sub total 3,182-
 Paid 0-
 Balance 3,182-

