

**Claimant: Daniel McClain**  
**Address: 10242 W Fountain Ave**  
Milwaukee, WI 53224  
**Phone Number: 414-366-2575**  
**Date of Incident: 01/16/2024**  
**Time: 12:00am – 1:30pm**  
**Location of the incident: 3160 N 28<sup>th</sup> Street**

2024 FEB 22 PM 2:34  
CLERK'S OFFICE  
CITY OF MILWAUKEE

To whom it may concern:

I arrived from work at 12am on Tuesday, January 16, 2024. Parked my White, 2015 Chrysler 200 on the east or even side of the street in front of 3160 N 28<sup>th</sup> Street. I was headed to work later that day at 1:30pm 1:30 pm when I observed my car was seriously damaged. It was pushed against a snowbank, the driver side head light broken, glass on the ground, fender bent, and bumper cracked/destroyed from the impact. Fluids from the car were also leaking onto the street. While inspecting my car the neighbor came outside, indicated she heard the collision, looked outside and witnessed the plow truck quickly leaving the scene.

The damage resulted from the negligence of a City of Milwaukee employee. I am requesting reimbursement for cost of damages totaling \$6,359.89 which includes cost for parts and labor.



**Claimant Signature:**


Date: 

Date:

2-20-24

---

**Witness Name:**

  
Diane Kelley  
Phone: 414-213-7995

Date:

OFFICE OF CITY ATTORNEY  
28 FEB '24 AM 08:15

TO FILE A CLAIM WITH THE CITY OF MILWAUKEE:

You will need the following information:

DATE of Incident 1/15/24

"City" Vehicle Number 3160 N 28th St

RECEIVED BY

OFFICE COPY

## JOHN AMATO CHRYSLER DODGE JEEP RAM

X

5900 N. Green Bay Ave.  
 Glendale, WI 53209  
 (414) 410-3535  
 www.amatoauto.com

RETURN/REFUND POLICY: ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE AND ARE SUBJECT TO A 20% RESTOCKING CHARGE. RETURNED ITEMS MUST BE IN THE ORIGINAL UNOPENED BOX OR CONTAINER. PLEASE NOTE THAT THE DEALERSHIP WILL NOT ACCEPT RETURNS OR MAKE REFUNDS AFTER 30 DAYS. NO REFUNDS OR RETURNS ON SPECIAL ORDER PARTS OR ELECTRICAL PARTS.

DATE ENTERED	YOUR ORDER NO.	DATE SHIPPED	INVOICE DATE	INVOICE NUMBER		
05 FEB 24	JN518427	05 FEB 24	***** INVOICE QUOTE	30907	DO NOT PAY	*****

S  
 O  
 L  
 D  
 T  
 O  
 CASH  
 ACCOUNT NO. P10  
 S  
 H  
 I  
 P  
 T  
 O

SHIP VIA		SLSM.	B/L NO.	TERMS	F.O.B.	
		9105		CASH	GLENDALE, WI	
QBD	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET
1	1	0	68143657AA	FENDER-FRONT	348.50	342.00
1	1	0	68422069AA	SPO. HEADLAMP-HE	1120.00	1120.00
1	1	0	1WZ18TZZAE	FASCIA-FRONT	598.40	587.00
			CORE DEPOSIT		100.00	100.00
1	1	0	68145477AA	HOSE-WASHER	33.43	16.00
1	1	0	68248759AA	RESERVOIR-W	207.27	147.00
			***** INVOICE QUOTE	DO NOT PAY	*****	
DISCLAIMER OF WARRANTY: ALL PARTS AND ACCESSORIES ARE SOLD BY THE DEALERSHIP AS-IS. ANY WARRANTIES ON THE PARTS OR PRODUCTS DESCRIBED ABOVE ARE THOSE OF THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS OR PRODUCTS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WITH RESPECT TO THE SAME. THE DEALERSHIP NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PARTS OR PRODUCTS. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. THIS DISCLAIMER IN NO WAY AFFECTS THE PROVISIONS OF ANY MANUFACTURER OR DISTRIBUTOR WARRANTIES.						
				PARTS	2312.00	
				SUBLET		
				FREIGHT	0.00	
				SALES TAX	136.41	
				TOTAL	\$2,448.41	

Nuno's Auto Body  
9209 W Fond Du Lac Ave  
Milwaukee, WI 53225  
Phone: 414-353-1333  
E-mail: nunosauto@gmail.com

\*\*\* PRELIMINARY ESTIMATE \*\*\*

02/05/2024 01:38 PM

Owner

Owner: DANIEL MCCLAIN

Inspection

Inspection Date: 02/05/2024 01:00 PM  
Primary Impact: Front  
Driveable: Yes

Inspection Type: Drive In  
Secondary Impact: Left Front Corner  
Rental Assisted:

Company: NUNO'S AUTO BODY  
Contact: Roxanne J Romo  
Address: 9209 W FOND DU LAC AVE  
City State Zip: Milwaukee, WI 53225  
Email: NUNOSAUTO@GMAIL.COM

Appraiser License #2 :

Work/Day: (414)353-1333  
FAX: (414)353-1335

Repairer

Target Complete Date/Time:

Days To Repair: 5

Vehicle

2015 Chrysler 200 S 4 DR Sedan  
6cyl Gasoline 3.6  
9-Speed Automatic

Lic Expire:  
Veh Insp#:  
Condition:  
Ext. Refinish: Two-Stage

VIN: 1C3CCCBG5FN518427  
Mileage Type: Actual  
Code: M1614C  
Int. Refinish:

Options

1st Row LCD Monitor(s)	2nd Row Head Airbags	AM/FM Stereo
Active Grille Shutter	Air Conditioning	Alarm System
Aluminum/Alloy Wheels	Anti-Lock Brakes	Auto Headlamp Control
Auxiliary Audio Input	Black Grille	Carpeting
Center Console	Color-Keyed Bumper(s)	Compact Spare Tire
Cruise Control	Digital Clock	Driver Information Sys
Dual Airbags	Elect. Stability Control	Electronic Compass
Floor Mats	Fog Lights	Ground Effects Package
Halogen Headlights	Head Airbags	Heated Power Mirrors
Intermittent Wipers	Keyless Access System	Keyless Entry System
Keyless Ignition System	Knee Air Bags	LED Brakelights
Leather Steering Wheel	Lighted Entry System	MP3 Decoder
Manual Lumbar Adjustment	Overhead Console	Perimeter Alarm System
Power Brakes	Power Door Locks	Power Drivers Seat
Power Steering	Power Windows	Pwr Accessory Outlet(s)

Pwr Driver Lumbar Supp	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	SiriusXM Satellite Radio	Split Folding Rear Seat
Sport Seats	Sport Suspension	Stability Cntrl Suspensn
Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Touch Screen Display	Traction Control System	Trip Computer
Velour/Cloth Seats	Wireless Audio Streaming	Wireless Phone Connect

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R	
<b>Front Bumper</b>											
1	E	6		Cover,Front Bumper	1WZ18TZZAE	\$587.00			3.9	SM	
2	L	6	13	Cover,Front Bumper	Refinish 2.6 Surface 0.6 Two-stage setup 0.5 Two-stage				3.7	RF	
3	E	63		Brkt,Front Bumper Mtg LT	68103181AC	\$21.00				INC SM	
<b>Front End Panel And Lamps</b>											
4	E	48	02	Headlamp Assy, Halogen LT	68285846AB	\$1,120.00*				INC SM	
<b>Cooling And Air Conditioning</b>											
5	E	149		Reservoir,W/S Washer	68248759AA	\$147.00			0.5	SM	
6	E	150		Hose,W/S Washer	68145477AA	\$16.00			0.2	SM	
<b>Front Body And Windshield</b>											
7	BR	83	10	Panel,Hood Aluminum	Blend Refinish 1.3 Blend 0.6 Two-stage				1.9*	RF	
8	E	103		Fender,Front LT High Strength Steel	68143657AA	\$342.00			1.7	SM	
9	L	103		Fender,Front LT	Refinish 1.9 Surface 0.5 Edge 0.4 Two-stage				2.8	RF	
<b>Front Doors</b>											
10	BR	207		Door Shell,Front LT	Blend Refinish 0.9 Blend 0.4 Two-stage				1.3	RF	
10	<b>Items</b>										
		MC	<b>Message</b>								
		02	PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO.								
		10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL								
		13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE								

**Estimate Total & Entries**

OEM Parts			\$2,233.00
Paint & Materials		9.7 Hours @ \$47.00	\$455.90
Parts & Material Total			\$2,688.90
Tax on Parts & Material		@ 5.600%	\$150.58

Labor	Rate	Repair Hrs	Total Hrs

	Replace Hrs			
Sheet Metal (SM)	\$67.00	6.3	6.3	\$422.10
Mech/Elec (ME)	\$102.00			
Frame (FR)	\$89.00			
Refinish (RF)	\$67.00	9.7	9.7	\$649.90
<b>Labor Total</b>		16.0 Hours		\$1,072.00
<b>Gross Total</b>				\$3,911.48
<b>Net Total</b>				\$3,911.48

Alternate Parts Y/05/00/00/05/05 Cumulative 05/00/00/05/05 Zip Code: 53225 Default  
Rate Name Default

Audatex Estimating 10.25.86 ES 02/05/2024 01:50 PM REL 10.25.86 DT 01/01/2024 DB 02/01/2024

State Disclosure: Not Selected

© 2024 Audatex North America, LLC.

A 50% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate.  
2.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

#### Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PNX OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PNX
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PNX Reiman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PNX Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage

SCLERA Audatex

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2024 Audatex North America, LLC.  
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.