


Claimant: Daniel McClain
Address: 10242 W Fountain Ave
Milwaukee, WI 53224
Phone Number: 414-366-2575
Date of Incident: 01/16/2024
Time: 12:00am – 1:30pm
Location of the incident: 3160 N 28th Street

OFFICE OF MILWAUKEE
2024 FEB 22 PM 2:34
CITY CLERK'S OFFICE

To whom it may concern:

I arrived from work at 12am on Tuesday, January 16, 2024. Parked my White, 2015 Chrysler 200 on the east or even side of the street in front of 3160 N 28th Street. I was headed to work later that day at 1:30pm 1:30 pm when I observed my car was seriously damaged. It was pushed against a snowbank, the driver side head light broken, glass on the ground, fender bent, and bumper cracked/destroyed from the impact. Fluids from the car were also leaking onto the street. While inspecting my car the neighbor came outside, indicated she heard the collision, looked outside and witnessed the plow truck quickly leaving the scene.

The damage resulted from the negligence of a City of Milwaukee employee. I am requesting reimbursement for cost of damages totaling \$6,359.89 which includes cost for parts and labor.




Claimant Signature:

Date: ~~01/16/2024~~

Date:

2-20-24

Witness Name:


Phone: 414-213-7965

Date:

OFFICE OF CITY ATTORNEY
28 FEB '24 AM 08:15

TO FILE A CLAIM WITH THE CITY OF MILWAUKEE:

You will need the following information:

- X DATE of Incident 1/15/24
- X "City" Vehicle Number 3160 N 284th St

JOHN AMATO CHRYSLER DODGE JEEP RAM

X

RECEIVED BY

OFFICE COPY

5900 N. Green Bay Ave.
 Glendale, WI 53209
 (414) 410-3535
 www.amatoauto.com

RETURN/REFUND POLICY: ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE AND ARE SUBJECT TO A 20% RESTOCKING CHARGE. RETURNED ITEMS MUST BE IN THE ORIGINAL UNOPENED BOX OR CONTAINER. PLEASE NOTE THAT THE DEALERSHIP WILL NOT ACCEPT RETURNS OR MAKE REFUNDS AFTER 30 DAYS. NO REFUNDS OR RETURNS ON SPECIAL ORDER PARTS OR ELECTRICAL PARTS.

DATE ENTERED 05 FEB 24	YOUR ORDER NO. RN518427	DATE SHIPPED 05 FEB 24	INVOICE DATE	INVOICE NUMBER 30907
---------------------------	----------------------------	---------------------------	--------------	-------------------------

**** I N V O I C E Q U O T E - DO NOT PAY ****

PAGE 1 OF 1

S
O
L
D
T
O

CASH

S
H
I
P
T
O

ACCOUNT NO. P10

SHIP VIA		SLSM.	B/L NO.	TERMS	F.O.B.		
		9105		CASH	GLENDALE, WI		
QTY	SHIP	P.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	68143657AA	FENDER-FRON	348.50	342.00	342.00
1	1	0	68422069AA	SPO HEADLAMP-HE	1120.00	1120.00	1120.00
1	1	0	1WZ18TZZAE	FASCIA-FRON	598.40	587.00	587.00
			CORE DEPOSIT			100.00	100.00
1	1	0	68145477AA	HOSE-WASHER	33.43	16.00	16.00
1	1	0	68248759AA	RESERVOIR-W	207.27	147.00	147.00
**** I N V O I C E Q U O T E -					DO NOT	PAY ****	
DISCLAIMER OF WARRANTY: ALL PARTS AND ACCESSORIES ARE SOLD BY THE DEALERSHIP AS-IS. ANY WARRANTIES ON THE PARTS OR PRODUCTS DESCRIBED ABOVE ARE THOSE OF THE MANUFACTURER OR DISTRIBUTOR OF THE PARTS OR PRODUCTS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WITH RESPECT TO THE SAME. THE DEALERSHIP NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PARTS OR PRODUCTS. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. THIS DISCLAIMER IN NO WAY AFFECTS THE PROVISIONS OF ANY MANUFACTURER OR DISTRIBUTOR WARRANTIES.							
PARTS							2312.00
SUBLET							
FREIGHT							0.00
SALES TAX							136.41
TOTAL							\$2,448.41

Nuno's Auto Body
9209 W Fond Du Lac Ave
Milwaukee, WI 53225
Phone: 414-353-1333
E-mail: nunosauto@gmail.com

*** PRELIMINARY ESTIMATE ***

02/05/2024 01:38 PM

Owner

Owner: DANIEL MCCLAIN

Inspection

Inspection Date: 02/05/2024 01:00 PM
Primary Impact: Front
Driveable: Yes

Inspection Type: Drive In
Secondary Impact: Left Front Corner
Rental Assisted:

Company: NUNO'S AUTO BODY
Contact: Roxanne J Romo
Address: 9209 W FOND DU LAC AVE
City State Zip: Milwaukee, WI 53225
Email: NUNOSAUTO@GMAIL.COM

Appraiser License #2 :

Work/Day: (414)353-1333
FAX: (414)353-1335

Repairer

Target Complete Date/Time:

Days To Repair: 5

Vehicle

2015 Chrysler 200 S 4 DR Sedan
6cyl Gasoline 3.6
9-Speed Automatic

Lic Expire:
Veh Insp#:
Condition:
Ext. Refinish: Two-Stage

VIN: 1C3CCCBG5FN518427
Mileage Type: Actual
Code: M1614C
Int. Refinish:

Options

1st Row LCD Monitor(s)
Active Grille Shutter
Aluminum/Alloy Wheels
Auxiliary Audio Input
Center Console
Cruise Control
Dual Airbags
Floor Mats
Halogen Headlights
Intermittent Wipers
Keyless Ignition System
Leather Steering Wheel
Manual Lumbar Adjustment
Power Brakes
Power Steering

2nd Row Head Airbags
Air Conditioning
Anti-Lock Brakes
Black Grille
Color-Keyed Bumper(s)
Digital Clock
Elect. Stability Control
Fog Lights
Head Airbags
Keyless Access System
Knee Air Bags
Lighted Entry System
Overhead Console
Power Door Locks
Power Windows

AM/FM Stereo
Alarm System
Auto Headlamp Control
Carpeting
Compact Spare Tire
Driver Information Sys
Electronic Compass
Ground Effects Package
Heated Power Mirrors
Keyless Entry System
LED Brakelights
MP3 Decoder
Perimeter Alarm System
Power Drivers Seat
Pwr Accessory Outlet(s)

Pwr Driver Lumbar Supp	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	SiriusXM Satellite Radio	Split Folding Rear Seat
Sport Seats	Sport Suspension	Stability Cntrl Suspensn
Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Touch Screen Display	Traction Control System	Trip Computer
Velour/Cloth Seats	Wireless Audio Streaming	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Front Bumper									
1	E	6		Cover,Front Bumper	1WZ18TZAE	\$587.00		3.9	SM
2	L	6	13	Cover,Front Bumper	Refinish			3.7	RF
					2.6 Surface				
					0.6 Two-stage setup				
					0.5 Two-stage				
3	E	63		Brkt,Front Bumper Mtg LT	68103181AC	\$21.00		INC	SM
Front End Panel And Lamps									
4	E	48	02	Headlamp Assy,Halogen LT	68285846AB	\$1,120.00*		INC	SM
Cooling And Air Conditioning									
5	E	149		Reservoir,W/S Washer	68248759AA	\$147.00		0.5	SM
6	E	150		Hose,W/S Washer	68145477AA	\$16.00		0.2	SM
Front Body And Windshield									
7	BR	83	10	Panel,Hood Aluminum	Blend Refinish			1.9*	RF
					1.3 Blend				
					0.6 Two-stage				
8	E	103		Fender,Front LT High Strength Steel	68143657AA	\$342.00		1.7	SM
9	L	103		Fender,Front LT	Refinish			2.8	RF
					1.9 Surface				
					0.5 Edge				
					0.4 Two-stage				
Front Doors									
10	BR	207		Door Shell,Front LT	Blend Refinish			1.3	RF
					0.9 Blend				
					0.4 Two-stage				
10	Items								
			MC	Message					
			02	PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO.					
			10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL					
			13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE					

Estimate Total & Entries

OEM Parts		\$2,233.00	
Paint & Materials	9.7 Hours @ \$47.00	\$455.90	
Parts & Material Total			\$2,688.90
Tax on Parts & Material	@ 5.600%		\$150.58
Labor	Rate	Repair Hrs	Total Hrs

		Replace Hrs		
Sheet Metal (SM)	\$67.00	6.3	6.3	\$422.10
Mech/Elec (ME)	\$102.00			
Frame (FR)	\$89.00			
Refinish (RF)	\$67.00	9.7	9.7	\$649.90
Labor Total			16.0 Hours	\$1,072.00
Gross Total				\$3,911.48
Net Total				\$3,911.48


Alternate Parts Y/05/00/00/05/05 Cumulative 05/00/00/05/05 Zip Code: 53225 Default
Rate Name Default

Audatex Estimating 10.25.86 ES 02/05/2024 01:50 PM REL 10.25.86 DT 01/01/2024 DB 02/01/2024
State Disclosure: Not Selected
© 2024 Audatex North America, LLC.

A 50% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate.
2.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Rebtl
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2024 Audatex North America, LLC.
AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.