

To Whom it may concern:

My name is RONALD D. JONES and I am appealing the decision made by the City Attorney and the Investigator Adjuster regarding claim # 11-S-178. I am requesting a hearing from the City of Milwaukee to find out why my vehicle went in one way and came out damaged

Sincerely, RONALD JONES  
November 3, 2011

Attention: Milwaukee City Clerk  
Room # 205

CITY OF MILWAUKEE CITY OF MILWAUKEE  
RECEIVED  
2011 NOV -4 PM 1:27 / NOV -4 PM 3:25  
RONALD D. LEONHARDT OFFICE OF  
CITY CLERK CITY ATTORNEY

Claim # 11-5-178  
(414) 234-7052  
8011 West Berleigh St  
Apt #2

Attention: Claims  
Reason, Estimates  
#(414) 286-3456



1621 W. LaSalle St.  
Milwaukee, WI 53209

**Justin Rupp**  
Assistant Bodyshop Manager/Estimator

Phone: (414) 540-2559  
Fax: (414) 228-7420

CITY OF MILWAUKEE  
RECEIVED  
2011 OCT 12 PM 12:36  
OFFICE OF  
CITY ATTORNEY

CITY OF MILWAUKEE  
2011 OCT 10 AM 7:36  
RONALD D. LEONHARDT  
CITY CLERK

1621 W. LA SALLE ST.  
MILWAUKEE, WI 53209  
PH: 414-540-2559 FX: 414-228-7420

CD LOG NO 34407-1 DATE 10/06/11

SHOP: ANDREW AUTO BODY REPAIR INSP DATE: 10/06/11  
ADDRESS: 1621 W. LASALLE ST. CONTACT: RUPP  
CITY STATE: GLENDALE, WI PHONE 1: (414) 540-2559  
ZIP: 53209- FAX: (414) 228-7420

OWNER:

POINT OF IMPACT: 0

LIC#: STATE: VIN:  
BODY COLOR: MILEAGE:  
CONDITION: ACCTNG CTL#:

CITY OF MILWAUKEE  
RECEIVED  
2011 OCT 12 PM 12:36  
OFFICE OF  
CITY ATTORNEY

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1995 CHEVROLET SUBURBAN C15 LT 4DOOR WAGON 8CYL GASOLINE 5.7  
CODE: U7142A/D OPTNS K/24GHYUJQFV

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
ELEC REMOTE CONTROL MIRRORS	POWER DOOR LOCKS
POWER WINDOWS	LUGGAGE RACK
PRIVACY GLASS	TILT STEERING WHEEL
FRT AND REAR AIR CONDITIONING	CRUISE CONTROL
OVERHEAD CONSOLE	

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS
E	0120	02	MLDG, WHEEL OPENING	LT 15546447 GM PART	31.11			0.3*
E	0107		FLARE, WHEEL OPENING	LT 15723501 GM PART	290.60			3.0
L	0107	13	FLARE, WHEEL OPENING	LT REFINISH				1.4
				0.7 SURFACE				
				0.6 TWO STAGE SETUP				
				0.1 TWO STAGE				
EC			BUG GUARD, HOOD	ECONOMY PART	125.00*			1.0*
			4 ITEMS					

MC MESSAGE(S)  
02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO  
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS				321.71
OTHER PARTS				125.00
PAINT MATERIAL				42.00
PARTS & MATERIAL TOTAL				488.71
TAX ON PARTS & MATERIAL @			5.600%	27.37
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	52.00	4.3		223.60
2-MECH/ELEC	102.00			
3-FRAME	52.00			
4-REFINISH	52.00	1.4		72.80
5-PAINT MATERIAL	30.00			
LABOR TOTAL				296.40
TAX ON LABOR		@	5.600%	16.60
SUBLET REPAIRS				
TOWING				
STORAGE				
GROSS TOTAL				829.08
NET TOTAL				829.08

SHOPLINK UG202 ES CD LOG 34407-1 DATE 10/06/11 10:12:22AM R6.37 CD 09/11  
 PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53209

HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

0.7 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

-----

My name is Gerardo Lopez the owner of a 1995 Chevy Suburban LS truck

I went to pick my truck up from the City towing lot because it had previously been towed. Since I didn't have my vehicle insured at the time I was informed that I had to pay a towing company to tow it off the premises. When the driver brought my car out from the towing lot I noticed that the front quarter panel on my truck was dented. I immediately went back to the cashier and informed her of the damage and she informed me to start this process. I am asking to be immediately compensated for the destruction of my vehicle

Gerardo Lopez

CITY OF MILWAUKEE  
RECEIVED

2011 JUN 23 PM 3:39

OFFICE OF  
CITY ATTORNEY

RONALD D. LEONHARDT  
CITY CLERK

2011 JUN 23 AM 9:13

CITY OF MILWAUKEE

Gerald

CITY USE ONLY		CUSTOMER INFORMATION	
TOW #:	1497018	NAME:	BARBARO SOKOS
DATE:	5/25/11	ADDRESS:	2011 West Burleigh St. #2
CLERK ID:	65	PHONE #:	(414) 234-7052

PHOTOS TAKEN  YES  NO  
 PHOTOS ATTACHED  YES  NO  
 ALL FORMS COMPLETED  YES  NO

DATE FILED: May 27, 2011

\*\*\*Complaint must be signed by citizen completing form.

**CITIZEN'S STATEMENT**

My driver side front panel has been dented by grill.

CITY OF MILWAUKEE  
 RECEIVED  
 OFFICE OF  
 CITY ATTORNEY  
 JUN 23 PM 3:39


*Barbaro Sokos*  
 \*\*\*SIGNATURE

May 27, 2011  
 DATE

-OVER-


FRONT

BACK




Dented IN

DRIVER'S SIDE



PASSENGER'S SIDE



File a claim for \*DAMAGE TO or THEFT FROM\* your vehicle, Write a detailed letter and send to:

CITY CLERK'S OFFICE,  
200 EAST WELLS STREET  
CITY HALL, ROOM 205  
MILWAUKEE, WI 53202  
414-286-2221

286-3456 Fax

**FOR USE ONLY**

**INVESTIGATION RESULTS**

ROUTE TO:  D. LAWRENCE  L. BLACK  RETURN TO LINDA

NATURE:

DATE: