

May 18, 2019

Milwaukee City Clerk
200 East Wells St.
Room 205
Milwaukee, WI 53202

CITY OF MILWAUKEE

2019 MAY 21 P 3:50

CITY CLERK'S OFFICE


Jeffrey Sell
N7648 Burns Rd.
Beaver Dam WI 53916
920 392 4586

RE: C.I. File No. 1030-2019-642

To whom it may concern,

I am requesting a hearing to appeal the denial of this claim.

Sincerely,



Jeffrey Sell

RECEIVED
OFFICE OF CITY ATTORNEY

MAY 22 2019

4:15 A.M./P.M.


Jeffrey Sell
N7648 Burns Rd
Beaver Dam, WI 53916-8801

CITY OF MILWAUKEE

2019 MAY 21 P 3:49

CITY GLENN COURAGE

MILWAUKEE WI 530

2019 MAY 20 09 PM 5:1



Milwaukee City Clerk
200 East Wells St, Rm 205,
Milwaukee WI 53203


53202-357099



CITY OF MILWAUKEE
Office of the City Attorney
OFFICE OF THE CITY ATTORNEY
800 City Hall
200 East Wells Street
Milwaukee, Wisconsin 53202-9551

Jeffrey Sell
N7648 Burns Road
Beaver Dam, WI 53916

PRESORTED
FIRST CLASS



U.S. POSTAGE PITNEY BOWES
ZIP 53005 \$ 000.38³
02 4W
0000337158 APR 29 2019

020-550 53916



CITY OF MILWAUKEE

Notice of claim to the City of Milwaukee

2019 MAR 27 P 2:12

March 5 2019

CITY CLERK'S OFFICE

RECEIVED
OFFICE OF CITY ATTORNEY

MAR 27 2019

3:35 A.M./P.M.

City Clerk
200 E. Wells St
Milwaukee, WI
53202-3567

Olivia Sell
2935 Downer St
Milwaukee WI
Phone: 920 820 0003

While my car was parked in front of my apartment on the street located at the above address it was plowed in with snow on around 02/12/2019. My car, a black 2008 Milan was parked in that spot since Sunday Feb. 10th. It wasn't until I first started shoveling it out on Thursday the 14th did I notice the damage. This car is owned by my dad, Jeffrey Sell. I contacted him and started a claim with the city on Feb. 15. The insurance company American Family won't cover this damage. This vehicles coverage is limited to Liability and Comprehensive only, no collision coverage is in the policy.

Enclosed with this letter are two body shop estimates one for \$2170.30 and one for \$1874.95.

My father and I are requesting a sum of \$1874.95 to be payed to him or to Heiser 76th Street Body Shop to repair the car. His information is below.

Thank you,
Olivia Sell

Olivia Sell

date
3-25-19

Jeffrey Sell (owner)

Jeffrey Sell

date
3-25-19

Jeffrey Sell
N7648 Burns Rd
Beaver Dam WI 53916
Phone: 920 392 4586

Heiser 76th Street Body Shop
7800 NORTH 76TH STREET
MILWAUKEE, WI 53223
PHONE: (414)357-2121 FAX: (414)357-2133

MAR 27 2019

3:35 AM
A.M.P.M.

*** PRELIMINARY ESTIMATE ***

02/28/2019 10:42 AM

Owner

Owner: JEFF SELL
Address: N7648 BURNS ROAD
City State Zip: Beaver Dam, WI 53916

Work/Day: (920)392-4586
FAX:

Inspection

Inspection Date: 02/28/2019 10:42 AM
Inspection Location: 76TH ST BODY SHOP
Address: 7800 N. 76TH ST

City State Zip: MILWAUKEE, WI 53223

Appraiser Name: TOM HUEBNER

Inspection Type:
Contact: LE PINE
Work/Day: (414)357-2121x
Home/Evening: (414)586-7000x
FAX: (414)357-2133x

Appraiser License #:

Repairer

Repairer: 76TH ST BODY SHOP
Address: 7800 N. 76TH ST

City State Zip: MILWAUKEE, WI 53223

Contact: LE PINE
Work/Day: (414)357-2121
Home/Evening: (414)586-7000
FAX: (414)357-2133

Target Complete Date/Time:

Days To Repair: 7

Vehicle

OEM Part Price Quote ID: ****

2008 Mercury Milan V6 Premier 4 DR Sedan
6cyl Gasoline 3.0
6-Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 3MEHM08188R606192
Mileage Type: Actual
Code: R3443D
Int. Refinish: Two-Stage

Options

2nd Row Head Airbags
Alarm System
Auto Headlamp Control
Bodyside Moldings
Climate Control For A/C
Driver Information Sys
Floor Mats
Head Airbags
Intermittent Wipers
LED Brakelights
Lighted Entry System

AM/FM In-dash CD Changer
Aluminum/Alloy Wheels
Automatic Dimming Mirror
Bucket Seats
Compact Spare Tire
Dual Airbags
Fog Lights
Heated Power Mirrors
Keyless Entry Keypad
Leather Seats
MP3 Decoder

Air Conditioning
Anti-Lock Brakes
Auxiliary Audio Input
Center Console
Cruise Control
Electronic Compass
Halogen Headlights
Illuminated Visor Mirror
Keyless Entry System
Leather Steering Wheel
Overhead Console

Power Brakes	Power Door Locks	Power Drivers Seat
Power Steering	Power Windows	Pwr Accessory Outlet(s)
Rear Window Defroster	Rem Trunk-L/Gate Release	Side Airbags
Side Mirror Lighting	Split Folding Rear Seat	Strg Wheel Radio Control
Tachometer	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trip Computer	USB Audio Input(s)	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Stripes And Mouldings									
1	RI	1044		Deflector,Rocker Panel LT	R & I Assembly			0.4	SM
Quarter And Rocker Panel									
2	I	389		Panel,Quarter LT	Repair			9.0*	SM
3	L	389	13	Panel,Quarter LT	Refinish			3.7	RF
					2.6 Surface				
					0.6 Two-stage setup				
					0.5 Two-stage				
4	BR	429		Door,Fuel Filler LT	Blend Refinish			0.2	RF
					0.1 Blend				
					0.1 Two-stage				
5	RI	429		Door,Fuel Filler LT	R & I Assembly			0.3	SM
Inner Quarter & Panels									
6	RI	241		Shield,Quarter Panel LT	R & I Assembly			0.2	SM
Rear Bumper									
7	N	565		Rear Bumper Cover R&I	Additional Labor			INC	SM
8	I	565		Cover,Rear Bumper	Repair			1.5*	SM
9	L	565		Cover,Rear Bumper	Refinish			3.1	RF
					2.6 Surface				
					0.5 Two-stage				
10	E	545		Supt,Rr Bumper Cover LT	6N7Z17D995A	\$39.52		1.3	SM
Manual Entries									
11	N			HAZARD. WSTE. REM.	Additional Labor	\$5.00*			SM
12	N			CORROSION PROTECTION	Additional Labor	\$10.00*		0.3*	SM
13	N			FLEX ADDITIVE	Additional Labor	\$5.00*			RF
14	N			TIE DOWN	Additional Labor			1.0*	SM*
15	I			ROUGH PULL	Repair			1.0*	SM*
15	Items								

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts			
Other Parts		\$39.52	
Paint & Materials		\$20.00	
Parts & Material Total	7.0 Hours @ \$44.00	\$308.00	
Tax on Parts & Material	@ 5.600%		\$367.52
			\$20.58

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs
-------	------	-------------	------------	-----------

Sheet Metal (SM)	\$64.00	2.2	12.8	15.0	\$960.00
Mech/Elec (ME)	\$105.00				
Frame (FR)	\$80.00				
Refinish (RF)	\$64.00	7.0		7.0	\$448.00
Labor Total				22.0 Hours	\$1,408.00
Tax on Labor		@ 5.600%			\$78.85
Gross Total					\$1,874.95
Net Total					\$1,874.95

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53223 default
OEM Part Prices DT 02/28/2019 10:42 AM EstimateID 530425820448038912 QuoteID ****
Rate Name Default


Audatex Estimating 8.0.555 ES 02/28/2019 10:44 AM REL 8.0.555 DT 01/01/2019 DB 02/15/2019
© 2019 Audatex North America, Inc.

1.7 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.


Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chippguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2019 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



PRESTIGE AUTO WORKS AND FINISHES INC
6301 W DOUGLAS AVENUE
MILWAUKEE, WI. 53218
PHONE 414-466-2111 FAX 414-466-9992
FEDERAL ID# 39-1661-727

MAR 27 2019

3:35 A.M./P.M.

*** PRELIMINARY ESTIMATE ***

02/28/2019 11:27 AM

Owner

Owner: JEFF SELL
Address: N7648 BURNS RD
City State Zip: Beaver Dam, WI 53916

Work/Day: (920)392-4586
FAX:

Inspection

Inspection Date: 02/28/2019 11:29 AM
Primary Impact: Left Rear Side

Inspection Type:
Secondary Impact:

Appraiser Name: DAVID GASSNER

Appraiser License # :

Repairer

Repairer: PRESTIGE
Address: 6301 W DOUGLAS AVE
City State Zip: Milwaukee, WI 53218

Contact:
Work/Day: (414)466-2111
FAX: (414)466-9992
Work/Day:

Remarks

ADDITIONAL DAMAGE POSSIBLE AFTER TEAR DOWN

Vehicle

OEM Part Price Quote ID: ****

2008 Mercury Milan V6 Premier 4 DR Sedan
6cyl Gasoline 3.0
6-Speed Automatic

Lic. Plate: ADJ2861
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: EBONY
Ext. Refinish: Two-Stage
Ext. Paint Code: M6373A,UA

Lic State: WI
VIN: 3MEHM08188R606192
Mileage: 114,863
Mileage Type: Actual
Code: R3443D
Int. Color:
Int. Refinish: Two-Stage
Int. Trim Code:

Options

2nd Row Head Airbags	AM/FM In-dash CD Changer	Air Conditioning
Alarm System	Aluminum/Alloy Wheels	Anti-Lock Brakes
Auto Headlamp Control	Automatic Dimming Mirror	Auxiliary Audio Input
Bodyside Moldings	Bucket Seats	Center Console
Climate Control For A/C	Compact Spare Tire	Cruise Control
Driver Information Sys	Dual Airbags	Electronic Compass

Floor Mats	Fog Lights	Halogen Headlights
Head Airbags	Heated Power Mirrors	Illuminated Visor Mirror
Intermittent Wipers	Keyless Entry Keypad	Keyless Entry System
LED Brakelights	Leather Seats	Leather Steering Wheel
Lighted Entry System	MP3 Decoder	Overhead Console
Power Brakes	Power Door Locks	Power Drivers Seat
Power Steering	Power Windows	Pwr Accessory Outlet(s)
Rear Window Defroster	Rem Trunk-L/Gate Release	Side Airbags
Side Mirror Lighting	Split Folding Rear Seat	Strg Wheel Radio Control
Tachometer	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trip Computer	USB Audio Input(s)	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Roof										
1	RI	354		Mldg,Roof Drip LT	R & I Assembly				0.3	SM
Quarter And Rocker Panel										
2	BR	130	13	Panel,Bodyside Otr Upr LT	Blend Refinish 0.8 Blend 0.6 Two-stage setup 0.4 Two-stage				1.8	RF
3	I	389		Panel,Quarter LT	Repair				8.0*	SM
4	L	389		Panel,Quarter LT	Refinish 2.4 Surface 0.5 Two-stage				2.9	RF
5	BR	429		Door,Fuel Filler LT	Blend Refinish 0.1 Blend 0.1 Two-stage				0.2	RF
6	RI	429		Door,Fuel Filler LT	R & I Assembly				0.3	SM
Rear Bumper										
7	N	571		Rr Bumper Cvr Overhaul	Additional Labor				2.2	SM
8	I	565		Cover,Rear Bumper	Repair				2.5*	SM
9	L	565		Cover,Rear Bumper	Refinish 2.6 Surface 0.5 Two-stage				3.1	RF
Rear Body, Lamps And Floor Pan										
10	RI	481		Taillamp Assembly,Otr LT	R & I Assembly				INC	SM
Manual Entries										
11	N			BATTERY DISCONNECT	Additional Labor				0.3*	SM
12	N			RESET ELECTRONICS	Additional Labor				1.0*	ME*
13	L			CORROSION PROTECTIO	Refinish				0.5*	RF*
14	SB			HAZ MAT DISP	Sublet Repair	\$5.50*				SM
15	EC			CLIPS/FASTENERS	Replace Economy	\$18.50*				SM
16	L			COVER CAR	Refinish				0.3*	RF*
17	L			MASK JAMBS	Refinish				0.5*	RF*
18	L			FLEX	Refinish	\$12.50*				SM
19	L			FEATHER/PRIME/BLOCK	Refinish				0.5*	RF*
20	L			ROPE GLASS	Refinish				0.3*	RF*
20	Items									

MC Message

13

INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts							
Paint & Materials						\$31.00	
	10.1 Hours @	\$43.00				\$434.30	
Parts & Material Total							\$465.30
Tax on Parts & Material			@ 5.600%				\$26.06
Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs			
Sheet Metal (SM)	\$62.00	0.6	13.0	13.6	\$843.20		
Mech/Elec (ME)	\$115.00		1.0	1.0	\$115.00		
Frame (FR)	\$68.00						
Refinish (RF)	\$62.00	10.1		10.1	\$626.20		
Labor Total				24.7 Hours		\$1,584.40	
Tax on Labor			@ 5.600%		\$88.73		
Sublet Repairs					\$5.50		
Tax on Sublet			@ 5.600%		\$0.31		
Gross Total							\$2,170.30
Net Total							\$2,170.30

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53218 Default
 OEM Part Prices DT 02/28/2019 11:27 AM EstimateID 530437167239929856 QuoteID ****
 Recycled Parts NOT REQUESTED
 Rate Name Default

Audatex Estimating 8.0.643 ES 02/28/2019 11:33 AM REL 8.0.643 DT 02/01/2019 DB 02/15/2019
 © 2019 Audatex North America, Inc.

2.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2019 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

