

**Alex Banks**

3044 N 59 st.  
Milwaukee, Wisconsin 53210  
414-378-7839  
Alexbanks000@gmail.com

CITY OF MILWAUKEE  
2021 DEC 21 PM 3:31  
CITY CLERK'S OFFICE

21st December 2021

**City Clerk**

ATTN: Claims  
200 E. Wells St., Room 205  
Milwaukee, WI 53202-3567

To whom this may concern,

On November 21st 2021 it was a very windy evening in Milwaukee, Wisconsin. The powerful wind caused a street sign (speed bump warning sign) to fall out of the ground post located in the middle of the block on 59th st between Burleigh and Chambers which resulted in damages to my car. The sign fell leaving a dent and scratches on my front end of my vehicle. This letter is regarding reimbursement for the damages from the city/county of Milwaukee.

**Alex Banks**

A handwritten signature in black ink that reads "Alex Banks". The signature is stylized, with a large, sweeping "B" and a long horizontal line extending to the right.

OFFICE OF CITY ATTORNEY  
22 DEC '21 PM 02:17

**BRILYN AUTOBODY LLC**  
**1201 W LAYTON AV**  
**MILWAUKEE WI 53221**

Estimate #8168

Phone/Fax #: 414-281-7210  
 Email: brilynauto@outlook.com

Date: 12/21/21

Name	ALEX BANKS	Year-Make-Model	2017 HONDA CIVIC EX
Address	3044 N. 59 <sup>th</sup> ST		SEDAN
City-State-Zip	MILW 53210	License #	ADK-6414
Cell-Work Phone	(414) 378-7839	Color	NH788P-ORCHID WHITE PEARL
Insured By		VIN #	19XFC2F74HE040134
Claim #		Mileage	
Adjuster			
Adjuster Phone		Adjuster Fax	

Repair	Replace	Parts Necessary and Estimate of Labor Required	Parts and Labor	Body Labor 60.00/hr	Refinish Labor 60.00/hr
X		FRONT BUMPER COVER		1 5	1 5
		R. SIDE & RO1 COVER		1 6	
X		HOOD		2 5	2 8
X		R. FENDER		4 5	2 0
		<u>2 1/2 DAYS TO REPAIR</u>			
		THREE STAGE PEARL			1 0
		Hazardous Waste Removal/Car Cover	5 00		3
		Restore Corrosion Protection	5 00		1
		Tint and Blend			5
		Clear Coat			1 5
		Paint and Materials (38.00)	368 60		
		SUBTOTAL OF LABOR AND REFINISH HOURS		10 1	9 7
		SUBTOTAL		378 60	606 00
				TOTAL	
					1566 60
				5.5% SALES TAX	
					86 16
				GRAND TOTAL	
					1652 76

The above report is based on our inspection and does not cover additional parts or labor that may be required after the work has been opened up. Occasionally after the work has been started, damage or broken parts are discovered which are not evident on the first inspection. Because of this, above prices cannot be guaranteed. This estimate is for immediate acceptance only.

USED PART PRICES ARE SUBJECT TO CHANGE DUE TO AVAILABILITY.

SCHOK'S AUTO BODY  
5701 WEST BURLEIGH STREET  
MILWAUKEE, WI 53210  
PHONE: 414-873-9944 FAX: 414-873-5040  
FED TAX ID# 39-1330692

\*\*\* PRELIMINARY ESTIMATE \*\*\*

12/21/2021 12:52 PM

**Owner**

Owner: Alex Banks  
Address:

Work/Day: (414)378-7839

**Inspection**

Inspection Date: 12/21/2021 12:52 PM  
Primary Impact: Right Front Corner

Inspection Type:  
Secondary Impact:

Appraiser Name: Mary Kuhn  
Email: Schoksauto@Gmail.com

Appraiser License # :

**Repairer**

Target Complete Date/Time:

Days To Repair: 6

**Vehicle**

2017 Honda Civic EX 4 DR Sedan  
4cyl Gasoline 2.0  
Continuously Variable Tr

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Refinish: Three-Stage User Defined

VIN: 19XFC2F74HE040134  
Mileage Type: Actual  
Code: H0364C  
Int. Refinish: Two-Stage

**Options - AudaVIN Information Received**

1st Row LCD Monitor(s)  
Air Conditioning  
Anti-Lock Brakes  
Center Console  
Cruise Control  
Electric Steering  
Head Airbags  
Illuminated Visor Mirror  
Keyless Ignition System  
Power Brakes  
Power Trunk (open/close)  
Rear View Camera  
Side View Camera(s)  
Strg Wheel Radio Control  
Tire Pressure Monitor  
Velour/Cloth Seats

2nd Row Head Airbags  
Alarm System  
Bucket Seats  
Chrome Grille  
Daytime Running Lights  
Emergency S.O.S. System  
Heated Power Mirrors  
Intermittent Wipers  
Lighted Entry System  
Power Door Locks  
Power Windows  
Rear Window Defroster  
Sirius Satellite Radio  
Tilt & Telescopic Steer  
Traction Control System  
Wireless Audio Streaming

AM/FM CD Player  
Aluminum/Alloy Wheels  
C.V.T.  
Compact Spare Tire  
Dual Airbags  
Floor Mats  
Heated Wiper Park  
Keyless Entry System  
MP3 Decoder  
Power Moonroof  
Projector Beam Headlamps  
Side Airbags  
Split Folding Rear Seat  
Tinted Glass  
USB Audio Input(s)  
Wireless Phone Connect

**AudaVIN options are listed in bold-italic fonts**

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
<b>Front Bumper</b>										
1	RI	6		Front Bumper Cover R&I	R & I Assembly				1.0	SM
2	N	12		Frt Bumper Cvr Overhau	Additional Labor				1.0	SM
3	I	6		Cover,Front Bumper	Repair				0.5*	SM
4	L	6	#	Cover,Front Bumper	Refinish				2.5*	RF
					1.0 Surface					
					1.0 Three-stage setup					
					0.5 Three-stage					
				# = 10, 14						
				>> Blend R side						
<b>Front Body And Windshield</b>										
5	I	83		Panel,Hood	Repair				1.0*	SM
				High Strength Steel						
6	L	83		Panel,Hood	Refinish				4.1	RF
					3.0 Surface					
					1.1 Three-stage					
7	E	104	46	Fender,Front RT	60211TBAA00ZZ	\$119.96			2.4	SM
8	L	104		Fender,Front RT	Refinish				2.9	RF
					1.7 Surface					
					0.5 Edge					
					0.6 Three-stage					
					0.1 Two-stage					
<b>Front Doors</b>										
9	BR	208		Door Shell,Front RT	Blend Refinish				1.4	RF
					0.7 Blend					
					0.7 Three-stage					
10	RI	238		Mldg,Front Door Belt RT	R & I Assembly				0.2	SM
11	RI	228		Housing,Mirror Outer RT	R & I Assembly				0.7	SM
12	RI	1307		Supt,Frt Door Handle RT	R & I Assembly				0.2	SM
<b>Manual Entries</b>										
13	EC	M03		Flex Additive	Replace Economy	\$3.00*				RF
14	EC	M17		Cover Car Exterior	Replace Economy	\$5.00*			0.3*	RF
15	SB	M60		Hazardous Waste Removal	Sublet Repair	\$10.00*				SM
15	<b>Items</b>									

MC	Message
10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL
14	INCLUDES 1.0 HOURS FIRST PANEL THREE-STAGE ALLOWANCE
46	PRINTABLE ALTERNATE PARTS COMPARE

**Estimate Total & Entries**

<b>OEM Parts</b>		\$119.96	
<b>Other Parts</b>		\$8.00	
<b>Paint &amp; Materials</b>	11.2 Hours @ \$39.00	\$436.80	
<b>Parts &amp; Material Total</b>			\$564.76
<b>Tax on Parts &amp; Material</b>	@ 5.50%		\$31.06

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs
-------	------	-------------	------------	-----------

Sheet Metal (SM)	\$60.00	4.5	2.5	7.0	\$420.00
Mech/Elec (ME)	\$95.00				
Frame (FR)	\$75.00				
Refinish (RF)	\$60.00	11.2		11.2	\$672.00
<b>Labor Total</b>				18.2 Hours	\$1,092.00
Tax on Labor		@ 5.500%			\$60.06
Sublet Repairs					\$10.00
Tax on Sublet		@ 5.500%			\$0.55
<b>Gross Total</b>					<b>\$1,758.43</b>
<b>Net Total</b>					<b>\$1,758.43</b>

Alternate Parts Y/01/00/00/01/01 Cumulative 01/00/00/01/01 Zip Code: 53210 Default  
Rate Name Default

Audatex Estimating 8.1.325 Update 3 ES 12/21/2021 12:55 PM REL 8.1.325 Update 3 DT 12/01/2021 DB 12/15/2021  
State Disclosure:WI


© 2021 Audatex North America, Inc.

0.1 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.  
3.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S THREE-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

**Op Codes**

- |                            |   |                                |
|----------------------------|---|--------------------------------|
| * = User-Entered Value     | ^ = Labor Matches System Assigned Rates | E = Replace OEM                |
| NG = Replace NAGS          | EC = Replace Economy                    | OE = Replace PXN OE Srpls      |
| UE = Replace OE Surplus    | ET = Partial Replace Labor              | EP = Replace PXN               |
| EU = Replace Recycled      | TE = Partial Replace Price              | PM = Replace PXN Reman/Rebtl   |
| UM = Replace Reman/Rebuilt | L = Refinish                            | PC = Replace PXN Reconditioned |
| UC = Replace Reconditioned | TT = Two-Tone                           | SB = Sublet Repair             |
| N = Additional Labor       | BR = Blend Refinish                     | I = Repair                     |
| IT = Partial Repair        | CG = Chipguard                          | RI = R & I Assembly            |
| P = Check                  | AA = Appearance Allowance               | RP = Related Prior Damage      |



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2021 Audatex North America, Inc.  
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

