

3337 N SHERMAN BLVD REAR PORCH - SIDE VIEW

NOTE: LEDGER TO ATTACH DIRECTLY TO EXISTING WOOD WALL FRAMING, NOT BRICK VENEER. VERIFY EXISTING SUPPORT OF BRICK VENEER IN THE FIELD. PROVIDE FLASHING & CAULKING AFTER INSTALLATION.

