

27 September 2005
7513 West Florist Avenue
Milwaukee, WI 53218

To Milwaukee City Clerk:

I would like to appeal your decision. At this time I am requesting a hearing on the matter of damage sustained by my vehicle.

CLAIMANT
LEON WANZO

Very truly,



Leon Wanzo

840-7749

CITY OF MILWAUKEE
2005 OCT -5 PM 2:00
RONALD D. LEONHARDT
CITY CLERK

CITY OF MILWAUKEE
2005 OCT -5 PM 4:27
OFFICE OF
CITY ATTORNEY

City Clerk
ATTN: CLAIMS


Site of Incident:
7513 WEST FLORIST AVENUE
MILWAUKEE, WI 53218

On 7/20/05, between 7:15 A.M. and 7:30 A.M., I was backing out of my garage. Before I could react to the green garbage container that was placed right in back of the garage overhead door, it caught the side of my Nissan pick-up truck, causing two deep scratches. This is a constant thing with the Sanitation Dept. The green containers are placed in front of the overhead door, usually, but this time they were right against the overhead door.

Contact no.: 414-840-7749

Claimant:

LEON WANZO



CITY OF MILWAUKEE
RECEIVED
2005 AUG - 3 PM 3:32
OFFICE OF
CITY ATTORNEY

CITY OF MILWAUKEE
05 AUG - 3 PM 12:41
RONALD D. LEONHARDT
CITY CLERK

RUSS DARROW COLLISION CENTER
 7676 NORTH 76TH STREET
 MILWAUKEE WI 53224-9010
 PHONE (414) 362-7520 FAX (414) 355-6744
 MOBILE ESTIMATING (414) 587-9015 AT DEALERSHIPS

CD LOG NO 8415-1 DATE 08/02/05

SHOP: RUSS DARROW COLLISION CENTER INSP DATE: 08/02/05
 ADDRESS: 7676 NORTH 76TH STREET CONTACT: MARTIN REHFELDT
 CITY STATE: MILWAUKEE, WI PHONE 1: (414) 362-7520
 ZIP: 53223- PHONE 2: (414) 354-8338
 FAX: (414) 355-6744

OWNER: WANZO, LEON HOME PHONE: (414) 464-7888
 ADDRESS: 7513 W FLORIST AVE
 CITY STATE: MILWAUKEE, WI
 ZIP: 53218

POINT OF IMPACT: 11

TYPE OF LOSS: /DRV

DAYS TO REPAIR: 4

LIC#: 993976 STATE: WI VIN: 1N6AA07BX4N542155
 BODY COLOR: BLACK MILEAGE:
 CONDITION: GOOD ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

CUST WILL NEED RETAL CAR FOR APPROX. 4 DAYS.

2004 NISSAN TITAN LE 4DOOR EXT CAB 8CYL GASOLINE 5.6
 CODE: Z8103C/A OPTNS P/24ABFUHXYZPS

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
4-WHEEL DRIVE	BUMPER COVER MOUNTED FOG LAMPS
HEATED FRONT SEATS	HEATED REMOTE CONTROL MIRRORS
POWER DOOR LOCKS	POWER WINDOWS
PRIVACY GLASS	SLIDING BACK GLASS
OVERHEAD CONSOLE	STRG WHEEL MTD RADIO CONTROLS

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
---	---	---	-----	-----	-----	---	---	-----	---
I	0390		PANEL, BEDSIDE OUTER RT REPAIR					1.0	*1

L	0390	13	PANEL, BEDSIDE OUTER RT REFINISH				4.2	4
				3.0	SURFACE			
				0.6	TWO STAGE SETUP			
				0.6	TWO STAGE			
N	0975		BED ASSEMBLY, SET BACK	ADDNL	LABOR OPERA		2.0	1
RI	0406		GUARD, MUD	RT	R&I ASSEMBLY		0.2	1
RI	0534		TAILLAMP ASSEMBLY	RT	R&I ASSEMBLY		0.3	1
N	0571		REAR BUMPER ASSY R&I	ADDNL	LABOR OPERA		0.5	1
EC	M14		CORROSION PROTECTION	ECONOMY	PART	10.00*	0.2*1*	
EC	M17		COVER CAR EXTERIOR	ECONOMY	PART	5.00*		2*
SB	M60		HAZARD. WSTE. REM.	SUBLET	REPAIR	4.25*		1*
RI			CAP, BED	R&I	ASSEMBLY		1.0*1*	
E			DECAL, SIDE BODY	NEW	PART	18.55*	0.3*1*	
			PART #99098-7S200					

11 ITEMS

MC MESSAGE(S)
 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS		18.55
OTHER PARTS		15.00
PAINT MATERIAL		117.60
PARTS & MATERIAL TOTAL		151.15
TAX ON PARTS & MATERIAL @	5.600%	8.46

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	48.00	2.0	3.5	264.00
2-MECH/ELEC	89.95			
3-FRAME	48.00			
4-REFINISH	48.00	4.2		201.60
5-PAINT MATERIAL	28.00			
LABOR TOTAL				465.60
TAX ON LABOR		@	5.600%	26.07
SUBLET REPAIRS				4.25
TAX ON SUBLET		@	5.600%	0.24
TOWING				
STORAGE				

GROSS TOTAL 655.77
 NET TOTAL 655.77

ADP SHOPLINK U1732 ES CD LOG 8415-1 DATE 08/02/05 04:49:40PM R6.37 CD 07/05
 EDU: 0722 HOST LOG
 (C) 1998 - 2005 ADP CLAIMS SOLUTIONS GROUP, INC.

1.2 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.

2004 NISSAN TITAN LE 4DOOR EXT CAB
CD LOG NO 8415-1

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

NOTICE: WHEN SELECTING A REPAIR FACILITY, THE VEHICLE OWNER SHOULD CONSIDER THAT THE REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AND THE RESTORATION OF CORROSIVE RESISTANT COATINGS AS RECOMMENDED BY THE MANUFACTURE. FAILURE TO HAVE THE VEHICLE PROPERLY REPAIRED COULD RESULT IN A SAFETY HAZARD