

1060 E Juneau Window Restoration Project

Photos of Existing Windows






East side building facing south 2nd floor window

East side facing north 2nd floor


Diagram of Units to Be Repaired

NUMBERS 14, 15, 16, 17, and 18, plus One Transom on the West Side



RATION SCHEDULE PLAN - 2001

Photos of Existing Damaged Units



Location of Units on Building








Photo Of Existing Storm Windows (New will match these)

