

July 31, 2023

Our names are Javier & Carmen Pinales, we are Filling claims for the incident that happened on July 14, 2023 around 4:20pm, we both had our vehicles that day Parked in front of our home when it was struck by a huge bark branch and it made several damages to the cars. We are seeking for the city of Milwaukee to pay for those damages. 1 of 2 vehicles at this time is not driveable due to the severe of damage on it, the other car even though has damages it still could be driven. The following is the make & model of the vehicle: 2016 Toyota Camry (severe damaged, unable to drive right now) & 2009 Chevy Avalanche, this are the cars we are filling claims for. We have attached 2 different estimates for each car and the total cost to get them fixed.

Thank you in this matter, if you need further information don't hesitate to contact us at 414-600-8219.


Home Address: 2624 N. Booth St.

Milwaukee, WI 53212

Email Address: javierpinales@att.net.

Sincerely,

Carmen H. Pinales



CITY OF MILWAUKEE
CITY CLERK'S OFFICE
JUL 31 PM 2:47

OFFICE OF CITY ATTORNEY
01 AUG '23 AM 08:56

**ANDREW AUTOMOTIVE BODY
REPAIR CENTER**

1621 W. LaSalle St., MILWAUKEE, WI 53209
Phone: (414) 540-2559
FAX: (414) 228-7420

Workfile ID: 83e92f86
PartsShare: 7sXwpQ
Federal ID: 39-1764755
State EPA: WID988603379

Preliminary Estimate

Customer: PINALES, CARMAN

Job Number:

Written By: Dave Luedke

Insured: PINALES, CARMA
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:

PINALES, CARMAN
2624 N. BOOTH STREET
MILWAUKEE, WI 53212
(414) 630-8219 Business

Inspection Location:

ANDREW AUTOMOTIVE BODY REPAIR
CENTER
1621 W. LaSalle St.
MILWAUKEE, WI 53209
Repair Facility
(414) 540-2559 Business

Insurance Company:

UNKNOWN

VEHICLE

2016 TOYO Camry XLE Automatic 4D SED 4-2.5L Gasoline Sequential MPI GOLD

VIN: 4T1BF1FK9GU139046
License:
State:

Interior Color: BLACK
Exterior Color: GOLD
Production Date:

Mileage In: 151,633
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat

DECOR

Dual Mirrors
Tinted Glass
Console/Storage

Overhead Console

Wood Interior Trim

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Rear Side Impact Air Bags

SEATS

Bucket Seats
Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint
Metallic Paint

OTHER

Traction Control
Stability Control
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/4yMKJB

Preliminary Estimate

Customer: PINALES, CARMA

Job Number:

2016 TOYO Camry XLE Automatic 4D SED 4-2.5L Gasoline Sequential MPI GOLD

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	INFORMATION LABELS						
2	Repl	Emission label 2.5 liter, w/o LE Federal	112980V342	1	1.55	0.2	
3	FRONT BUMPER						
4		O/H front bumper				2.4	
5	<> Repl	Bumper cover	5211907912	1	235.83	Incl.	2.8
6		Add for Clear Coat					1.1
7	R&I	License bracket w/o sport mesh lower grille				0.2	
8	Repl	Prep unprimed bumper		1			0.7
9	FRONT LAMPS						
10	R&I	RT R&I headlamp assy				0.3	
11	R&I	LT R&I headlamp assy				0.3	
12	HOOD						
13	Repl	Hood	5330106160	1	563.90	1.8	3.0
14		Overlap Major Non-Adj. Panel					-0.2
15		Add for Clear Coat					0.6
16		Add for Underside(Complete)					1.5
17		Add for Clear Coat					0.3
18	#	CAULK HOOD		1	10.00	0.5	
19	FENDER						
20	Blnd	LT Fender					1.0
21	Blnd	RT Fender					1.0
22	R&I	RT Fender liner				0.4	
23	R&I	LT Fender liner				0.4	
24	WINDSHIELD						
25	Repl	Windshield Toyota, w/o precrash 2.5 liter	5610106540	1	786.74	Incl.	
26	R&I	Mirror inside w/o auto dimming				Incl.	
27	ROOF						
28	Repl	Roof panel	6311106440	1	861.51	19.5	2.8
29		Overlap Major Non-Adj. Panel					-0.2
30		Add for Clear Coat					0.5
31	Blnd	LT Outer rail					0.7
32	Blnd	RT Outer rail					0.7
33	R&I	RT Drip molding				Incl.	
34	R&I	LT Drip molding				Incl.	
35	R&I	R&I headliner				Incl.	
36	PILLARS, ROCKER & FLOOR						
37	* Rpr	LT Hinge pillar (HSS)			s	5.0	1.6
38	Repl	RT Hinge pillar (HSS)	6113106160	1	327.23 s	9.5	1.6
39		Overlap Major Non-Adj. Panel					-0.2
40	FRONT DOOR						

Preliminary Estimate

Customer: PINALES, CARMA

Job Number:

2016 TOYO Camry XLE Automatic 4D SED 4-2.5L Gasoline Sequential MPI GOLD

41		R&I	LT R&I door assy				1.1
42	BACK GLASS						
43		R&I	Back glass Toyota				Incl.
44		Repl	Reveal molding	7557306080	1	47.98	Incl.
45	QUARTER PANEL						
46		Blnd	LT Quarter panel				1.5
47		Repl	LT Quarter panel protector	5874806100	1	17.07	0.2
48		Blnd	RT Quarter panel				1.5
49		Repl	RT Quarter panel protector	5874706100	1	17.07	0.2
50	REAR LAMPS						
51		R&I	RT Tail lamp assy w/o smoked				0.3
52		R&I	LT Tail lamp assy w/o smoked				0.3
53	REAR BUMPER						
54		R&I	R&I bumper cover				1.0
55	#	Subl	HAZARDOUS WASTE		1	5.00	
56	**	Repl	A/M COVER CAR EXTERIOR		1	10.00	0.3
57	**	Repl	A/M FLEX ADDITIVE (PER COVER)		1	10.00	
58	#	Refn	COLOR TINT				0.5
59	**	Repl	A/M SEAM SEALER (PER FOOT)		4	20.68	0.1
60	**	Repl	A/M BACK GLASS URETHANE KIT		1	30.00 T	
61	**	Repl	A/M WINDSHIELD URETHANE KIT		1	30.00	
62	VEHICLE DIAGNOSTICS						
63	*	Rpr	Pre-repair scan			m	0.5 M
64	*	Rpr	Post-repair scan			m	0.5 M
65	#		POSSIBLE HIDDEN DAMAGE		1		
66	#	Rpr	COLOR SAND AND BUFF (PER PANEL)				1.0
SUBTOTALS					2,974.56	46.0	22.8

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,944.56
Body Labor	45.0 hrs	@	\$ 70.00 /hr	3,150.00
Paint Labor	22.8 hrs	@	\$ 70.00 /hr	1,596.00
Mechanical Labor	1.0 hrs	@	\$ 165.00 /hr	165.00
Paint Supplies	22.8 hrs	@	\$ 50.00 /hr	1,140.00
Body Supplies	38.8 hrs	@	\$ 4.00 /hr	155.20
Miscellaneous				30.00
Subtotal				9,180.76
Sales Tax	\$ 9,180.76	@	5.5000 %	504.94
Grand Total				9,685.70



East Side Auto Body

3888 N. Fratney St.
Milwaukee, WI 53212
Work Phone: (414) 963-8989
Fax: (414) 963-8852
moesa236@gmail.com

Estimate

Est # 9167
ID # 13473890

Vehicle Info

2016 Toyota -Camry XSE
4T1BF1FK9GU139046
License: AFD4931 WI
Body Type: 4 Door Sedan
Engine: 2.5L 4 Cyl Gas Injected
Transmission: 6 Speed Auto Trans
Drive Type: FWD

Owner

Carmen Pilnales
(414) 630-8219


Insurance Company

Inspection Date: 07/17/2023
Repair Days: 11

	Oper	Description	Part Number	Price	Labor
FRONT BUMPER					
1	Replace	FRT BUMPER COVER	TO1000409	\$185.00	Included 2.8 hrs. Paint panel 1.1 hrs. Refinish
		1.1 hrs. Clearcoat			
2	Overhaul	O/H FRONT COVER (FRT BUMPER COVER ASSY)			2.2 hrs. Body
3	Replace	FRT LWR BUMPER COVER GRILLE	TO1036158	\$106.00	Included
HOOD					
4	Repair	HOOD PANEL			4 hrs. Body 3 hrs. Paint panel 1.2 hrs. Refinish
		1.2 hrs. Clearcoat			
FRONT FENDER					
5	Blend	L FENDER PANEL			1.1 hrs. Refinish
		1.1 hrs. Blend			
6	Blend	R FENDER PANEL			1.1 hrs. Refinish
		1.1 hrs. Blend			
WINDSHIELD					
7	Replace	W/SHIELD GLASS	FW03473GBY	\$334.14	2.5 hrs. Glass
ROCKER/PILLARS/FLOOR					
8	Repair	R OTR ROOF RAIL			3 hrs. Body 3.4 hrs. Paint panel 1.4 hrs. Refinish
		1.4 hrs. Clearcoat			
ROOF					
9	Replace	ROOF PANEL	63111-06440	\$828.44	18 hrs. Body 3 hrs. Paint panel 1.2 hrs. Refinish
		1.2 hrs. Clearcoat			
10	R&R	ADD TO R&R ROOF TO R&I/R&R SIDE CURTAIN AIR BAG MODULES (ADD TO R&I/R&R SIDE CUR			1.8 hrs. Mechanical

Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	27.2	\$70.00	\$1,904.00	✓
Body Supplies	27.2	\$48.00	\$1,305.60	✓
Glass Labor	2.5	\$60.00	\$150.00	✓
Mechanical Labor	1.8	\$135.00	\$243.00	✓
Paint Labor	19.3	\$70.00	\$1,351.00	✓
Paint Supplies	19.3	\$48.00	\$926.40	✓
Aftermarket Parts			\$291.00	✓
OEM Parts			\$1,162.58	✓
Taxable Amount			\$7,333.58	
Tax	5.6%		\$410.68	
Grand Total			\$7,744.26	



METICULOUS AUTO BODY INC

Details Make the Difference
8800 FOND DU LAC AVENUE, MILWAUKEE, WI
53225
Phone: (414) 464-9000
FAX: (414) 464-5950

Workfile ID: 34119b0a
PartsShare: 7ttmkx
Federal ID: 39-1960215

Preliminary Estimate

Customer: Pinales, Carmen

Written By: Brent Kreitzman

Insured: Pinales, Carmen
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Pinales, Carmen
(414) 630-8219 Cell

Inspection Location:
METICULOUS AUTO BODY INC
8800 FOND DU LAC AVENUE
MILWAUKEE, WI 53225
Repair Facility
(414) 464-9000 Business

Insurance Company:

VEHICLE

2009 CHEV Avalanche LT1 Crew Cab 130" WB 4WD 4D P/U 8-5.3L Flex Fuel SFI

VIN: 3GNFK22079G188240
License:
State: WI

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package

DECOR

Dual Mirrors
Body Side Moldings

Privacy Glass

Console/Storage

CONVENIENCE

Air Conditioning
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Climate Control
Parking Sensors
Home Link

RADIO

AM Radio
FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

Premium Radio

Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System
Hands Free Device

SEATS

Cloth Seats
Bucket Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package
Hard Tonneau Cover
Running Boards/Side Steps

Get live updates at www.carwise.com/e/4z5x4e

Preliminary Estimate

Customer: Pinales, Carmen

2009 CHEV Avalanche LT1 Crew Cab 130" WB 4WD 4D P/U 8-5.3L Flex Fuel SFI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		ROOF					
2	*	Rpr Roof panel Avalanche, w/o roof rack w/o sunroof				5.5	3.4
3		Add for Clear Coat					1.4
4		QUARTER PANEL					
5		Repl LT Upper qtr trim black	15908598	1	459.97	0.2	
6		REAR BODY & FLOOR					
7	*	Repl LKQ Rear cover +30%	25803530	1	539.50	0.3	
8		TAIL GATE					
9	**	Repl A/M Spoiler w/o camera gray	15902099	1	411.00	0.3	
10		R&I Inner panel				0.3	
11		REAR LAMPS					
12	*	Rpr RT Combo lamp assy Avalanche Note: Buff				0.5	
13	*	Rpr LT Combo lamp assy Avalanche Note: Buff				0.5	
14		REAR BUMPER					
15		Repl RT Step pad outer Avalanche	15140926	1	214.05	0.3	
16	#	***** ADD-ONS *****		1			
17	#	Repl Corrosion protection primer		1	10.00 T	0.2	
18	#	Cover car		1	10.00		
19	#	Subl Hazardous Waste Removal		1	3.00 T		
20	#	Color tint / color match		1			2.0
SUBTOTALS					1,647.52	8.1	6.8

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,634.52
Body Labor	8.1 hrs @	\$ 70.00 /hr	567.00
Paint Labor	6.8 hrs @	\$ 70.00 /hr	476.00
Paint Supplies	6.8 hrs @	\$ 48.00 /hr	326.40
Miscellaneous			13.00
Subtotal			3,016.92
Sales Tax	\$ 3,016.92 @	5.5000 %	165.93
Grand Total			3,182.85
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			3,182.85

MyPriceLink Estimate ID / Quote ID:

1114561173753176064 / 127128340



East Side Auto Body

3888 N. Fratney St.
Milwaukee, WI 53212
Work Phone: (414) 963-8989
Fax: (414) 963-8852
moesa236@gmail.com

Estimate

Est # 9169
ID # 13473995

Vehicle Info

2009 Chevrolet -Avalanche LT
3GNFK22079G188240
License: RJ2285 WI
Body Type: 4 Door Crew Cab
Engine: 5.3L 8 Cyl Gas Injected
Drive Type: 4WD

Owner

Carmen Pilnales
(414) 630-8219

Insurance Company

Inspection Date: 07/17/2023
Repair Days: 5

	Oper	Description	Part Number	Price	Labor
QUARTER PANEL					
1	Repair	L QUARTER OUTER PANEL			3 hrs. Body 3.2 hrs. Paint panel 1.3 hrs. Refinish
		1.3 hrs. Clearcoat			
2	Repair	R QUARTER OUTER PANEL			2 hrs. Body 3.2 hrs. Paint panel 1.3 hrs. Refinish
		1.3 hrs. Clearcoat			
REAR GATE					
3	Repair	REAR GATE SHELL			3 hrs. Body 2.9 hrs. Paint panel 1.2 hrs. Refinish
		1.2 hrs. Clearcoat			
4	Replace	REAR GATE MOULDING	25865156	\$373.26	0.4 hrs. Body
REAR LAMPS					
5	Replace	R REAR COMBINATION LAMP ASSEMBLY	GM2801243R	\$237.00	0.3 hrs. Body
6	Replace	L REAR COMBINATION LAMP ASSEMBLY	GM2800243R	\$237.00	0.3 hrs. Body
REAR BUMPER					
7	Replace	R REAR OTR BUMPER STEP PAD	15140926	\$214.05	0.2 hrs. Body

Totals

Type	Labor Time	Cost	Total	Taxable
Body Labor	9.2	\$70.00	\$644.00	✓
Body Supplies	9.2	\$48.00	\$441.60	✓
Paint Labor	13.1	\$70.00	\$917.00	✓
Paint Supplies	13.1	\$48.00	\$628.80	✓
Aftermarket Parts			\$474.00	✓
OEM Parts			\$587.31	✓
Taxable Amount			\$3,692.71	
Tax	5.6%		\$206.79	
Grand Total			\$3,899.50	