

September 13, 2018

SEP 17 2018

12:43 A.M. (P.M.)

Barbara England
1808 E. Kenwood Blvd.
Milwaukee, WI 53211
414-745-9165
bj411@gmail.com

City Clerk
ATTN: Claims
200 E. Wells St., Room 205
Milwaukee, WI 53202-3567

CITY OF MILWAUKEE
2018 SEP 14 PM 12:57
CITY CLERK'S OFFICE

Dear City Clerk,

I am writing to request reimbursement in the amount of \$16,887 from the City of Milwaukee for diagnosis and treatment of basement clear water drainage problems at 1808 E. Kenwood Blvd on Milwaukee's East Side. Symptoms began in February of 2018 and after several attempts at a resolution, it was finally resolved in May of 2018.

In summary, the basement clear water drainage problem took about 3 months to identify that a sewer pipe originating from my home out into the street in front of my house was completely blocked by tree roots. The source of roots was a city tree planted between the sidewalk and street curb slightly north east of the blocked drain pipe. In order to correct the problem, the concrete in front of the house had to be removed in order to dig down through the street to access the pipe, clear it of roots, repair it and replace the concrete.

Exhibit #1: Picture of replaced concrete in front of 1808 E. Kenwood Blvd, which includes the city tree the source of the roots causing the problem.

At the risk of over-communicating, the following lists the sequence of events with approximate time-frames starting from identification of the problem to its eventual solution.

02/20/2018 – It started the night there was a very heavy rain on top of the ground that was frozen and still covered in snow. Clear water from the floor drain backed up in the basement covering the basement floor around the drain with about three inches of clear water, up to about 3-6 yards from the drain. Because that area is sloped towards the drain, the water didn't cause any damage to the water heater, or any items in the basement. I spent time carting gallons of clear water up the stairs out to the back yard during this period of time. At the outset, I called the City of Milwaukee and they sent someone out to look at the situation, then informed me that there was no problem with the sewer that could be responsible for the water in my basement.

September 13, 2018

Barbara England
1808 E. Kenwood Blvd.
Milwaukee, WI 53211
414-745-9165
bj411@gmail.com

City Clerk
ATTN: Claims
200 E. Wells St., Room 205
Milwaukee, WI 53202-3567

According to the Nextdoor Downer Woods website, many home owners were having this problem that very night, so Plumbers and Rotorooters were busy working to unplug gutter drains and House Traps. I found one Plumber willing to come to my home after hours in order to attempt unplugging the drain. They were unable to solve the problem, and without a serious attempt to root the House Trap because of debris, which was later identified as possible old dental floss, they concluded (erroneously) that the House Trap was obstructed and needed to be replaced and mailed an estimate for fixing it Exhibit #3.

02/20/2018 - Exhibit#2: ROZGA Plumbing & Heating fill for \$705.88 for attempting to clear drain.

02/21/2018 - Exhibit #3: (two pages) ROZGA proposal for \$4314.00 to REPLACE the House Trap with the caveat that the estimate didn't include anything else they might find.

Water slowly drained from the basement after it stopped raining. I was concerned about the diagnosis, because I didn't feel that there was clear evidence that the House Trap was blocked, so I arranged for a second opinion (See* below Exhibits # 5 and #6).

04/05/2018 – During the spring rains, water started coming from the drain again on 04/05/2018. As of yet no one actually took off the drain cover, and tried to relieve the problem from the drain itself. I read about Ameri-Drain & Sewer Services on Next Door Downer Woods, so the owner came out and serviced the floor drain itself. He managed to get the water to drain after flushing the drain itself. When he left water was flowing.

04/05/2018 – Exhibit #4: Ameri-drain \$89.

*4/24/2018 - Exhibit #5: Heiden Plumbing Co, Inc. charge of \$126.72 for second estimate including trip charge, and Labor for doing very little except review the ROZGA Bill and talk to me.

September 13, 2018

Barbara England
1808 E. Kenwood Blvd.
Milwaukee, WI 53211
414-745-9165
bj411@gmail.com

City Clerk
ATTN: Claims
200 E. Wells St., Room 205
Milwaukee, WI 53202-3567

*04/26/2015 – Estimate #6: Heiden Estimate for replacing the House Trap.

Clear water started backing up in the basement with a vengeance during the spring rains. Ameri-drain came once again, but couldn't get the water flowing again, and left without a charge or documentation.

05/01/2018 – S&K Pump & Plumbing, Inc. managed to get a snake thru the House Trap and snaked the drain thru the House Trap out to the street. When they left the drain was running.
Exhibit # 7 – Bill from S&K for \$398.11

05/09/2018 – S&K Pump & Plumbing, Inc.

Water returned, and S&K snaked the line more, but water returned again that evening. Snake became lodged at 105 feet. They left a good working pump this time to remove water, so I didn't have to climb the steps with buckets of water to empty in the back yard and planned to return with several men on 05/14/2018 to remove the lodged snake.

05/14/2018 – Couldn't remove snake. Subcontracted Excavator for excavation work in the street.

5/14-5/18/2018 – Exhibit #8 (2 pages) – Bill for \$15,565.90 covering charges to complete work.

I've tried to describe the situation to the best of my ability, considering that this topic is no in my area of expertise. After all was said and done, the pipe was blocked by roots from a city tree located on city property near the blocked pipe. During the excavation, the Bed Rock Sewer & Water Company subcontracted to do the work, showed me a football sized clump of tree roots in the obstructed pipe that they located in the street pointing to the city tree in front of my house as shown in Exhibit #1.

September 13, 2018

Barbara England
1808 E. Kenwood Blvd.
Milwaukee, WI 53211
414-745-9165
bj411@gmail.com

City Clerk
ATTN: Claims
200 E. Wells St., Room 205
Milwaukee, WI 53202-3567

I've owned this home for over 40 years, and never had such a problem. As of 3 years ago I am widowed, and the charge of \$15,595.90 plus the costs accrued in order to understand and identify the problem puts a strain on my financial situation, not to mention the stress and wear and tear it caused me. I suspect this is a recurring problem homeowners in general aren't fully aware of. It seems as though trees like this should not be planted proximate to drain pipes. I do have two large Blue Spruce trees in my front lawn which are elevated from the street, and according to landscapers do have roots that would cause such a problem. Perhaps the offending tree should be removed by the city to prevent a recurrence.


I hope that the city will agree that the responsibility of this bill lies with them. I can provide more information as necessary.

Summary of costs:

02/20 - 705.88
04/05 - 89.00
04/24 - 126.72
05/04 - 398.11
05/31 - 15,556.90
Total. \$16,887.00

Please forward this information and request to the appropriate departments for consideration. I can be contacted at 414-745-9165 or bj411@gmail.com.

Thank you for your help and consideration,


Barbara England

1



ROZGA

#2 **PLUMBING & HEATING CORP.**
Help is on the way! Since 1981
 www.rozgacorp.com | 414-258-9911

Date	2/24/14
Tech	ERIC W
Job #	

Billing Address:		Job Address:	
Name:	BURBANK LINDA	Name:	
Address:	1106 KENNETH BLVD	Address:	
City, State, Zip:		City, State, Zip:	
Phone:	414-258-9168	Email:	
<input checked="" type="checkbox"/> Time & Material Job	Rate: 89.90	Per/Hour	<input type="checkbox"/> Estimate:

I hereby authorize the below service to be performed along with necessary materials by the ROZGA PLUMBING & HEATING CORPORATION, its employees and/or subcontractors and release same from any liability for any damages arising from the nature, design and/or condition of existing plumbing, HVAC, ductwork, and/or electrical and its appurtenances that is not the result of negligence. I also agree that full payment is due upon completion with interest added at 1.5% per month on any unpaid balance after completion of work. Failure to pay will result in further legal action. All legal and collection fees will be the responsibility of debtor. I am also aware of a mechanics lien as outlined in Wisconsin Stat. 779.02(2)(a) and of the terms and conditions printed on the back of this page.

Customer Signature X _____

Make:	Serial #:
Model #:	Filter:

QTY	DESCRIPTION	EACH	PRICE
278	PLUMBING -> ERIC W	89.90	24992
	WORK PERFORMED WITH NO FEE TO THE CUSTOMER. I AM NOT RESPONSIBLE FOR ANY DAMAGE TO THE PROPERTY OR PERSONS. I WAS UNDER NO OBLIGATION TO BE RESPONSIBLE FOR THE CUSTOMER'S LOSS OF WATER. I AM NOT RESPONSIBLE FOR THE CUSTOMER'S LOSS OF WATER. ERIC W		
Option #1			
Option #2			
Material			
Consumables			
Comfort Plus	15% Off of HVAC Repairs (Labor & Materials Only)		
Platinum Discount	10% Off of HVAC Accessory Installation		

Acceptance of work performed: I find the service and materials performed & installed have been completed in accordance with this agreement. I agree to pay reasonable attorney fees, collection fees and court costs in the event of legal action pursuant to collection of amount due.

Customer Signature X Burbank Linda

I do hereby state that the above service has been done in workmanlike manner and to applicable codes.

Service Charge	
Subtotal	24992
Tax	
Total	

#3 plot 2



Rozga - Proposal

Date	2/21/2018
Estimate #	E-15170
P.O. No.	

Bill To	Due Date	2/21/2018
Barbara England S81 W12719 Hi-View Drive Muskego, WI 53150		

Ship To	
1808 E Kenwood Blvd Milwaukee, WI 53211	
Referred By	Angies List

Primary #	414-745-9165	Mobile #	414-745-9165	Home #		Work #	
-----------	--------------	----------	--------------	--------	--	--------	--

Author	Bryan P.	Project	"House Trap Removal"
--------	----------	---------	----------------------

Description

When we are complete, you will know the condition of your inside and exterior sewer, given a digital copy for your records and have a new full sized 6" directional clean out in which to use for drain cleaning in the future.

Misc. Plumbing Material: 6" PVC pipe and fittings, clay x cast ferenco couplings, clean out adaptor, stone and concrete.

Permit Included

*** We have performed many of these conversions for our customers and the base scope work as described above falls within the \$3,800 to \$4,400 range. The actual labor, material, permit, dump truck and hydroexcavating equipment costs required for your project will be invoiced upon completion within this range.

The \$4,300 amount below is the middle budgetary reference, we will keep in constant communication during the project. ***

A down payment of \$1,500.00 to be made with the signed proposal and the balance due to be paid to the installer upon completion.

Thank you for the opportunity for work, we appreciate it!

Bryan Pitrof
Plumbing Supervisor / Master Plumber

- * Proposal good for 30 days.
- * Your acceptance of this proposal would commit you to the full payment of all work done.
- * Any unpaid balance will be charged a 1% late charge per month.
- * Upon acceptance of our proposal we ask for a down payment, any necessary progress draws, with the balance due in full upon completion. Please sign, date and return this proposal with down payment to the address listed above. Should you have any questions, please don't hesitate to give us a call.

Total	\$4,314.00
Down Payment	1500.00

Signature: _____ Date: _____

#3 p 2 of 2



Rozga - Proposal

Date	2/21/2018
Estimate #	E-15170
P.O. No.	

Bill To	Due Date	2/21/2018
Barbara England S81 W12719 Hi-View Drive Muskego, WI 53150		

Ship To	
1808 E Kenwood Blvd Milwaukee, WI 53211	
Referred By	Angies List

Primary #	414-745-9165	Mobile #	414-745-9165	Home #		Work #	
Author	Bryan P.	Project "House Trap Removal"					

Description

Base Scope Includes:

Due to your basement underfloor main drain 'house trap' being clogged, broken or non functional we are proposing the following for a long term solution to allow for proper access the rest of your outside sewer out to the street with a video inspection camera and sewer machine.

Our first day begins with laying down tarps and floor protection in our walkway and work area, we then move on to concrete break up in the front of the basement by the old house trap clean out area, including up to a 3'x4' trench, excavation up to 4' down to expose the House Trap. We then cut out and replace up to 3' of horizontal PVC pipe and install a new 6" PVC Pipe and full size PVC 6" clean out to be brought up to finish concrete height. This will finally allow for the proper full size 6" sewer cutting bit on our sewer cleaning machines. This was never able to be done before due the old, original 4" clean out riser for the original clean out serving the 6" drain pipe down below.

All work based on being performed inside the front foundation footing.

Included is to use our sewer camera to verify the condition of the remaining sewer both upstream and downstream to the street connection to the main. We will discuss our findings and leave you a digital copy of the sewer inspection.

Included is to bring in stone backfill to fill in the entire trench.

Included is to restore the concrete floor.

*Due to the nature of underground work, there is the potential for obstacles to be encountered, such as: utilities, lead water service, tree root obstruction, poor condition of piping not allowing for a solid connection and the arrangement of additional fittings at this front juncture. In the event we do come across any of the items, options or additional work and cost will be discussed with you.

* Proposal good for 30 days.

* Your acceptance of this proposal would commit you to the full payment of all work done.

* Any unpaid balance will be charged a 1% late charge per month.

* Upon acceptance of our proposal we ask for a down payment, any necessary progress draws, with the balance due in full upon completion. Please sign, date and return this proposal with down payment to the address listed above. Should you have any questions, please don't hesitate to give us a call.

Total

Down Payment 1500.00

Signature: _____ Date: _____

Phone #	414-258-9911	Fax #	414-258-9921	Page 1	Web Site	www.rozgaCorp.com
---------	--------------	-------	--------------	--------	----------	-------------------

4

Ameri-Drain & Sewer Services

~ SEWER & DRAIN SERVICES ~

1000 SOUTH 108TH ST. WEST ALLIS WI • 414 514 2371

We Drain Drains, Not Pocketbooks.

NAME _____
 ADDRESS 1803 E. Kenwood
 PHONE _____ DATE 7-5-18

WORK DESCRIPTION	PRICE
<p>Serviced catch basin type floor drain, back flow preventer was frozen shut with rust and buildup. Floor drain is now open flushed out and flowing.</p>	39 ⁰⁰
<p>Fill in full fill</p>	
SUB TOTAL	-
TAX	-
TOTAL	000 01

PLEASE MAKE CHECKS PAYABLE TO: AMERI-DRAIN
 > RETURNED CHECKS SUBJECT TO A \$40 NSF CHARGE
 > ALL ACCOUNTS ARE TO BE PAID IN FULL AT THE TIME OF SERVICE

Thank you, we appreciate your business.

#5

HEIDEN PLUMBING CO., INC. - 1100 W. Bruce Street, Milwaukee, WI 53204 (414) 937-8420 - FAX (414) 937-8425

NAME:	SERVICE DATE:	
ADDRESS:	JOB LOCATION:	
CITY, STATE, ZIP:	INVOICE NO.:	ACCOUNT NO.:
PHONE:	CONTACT INFORMATION:	

DESCRIPTION OF WORK:

RECOMMENDATIONS:

As required by the Wisconsin construction lien law, Contractor hereby notified Owner that persons or companies furnishing labor or materials for the construction on Owner's land may have lien rights on Owner's land or buildings if not paid. Those entitled to lien rights, in addition to Contractor, are those who contract directly with the Owner or those who give the Owner notice within 60 days after they first furnished labor or materials for the construction. Accordingly, Owner probably will receive notices from those who furnish labor or materials for the construction, and should give a copy of each notice received to his mortgage lender, if any. Contractor agrees to cooperate with the Owner and his lender, if any, to see that all potential lien claimants are duly paid.

TRUCK / TRIP CHARGE:	
TOTAL MATERIALS:	
TOTAL LABOR:	
SUB TOTAL	
SALES TAX	
TOTAL	

ARRIVAL TIME:	DEPARTURE TIME:
CUSTOMER'S APPROVAL:	

HEIDEN

Plumbing, Heating & Cooling

-Since 1925-

Heiden Plumbing Co., Inc.
1100 West Bruce Street, Milwaukee, WI 53204 (414) 937-8420 - FAX (414) 937-8425

#6

PROPOSAL

Date: 4/26/2018

Proposal Submitted To:

Barbara England
1808 E. Kenwood Blvd
Milwaukee, WI 53211

Job Location:

Barbara England
1808 E. Kenwood Blvd
Milwaukee, WI 53211

Phone: 414-745-9165

HOUSE TRAP

We propose to provide labor, material, and equipment to complete the following:

- Break out a 2' x 4' area of concrete floor around house trap cleanout.
- Excavate down to the horizontal sewer and remove house trap.
- Camera sewer out to the main and let the owner know condition of line.
- Install a full size wye fitting into main and extend riser pipe 2" above finish floor.
- Work shall be inspected by area plumbing inspector.
- Bed pipe with stone, backfill with excavated materials.
- Patch floor to match existing thickness and finish.
- Remove excess rubble.

Please note: Condition of sewer beyond house trap is unknown.

If further work is needed (including snaking or jetting) extra charges will apply.

Terms: Signed proposal with 50% down payment to start job. Balance upon completion.

All for the Total Sum of: \$4,650.00

Please Note: Any changes and or additions not listed above could result in extra charges.

Please return with your signature below AND on the TERMS & CONDITIONS page.

Authorized Signature

Amy Wydenka (JCS)

Customer Signature

PLEASE PRINT & SIGN NAME

This proposal may be withdrawn by us if not accepted within 15 days.

"AS REQUIRED BY THE WISCONSIN CONSTRUCTION LIEN LAW, BUILDER HEREBY NOTIFIES OWNER THAT PERSONS OR COMPANIES FURNISHING LABOR OR MATERIALS FOR THE CONSTRUCTION ON OWNER'S LAND MAY HAVE LIEN RIGHTS ON OWNER'S LAND AND BUILDING IF NOT PAID. THOSE ENTITLED TO LIEN RIGHTS, IN ADDITION TO THE UNDERSIGNED BUILDER, ARE THOSE WHO CONTRACT DIRECTLY WITH THE OWNER OR THOSE WHO GIVE THE OWNER NOTICE WITHIN SIXTY DAYS (60) AFTER THEY FIRST FURNISH LABOR OR MATERIALS FOR THE CONSTRUCTION. ACCORDINGLY, OWNER PROBABLY WILL RECEIVE NOTICES FROM THOSE WHO FURNISH LABOR OR MATERIALS FOR THE CONSTRUCTION, AND SHOULD GIVE A COPY OF EACH NOTICE RECEIVED TO HER/HER MORTGAGE LENDER. IF ANY, TO SEE THAT ALL POTENTIAL LIEN CLAIMANTS ARE DULY PAID"

(OVER FOR OTHER GENERAL CONTRACT CONDITIONS & TERMS)

THANK YOU FOR THIS OPPORTUNITY TO QUOTE YOU!!

#7

S&K PUMP & PLUMBING, INC.

26307

snkpump.com
service@snkpump.com

20880 W. ENTERPRISE AVE. • BROOKFIELD, WI 53045 • TEL: 262-782-7190 • FAX: 262-782-9642

JOB AT: BARBARA England
1808 E. Kenwood
Milwaukee, WI 53211

BILL TO:
414 722 2194 85 4608
Auth: 01319C 10/18

PHONE: 414-745-9165

DATE: 5/7/78 JOB NO: 102619

- snaked out sewer 75ft with 1 1/4" cable + 4" SHARK. Found roots @ 40'.
Tested + Good Run off.

- Tested Floor drain/CATCH BASIN with hose
Running full bore. Good Run off

TRIP	85	00
Auger Fee	90	00
LABOR	252	00
	<u>\$377.00</u>	
56%	214	11
	<u>\$398.11</u>	

Full Sized Cutter - went to front -

BRUCE SINOTTE

PAYMENT DUE UPON COMPLETION

REC'D BY Barbara England

SERVICE CHARGE OF 1 1/2% PER MONTH WILL BE CHARGED ON ALL INVOICES UNPAID AFTER 30 DAYS

30 DAY SERVICE GUARANTEE ON REPAIRS. NEW PARTS AS PER MFG WARRANTY.

S&K PUMP & PLUMBING, INC.

20880 W. ENTERPRISE AVE • BROOKFIELD, WI 53045
 TEL: 262-782-7190 • FAX: 262-782-9642

snkpump.com
 service@snkpump.com

#8 p1 of 2

WELL PUMPS • PLUMBING • WATER SYSTEMS • WATER SOFTENERS
 IRON FILTERS • DRINKING WATER SYSTEMS
 SALES • SERVICE • RENTALS
24 HOUR SERVICE
 RADIO DISPATCHED TRUCKS

SERVICE INVOICE 102750

DATE: 05/31/18 By: brian
 Printed 05/31/18 12:31
 Page 1 ORIGINAL

LOCATION: 1808EKEN

BARBARA ENGLAND
 1808 EAST KENWOOD BLVD
 MILWAUKEE, WI 53211

BILL TO: 1808EKEN

BARBARA ENGLAND
 1808 EAST KENWOOD BLVD
 MILWAUKEE, WI 53211

Contact: (414)745-9165 Call Job# TERMS
 Service Order # 102750/213 P.O.# sv16 CASH ON DE

Qty	Item	List	Sale	Extended
1	*SUB JETTING/CAMERA OF MAIN SEWER		885.00	885.00
1	*SUB EXCAVATION/REPAIR/PATCHING		13675.00	13675.00

Empl Code	Date	Hours
265	05/14/18	01.83
213	05/09/18	01.50
213	05/18/18	01.50
213	05/09/18	00.83
213	05/11/18	04.17
213	05/14/18	01.67

Total Labor 952.56

PD
06/25/2018
CK# 3307

Tax: 53.34
 Total: 15,565.90
 Paid: 0.00
 Balance Due: 15,565.90

TERMS: Payment due upon receipt.
 1½% per month will be added to accounts 30 days past due.

**30 DAY SERVICE GUARANTEE ON REPAIRS
 NEW PARTS AS PER MFG. WARRANTY.**

CUSTOMER COPY

S&K #8p20tz PUMP & PLUMBING, INC.

20880 W. ENTERPRISE AVE • BROOKFIELD, WI 53045
 TEL: 262-782-7190 • FAX: 262-782-9642

snkpump.com
 service@snkpump.com

WELL PUMPS • PLUMBING • WATER SYSTEMS • WATER SOFTENERS
 IRON FILTERS • DRINKING WATER SYSTEMS
 SALES • SERVICE • RENTALS
24 HOUR SERVICE
 RADIO DISPATCHED TRUCKS

SERVICE INVOICE 102750

DATE: 05/31/18 By: brian
 Printed 05/31/18 12:31
 Page 1 ORIGINAL

BILL TO: 1808EKEN
 BARBARA ENGLAND
 1808 EAST KENWOOD BLVD
 MILWAUKEE, WI 53211

LOCATION: 1808EKEN
 BARBARA ENGLAND
 1808 EAST KENWOOD BLVD
 MILWAUKEE, WI 53211

Contact: (414)745-9165 Call Job# TERMS

Service Order # 102750/213 P.O.# sv16 CASH ON DE

City	Item	List	Sale	Extended
------	------	------	------	----------

SERVICE RELATED TO WORK ON FLOOR DRAIN/CATCH BASIN AND MAIN SEWER LINE FROM 5-9-18 TO 5-18-18
 5-9-18 RETURNED DUE TO LEAK AT CLEANOUT DRAIN. REMOVED, RETAPED AND REINSTALLED. RETURNED LATER THAT DAY AND SNAKED OUT CATCH BASIN DRAIN. TRIP PLUS 1 HR 40 MINS NO CHARGE.
 5-11-18 RETURNED TO CLEAN OUT MAIN SEWER AS IT WAS BACKING UP AGAIN. RAN INTO REPEATED OBSTRUCTIONS AND AT 105' SNAKE BECAME LODGED. WILL RETURN MON TO ATTEMPT TO REMOVE. NO TRIP CHARGE, 2.67 HRS AT STRAIGHT TIME - \$448.56
 5-14-18 RETURNED WITH 2 MEN. SNAKE IS BOUND TIGHT AT 105' AND WILL NOT REVERSE. SUSPECT SNAKE IS PACKED TIGHT IN ROOTS AND EXITED SEWER IN STREET AND BECAME STUCK. ARRANGED FOR EXCAVATION. LABOR 2 MEN 1 HOUR EACH \$336.00
 5-17/18-18 SUBCONTRACTED EXCAVATOR TO BLOCK OFF STREET, CUT PAVEMENT AND EXPOSE SEWER. CUT INTO SEWER AND FOUND PACKED FULL OF TREE ROOTS. ARRANGED FOR JETTING OF SEWER. RAN JETTER AND CAMERA IN BOTH DIRECTIONS TO HOME AND TO MAIN SEWER. ASIDE FROM A FEW BELLIES IN PIPE, SEWER LOOKS GOOD NOW. RETRIEVED SNAKE FROM SEWER, REPAIRED SECTION OF PIPE THAT WAS REMOVED, TESTED RUNOFF. BACKFILLED HOLE WITH SPOIL SLURRY AND CONCRETE PER CITY. LABOR 1 HOUR \$168.00
 TOTAL S&K LABOR \$952.56 PLUS SUBCONTRACT FEES LISTED BELOW.

JETTER/CAMERA SUB FEES \$ 885.00
 EXCAVATOR SUB FEES \$13,675.00
 INCLUDES CITY OF MILWAUKEE PERMIT, BARRICADES, EXCAVATION EQUIPMENT, DUMP TRUCKS, DUMP SITE FEE, STONE, SLURRY, CONCRETE AND ALL LABOR.

ORIGINAL Continued: 2

TERMS: Payment due upon receipt.
 1 1/2% per month will be added to accounts 30 days past due.

**30 DAY SERVICE GUARANTEE ON REPAIRS
 NEW PARTS AS PER MFR. WARRANTY.**

CUSTOMER COPY