

2-18-21

1 To Whome this May Concern  
I Sara Clemons Will Like to  
Appeal this Decision I am a br  
/r. DLD Lady. What did worry  
I am sorry for what happen  
On February 4. 2020 in My Garage  
I Understand that they did what  
they had to do but to Causes  
Damaged to my Car NO I dont  
Understand that so yes I  
Feel that the M.P.D ARE liable  
for the Damaged its Wasnt me  
they was Looking for if it was  
me I would have to pay or Jail  
its Just not Right Thanks God  
For Detective Rose marie Galindo  
She is the One that bought the  
Clime to me x told me where  
to Take it x that what I did  
I have Dents x Stretch on the  
Top of My Car

Thank  
you

Our denial letter was  
mailed 2-1-21; client  
appeal postmarked  
2-19-21  
City Atty's Office  
(INCLUDE)

CITY OF MILWAUKEE  
2021 FEB 23 AM 11:11  
CITY CLERK'S OFFICE

OFFICE OF CITY ATTORNEY  
24 FEB '21 AM 10:03

PD-43 05/07

# MILWAUKEE POLICE DEPARTMENT DAMAGE NOTICE

(SUPERVISOR TO LEAVE IN PROMINENT PLACE AT SCENE)

The Milwaukee Police Department received a call for

service on: 02-04 20 20 at: 2:07 0 a.m./p.m.  
(DATE) (TIME)  
at: 5040 N 26th (garage)  
(ADDRESS)

to:  confirm welfare of occupant(s)

make an arrest

execute a search warrant

recover evidence of crime

other (describe) \_\_\_\_\_

The following damage to premises or vehicle occurred:

top of vehicle  
minor scrapes

Supervisor's Name: SBT D. RATLIFF  
(PRINT)

5 LATE 018020  
(DIST. / WORK LOC.) (SHIFT) (EMPLOYEE I.D. #)

**SEE NOTICE ON REVERSE SIDE**

AMATO COLLISION CENTER  
8301 NORTH 76TH STREET  
MILWAUKEE, WI 53223  
OFFICE: (414)357-8500 FAX: (414)357-8161

\*\*\* PRELIMINARY ESTIMATE \*\*\*

02/12/2020 10:17 AM

Owner

Owner: SARA CLEMONS  
Address:

Work/Day: (414)841-1341

Inspection

RECEIVED  
OFFICE OF CITY ATTORNEY

Inspection Date: 02/12/2020 10:19 AM

Inspection Type:

FEB 17 2020

Contact: JASON BRAATZ

2:45 A.M./P.M.

Repairer

Repairer: AMATO COLLISION CENTER  
NORTH  
Address: 8301 N 76TH ST  
City State Zip: MILWAUKEE, WI 53223  
Email: amatocolln@yahoo.com

Contact: JASON BRAATZ

Work/Day: (414)357-7800  
Work/Day: (414)357-8161

Target Complete Date/Time:

Days To Repair: 5

Vehicle

2017 Hyundai Elantra SE 4 DR Sedan  
4cyl Gasoline 2.0  
6-Speed Automatic

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Color: TAN  
Ext. Refinish: Two-Stage

VIN: 5NPD74LF2HH111524  
Mileage Type: Actual  
Code: E2374A  
Int. Color:  
Int. Refinish: Two-Stage

Options

2nd Row Head Airbags  
Alarm System  
Bucket Seats  
Daytime Running Lights  
Elect. Stability Control  
Head Airbags  
Intermittent Wipers  
Lighted Entry System  
Perimeter Alarm System  
Power Windows  
Side Airbags  
Stability Cntrl Suspensn  
Tachometer  
Tire Pressure Monitor  
U.S.A. Built Vehicle

AM/FM CD Player  
Anti-Lock Brakes  
Center Console  
Driver Knee Airbag  
Electric Steering  
Heated Power Mirrors  
Keyless Entry System  
MP3 Decoder  
Power Brakes  
Rear Window Defroster  
SiriusXM Satellite Radio  
Steel Wheels  
Tilt & Telescopic Steer  
Traction Control System  
Velour/Cloth Seats

Air Conditioning  
Auxiliary Audio Input  
Cruise Control  
Dual Airbags  
Halogen Headlights  
Illuminated Visor Mirror  
Knee Air Bags  
Overhead Console  
Power Door Locks  
Rem Trunk-L/Gate Release  
Split Folding Rear Seat  
Strg Wheel Radio Control  
Tinted Glass  
Trip Computer

2020 FEB 14 PM 4:30

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
<b>Roof</b>										
1	I	341		Panel,Roof	Repair				10.0*	SM
2	L	341	13	Panel,Roof	Refinish				4.6	RF
					3.3 Surface					
					0.6 Two-stage setup					
					0.7 Two-stage					
3	RI	383		Mldg,Roof Side LT	R & I Assembly				0.3	SM
4	RI	384		Mldg,Roof Side RT	R & I Assembly				0.3	SM
5	RI	1187		Antenna,Assembly	R & I Assembly				0.7	SM

**Manual Entries**

6	EC	M17		Cover Car Exterior	Replace Economy	\$10.00*				RF
7	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*				SM
7				Items						

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

Other Parts					\$10.00
Paint & Materials	4.6 Hours @	\$40.00			\$184.00
Parts & Material Total					\$194.00
Tax on Parts & Material	@	5.600%			\$10.86

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$60.00	1.3	10.0	11.3	\$678.00
Mech/Elec (ME)	\$105.00				
Frame (FR)	\$60.00				
Refinish (RF)	\$60.00	4.6		4.6	\$276.00
Labor Total				15.9 Hours	\$954.00
Tax on Labor		@	5.600%		\$53.42
Sublet Repairs					\$5.00
Tax on Sublet		@	5.600%		\$0.28
Gross Total					\$1,217.56
Net Total					\$1,217.56

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53223 Default  
 SPPL Yes Zip Code: 00000 Default  
 Rate Name Default

Audatex Estimating 8.0.643 Update 6 ES 02/13/2020 03:21 PM REL 8.0.643 Update 6 DT 01/01/2020 DB 02/08/2020  
 © 2020 Audatex North America, Inc.

1.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

**Op Codes**

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Rebld
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



Tender Car Auto Body  
1825 S. Kinnickinnic Ave  
Milwaukee, WI 53204  
Tel: (414) 389-1014 Fax: (414) 389-1779  
tendercar@gmail.com # 27-0157878

\*\*\* PRELIMINARY ESTIMATE \*\*\*

02/13/2020 03:02 PM

**Owner**

Owner: Sara Clements

RECEIVED  
OFFICE OF CITY ATTORNEY

**Inspection**

Inspection Date: 02/13/2020 03:02 PM

Inspection Type: FEB 17 2020

Appraiser Name: Juan Irizarry

Appraiser License #: 245 A.M./P.M.

**Repairer**

Address: 1825 South Kinnickinnic  
City State Zip: Milwaukee, WI 53204  
Email: tendercar@gmail.com

Work/Day: (414)389-1014  
Work/Day:

Target Complete Date/Time:

Days To Repair: 6

**Vehicle**

2017 Hyundai Elantra SE 4 DR Sedan  
4cyl Gasoline 2.0  
6-Speed Automatic

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Refinish: Two-Stage

VIN: 5NPD74LF2HH111524  
Mileage Type: Actual  
Code: E2374A  
Int. Refinish:

**Options**

2nd Row Head Airbags  
Alarm System  
Bucket Seats  
Daytime Running Lights  
Elect. Stability Control  
Head Airbags  
Intermittent Wipers  
Lighted Entry System  
Perimeter Alarm System  
Power Windows  
Side Airbags  
Stability Cntrl Suspensn  
Tachometer  
Tire Pressure Monitor  
U.S.A. Built Vehicle

AM/FM CD Player  
Anti-Lock Brakes  
Center Console  
Driver Knee Airbag  
Electric Steering  
Heated Power Mirrors  
Keyless Entry System  
MP3 Decoder  
Power Brakes  
Rear Window Defroster  
SiriusXM Satellite Radio  
Steel Wheels  
Tilt & Telescopic Steer  
Traction Control System  
Velour/Cloth Seats

Air Conditioning  
Auxiliary Audio Input  
Cruise Control  
Dual Airbags  
Halogen Headlights  
Illuminated Visor Mirror  
Knee Air Bags  
Overhead Console  
Power Door Locks  
Rem Trunk-L/Gate Release  
Split Folding Rear Seat  
Strg Wheel Radio Control  
Tinted Glass  
Trip Computer

**Damages**

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
<b>Roof</b>									
1	I	341		Panel,Roof	Repair			10.0*	SM
2	L	341	13	Panel,Roof	Refinish			4.6	RF
					3.3 Surface				
					0.6 Two-stage setup				
					0.7 Two-stage				
3	RI	383		Mldg,Roof Side LT	R & I Assembly			0.3	SM
4	RI	384		Mldg,Roof Side RT	R & I Assembly			0.3	SM
5	RI	1187		Antenna,Assembly	R & I Assembly			0.7	SM
<b>Manual Entries</b>									
6	L			COLOR SAND AND BUFF	Refinish			1.0*	RF*
7	EC			COVER CAR	Replace Economy	\$8.00*		0.4*	SM
8	SB			HAZARDUS WASTE REMOVAL	Sublet Repair	\$10.00*			SM
9	N			COLOR TINT	Additional Labor			1.0*	RF*
9				Items					

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

<b>Other Parts</b>						\$8.00	
<b>Paint &amp; Materials</b>		6.6 Hours @	\$40.00			\$264.00	
<b>Parts &amp; Material Total</b>							\$272.00
<b>Tax on Parts &amp; Material</b>			@ 5.600%				\$15.23
<b>Labor</b>	<b>Rate</b>	<b>Replace Hrs</b>	<b>Repair Hrs</b>	<b>Total Hrs</b>			
Sheet Metal (SM)	\$60.00	1.7	10.0	11.7		\$702.00	
Mech/Elec (ME)	\$125.00						
Frame (FR)	\$75.00						
Refinish (RF)	\$60.00	5.6	1.0	6.6		\$396.00	
<b>Labor Total</b>				18.3 Hours			\$1,098.00
<b>Tax on Labor</b>			@ 5.600%			\$61.49	
<b>Sublet Repairs</b>						\$10.00	
<b>Tax on Sublet</b>			@ 5.600%			\$0.56	
<b>Gross Total</b>							\$1,457.28
<b>Net Total</b>							\$1,457.28

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53204 Default  
 Rate Name Default

Audatex Estimating 8.0.642 Update 6 ES 02/13/2020 03:05 PM REL 8.0.642 Update 6 DT 02/01/2020 DB 02/08/2020  
 © 2020 Audatex North America, Inc.

1.3 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

**Op Codes**

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc.  
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

