

5.8.2013

TO THE CITY OF MILWAUKEE,
OFFICE OF THE CITY ATTORNEY.

RE CI FILE NO. 1058.2013.950

COMMUNICATION FROM, BOBBY LOWE

ON MARCH 8, 2013, I WAS sitting in my living room, as always looking outside, I ~~SAW~~ SAW this man pulling this GARBAGE CART BETWEEN TWO VEHICLE which was my CAR and VAN the ~~MAN~~ MAN HIT my CAR with the garbage cart, and kept going like it was O.K. two PARK VEHICLE, I try to STOP them they JUST KEEP ~~going~~ going. I am asking of City MILWAUKEE, PLEASE FIX my CAR.

THANK-YOU

BOBBY LOWE

3-19-13

TO THE CITY OF MILWAUKEE.

DATE. 3.8.13

TIME. HOURS of 7:00 A.M. ON 7:30

WHERE. AT. 7469 N. 51 ST. MILW WI 53223

THE YOUNG-MAN. HIT my CAR with the GARBAGE CART. I try to STOP him he kept going like it was OK. I work for ^{HARD} things I have an things I own are in good condition. I saw ~~with~~ this looking out my window. Hit A PARK CAR, that's NOT right.

CITY OF MILWAUKEE

2013 MAR 20 PM 4:00

CITY CLERK'S OFFICE

RECEIVED

MAR 21 2013

OFFICE OF
CITY ATTORNEY

76TH STREET BODY SHOP (HEISER)
 7800 NORTH 76TH STREET
 MILWAUKEE, WI 53223
 PHONE: (414) 357-2121 FAX: (414) 357-2133

RECEIVED
 MAR 21 2013

CD LOG NO 27601-1 DATE 03/12/13

OFFICE OF
 CITY ATTORNEY

SHOP: 76TH ST BODY SHOP (HEISER) INSP DATE: 03/12/13
 ADDRESS: 7800 N. 76TH ST PHONE 1: (414)357-2121
 CITY STATE: MILWAUKEE, WI PHONE 2: (414)586-7000
 ZIP: 53223- FAX: (414)357-2133

OWNER:

POINT OF IMPACT: 0

LIC#: STATE: VIN: 1N4BA41E04C880974
 BODY COLOR: MILEAGE:
 CONDITION: ACCTNG CTL#:

DEFINITIONS:
 *=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS
 EC=REPLACE ECONOMY UE=REPLACE OE SURPLUS UC=RECONDITIONED PRT
 UM=REMAN/REBUILT PRT EU=REPLACE SALVAGE EP=REPLACE PXN
 OE=REPLACE PXN OE SRPLS PC=PXN RECONDITIONED PM=PXN REMAN/REBUILT
 TE=PARTL REPL PRICE ET=PARTL REPL LABOR IT=PARTIAL REPAIR
 I=REPAIR L=REFINISH BR=BLEND REFINISH
 TT=TWO-TONE CG=CHIPGUARD SB=SUBLET
 N=ADDITIONAL LABOR RI=R&I ASSEMBLY P=CHECK
 AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

2004 NISSAN MAXIMA SE 4DOOR SEDAN 6CYL GASOLINE 3.5
 CODE: Z1663D/A OPTNS B/24J

OPTIONS:
 TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES
 AUTOMATIC TRANS

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
I	0249		PNL, FRONT DOOR OUTE RT	REPAIR				1.0	*1
			BUFF OUT MARKS ON DOOR						
L	0249	13	PNL, FRONT DOOR OUTE RT	REFINISH				3.5	4
				2.4 SURFACE					
				0.6 TWO STAGE SETUP					
				0.5 TWO STAGE					
RI	0272		MLDG, FRONT DOOR BEL RT	R&I ASSEMBLY				0.3	1
RI	0060		MLDG, FRONT DOOR SID RT	R&I ASSEMBLY				0.3	1
RI	0230		MIRROR, OUTER R/C RT	R&I ASSEMBLY				0.3	1
RI	0228		HANDLE, FRONT DOOR O RT	R&I ASSEMBLY				1.3	1
I	0325		PNL, REAR DOOR OUTER RT	REPAIR				1.5	*1
L	0325		PNL, REAR DOOR OUTER RT	REFINISH				2.3	4
				1.9 SURFACE					

				0.4 TWO STAGE	
RI0335	MLDG, REAR DOOR BELT RT	R&I ASSEMBLY			0.2 1
RI0321	MLDG, REAR DOOR SIDE RT	R&I ASSEMBLY			0.3 1
RI0456	TAPE, REAR DOOR	RT R&I ASSEMBLY			0.1 1
RI0306	HANDLE, RR DOOR OUTE RT	R&I ASSEMBLY			1.1 1
I 0390	PANEL, QUARTER	RT REPAIR			1.0*1
L 0390 10	PANEL, QUARTER	RT REFINISH			1.9*4
				1.5*SURFACE	
				0.4 TWO STAGE	
RI0538	LENS & HSG, TAILLAMP RT	R&I ASSEMBLY			0.1 1
	R&I FOR PAINT				
N 0566	REAR BUMPER COVER R&I	ADDNL LABOR OPERA			1.0*1
	DROP DOWN RT SIDE FOR PAINT				
N M14	CORROSION PROTECTION	ADDNL LABOR OPERA		*	0.3*4*
N M60	HAZARD. WSTE. REM.	ADDNL LABOR OPERA	5.00*		1*
N	MLDG REBACK	ADDNL LABOR OPERA			0.8*1*
	REBACK 2 RT SIDE MLDGS				

19 ITEMS

MC MESSAGE(S)
 10 INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL
 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

OTHER PARTS					5.00
PAINT MATERIAL					272.00
PARTS & MATERIAL TOTAL					277.00
TAX ON PARTS & MATERIAL @				5.600%	15.51
LABOR	RATE	REPLACE HRS	REPAIR HRS		
1-SHEET METAL	54.00	4.0	5.3		502.20
2-MECH/ELEC	85.00				
3-FRAME	54.00				
4-REFINISH	54.00	7.7	0.3		432.00
5-PAINT MATERIAL	34.00				
LABOR TOTAL					934.20
TAX ON LABOR		@		5.600%	52.32
SUBLET REPAIRS					
TOWING					
STORAGE					

GROSS TOTAL 1,279.03

NET TOTAL 1,279.03

SHOPLINK U1836 ES CD LOG 27601-1 DATE 03/12/13 12:53:35AM R6.37 CD 02/13
 PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEocode 53223
 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.9 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

2004 NISSAN MAXIMA SE 4DOOR SEDAN
CD LOG NO 27601-1

Rental car additional \$30/Day
 Veh. would be in shop 3 days

RUSS DARROW COLLISION CENTER
 7676 NORTH 76TH STREET
 MILWAUKEE WI 53224-9010
 PHONE (414) 362-7520 FAX (414) 355-6744
 MOBILE ESTIMATING (414) 587-9015 AT DEALERSHIPS

*** PRELIMINARY ESTIMATE ***

03/18/2013 10:09 AM

Inspection

Inspection Date: 03/18/2013 10:10 AM
 Primary Impact: Right Side

Inspection Type:
 Secondary Impact:

Repairer

Repairer: COLLISION CENTER
 Address: 7676 N 76th Street
 City State Zip: Milwaukee, WI 53223

Contact:
 Work/Day: (414)362-7520
 FAX: (414)355-6744
 Work/Day:

Vehicle

2004 Nissan Maxima SE 4 DR Sedan
 6cyl Gasoline 3.5
 5 Speed Automatic

RECEIVED
 MAR 21 2013
 OFFICE OF
 CITY ATTORNEY

Lic. Plate:
 Lic Expire:
 Prod Date: 12/2003
 Veh Insp# :
 Condition:
 Ext. Color: PEWTER EFFECT
 Ext. Refinish: Two-Stage
 Ext. Paint Code: KY2

Lic State: WI
 VIN: 1N4BA41E04C880974
 Mileage: 130,511
 Mileage Type: Actual
 Code: Z1663D
 Int. Color:
 Int. Refinish: Two-Stage
 Int. Trim Code:

Options

Air Conditioning	Alarm System	Aluminum/Alloy Wheels
Anti-Lock Brakes	Automatic Dimming Mirror	Bucket Seats
Cargo/Trunk Net	Center Console	Climate Control For A/C
Compact Disc W/Tape	Cruise Control	Driver Airbags
Fog Lights	Garage Door Opener	Front Airbags
Intermittent Wipers	Keyless Entry System	Leather Steering Wheel
Lighted Entry System	Overhead Console	Power Brakes
Power Door Locks	Power Drivers Seat	Power Mirrors
Power Steering	Power Windows	Rear Window Defroster
Rem Trunk-L/Gate Release	Side Airbags	Skyview Glass Roof
Sport Suspension	Strg Wheel Radio Control	Tachometer
Telescopic Steering Whl	Tilt Steering Wheel	Tinted Glass
Trip Computer	Velour/Cloth Seats	

Damages

Line	Op	Guide	MC Description	MFR Part No.	Price	ADJ% B%	Hours	R
------	----	-------	----------------	--------------	-------	---------	-------	---

1	BR	208	Door Shell,Front RT	Blend Refinish 0.9 Blend 0.4 Two-stage	1.3	RF
2	RI	232	Pnl,Inner Door Trim RT	R & I Assembly	INC	SM
3	BR	60	13 Mldg,Front Door Side RT	Blend Refinish 0.3 Blend 0.6 Two-stage setup 0.1 Two-stage	1.0	RF
4	RI	60	Mldg,Front Door Side RT	R & I Assembly	0.3	SM
5	RI	230	Mirror,Outer R/C RT	R & I Assembly	0.3	SM
6	RI	228	Handle,Front Door Otr RT	R & I Assembly	1.3	SM
7	I	288	Door Shell,Rear RT	Repair	4.5*	SM
8	L	288	Door Shell,Rear RT	Refinish 1.9 Surface 0.4 Two-stage	2.3	RF
9	RI	447	Mldg,Rear Vent Glass RT	R & I Assembly	0.4	SM
10	RI	335	Mldg,Rear Door Belt RT	R & I Assembly	0.2	SM
11	BR	321	Mldg,Rear Door Side RT	Blend Refinish 0.2 Blend 0.1 Two-stage	0.3	RF
12	RI	321	Mldg,Rear Door Side RT	R & I Assembly	0.3	SM
13	RI	306	Handle,RR Door Outer RT	R & I Assembly	1.1	SM
14	I	390	Panel,Quarter RT	Repair	1.0*	SM
15	L	390	Panel,Quarter RT	Refinish 2.2 Surface 0.4 Two-stage	2.6	RF
16	RI	495	Finisher,Qtr Upper RT	R & I Assembly	0.3	SM
17	RI	454	Guard,Quarter Mud RT	R & I Assembly	0.2	SM
18	RI	538	Lens & Hsg, Tailamp RT	R & I Assembly	0.1	SM
19	N	566	Rear Bumper Cover R&I	Additional Labor	2.2*	SM
20	EC	M14	Corrosion Protection	Replace Economy	0.3*	RF
21	L	M15	Color Tint	Refinish	1.0*	RF
22	EC	M17	Cover Car Exterior	Replace Economy	\$5.00*	RF
23	SB	M60	Hazardous Waste Removal	Sublet Repair	\$5.00*	SM

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts	\$5.00	
Paint Materials	\$316.80	
Parts & Material Total		\$321.80
Tax on Parts & Material	@ 5.600%	\$18.02

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$56.00	4.5	7.7	12.2	\$683.20
Mech/Elec (ME)	\$105.00				
Frame (FR)	\$65.00				
Refinish (RF)	\$56.00	8.8		8.8	\$492.80
Paint Materials	\$36.00				

Labor Total		21.0 Hours	\$1,176.00
Tax on Labor	@ 5.600%		\$65.86
Sublet Repairs			\$5.00
Tax on Sublet	@ 5.600%		\$0.28
Gross Total			\$1,586.96
Net Total			\$1,586.96

Alternate Parts Y/00/00/00/00/00 CUM 50/00/00/00/00 Zip Code: 53224 Default

Audatex Estimating 6.0.925 ES 03/18/2013 10:19 AM REL 6.0.925 DT 01/01/2013 DB 03/15/2013
Copyright (C) 2011 Audatex North America, Inc.

2.0 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	ER = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Rebld	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2011 Audatex North America, Inc.
Audatex Estimating is a trademark of Audatex North America, Inc.