




2nd floor 1898 block corridor -



1st floor 1898 block northwest st



1st floor 1898 block typical classroom



Photo1 South elevation of 1884



Photo2 South elevation of 1884, 1888, a



Photo3 West elevation of 1898



Photo4 East elevation of 1884 block er



Photo5 North elevation.j



Photo6 North elevation of 1884



Photo7 North elevation of 1884 boiler house at



Photo8 West elevation of 1958 e



1st floor 1884 block corridor - loc




1st floor 1884 block typical class



1st floor 1888 block central stair -



1st floor 1888 block corridor -



1st floor 1888 block typical classroc



1st floor 1888 block typical classroom




1st floor 1888 block typical cloak



1st floor 1898 block corridor -




1st floor 1898 block typical classroom




1st floor 1884 block east sta




1st floor 1884 block corridor - lo



1st floor 1884 block typical classro



1st floor 1884 block typical cloak



1st floor 1888 block assembly hall