

10682022974



MILWAUKEE AUTO BODY
6462 NORTH 40TH STREET
MILWAUKEE, WI 53209-3002
PHONE: (414)353-5840
FAX: (414)353-6211

*** PRELIMINARY ESTIMATE ***

08/05/2022 10:46 AM

Owner

Owner: VANESSA SANDERS
Address: 3838 N. 38

Cell: (414)554-4809

Inspection

Inspection Date: 08/05/2022 10:47 AM

Inspection Type:

Contact: GARY RINGWELSKI
City State Zip: Milwaukee, WI 53209

FAX:

Repairer

Repairer: MILWAUKEE AUTO BODY
Address:
City State Zip: Milwaukee, WI 53209
Email: milwauto@wi.rr.com

Contact: GARY
Work/Day: (414)353-5840
Work/Day:

Target Complete Date/Time:

Days To Repair: 10

Vehicle

OEM Part Price Quote ID: 109747290

2016 Ford Fiesta SE 4 DR Sedan
4cyl Gasoline 1.6
6-Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 3FAUP4BJ1GM128948
Mileage Type: Actual
Code: P0153C
Int. Refinish: Two-Stage

Options

1st Row LCD Monitor(s)
Air Conditioning
Anti-Lock Brakes
Bucket Seats
Compact Spare Tire
Digital Signal Processor
Dual Airbags
Electronic Compass
Halogen Headlights
Keyless Entry System
MP3 Decoder
Power Door Locks
Power Windows
Side Airbags

2nd Row Head Airbags
Alarm System
Auto Headlamp Control
Center Console
Cruise Control
Driver Information Sys
Elect. Stability Control
Ext Mirror Turn Signals
Head Airbags
Leather Steering Wheel
Overhead Console
Power Mirrors
Pwr Accessory Outlet(s)
Split Folding Rear Seat

AM/FM CD Player
Aluminum/Alloy Wheels
Auxiliary Audio Input
Chrome Grille
Daytime Running Lights
Driver Knee Airbag
Electric Steering
Floor Mats
Intermittent Wipers
Lighted Entry System
Power Brakes
Power Steering
Rear Window Defroster
Strg Wheel Radio Control

10682022974

2016 Ford Fiesta SE 4 DR Sedan
Claim #:

08/05/2022 10:46 AM

Tachometer	Theft Deterrent System	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trip Computer	USB Audio Input(s)	Velour/Cloth Seats
Wireless Audio Streaming	Wireless Phone Connect	

Damages

Line Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Rear Doors								
1	BR	288	13 Door Shell,Rear RT	Blend Refinish 0.9 Blend 0.6 Two-stage setup 0.5 Two-stage			2.0	RF
Quarter And Rocker Panel								
2	L	390	Panel,Quarter RT	Refinish 2.0 Surface 1.5 Edge 0.7 Two-stage			4.2	RF
3	E	390	Pnl,Qtr (in Window Opn RT	G2BZ5427840A	\$766.88		22.5	SM
Deck Lid And Back Glass								
4	BR	479	Lid,Rear Deck	Blend Refinish 0.9 Blend 0.4 Two-stage			1.3	RF

4 Items

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts		\$766.88
Paint & Materials	7.5 Hours @ \$45.00	\$337.50
Parts & Material Total		\$1,104.38
Tax on Parts & Material	@ 5.500%	\$60.74

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$65.00	22.5		22.5	\$1,462.50
Mech/Elec (ME)	\$95.00				
Frame (FR)	\$95.00				
Refinish (RF)	\$65.00	7.5		7.5	\$487.50
Labor Total				30.0 Hours	\$1,950.00
Tax on Labor		@ 5.500%			\$107.25
Gross Total					\$3,222.37
Net Total					\$3,222.37

Alternate Parts Y/01/00/00/01/01 Cumulative 01/00/00/01/01 Zip Code: 53209 Default
 OEM Part Prices DT 08/05/2022 10:47 AM EstimateID 984846161657470976 QuoteID 109747290
 SPPL Yes Zip Code: 00000 Default
 Rate Name Default

#10 682022974

OFFICE OF CITY ATTORNEY
09 AUG 22 AM 09:19

CITY OF MILWAUKEE
2022 AUG -8 PM 2:44
CITY CLERK'S OFFICE



SCHOK'S AUTO BODY
5701 WEST BURLEIGH STREET
MILWAUKEE, WI 53210
PHONE: 414-873-9944 FAX: 414-873-5040
FED TAX ID# 39-1330692

*** PRELIMINARY ESTIMATE ***

08/04/2022 09:52 AM

Owner

Owner: Vanessa Sanders
Address: 3838 N. 38th St.

Work/Day: (414)554-4809

Inspection

Inspection Date: 08/04/2022 09:53 AM
Primary Impact: Right Rear Side

Inspection Type:
Secondary Impact:

Appraiser Name: Mary Kuhn
Email: Schoksauto@gmail.com

Appraiser License # :

Repairer

Target Complete Date/Time:

Days To Repair: 7

Vehicle

OEM Part Price Quote ID: ****

2016 Ford Fiesta SE 4 DR Sedan
4cyl Gasoline 1.6
6-Speed Automatic

Lic Expire:
Veh Insp# :
Condition:

Ext. Color: Magnetic

Ext. Refinish: Two-Stage
Ext. Paint Code: PN4DQ

VIN: 3FADP4BJ1GM128948
Mileage Type: Actual
Code: P0153C
Int. Color: Match Point/View Charcoal
Black],[3D
Int. Refinish: Two-Stage
Int. Trim Code: 000DW

Options - AudaVIN Information Received

1st Row LCD Monitor(s)
Air Conditioning
Anti-Lock Brakes
Auxiliary Audio Input
Chrome Grille
Daytime Running Lights
Driver Knee Airbag
Electric Steering
Floor Mats
Intermittent Wipers
Lighted Entry System
Power Brakes
Power Steering
Rear Window Defroster

2nd Row Head Airbags
Alarm System
Auto Headlamp Control
Bucket Seats
Compact Spare Tire
Digital Signal Processor
Dual Airbags
Electronic Compass
Halogen Headlights
Keyless Entry System
MP3 Decoder
Power Door Locks
Power Windows
Side Airbags

AM/FM CD Player
Aluminum/Alloy Wheels
Automatic Trans
Center Console
Cruise Control
Driver Information Sys
Elect. Stability Control
Ext Mirror Turn Signals
Head Airbags
Leather Steering Wheel
Overhead Console
Power Mirrors
Pwr Accessory Outlet(s)
Split Folding Rear Seat

10682022974

2016 Ford Fiesta SE 4 DR Sedan
Claim #:

08/04/2022 09:52 AM

Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Traction Control System	Trip Computer	USB Audio Input(s)
Velour/Cloth Seats	Wireless Audio Streaming	Wireless Phone Connect

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Roof										
1	I	342		Panel,Roof	Repair				2.0*	SM
2	L	342		Panel,Roof	Refinish				3.5	RF
					2.9 Surface					
					0.6 Two-stage					
Rear Doors										
3	BR	288	13	Door Shell,Rear RT	Blend Refinish				2.0	RF
					0.9 Blend					
					0.6 Two-stage setup					
					0.5 Two-stage					
4	E	258		Mldg,Rear Door Belt RT	AE8Z5425596A	\$38.72			0.2	SM
5	RI	292		Handle,RR Door Outer RT	R & I Assembly				0.2	SM
Quarter And Rocker Panel										
6	I	390		Panel,Quarter RT	Repair				8.0*	SM
7	L	390		Panel,Quarter RT	Refinish				2.4	RF
					2.0 Surface					
					0.4 Two-stage					
Deck Lid And Back Glass										
8	L	479		Lid,Rear Deck	Refinish				2.6	RF
					2.2 Surface					
					0.4 Two-stage					
Rear Bumper										
9	RI	565		Rear Bumper Cover R&I	R & I Assembly				1.8	SM
Rear Body, Lamps And Floor Pan										
10	RI	573		Lens,Taillamp Outer RT	R & I Assembly				INC	SM
10	Items									

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts		\$38.72
Paint & Materials	10.5 Hours @ \$42.00	\$441.00
Parts & Material Total		\$479.72
Tax on Parts & Material	@ 5.500%	\$26.38

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$64.00	2.2	10.0	12.2	\$780.80
Mech/Elec (ME)	\$125.00				
Frame (FR)	\$85.00				
Refinish (RF)	\$64.00	10.5		10.5	\$672.00

106 82022974

Labor Total		22.7 Hours		\$1,452.80
Tax on Labor	@ 5.500%		\$79.90	
Gross Total				\$2,038.80
Net Total				\$2,038.80

Alternate Parts Y/01/00/00/01/01 Cumulative 01/00/00/01/01 Zip Code: 53210 Default
OEM Part Prices DT 08/04/2022 09:53 AM EstimateID 984470199300268032 QuotelD ****
Rate Name Default

Audatex Estimating 8.1.519 ES 08/04/2022 09:55 AM REL 8.1.519 DT 07/01/2022 DB 08/01/2022

State Disclosure:WI

© 2022 Audatex North America, Inc.

**2.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.**

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

- | | | |
|----------------------------|---|--------------------------------|
| * = User-Entered Value | ^ = Labor Matches System Assigned Rates | E = Replace OEM |
| NG = Replace NAGS | EC = Replace Economy | OE = Replace PXN OE Srpls |
| UE = Replace OE Surplus | ET = Partial Replace Labor | EP = Replace PXN |
| EU = Replace Recycled | TE = Partial Replace Price | PM = Replace PXN Reman/Reblt |
| UM = Replace Reman/Rebuilt | L = Refinish | PC = Replace PXN Reconditioned |
| UC = Replace Reconditioned | TT = Two-Tone | SB = Sublet Repair |
| N = Additional Labor | BR = Blend Refinish | I = Repair |
| IT = Partial Repair | CG = Chipguard | RI = R & I Assembly |
| P = Check | AA = Appearance Allowance | RP = Related Prior Damage |



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2022 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.