

mailed 04/27/2024

TO: THE OFFICE OF THE CITY CLERK OF MILWAUKEE
and/or THE OFFICE OF THE CITY ATTORNEY OF MILWAUKEE

FROM: CRISSY L HERRELL

9021 H N SWAN RD

MILWAUKEE, WI 53224

PHONE NUMBER: (414) 236-2218 can be reached anytime

I, CRISSY L HERRELL, am sending this document to you to inform you of my intent of seeking money damages in the amount of \$5,995 dollars, due to the loss of use of my vehicle which happened on 01/12/2024.

copy of signature Crissy L Herrell

actual signature Crissy L Herrell 04/27/2024

ESTIMATES: Enclosed are 2 itemized estimates that exceed the value of the vehicle

ALSO ENCLOSED: A LETTER DETAILING THE DESCRIPTION OF INCIDENT AND EXPLANATION OF DAMAGES

DATE OF INCIDENT: 01/12/2024

TIME: SOMETIME BETWEEN 9PM, 01/12/2024 AND 7AM 01/13/2024

ADDRESS:

CITY OF MILWAUKEE
CITY CLERK'S OFFICE
2024 MAY - 1 2:53

DEAR OFFICE OF CITY ATTORNEY,

On the evening of 01-12-2024 @ 9:00 PM I parked my 2008 chevy TRAILBLAZER next to a vacant lot located between the addresses of 9104 W. Alyn and 9120 W. Alyn in the city of Milwaukee, WI. We had a terrible blizzard that evening and the heavy load of snow split a tree, that was located on the side of the sidewalk nearest to the curb, in half, the long way and it landed right on the roof of my TRAILBLAZER. I do have pictures on my phone also. THE DEPT OF FORESTRY has pictures. I discovered it @ 7:00 AM 01-13-2024.

So I'm not really sure what's fair, how much to ask for. I purchased the vehicle in August of 2023 it was listed at \$5,995 at Wiegman's on Fond du Lac ave. however Rob the owner is a friend as I've been taking my cars there for years so he let me have it for \$5,495 + taxes plates, and registration it came to \$6,495. and I had only driven it for one week, in October, because my ride to work had their car in the shop. I purchased it to use this spring as I planned on moving closer to my work.

I can no longer use it to move furniture as the tree broke out my back window and dented the back door right in the corner where the door and body meet so the back door doesn't open anymore and a window cannot be installed without doing all kinds of body work that would end up exceeding the value of the vehicle. So I haven't had the work done cz I didn't want to fix it only to have you say it's cheaper to buy you another car of the same value. Also the city did not come to get the tree off my vehicle for 5 days I missed 4 days of work. But I'm not really worried about reimbursement for that, as I just used up some paid time off days, and I was glad to do it as it was 40 below zero anyway. So to be fair, I'm not asking for that back.

I've put a for sale sign in the window but I've only had one offer for \$1,000. Cause what I've got now is a gas guzzler without purpose, heat, air, or a back window (the heat & air work but w/no window they make no difference).

Also as it was only 5,995 I only have liability on it.

Also I did not take the \$1,000 offer on it cz, I dont know it just feels like too much of a loss and I want to see where I stand with you guys first.

So I guess call me so we can figure this out.

Thank you

Crissey J. Herrell

(414) 236-2218 anytime

P.S. I wanted to send you the Kelley Blue Book value from Jan 12, 2024 but I couldn't get the app to work.



METICULOUS AUTO BODY INC

Details Make the Difference
8800 FOND DU LAC AVENUE, MILWAUKEE, WI
53225
Phone: (414) 464-9000
FAX: (414) 464-5950

Workfile ID: a62ba1dc
PartsShare: 7MnxXd
Federal ID: 39-1960215

Preliminary Estimate

Customer: Herrell, Crissy

Written By: Kaitlin Mayerson*

Insured: Herrell, Crissy
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Herrell, Crissy
(414) 236-2218 Cell

Inspection Location:
METICULOUS AUTO BODY INC
8800 FOND DU LAC AVENUE
MILWAUKEE, WI 53225
Repair Facility
(414) 464-9000 Business

Insurance Company:

VEHICLE

2008 CHEV TrailBlazer 4WD w/1FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI

VIN: 1GNDT13S082203473
License:
State: WI

Interior Color:
Exterior Color:
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:

Job #:

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks

DECOR

Dual Mirrors
Tinted Glass
Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Window Wiper
Climate Control

RADIO

AM Radio
FM Radio
Stereo
Search/Seek
CD Player

Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package

Get live updates at www.carwise.com/e/4Hdq5w

Preliminary Estimate

Customer: Herrell, Crissy

2008 CHEV TrailBlazer 4WD w/1FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		RESTRAINT SYSTEMS					
2	R&I	RT Head air bag short wheel base			m	0.5	
3	R&I	LT Head air bag short wheel base			m	0.5	
4		ROOF					
5	*	Rpr Roof panel w/o sunroof				<u>20.0</u>	3.8
6		Add for Clear Coat					1.5
7	R&I	RT R&I luggage rack				0.6	
8	R&I	LT R&I luggage rack				Incl.	
9	R&I	Sunroof glass				0.5	
10	R&I	Headliner w/o sunroof, w/o rear entertainment w/o digital audio				4.5	
11		PILLARS, ROCKER & FLOOR					
12	R&I	RT W/S pillar trim gray				Incl.	
13	R&I	LT W/S pillar trim gray				Incl.	
14	R&I	RT Uptr ctr plr trim w/head air bag				Incl.	
15	R&I	LT Uptr ctr plr trim w/head air bag				Incl.	
16	R&I	RT Lwr ctr plr trim ebony				0.4	
17	R&I	LT Lwr ctr plr trim ebony				0.4	
18		QUARTER PANEL					
19	*	Rpr LT Quarter panel w/short wheel base				<u>8.0</u>	2.6
20		Overlap Major Adj. Panel					-0.4
21		Add for Clear Coat					0.4
22	R&I	LT Qtr glass GM, all, w/short wheel base tinted				2.0	
23		LIFT GATE					
24	*	R&I Lift gate glass GM, w/o rear defogger tinted				<u>3.0</u>	
25	*	Repl LKQ lift gate +30%	89023979	1	286.00	<u>3.8</u>	3.1
26		Overlap Major Adj. Panel					-0.4
27		Add for Clear Coat					0.5
28		Add for rear wiper				0.4	
29		Refn lift gate exterior surface only					2.1
30		Refn lift gate underside					1.0
31		Refn molding side					0.3
32		Refn molding upper					1.0
33		Refn outer handle					0.3
34	#	R&I LKQ Transfer				3.0	
35	#	***** ADD-ONS *****		1			
36	#	Cover car		1	10.00		
37	#	Subl Hazardous Waste Removal		1	3.00 T		
38	#	Repl Corrosion protection primer		1	10.00 T	0.2	
39	#	Repl Flex additive		1	8.00 T		

Preliminary Estimate

Customer: Herrell, Crissy

2008 CHEV TrailBlazer 4WD w/1FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI

40	#	Rpr	Setup & measure		2.0
41	#	Rpr	Rough pull		6.0
42	**	Repl	A/M Urethane kit	1	
43	#	Rpr	FIT TIME		4.0
SUBTOTALS				317.00	59.8
					15.8

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				296.00
Body Labor	59.8 hrs	@	\$ 70.00 /hr	4,186.00
Paint Labor	15.8 hrs	@	\$ 70.00 /hr	1,106.00
Paint Supplies	15.8 hrs	@	\$ 48.00 /hr	758.40
Miscellaneous				21.00
Subtotal				6,367.40
Sales Tax	\$ 6,367.40	@	7.9000 %	503.02
Grand Total				6,870.42
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				6,870.42

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

CALIBER COLLISION

CALIBER - GLENDALE WI
RESTORING THE RHYTHM OF YOUR LIFE
2300 Florist Ave, Glendale, WI 53209
Phone: (414) 351-1123
FAX: (414) 351-1548

Workfile ID: a0725c68
Federal ID: 33-0730794
Federal EPA: WIR000033415

Preliminary Estimate

Customer: Herrell, Chrissy

Written By: Laurence Smith

Insured: Herrell, Chrissy
Type of Loss:
Point of Impact: 06 Rear

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Herrell, Chrissy
(262) 225-7428 Cell

Inspection Location:
CALIBER - GLENDALE WI
2300 Florist Ave
Glendale, WI 53209
Repair Facility
(414) 351-1123 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2008 CHEV TrailBlazer 4WD w/2FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI maroon

VIN: 1GNDT13S082203473	Interior Color: Dk Grey	Mileage In: 207,782	Vehicle Out:
License:	Exterior Color: maroon	Mileage Out:	
State:	Production Date:	Condition:	Job #:

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors

DECOR

Dual Mirrors
Body Side Moldings
Privacy Glass

Console/Storage

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel

Cruise Control
Rear Defogger
Keyless Entry
Alarm
Rear Window Wiper
Climate Control

RADIO

AM Radio
FM Radio

Stereo

Search/Seek
CD Player
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System

ROOF

Luggage/Roof Rack

SEATS

Cloth Seats
Bucket Seats
Reclining/Lounge Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package

Preliminary Estimate

Customer: Herrell, Chrissy

2008 CHEV TrailBlazer 4WD w/2FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI maroon

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	ROOF						
open	Repl	Roof panel w/o sunroof	10381191	1	803.60	20.0	3.8
3		Add for Clear Coat					1.5
4	R&I	RT R&I luggage rack				0.6	
5	Repl	LT Side rail short wheel base w/o chrome	25853983	1	724.29	Incl.	
6	R&I	Headliner w/o sunroof, w/o rear entertainment w/digital audio				Incl.	
7	QUARTER PANEL						
8	*	Blnd RT Quarter panel w/short wheel base					2.6
9	*	Blnd LT Quarter panel w/short wheel base					2.6
10	R&I	RT Qtr glass GM, all, w/short wheel base tinted				2.0	
11	R&I	LT Qtr glass GM, all, w/short wheel base tinted				2.0	
12	LIFT GATE						
13	*	Repl LKQ lift gate +25%	89023979	1	293.75	0.8	3.1
14		Overlap Major Adj. Panel					-0.4
15		Add for Clear Coat					0.5
16	*	Repl LKQ Lift gate glass GM, w/rear defogger privacy +25%	25917707	1	212.50	1.0	
17	Repl	LT Support strut	15093449	1	39.05	0.2	
18	#	Repl Corrosion Protection / Primer		1	15.00 T	0.3	
19	Repl	LT Side molding Chevrolet	15895307	1	145.48	0.2	
20	R&I	RT Side molding Chevrolet				0.2	
21	*	R&I License pocket				0.7	
22	R&I	Upper molding Chevrolet				0.5	
open	Repl	Emblem bowtie	20830823	1	92.00	0.2	
24	R&I	Handle				0.4	
25	R&I	Wiper arm				0.2	
26	*	R&I Wiper motor			m	0.9	
27	R&I	Upper molding gray				0.3	
28	R&I	Lower trim panel gray				0.3	
29	VEHICLE DIAGNOSTICS						
30	#	Post-repair scan		1	80.00 T	0.5	
31	#	Pre-repair scan		1	40.00 T	0.5	
32	#	Subl Hazardous Waste Disposal		1	6.00 T		
33	#	Repl Urethane Kit - Stock/Aftermarket		1	36.00 T		
34	#	Urethane Adhesive Removal		1	T	0.3	
35	#	Repl Seam Sealer		1	30.00 T	0.5	
SUBTOTALS					2,517.67	32.6	13.7

Preliminary Estimate

Customer: Herrell, Chrissy

2008 CHEV TrailBlazer 4WD w/2FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI maroon

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				2,310.67
Body Labor	32.6 hrs	@	\$ 82.00 /hr	2,673.20
Paint Labor	13.7 hrs	@	\$ 82.00 /hr	1,123.40
Paint Supplies	13.7 hrs	@	\$ 56.00 /hr	767.20
Miscellaneous				207.00
Subtotal				7,081.47
Sales Tax	\$ 7,081.47	@	5.9000 %	417.81
Grand Total				7,499.28

MyPriceLink Estimate ID / Quote ID:

1210303764993417216 / 135775352

=====

Caliber Collision is the industry leader in quality collision repair. Since day one, our highest purpose has been to get people just like you back on the road as quickly as possible and fully restored to the rhythm of your life. You can be sure we do everything possible to ensure your complete satisfaction including:

- Personalized, high quality service from the largest collision repair company in the U.S.
- Consistently ranked among the highest customer satisfaction scores in the industry.
- Approved by every major insurance company in the U.S.
- Expedited car rental and towing services to get you back on the road again in no time.
- Repair work backed by a written, lifetime warranty honored at every location.
- 24/7/365 customer service to answer questions and put your mind at ease.

This is a preliminary estimate based on visible damage. There may be additional repairs needed once the vehicle is taken apart by our I-CAR Gold Class technicians to identify any additional damage.

If an insurance company has written an estimate for you, please provide us with a copy. Properly endorsed insurance company checks are welcome as payment for the repair of your vehicle. Caliber Collision gladly accepts all major credit cards, debit cards, cashier's and traveler's checks. See your Caliber Collision center for details on acceptance of personal checks.

Before leaving your vehicle with us, please remove all important personal and valuable items from your vehicle. Caliber Collision is not responsible for belongings left in your vehicle.

Please let us know how we can be of further assistance, and when we can schedule an appointment for your vehicle to be repaired.

Caliber Collision - Restoring The Rhythm Of Your Life

=====

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: Herrell, Chrissy

2008 CHEV TrailBlazer 4WD w/2FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI maroon

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE1GN02, CCC Data Date 04/09/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Herrell, Chrissy

2008 CHEV TrailBlazer 4WD w/2FL Fleet Preferred Equip Group (Fleet) 4D UTV 6-4.2L Gasoline SFI maroon

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
2	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#10381191 Roof panel w/o sunroof Quote: 2140212380 Expires: 05/18/24	\$ 803.60
5	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#25853983 LT Side rail short wheel base w/o chrome Quote: 2150458994 Expires: 05/18/24	\$ 724.29
13	LKQ Corp 2101 Beloit Avenue Janesville WI 53546 (800) 362-9451	#~380113901 LKQ lift gate +25% Decklid / Tailgate LT,4DR,28I (REAR DOOR EXTENDS INTO WHEEL WELL, 113 ,S#\$N1579 Quote: 2471532706 Expires: 06/02/24	\$ 235.00
16	LKQ Corp 2101 Beloit Avenue Janesville WI 53546 (800) 362-9451	#~383591845 LKQ Lift gate glass GM, w/rear defogger privacy +25% Back Glass LT (REAR DOOR EXTENDS INTO WHEEL WELL, 113 WB), W/PRIVACY ,S#\$CT474 Quote: 2471534690 Expires: 06/02/24	\$ 170.00
17	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15093449 LT Support strut Quote: 2150856181 Expires: 05/18/24	\$ 39.05
19	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#15895307 LT Side molding Chevrolet Quote: 2148860022 Expires: 05/18/24	\$ 145.48
23	Kunes Buick GMC of Greenfield Inc. 3615 S.108th Street Greenfield, WI 53228	#20830823 Emblem bowtie Quote: 2150258685 Expires: 05/18/24	\$ 92.00