

STREET / SIDEWALK / ENCROACHMENT
FIELD INVESTIGATION REPORT

CITY OF MILWAUKEE
Department of Public Works – Forestry Division

Encroachment Record # PWCF-25-04053

In accordance with Sections 116-56 of the Milwaukee Code of Ordinances,

the property at: 2967 N. 45th Street
(Address of encroachment)

having Tax Key No. 3070048000, was inspected and the following was noted:

Encroachment – City Right of Way

- ☐ Street Encroachment
☐ Sidewalk Encroachment
☒ Alley Encroachment

What is Encroaching?

- ☒ Tree Limbs
☒ Shrubs
☒ Vegetation

In order to achieve compliance, the following must be completed within 15 days:

- ☒ Prune or remove all vegetation back to the property line and/or to a height of no less than 14 ft. directly above alley or street pavement.
☐ Prune or remove all vegetation back to the property line and/or to a height of no less than 8 ft. directly above the sidewalk pavement.

(Additional Notes)

**** All encroachments must be removed to comply with the above stated city ordinances. **** Please refer to the enclosed diagram for required clearances.

To view violation photos or documents related to this record, please go to milwaukee.gov/lmsviolation

1. On the middle of the page under General Search, enter the record number (found at the top of this notice) under Record Number and hit enter.
2. Select "Record Info" drop down and choose "Attachments".
3. Select on any of the blue links to see the photos or files attached to that record. Once you select a blue link you may need to go to your downloads folder to see the records.

District C Section# 307

Inspection Date 07-07-2025

Inspector Strankowski

Compliance Check Date 7-23-25

Compliance? NO Done By Owner

Completion Date _____