Amy Werdin

1144 Iris Lane Grafton, WI 53024 Phone: (414) 550-7648

September 25, 2006

Milwaukee City Clerk 200 E. Wells Street Room 205 Milwaukee, WI 53202 2006 SEP 27 PH 4: 05
RONALD D LEONHARDT

Dear Sir or Madam:

I received a letter from you stating that you were denying my claim for \$287.88 for the damage done to my vehicle on June 7, 2006 when a tire fell off a City dump truck into my lane of traffic on Good Hope Road and N. 51st Boulevard.

I am requesting a hearing for this matter. This is in regards to C.I. File No: 06-V-114.

I look forward to hearing from you as to when this will occur. Thank you.

Sincerely,

Amy Werdin

POFFIC OF

RECEIVERUNE

Amy Werdin

1144 Iris Lane Grafton, WI 53024 Phone: (414) 550-7648

June 27, 2006

City Clerk

ATTN: CLAIMS

200 E. Wells Street, Room 205 Milwaukee, WI 53202-3567

Dear Sir or Madam:

I am filing a claim against the City of Milwaukee in regards to an incident that happened on Wednesday, June 7, 2006. I am seeking \$287.88 in damages that occurred to my car as a result of this incident.

On Wednesday, June 7, 2006 at approximately 8:15am I was driving east on Good Hope Road, just before the railroad overpass by N. 51st Boulevard. Good Hope Road is a 4-lane divided road. I was in the right lane. As I was driving, a large yellow City of Milwaukee dump truck traveling in the left lane passed by me. As the truck passed me and was now two cars ahead of me I saw a large tire fly out of the top of the truck and land in my lane of traffic. The car in front of me ran the tire over and then I proceeded to run it over as well as there was no where else for me to go. Both of us pulled over to assess the damage to our cars. The woman in front of me had two flat tires. I had one flat tire due to a bent rim on my front right passenger side.

I then had to have my car towed to a dealership where they had to replace the rim and adjust the alignment.

I have attached the invoice from the dealership, which shows the monetary damages incurred and paid for as a result of this incident. I have also attached a photo of the rim that was bent when I ran over the tire that fell out of the dump truck.

I appreciate you taking the time to consider my claim and look forward to hearing from you soon.

- werden

Sincerely,

Amy Werdin

Encl.

CITY FICE OF ...







11333 W. BURLEIGH ST. * WAUWATOSA, WI 53222 PHONE: 414/771/8810 FAX: 414/771/9094 www.dodge4you.com

CELL: 414-550-7647

												CELL:	414-550-7647
CUSTOMER NO.	115909		ÉDWARI						11		06709	/06	DOC\$214052
ERIC WERDIN 1144 IRIS LANE GRAFTON, WI 53024			LABOR RATE LIGH		rigen	ĵa755		MILEAC	MILEAGE 119,074		BRIGHT SILV		STOCK NO.
			00/DODGE/STRATUS/STRATUS						· · · · · · · · · · · · · · · · · · ·		.L :		DELIVERY MILES
			VEHICLE IC3	NOE J	4 6	хх	Y N Z	2 4	0 9	4 6	544771	LER NO.	03/31/00
			F. T. E. NO.	'			P.O. NO				°067b7	/06	
1		414 ⁵⁵ 815-4423	COMMENTS								L		MO: 119075
J# 1 22D0Z	WHEEL OWNER STATES	S & TIRES RAN OVER TIRE IN ROAD D REPLACED RIGHT FRONT	CHECK A	TECH(S	1 - 9014		~ * * = =	~	•••	27.60			
J# 2 01D0Z	OWNER STATES	STMENTS SAVE OLD RIM		TECH(S):9014	ŀ				0.00		\$15 PER DAY (THAN 20,000 L MOTOR VEHICL	HARGED BETWEEN \$10 AND ON MOTOR VEHICLES LESS .BS. AND \$25 PER DAY ON .ES OVER 20,000 LBS.
J# 3 01DOZIN	INSIDE VEHICE FO INFOR OWNER STATES COMPLETED	MATION		TECH(S):9014	Į				0.00		The parts check hereof are co warranty, copies the selling dealer applicable to the this repair. The d manufacturer's w	ANTY INFORMATION of Warranty on the face side versed by a manufacturer's of which are available through There are no other warranties parts or service turnished in ealer is not a party to any such varranty.
J# 4 31DOZBT(VEHICLE TOWER CHECK FOR SUB VEHICLE TOWER	BLE TOWING) TO DEALERSHIP, SEE R BLET TOW BILL(S) AND P O IN FOR REPAIR OR EST BLET SECTION FOR CHARGE	ELATED CO ROPER CHA IMATE SE	F RFIA	FOR C	AUSE				0.00	į	THE DEALER CLAIMS ALL WAI OR IMPLIED, INI RANTIES OF ME FOR A PARTICUI ASSUMES NOR PERSON TO ASS IN CONNECTION PARTS AND/OR NOT RE FAUTITIE	HEREBY EXPRESSLY DIS- RRANTIES, EITHER EXPRESS CLUDING ANY IMPLED WAR- RCHANTABILITY OR FITNESS AR PURPOSE, AND NETISER AUTHORIZES ANY OTHER AUTHORIZES ANY OTHER SUME FOR IT ANY LIABILITY I WITH THE SALE OF THESE ESTRICE BUYER SHALL ESTO RECOVER FROM THE ER ANY CONSECUENTIAL HAGES TO PROPERTY, LOSS OF USE, LOSS OF PROFILES OR INCOME OR
J# 5 22D0ZHC	OWNER STATES	. COV/CENTER CAP ESTIMATE ON WHEEL COVI PART #RN33PAKAA		TECH(S)	9014					0.00		SELLING DEAL DAMAGES, DA DAMAGES FOR TIME, LOSS OF ANY OTHER INC	ER ANY CONSEQUENTIAL MAGES TO PROPERTY, LOSS OF USE, LOSS OF PROFITS, OR INCOME, OR IDENTAL DAMAGES.
J# 6+27DOZAL4	OWNER STATES	EL ALIGNMENT PERFORM 4 WHEEL ALIGNM PLETE 4 WHEEL ALIGNMEN	ENT	TECH(S) OPER VE						79.95			
						TOTAL -	LABOR	₹	1	07.55			
		7-AB WHEEL S				TOTAL -	PARTS	}		98.14 98.14	Transportation of the state of		
J0B # 4 19	373 4018	INV#-INV.DATE-DESCRIP 06/08/06 TOWING	40184			TOTAL -				55.90 55.90			
JOB # A JOB # A	VIRO ENVII	RIPTION ICE SHOP SUPPLIES RONMENTAL SERVICE CHAR	GES			TOTAL -	MISC			8.87 2.15 1.02	Trymmus Lands Arguments (Alberta Constanting	Z STUFFED	AAA
CUSTOMER HERE ORIG APPROVED REVI: BY ERIC COMMENTS	BY ACKNOWLEDGE INAL ESTIMATE SED ESTIMATE (CC	ES RECEIVING OF \$0.00 (+TAX) (# 1) OF \$390.00 (+TAX) OMMENTS RECEIVED AUTH I	AX) ON 06 BY PHONE	/09/06	AT 08	:30am					ANN MANAGEMENT AND	EXCEPTENCE EXCEPTENCE THOMOTINE	Approved Auto Repair
DELETED OPERA D8DOZ	FION(S) ELECTRICAL		* * * * - * - * - *			******					No. 1- Committee		OU!
													Richannopap

Recognition of the Committee of the Comm

CUSTOMER COPY

[CONTINUED ON NEXT PAGE] 01:27pm



CELL: 414-550-7647

CUSTOMER NO 11590	9	EDWARD AN	DERSON	9545	TAG NO. 1194	06/09/06	DOCS214052	
ERIC WERDIN		LABOR RATE	[™] ₩55755	Mil	119,074	BRIGHT SILV	STOCK NO.	
1144 IRIS LANE GRAFTON, WI 53024		00/DODGE/STRATUS/STRATUS			04/26/00	O DELIVERY MILES		
·	T B 3 E) 4 6 X X Y	/ N 2	40946	SELLING DEALER NO.	103731700		
		FT.E.NO.	·····	P O. NO.		°06707/06		
3E262E268-3864	414-815-4423	COMMENTS		J			™60° ° ° 119075	

* PAY METHOD: CASH.... CHECK#..... IN/HOUSE CHG #..... AMEX..... DISCOVER REC'D DATE:

DODGE CITY, YOUR "FIVE-STAR" DEALER, WANTS YOU TO BE 100% SATISFIED. IF A PROBLEM--DON'T HESITATE TO LET US KNOW!!!

CONTINUED MAINTENANCE SERVICE SATURDAYS FROM 8:00 - 12 NOON

CUSTOMER SIGNATURE

TOTAL LABOR.... 107.55 TOTAL PARTS.... 98.14 TOTAL SUBLET... 55.90 TOTAL G.O.G....
TOTAL MISC CHG. 0.00 11.02 TOTAL MISC DISC 0.00 TOTAL TAX..... 15.27

TOTAL INVOICE \$ 287.88 STORAGE IS CHARGED BETWEEN \$10 AND \$15 PER DAY ON MOTOR VEHICLES LESS THAN 20,000 LBS. AND \$25 PER DAY ON MOTOR VEHICLES OVER 20,000 LBS.

WARRANTY INFORMATION
The parts checked "Warranty" on the face side hereof are covered by a manufacturer's warranty, copies of which are available through the selling dealer. There are no other warranties applicable to the parts or service furnished in this repair. The dealer is nor a party to any such manufacturer's warranty.

Manufacturer's warrarry.
THE DEALER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS
OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS
FOR A PARTICULAR PURPOSE, AND NEITHER
ASSUMES NOR AUTHORIZES ANY OTHER
PERSON TO ASSUME FOR IT ANY LIABILITY
IN CONNECTION WITH THE SALE OF THESE
PARTS ANDOR SERVICE, BUYER SHALL
NOT BE ENTITLED TO RECOVER FROM THE
SELLING DEALER ANY CONSEQUENTIAL
DAMAGES, DAMAGES TO PROPERTY,
DAMAGES FOR LOSS OF USE, LOSS OF
TIME, LOSS OF PROFITS, OR INCOME, OR
ANY OTHER INCIDENTAL DAMAGES.





THANK YOU!

PAGE 2 OF 2


CUSTOMER COPY

[END OF INVOICE] 01:27pm

Dodge City Of Waywatosa 11333 W. Burleigh

Name Address

Telephone Vehicle (VIN) License Technician Mileage Time Printed



Left Front

- April 1	Actual		Before	1 1	Specified	Ra	 LD	ge	****
para mana	Ø, 24 p, q.e	-	Ø.3°	***	-0,6° 2.7°		-	.I. 60 30	
A	0.06° 7.0°	to compare transcent	-W.53° 6.8°	1	-0.050	(3) ₂	1	<u>.</u>	
	7, E0	forms and	7.10	1	5 66 4 16 16 In 186 4 10 15		-	2 q	- 1

Camber Caster ĭoe SAl Included Angle Turning Angle Diff. | Actual | Before | Specified Range 0.2° | 0.2° | -0.6° | 3.1° | 2.5° | 2.2° | 2.2° | 2.5° | 7.8° | 7.4° | 7.5° | 7.6° | 9.50 4.50 2.150 A 3 4 4 #

Right Front

Frant

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

1	Actual	Before	Specified	Rangel
1	0.09	8.10	-0.70	Ø. 7°
W-1		Ø.40	-1.00	1.00
	-0.20	-0.5°	* * * * * * * * * * * * * * * * * * *	4 F 9 R 5
	0.13	-0.034	-0.10	Ø.30°
,		t kalgajar -	0 0 4 d k	*****

Laft Sear

Actual | Before | Specified Range | -2,4° | -8,3° | -2,6° | 0,2° | 0,2° | 0,2° | 0,0° | 0,0° | 0,15° |

Camber Toe

Right Rear | Actual | Before | Specified Range | -0.2° | -0.6° | -0.6° | 0.2° | 0.07° | -0.74° | -0.05° | 0.15°

Rear

Oross Camber Total Toe Thrust Angle

r Actual | Before | Specified Range: -0.2° 0.15° 2.81° 9.39 -0.719 -0.199 0.389 -0.139 0.30° 9.15°i

