

RECEIVED
OFFICE OF CITY ATTORNEY

DEC 22 2021

9:57 A.M./P.M.

AB

Darrell Wilson

5341 North 57th Street

Milwaukee, WI 53218

December 17, 2021

Tearman Specncer

Milwaukee City Attorney Office

RE: Communication from Darrell Wilson

C.I. File No. 1068-2021-1178

Dear Sir,

My name is Teresa Beamon-Wilson, I am writing on the behalf of my husband Darrell Wilson.

And I am responding to the letter date November 22, 2021. This letter is a written appeal on you all decision as for the damages cause by a falling branch from a city tree. These trees I had called about a number of times. I told them at city call center about branches falling from that tree and others in close proximity. The city is 100% liable for the damages to my husband vehicle. I have spoken to my Alderman and my husband Darrell Wilson, is requesting a hearing regarding this matter.

Thank you,

Darrell Wilson

414-617-8017



**Gerber Collision & Glass -
Milwaukee/Douglas Ave.**

Highly Wreck - ommended!
6301 W Douglas Ave, Milwaukee, WI 53218
Phone: (414) 466-2111

Workfile ID: 03eb37f2
Federal ID: 51-0394062
State ID: N/A
Federal EPA: N/A
State EPA: N/A

Preliminary Estimate

Customer: WILSON, DARRELL

Written By: Michael Schwister

Insured: WILSON, DARRELL
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
WILSON, DARRELL

5341 N 57TH ST
MILWAUKEE, WI 53218
(414) 554-5484 Cell

Inspection Location:
Gerber Collision & Glass -
Milwaukee/Douglas Ave.
6301 W Douglas Ave
Milwaukee, WI 53218
Repair Facility
(414) 466-2111 Business

Insurance Company:
SELF PAY

2021 AUG 26 AM 10:39
CITY CLERK'S OFF
CITY OF MILWAUKEE

VEHICLE

2011 CHRY 200 Limited 2D CNVT 6-3.6L Gasoline Electronic Fuel Injection SILVER

VIN: 1C3BC7EG6BN532166 Interior Color: Mileage In: 101,432 Vehicle Out:
License: MV5512B Exterior Color: SILVER Mileage Out:
State: WI Production Date: 4/2011 Condition: Job #:

TRANSMISSION
Automatic Transmission
POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
DECOR
Dual Mirrors
Tinted Glass
Console/Storage

CONVENIENCE
Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Remote Starter
Home Link
RADIO
AM Radio

FM Radio
Stereo
Search/Seek
CD Player
Auxiliary Audio Connection
Satellite Radio
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Hands Free Device
ROOF
Power Convertible Roof

SEATS
Bucket Seats
Leather Seats
Heated Seats
WHEELS
Aluminum/Alloy Wheels
PAINT
Clear Coat Paint
OTHER
Fog Lamps
Traction Control
Stability Control
California Emissions
Power Trunk/Liftgate

Get live updates at www.carwise.com/e/44SV3d

Preliminary Estimate

Customer: WILSON, DARRELL

2011 CHRY 200 Limited 2D CNVT 6-3.6L Gasoline Electronic Fuel Injection SILVER

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		RETRACTABLE TOP					
open	Repl	Front roof pnl	1HY77TZAA	1	954.00	2.0	2.0
3		Add for Clear Coat					0.8
open	Repl	Front w/strip	68028556AA	1	222.00	1.2	
open	Repl	RT Front seal	68026896AA	1	117.00	0.3	
open	Repl	LT Front seal	68026897AA	1	123.00	0.3	
7	R&I	Headliner front				0.7	
8	#	Rpr Front Filler Panel				1.0	1.5
9		VEHICLE DIAGNOSTICS					
10	*	Rpr Pre-repair scan				m 0.5	M
11	*	Rpr Post-repair scan				m 0.5	M
12	#	Subl Hazardous Waste		1	3.50	T	
13	#	Cover Car		1	10.00	T	
14	#	Refn Color Tint					1.0
SUBTOTALS					1,429.50	6.5	5.3

NOTES

Estimate Notes:
Possible hidden damage after tear down.

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,416.00
Body Labor	5.5 hrs @	\$ 65.00 /hr	357.50
Paint Labor	5.3 hrs @	\$ 65.00 /hr	344.50
Mechanical Labor	1.0 hrs @	\$ 115.00 /hr	115.00
Paint Supplies	5.3 hrs @	\$ 45.00 /hr	238.50
Body Supplies	5.8 hrs @	\$ 3.50 /hr	20.30
Miscellaneous			13.50
Subtotal			2,505.30
Sales Tax	\$ 2,505.30 @	5.5000 %	137.79
Grand Total			2,643.09

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: WILSON, DARRELL

2011 CHRY 200 Limited 2D CNVT 6-3.6L Gasoline Electronic Fuel Injection SILVER

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3PR11, CCC Data Date 08/10/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Aln.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.



METICULOUS AUTO BODY INC

Details Make the Difference
8800 FOND DU LAC AVENUE, MILWAUKEE, WI
53225
Phone: (414) 464-9000
FAX: (414) 464-5950

Workfile ID: a415d084
PartsShare: 6p7b2r
Federal ID: 39-1960215

Preliminary Estimate

Customer: Wilson, Darrell

Written By: Kaitlin Mayerson*

Insured: Wilson, Darrell
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0

Owner:
Wilson, Darrell
5341 N. 57th st.
Milwaukee, WI 53218
(414) 554-5484 Cell

Inspection Location:
METICULOUS AUTO BODY INC
8800 FOND DU LAC AVENUE
MILWAUKEE, WI 53225
Repair Facility
(414) 464-9000 Business

Insurance Company:

VEHICLE

2011 CHRY 200 Limited 2D CNVT 6-3.6L Gasoline Electronic Fuel Injection

VIN: 1C3BC7EG6BN532166	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color:	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

POWER

- Power Steering
- Power Brakes
- Power Windows
- Power Locks
- Power Mirrors
- Heated Mirrors
- Power Driver Seat
- Power Passenger Seat

DECOR

- Dual Mirrors
- Tinted Glass
- Console/Storage

CONVENIENCE

- Air Conditioning
- Intermittent Wipers
- Tilt Wheel
- Cruise Control
- Rear Defogger
- Keyless Entry
- Alarm
- Steering Wheel Touch Controls
- Telescopic Wheel
- Climate Control
- Remote Starter
- Home Link

RADIO

- AM Radio

- FM Radio
- Stereo
- Search/Seek
- CD Player
- Auxiliary Audio Connection
- Satellite Radio

SAFETY

- Drivers Side Air Bag
- Passenger Air Bag
- Anti-Lock Brakes (4)
- 4 Wheel Disc Brakes
- Front Side Impact Air Bags
- Hands Free Device

ROOF

- Power Convertible Roof

SEATS

- Bucket Seats
- Leather Seats
- Heated Seats

WHEELS

- Aluminum/Alloy Wheels

PAINT

- Clear Coat Paint

OTHER

- Fog Lamps
- Traction Control
- Stability Control
- Power Trunk/Liftgate

Get live updates at www.carwise.com/e/44VNMp

Preliminary Estimate

Customer: Wilson, Darrell

2011 CHRY 200 Limited 2D CNVT 6-3.6L Gasoline Electronic Fuel Injection

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		ROOF					
2	*	Rpr W'shield header				1.5	1.0
3		Add for Clear Coat					0.2
4		R&I Header trim w/auto temp cntrl				Incl.	
5		RETRACTABLE TOP					
6	*	Repl Front roof pnl	1HY77TZAA	1	954.00	6.0	2.0
7		Add for Clear Coat					0.8
8	#	***** ADD-ONS *****		1			
9	#	Cover car		1	10.00		
10	#	Subl Hazardous Waste Removal		1	3.00 T		
11	#	Repl Corrosion protection primer		1	10.00 T	0.2	
12		R&I Headliner front				0.7	
13		R&I Headliner center and rear				0.7	
SUBTOTALS					977.00	9.1	4.0

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			964.00
Body Labor	9.1 hrs @	\$ 62.00 /hr	564.20
Paint Labor	4.0 hrs @	\$ 62.00 /hr	248.00
Paint Supplies	4.0 hrs @	\$ 42.00 /hr	168.00
Miscellaneous			13.00
Subtotal			1,957.20
Sales Tax	\$ 1,957.20 @	5.5000 %	107.65
Grand Total			2,064.85
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			2,064.85

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.





