

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 27 2018

3.08 A.M./P.M.

1907 N 47th St.
Milwaukee, WI 53208
August 24, 2018

Grant Langley-City Attorney
City of Milwaukee
Office of the City Attorney
200 E. Wells St, Room 2005
Milwaukee, WI 53202

Re: C.I. File #1030-2018-1677
Claimant: Sammie Reed III

Dear Mr. Langley,

Thank you for reading this letter. I am in receipt of your answer dated August 20, 2018 in response to my claim letter dated July 31, 2018 and received by the City Clerk on August 2, 2018, denying my claim for the damage done to my 2009 Hyundai Sonata by one of the city sweepers on or about May 16, 2018.

Though I am disappointed in your decision, **please consider this my official appeal of that decision.** I am requesting that a formal hearing be held on this matter.

If you need any additional information, don't hesitate to contact me at the number or email provided below.

Truly,




Sammie Reed III
steinhausreed8@gmail.com
414-551-2783

w/encl

CITY OF MILWAUKEE
2018 AUG 24 PM 2:59
CITY CLERK'S OFFICE

U.S. POSTAGE PITNEY BOWES
ZIP 53005 \$000.37⁸
02 4W
0000337172 AUG 22 2018



PRESORTED
FIRST CLASS

Sammie L. Reed, III
1907 N. 47th Street
Milwaukee, WI 53208



CITY OF MILWAUKEE
Office of the City Attorney
OFFICE OF THE CITY ATTORNEY
800 City Hall
200 East Wells Street
Milwaukee, Wisconsin 53202-3551

*claim
Denial
Rec'd
8-23-2018*



1907 N. 47th St.,
Milwaukee, WI 53208
July 31, 2018

City Clerk
200 E. Wells, Room 205
Milwaukee, WI 53202-3567

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:50 A.M./P.M.
H


Re: May 16, 2018 Street sweeper crash to my vehicle

Dear Sir or Madam,

In accordance to our talk on or about May 16, 2018, after my 2009 Honda Sonata was parked legally on the street at the above address and struck by a city owned and operated street sweeper #41036 on this same day (which I witnessed leaving the scene of the accident), enclosed are 2 estimates for the damage to repair my vehicle. This is done in accordance with Section 893.80(1), Wis. Stats.

If you have any questions or need any additional information from me, please do not hesitate to contact me at the telephone number or email address provided below.

Truly,



Sammie L. Reed III-Claimant
414-551-2783
steinhausreed8@gmail.com

CITY OF MILWAUKEE
2018 AUG -2 P 3:22
CITY CLERK'S OFFICE

RECEIVED
OFFICE OF CITY ATTORNEY

SOMMER'S BUICK-PONTIAC-SUBARU
7211 W. MEQUON ROAD / PO BOX 37
MEQUON, WI 53092
OFFICE: (262) 242-0100 FAX (262) 242-3702
BODY SHOP MANAGER SCOTT GIERACH

AUG 03 2018

11:50 A.M./P.M.

*** PRELIMINARY ESTIMATE ***

07/17/2018 03:25 PM

Owner

Owner: Sammie Reed III
Address: 1907 N 47th St.
City State Zip: Milwaukee, WI 53208
Email: steinhausreed8@gmail.com

Cell: (414)551-2783
FAX:

Inspection

Inspection Date: 07/17/2018 03:00 PM
Inspection Location: Sommer's Automotive
City State Zip: Mequon, WI 53092
Primary Impact: Left Rear Side
Driveable: Yes

Inspection Type: Drive In
Contact:
FAX:
Secondary Impact:
Rental Assisted:

Appraiser Name: Steve Rahlf

Appraiser License # :

Repairer

Repairer: Sommer's Inc
Address: 7211 W Mequon Rd

Contact: Scott Gierach
Work/Day: (262)242-7170
FAX: (262)242-3702

City State Zip: Mequon, WI 53092

Work/Day:

Target Complete Date/Time:

Days To Repair: 6

Remarks

No Insurance Claim Made Yet / Preliminary Estimate Only

Vehicle

2009 Hyundai Sonata SE V6 4 DR Sedan
6cyl Gasoline 3.3
5 Speed Automatic

Lic.Plate: 493-ZHS
Lic Expire: 06/2019
Prod Date: 03/2720
Veh Insp# :
Condition:
Ext. Color: WILLOW GRAY MET
Ext. Refinish: Two-Stage
Ext. Paint Code: DS

Lic State: WI
VIN: 5NPEU46F69H440009
Mileage: 81,084
Mileage Type: Actual
Code: E3164D
Int. Color: GRAY
Int. Refinish: Two-Stage
Int. Trim Code: U7

Options - AudaVIN Information Received

AM/FM CD Player
Aluminum/Alloy Wheels

Air Conditioning
Anti-Lock Brakes

Alarm System
Auto Headlamp Control

Auxiliary Audio Input	Auxiliary Lighting	Bodyside Moldings
Cargo/Trunk Net	Center Console	Color-Keyed Bumper(s)
Compact Spare Tire	Cruise Control	Digital Signal Processor
Dual Airbags	Floor Mats	Fog Lights
Head Airbags	Heated Power Mirrors	IPOD Control
Illuminated Visor Mirror	Intermittent Wipers	Keyless Entry System
Leather Shift Knob	Leather Steering Wheel	Lighted Entry System
MP3 Decoder	Overhead Console	Power Brakes
Power Door Locks	Power Drivers Seat	Power Steering
Power Windows	Pwr Accessory Outlet(s)	Pwr Driver Lumbar Supp
Rear Spoiler	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	Split Folding Rear Seat	Sport Seats
Sport Suspension	Stability Cntrl Suspensn	Strg Wheel Radio Control
Sunscreen Glass	Tachometer	Tilt & Telescopic Steer
Tinted Glass	Tire Pressure Monitor	Traction Control System
Trip Computer	USB Audio Input(s)	Velour/Cloth Seats
XM Satellite Radio		

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:50 AM/P.M.

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Stripes And Mouldings										
1	RI	100		Mldg,Rear Door Side LT	R & I Assembly				0.3	SM
Rear Doors										
2	BR	287		Door Shell,Rear LT	Blend Refinish				1.3	RF
					0.9 Blend					
					0.4 Two-stage					
3	RI	235		W/Strip,Belt Outer LT	R & I Assembly				0.6	SM
4	RI	1215		Cover,Rr Door Handle LT	R & I Assembly				INC	SM
5	RI	305		Handle,Rr Door Outer LT	R & I Assembly				1.2	SM
6	RI	1149		Supt,Rr Door Handle LT	R & I Assembly				0.2	SM
Quarter And Rocker Panel										
7	BR	94	13	Panel,Bodyside Otr Upr LT	Blend Refinish				1.7	RF
					0.7 Blend					
					0.6 Two-stage setup					
					0.4 Two-stage					
8	I	389		Panel,Quarter LT	Repair				5.0*	SM
				>> 2 Large Dents						
9	L	389		Panel,Quarter LT	Refinish				2.8	RF
					2.3 Surface					
					0.5 Two-stage					
10	RI	627		Mldg,Quarter Side L/F	R & I Assembly				0.2	SM
Rear Bumper										
11	N	584		Rear Bumper Cover R&l	Additional Labor				1.8	SM
Rear Body, Lamps And Floor Pan										
12	RI	533		Taillamp Assembly,Otr LT	R & I Assembly				INC	SM
Manual Entries										
13	EC	M07		Pinstripes-Tape	Replace Economy	\$15.00*			1.0*	SM
14	EC	M14		Corrosion Protection	Replace Economy				0.3*	RF
15	L	M17		Cover Car Exterior	Refinish				0.3*	RF
16	SB	M60		Hazardous Waste Removal	Sublet Repair	\$6.00*				SM
17	L	M66		Color Sand And Buff	Refinish				0.6*	RF
18	L			Masking Refinish/Jambs	Refinish				0.3*	RF*

19 L	Feather/Prime/Block	Refinish	\$20.00*	0.5*	RF*
20 RI	Edge Guard Mlds	R & I Assembly		0.4*	SM*
20 Items					

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts		\$35.00
Paint & Materials	7.8 Hours @ \$45.00	\$351.00
Parts & Material Total		\$386.00
Tax on Parts & Material	@ 5.600%	\$21.62

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$65.00	3.9	6.8	10.7	\$695.50
Mech/Elec (ME)	\$115.00				
Frame (FR)	\$85.00				
Refinish (RF)	\$65.00	7.8		7.8	\$507.00

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:52 AM P.M.

Labor Total			18.5 Hours		\$1,202.50
Tax on Labor	@ 5.600%				\$67.34
Sublet Repairs					\$6.00
Tax on Sublet	@ 5.600%				\$0.34
Gross Total					\$1,683.80
Net Total					\$1,683.80

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53092 Default
Rate Name Default

Audatex Estimating 8.0.554 ES 07/17/2018 03:40 PM REL 8.0.554 DT 07/01/2018 DB 07/15/2018
© 2018 Audatex North America, Inc.

1.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned

UC = Replace Reconditioned
N = Additional Labor
IT = Partial Repair
P = Check

TT = Two-Tone
BR = Blend Refinish
CG = Chipguard
AA = Appearance Allowance

SB = Sublet Repair
I = Repair
RI = R & I Assembly
RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:50 A.M./P.M.



RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:30 (A.M./P.M.)



Gmail

More

COMPOSE

Sommer's Automotive estimate for Reed III, Sammie : 2009 Hyundai Sonata

- Inbox (99)
- Starred
- Sent Mail
- Drafts (8)
- Unwanted
- More

Heidi +

? **Steven Rahlf** <stever@sommercars.com>
 03/11/18
 Hi Sammie,
 Attached is a copy of the estimate & photos for your 2009 Hyundai Sonata with damage to the Left Rear 1/4 Panel area
 Please let me know if you have any questions or if I can assist you in any way.
 It was really nice seeing you my friend !! Take Care !!
 Thank You,
 Steve
 262-242-0100 Ext - 268

14 Attachments



No Hangouts contacts
[Find someone](#)

[Click here to Reply or Forward](#)

0.12 GB (0%) of 15 GB used

[Terms](#) · [Privacy](#) · [Program Policy](#)

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:50 A.M./P.M.

AMATO COLLISION CENTER
8301 NORTH 76TH STREET
MILWAUKEE, WI 53223
OFFICE: (414)357-8500 FAX: (414)357-8161

*** PRELIMINARY ESTIMATE ***

07/27/2018 12:24 PM

Owner

Owner: SAMMIE REED III
Address:

Work/Day: (414)551-2783

RECEIVED
OFFICE OF CITY ATTORNEY

Inspection

Inspection Date: 07/27/2018 12:25 PM

Inspection Type:

AUG 03 2018

Contact: JASON BRAATZ

11:52 A.M./P.M.

Repairer

Repairer: AMATO COLLISION CENTER
NORTH
Address: 8301 N 76TH ST
City State Zip: MILWAUKEE, WI 53223
Email: amatocolln@yahoo.com

Contact: JASON BRAATZ

Work/Day: (414)357-7800

Work/Day: (414)357-8161

Target Complete Date/Time:

Days To Repair: 6

Vehicle

2009 Hyundai Sonata Limited V6 4 DR Sedan
6cyl Gasoline 3.3
5 Speed Automatic

Lic Expire:
Veh Insp# :
Condition:
Ext. Refinish: Two-Stage

VIN: 5NPEU46F69H440009
Mileage Type: Actual
Code: E3164C
Int. Refinish: Two-Stage

Options

AM/FM In-dash CD Changer
Aluminum/Alloy Wheels
Auto Headlamp Control
Auxiliary Lighting
Center Console
Compact Spare Tire
Dual Airbags
Fog Lights
Heated Front Seats
Illuminated Visor Mirror
Keyless Entry System
Leather Steering Wheel
Overhead Console
Power Drivers Seat
Power Windows
Rear Window Defroster

Air Conditioning
Amplifier
Automatic Dimming Mirror
Bodyside Moldings
Chrome Grille
Cruise Control
Dual Zone Auto A/C
Garage Door Opener
Heated Power Mirrors
Infinity Sound System
Leather Seats
Lighted Entry System
Power Brakes
Power Moonroof
Pwr Accessory Outlet(s)
Rem Trunk-L/Gate Release

Alarm System
Anti-Lock Brakes
Auxiliary Audio Input
Bucket Seats
Color-Keyed Bumper(s)
Digital Signal Processor
Electronic Compass
Head Airbags
IPOD Control
Intermittent Wipers
Leather Shift Knob
MP3 Decoder
Power Door Locks
Power Steering
Pwr Driver Lumbar Supp
Side Airbags

Split Folding Rear Seat	Stability Cntrl Suspens	Strg Wheel Radio Control
Subwoofer	Tachometer	Telescopic Steering Whl
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Traction Control System	Trip Computer	USB Audio Input(s)
Wood Interior Trim	XM Satellite Radio	

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
Stripes And Mouldings										
1	RI	109		Mldg,Rear Door Side L/R	R & I Assembly				0.3	SM
Rear Doors										
2	BR	287		Door Shell,Rear LT	Blend Refinish				1.3	RF
					0.9 Blend					
					0.4 Two-stage					
3	RI	235		W/Strip,Belt Outer LT	R & I Assembly				0.6	SM
4	RI	305		Handle,Rr Door Outer LT	R & I Assembly				1.2	SM
Quarter And Rocker Panel										
5	BR	94	13	Panel,Bodyside Otr Upr LT	Blend Refinish				1.7	RF
					0.7 Blend					
					0.6 Two-stage setup					
					0.4 Two-stage					
6	I	389		Panel,Quarter LT	Repair				6.0*	SM
7	L	389		Panel,Quarter LT	Refinish				2.8	RF
					2.3 Surface					
					0.5 Two-stage					
8	RI	605		Mldg,Quarter Side L/F	R & I Assembly				0.2	SM
Rear Bumper										
9	N	584		Rear Bumper Cover R&I	Additional Labor				1.8	SM
Rear Body, Lamps And Floor Pan										
10	RI	533		Taillamp Assembly,Otr LT	R & I Assembly				INC	SM
Manual Entries										
11	EC	M07		Pinstripes-Tape	Replace Economy	\$20.00*			0.5*	SM
12	L	M14		Corrosion Protection	Refinish				0.5*	RF
13	L	M17		Cover Car Exterior	Refinish	\$3.00*			0.2*	RF
14	SB	M60		Hazardous Waste Removal	Sublet Repair	\$5.00*				SM
14	Items									

RECEIVED
OFFICE OF CITY ATTORNEY

AUG 03 2018

11:50 A.M./P.M.

MC Message

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Other Parts		\$23.00
Paint & Materials	6.5 Hours @ \$38.00	\$247.00
Parts & Material Total		\$270.00
Tax on Parts & Material	@ 5.600%	\$15.12

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$58.00	2.8	7.8	10.6	\$614.80

Mech/Elec (ME)	\$105.00				
Frame (FR)	\$58.00				
Refinish (RF)	\$58.00	6.5	6.5	\$377.00	
Labor Total			17.1 Hours		\$991.80
Tax on Labor		@ 5.600%		\$55.54	
Sublet Repairs				\$5.00	
Tax on Sublet		@ 5.600%		\$0.28	
Gross Total					\$1,337.74
Net Total					\$1,337.74

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53223 Default
 SPPL Yes Zip Code: 00000 Default
 Rate Name Default

RECEIVED
OFFICE OF CITY ATTORNEY

Audatex Estimating 8.0.414 ES 07/27/2018 12:28 PM REL 8.0.414 DT 07/01/2018 DB 07/15/2018
 © 2018 Audatex North America, Inc.

AUG 03 2018


1.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

11:50 A.M./P.M.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

- | | | |
|----------------------------|---|--------------------------------|
| * = User-Entered Value | ^ = Labor Matches System Assigned Rates | E = Replace OEM |
| NG = Replace NAGS | EC = Replace Economy | OE = Replace PXN OE Srpls |
| UE = Replace OE Surplus | ET = Partial Replace Labor | EP = Replace PXN |
| EU = Replace Recycled | TE = Partial Replace Price | PM = Replace PXN Reman/Reblt |
| UM = Replace Reman/Rebuilt | L = Refinish | PC = Replace PXN Reconditioned |
| UC = Replace Reconditioned | TT = Two-Tone | SB = Sublet Repair |
| N = Additional Labor | BR = Blend Refinish | I = Repair |
| IT = Partial Repair | CG = Chipguard | RI = R & I Assembly |
| P = Check | AA = Appearance Allowance | RP = Related Prior Damage |



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.
 AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

